

location provided under the caption
ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Sikorsky Aircraft Corporation: Docket No. 2002–SW–39–AD.

Applicability: Model S76A, B, and C helicopters, with main landing gear brake assembly (brake assembly), part number (P/N) 5007555, 5007555–1, or 5007555–2 installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent reduced braking performance and subsequent loss of control of the helicopter, accomplish the following:

(a) Within 60 days, determine if a main landing gear brake disc (disc), part number (P/N) 5014067, is installed in the braking assembly in accordance with:

(1) Section III-Accomplishment Instructions, paragraph 1.A. through 1.D., of Aircraft Braking Systems Corporation Alert Service Bulletin S76–32–A24, dated April 10, 2002 (ASB A24) for braking assembly, P/N 5007555 and P/N 5007555–1, and

(2) Section III-Accomplishment Instructions, paragraph 1.A. and 1.B., of Aircraft Braking Systems Corporation Alert Service Bulletin S76–32–A25, dated May 15, 2002 (ASB A25), for braking assembly, P/N 5007555–2.

(b) If disc, P/N 5014067, is installed, within 90 days, remove that disc and replace it with disc, P/N 5007672, and re-identify:

(1) Brake assembly, P/N 5007555 and P/N 5007555–1, as brake assembly, P/N 5007555–3, in accordance with the conversion of brake assembly instructions on page 6 of ASB A24, and

(2) Brake assembly, P/N 5007555–2, as brake assembly, P/N 5007555–4, in accordance with the conversion of brake assembly instructions on page 6 of ASB A25.

Note 2: Sikorsky Aircraft Corporation ASB No. 76–32–27, dated April 30, 2002, contains Aircraft Braking Systems Corporation ASB S76–32–A24, dated April 10, 2002, and Sikorsky Aircraft Corporation ASB No. 76–32–28, dated May 17, 2002, contains Aircraft Braking Systems Corporation ASB S76–32–A25, dated May 15, 2002.

(c) Until all installed discs, P/N 5014067, on the helicopter are replaced with disc, P/N 5007672, and all brake assemblies are re-identified in accordance with paragraph (b) of this AD, before further flight, increase the Category A-Rejected Takeoff Distance, the Category A-Landing Distance, and the Category B-Landing Distance as stated in the current Rotorcraft Flight Manual (RFM) by multiplying these rejected takeoff and landing distances by a factor of 1.67.

Note 3: There are temporary revisions to the RFM available from the helicopter manufacturer that documents increased rejected takeoff and landing distances.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Boston Aircraft Certification Office, Engine and Propeller Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Boston Aircraft Certification Office.

Note 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Boston Aircraft Certification Office.

(e) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

Issued in Fort Worth, Texas, on January 29, 2003.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 03–3031 Filed 2–6–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002–SW–27–AD]

RIN 2120–AA64

Airworthiness Directives; Bell Helicopter Textron Canada Model 222, 222B, and 222U Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes adopting a new airworthiness directive (AD) for the specified Bell Helicopter Textron Canada (Bell) helicopters. This proposal would require a one-time inspection of the adjustable stop screws of the magnetic brake assembly; repairing, as appropriate, certain mechanical damage to the cyclic and collective flight control magnetic brake arm assembly (arm assembly), if necessary; and installing the stop screw with the proper adhesive, adjusting the arm assembly travel and applying slippage marks. This proposal is prompted by reports that the magnetic brake adjustable screws have backed out, which limited travel of the arm assembly. The actions specified by this proposed AD are intended to detect loose adjustable stop screws, that could result in limiting the travel of the cyclic and collective arm assembly, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before April 8, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Office of the Regional Counsel, Southwest Region, Attention: Rules Docket No. 2002–SW–27–AD, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137. You may also send comments electronically to the Rules Docket at the following address: 9-asw-adcomments@faa.gov. Comments may be inspected at the Office of the Regional Counsel between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Charles Harrison, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193–0110, telephone (817) 222–5128, fax (817) 222–5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications should identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments will be considered before taking action on the proposed rule. The proposals contained in this document may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their mailed comments submitted in response to this proposal must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. 2002-SW-27-AD." The postcard will be date stamped and returned to the commenter.

Discussion

Transport Canada, the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on Bell Model 222, 222B, and 222U helicopters with Instrument Flight Rule (IFR) kits, part number (P/N) 222-706-013, installed, and all delivered spare magnetic brakes, P/N 222-706-013, manufactured by Memcor Truohm, Inc., under P/N MP 498-3. Transport Canada advises that the stop screws, P/N MS51959-3, of the magnetic brake, P/N 204-001-376-003 (Memcor Truohm P/N MP 498-3), were installed without the proper adhesive.

Bell has issued Bell Helicopter Textron Alert Service Bulletin (ASB) No. 222-01-87, for Model 222 and 222B helicopters, and ASB No. 222U-01-58, for Model 222U helicopters, both dated January 19, 2001. Both ASB's specify a one-time inspection of the magnetic brake adjustable stop screw, P/N M551959-3; repairing any arm assembly mechanical damage created by the screws; and installing the stop screw with the proper adhesive and adjusting the arm assembly shaft travel. Transport Canada classified these ASB's as

mandatory and issued AD No. CF-2002-17, dated March 4, 2002, to ensure the continued airworthiness of these helicopters in Canada.

These helicopter models are manufactured in Canada and are type certificated for operation in the United States under the provisions of 14 CFR 21.29 and the applicable bilateral agreement. Pursuant to the applicable bilateral agreement, Transport Canada has kept the FAA informed of the situation described above. The FAA has examined the findings of Transport Canada, reviewed all available information, and determined that AD action is necessary for products of these type designs that are certificated for operation in the United States.

This unsafe condition is likely to exist or develop on other helicopters of these same type designs registered in the United States. Therefore, the proposed AD would require inspecting the adjustable stop screws of the magnetic brake assembly to ensure they are installed correctly; repairing the arm assembly, if necessary; installing the stop screw with the proper adhesive; adjusting the arm assembly travel; and applying slippage marks. The actions would be required to be accomplished in accordance with the ASB's described previously.

The FAA estimates that 92 helicopters of U.S. registry would be affected by this proposed AD, that it would take approximately 3 work hours per helicopter to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Required parts would cost approximately \$3,785. Based on these figures, the total cost impact of the proposed AD on U.S. operators is estimated to be \$364,780, assuming all parts are replaced.

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this

action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Bell Helicopter Textron, a Division of Textron Canada: Docket No. 2002-SW-27-AD.

Applicability: Model 222, 222B, and 222U helicopters, with a magnetic brake, part number (P/N) 204-001-376-105 or 107, installed, that was manufactured by Memcor Truohm, Inc. as P/N MP498-105 or -107, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within 100 hours time in service and before installation of any affected magnetic brake, unless accomplished previously.

To detect loose adjustable stop screws, that could result in limiting the travel of the cyclic and collective arm assembly, and subsequent loss of control of the helicopter:

(a) Inspect and, if necessary, repair, adjust, and apply slippage marks to the magnetic brake assembly in accordance with the Accomplishment Instructions, paragraphs 5. through 11. in Bell Helicopter Textron Alert Service Bulletin (ASB) No. 222-01-87, applicable to Model 222 and 222B helicopters, or ASB No. 222U-01-58, applicable to Model 222U helicopters, both dated January 19, 2001, except if damage to

the arm assembly exceeds 0.030 inch (0.762 mm), replace the magnetic brake assembly with an airworthy magnetic brake assembly. Contacting the manufacturer is not required.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished.

Note 3: The subject of this AD is addressed in Transport Canada (Canada) AD CF-2002-17, dated March 4, 2002.

Issued in Fort Worth, Texas, on January 29, 2003.

David A. Downey,
Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 03-3030 Filed 2-6-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOUSING AND URBAN DEVELOPMENT

24 CFR Part 3500

[Docket No. FR-4727-N-01]

Real Estate Settlement Procedures Act (RESPA); Rule on Simplifying and Improving the Process of Obtaining Mortgages to Reduce Settlement Costs to Consumers: Target Publication Date of Final Rule

AGENCY: Office of the Assistant Secretary for Housing-Federal Housing Commissioner, HUD.

ACTION: Notice of target publication date of RESPA final rule.

SUMMARY: On July 29, 2002, HUD published its proposed rule on "RESPA; Simplifying and Improving the Process of Obtaining Mortgages to Reduce Settlement Costs to Consumers" (RESPA rule). This notice advises the public of HUD's anticipated publication date for the RESPA final rule.

FOR FURTHER INFORMATION CONTACT: Ivy Jackson, Acting Director, Office of RESPA and Interstate Land Sales, Room 9146, U.S. Department of Housing and Urban Development, 451 Seventh Street, SW., Washington, DC 20410; telephone (202) 708-0502 (this is not a toll-free number) or for legal questions Kenneth A. Markison, Assistant General Counsel

for GSE/RESPA, or Steven J. Sacks or Teresa L. Baker (Senior RESPA Attorneys); Room 9262, telephone (202) 708-3137. Persons with hearing or speech impairments may access this number via TTY by calling the toll-free Federal Information Relay Service at (800) 877-8339. The address for the above listed persons is: Department of Housing and Urban Development, 451 Seventh Street, SW., Washington, DC 20410.

SUPPLEMENTARY INFORMATION: On December 9, 2002, over 60 Federal departments, agencies and commissions (collectively, Federal agencies) published, in the **Federal Register**, their respective agendas of regulations and regulatory plans. This compilation, referred to as the Unified Agenda, is published semiannually under the coordination of the Office of Management and Budget. The Unified Agenda provides for uniform reporting by Federal agencies of regulatory and deregulatory actions that are under development and expected to be issued within the next six to 12 months. In the fall, each Federal agency's semiannual agenda of regulations is accompanied by the agency's regulatory plan. The regulatory plan contains the Federal agency's most important significant regulatory actions that the agency expects to issue in the new fiscal year. Both documents provide the agencies' estimates of publication dates for their proposed and final rules. HUD's fall semiannual agenda of regulations and regulatory plan can be found in the December 9, 2002, **Federal Register** at 67 FR 74550 and 67 FR 74140, respectively.

HUD's regulatory plan advised that HUD's RESPA final rule would be published in January 2003. (See 67 FR 74147). This date is incorrect. HUD anticipates that its RESPA final rule will be published in the spring of 2003.

Dated: January 30, 2003.

John C. Weicher,

Assistant Secretary for Housing-Federal Housing Commissioner.

[FR Doc. 03-2973 Filed 2-6-03; 8:45 am]

BILLING CODE 4210-27-P

DEPARTMENT OF TRANSPORTATION

Research and Special Programs Administration

49 CFR Part 192

[Docket No. RSPA-00-7666; Notice 5]

RIN 2137-AD54

Pipeline Safety: Pipeline Integrity Management in High Consequence Areas (Gas Transmission Pipelines)

AGENCY: Office of Pipeline Safety (OPS), Research and Special Programs Administration (RSPA), DOT

ACTION: Notice of workshop.

SUMMARY: This notice announces a two-day workshop on proposed regulations on "Pipeline Integrity Management in High Consequence Areas", jointly organized by the Interstate Natural Gas Association of America (INGAA) Foundation and the American Gas Association (AGA). This workshop is intended to give participants an understanding of the integrity management program requirements being proposed in the rule and the process to comment on the proposed rulemaking. An OPS representative will give an overview of the proposed regulation and answer questions about it.

DATES: The workshop is open to all. There is no registration fee. This workshop will be held on February 20, 2003, from 8 a.m. to 5 p.m., and on February 21, 2003, from 8 a.m. to 12 noon.

ADDRESSES: The workshop will be held at the Renaissance Houston Hotel, 6 Greenway Plaza, Houston, Texas, 713-629-1200.

FOR FURTHER INFORMATION CONTACT: Contact Mike Israni by phone at (202) 366-4571, by e-mail at mike.israni@rspa.dot.gov. General information about RSPA/OPS programs may be obtained by accessing OPS's Internet page at <http://ops.dot.gov>. For other details on this workshop contact Linda A. Thomas of INGAA at 202-216-5925.

SUPPLEMENTARY INFORMATION:

Background

RSPA/OPS has just proposed a rule to require operators of gas transmission pipelines to develop integrity management programs. The programs include conducting baseline and periodic assessments of pipeline segments. This follows rulemaking that requires integrity management programs for hazardous liquid pipelines.