

Restatement of Certain Requirements of AD 2001-17-26 R1:

Inspection

(a) For Model DH.125, HS.125, and BH.125 series airplanes; BAe.125 series 800A, 800A (C-19A), 800A (U-125A), 1000A, and 1000B airplanes; and Model Hawker 800, 800 (including variant U-125A), 800XP, and 1000 airplanes: Perform an eddy current inspection of the actuator cylinder head lugs for cracking or corrosion per Raytheon Service Bulletin 32-3391, dated August 2000, at the time specified in paragraph (a)(1), (a)(2), (a)(3), or (a)(4) of this AD, as applicable.

(1) For actuator cylinder heads that have 3,000 or less total landings as of October 3, 2001 (the effective date of AD 2001-17-26 R1, amendment 39-12619): Perform the eddy current inspection within 24 months after October 3, 2001.

(2) For actuator cylinder heads that have 3,001 to 4,000 total landings as of October 3, 2001: Perform the eddy current inspection within 6 months after October 3, 2001.

(3) For actuator cylinder heads that have been in service for more than 7 years as of October 3, 2001: Perform the eddy current inspection within 6 months after October 3, 2001.

(4) For actuator cylinder heads that have 4,001 or more total landings as of October 3, 2001: Perform the eddy current inspection within 10 landings after October 3, 2001.

New Requirements of this AD:

(b) For Model BAe.125 series 800B airplanes: Perform an eddy current inspection of the actuator cylinder head lugs for cracking or corrosion per Raytheon Service Bulletin 32-3391, dated August 2000, at the time specified in paragraph (b)(1), (b)(2), or (b)(3) of this AD, as applicable.

(1) For actuator cylinder heads that have 3,000 or less total landings as of the effective date of this AD: Perform the eddy current inspection within 24 months after the effective date of this AD.

(2) For actuator cylinder heads that have 3,001 to 4,000 total landings as of the effective date of this AD: Perform the eddy current inspection within 6 months after the effective date of this AD.

(3) For actuator cylinder heads that have been in service for more than 7 years or that have 4,001 or more total landings as of the effective date of this AD: Perform the eddy current inspection at the earlier of the times specified in paragraph (b)(3)(i) or (b)(3)(ii) of this AD.

(i) Within 6 months after the effective date of this AD.

(ii) Within 10 landings after the effective date of this AD.

If No Cracking or Corrosion

(c) If no cracking or corrosion is found during the inspection required by paragraph (a) or (b) of this AD, before further flight, accomplish follow-on actions (e.g., "vibro-etching" the MLG actuator data plate, painting a blue stripe on the actuator cylinder head to indicate 1¹/₃₂-inch oversize bushings, replacing bushings, and applying corrosion protection to the lug bores), per Raytheon Service Bulletin 32-3391, dated August 2000.

If Any Cracking or Corrosion

(d) If any cracking or corrosion is found during the inspection required by paragraph (a) or (b) of this AD, before further flight, accomplish either of the actions specified in paragraph (d)(1) or (d)(2) of this AD, per Raytheon Service Bulletin 32-3391, dated August 2000:

(1) Replace the actuator of the MLG with a new or serviceable actuator; or

(2) Replace the actuator cylinder head with a new cylinder head.

Note 2: Raytheon Service Bulletin 32-3391, dated August 2000, references Precision Hydraulics Component Maintenance Manual 32-30-1105 as an additional source of service information.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Wichita Aircraft Certification Office (ACO), FAA. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

Special Flight Permits

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Incorporation by Reference

(g) The actions shall be done in accordance with Raytheon Service Bulletin 32-3391, dated August 2000. This incorporation by reference of that document was approved previously by the Director of the Federal Register as of October 3, 2001 (66 FR 45575, August 29, 2001). Copies may be obtained from Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

Effective Date

(h) This amendment becomes effective on April 4, 2003.

Issued in Renton, Washington, on February 19, 2003.

Ali Bahrami,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 03-4586 Filed 2-27-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-SW-43-AD; Amendment 39-13061; AD 2003-04-12]

RIN 2120-AA64

Airworthiness Directives; Bell Helicopter Textron Canada Limited Model 427 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the specified Bell Helicopter Textron Canada (Bell) model helicopters that requires modifying the auxiliary fin assemblies and revising the Limitations section of the Rotorcraft Flight Manual (RFM) to reduce the never-exceed speed (Vne) for a tail rotor pedal stop failure. This amendment is prompted by several incidents of main rotor blades contacting the top of the fin that have resulted in an upper tuning weight (weight) becoming loose. The actions specified by this AD are intended to prevent a main rotor blade from striking an auxiliary fin, loss of a tuning weight, impact with a tail or main rotor blade, and subsequent loss of control of the helicopter.

DATES: Effective April 4, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of April 4, 2003.

ADDRESSES: The service information referenced in this AD may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4, telephone (450) 437-2862 or (800) 363-8023, fax (450) 433-0272. This information may be examined at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Sharon Miles, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Regulations Group, Fort Worth, Texas 76193-0111, telephone (817) 222-5122, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to add an AD for Bell Model 427 helicopters was published in the

Federal Register on November 28, 2001 (66 FR 59377). That NPRM would have required modifying the fins, part number (P/N) 427-035-836-101 and 427-035-836-102, to relocate the weights, P/N 407-023-003-145. That proposal recognized that relocating the tuning weights was an interim action and anticipated that contact between the main rotor blades and the top portion of the fins would be addressed in a separate AD. However, prior to publishing the final rule based on that NPRM, the manufacturer published service information about reducing the height of the fins. Further, Transport Canada issued a revised AD requiring the height reduction in Canada. Hence, reducing the height of the fins made the relocation of the tuning weights unnecessary, therefore a supplemental proposal was published in the **Federal Register** on October 18, 2002 (67 FR 64326). That action proposed to require modifying the auxiliary fin assemblies to reduce the height and revising the Limitations section of the RFM to reduce the Vne for a tail rotor pedal stop failure from 80 knots indicated airspeed (KIAS) to 60 KIAS.

Transport Canada, the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on Bell Model 427 helicopters. Transport Canada advises of several ground incidents of main rotor blades contacting the top portion of a fin. Such incidents occurred on helicopters with an internal gross weight capability of 6,350 lbs. and the larger auxiliary fin assemblies.

Bell has issued Alert Service Bulletin 427-01-7, dated November 16, 2001 (ASB), which specifies reducing the height of the auxiliary fin assembly, part number (P/N) 427-035-836-101, -102, -105, and -106 within 300 hours time-in-service (TIS). Transport Canada classified this ASB as mandatory and issued AD No. CF-2001-05R1, dated February 13, 2002, to ensure the continued airworthiness of these helicopters in Canada.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed with the exception of minor non-substantive changes and updating the Rotorcraft Flight Manual from Revision 3 to Revision 5, which is referenced in Note 2 of the AD.

The FAA estimates that 30 helicopters of U.S. registry will be affected by this AD, that it will take approximately 12

work hours per helicopter to accomplish the actions, and that the average labor rate is \$60 per work hour. Required parts will cost approximately \$1,685 per helicopter. Based on these figures, the total cost impact of the AD on U.S. operators is estimated to be \$72,150 to perform the modifications and revisions for the entire fleet.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2003-04-12 Bell Helicopter Textron

Canada: Amendment 39-13061. Docket No. 2001-SW-43-AD.

Applicability: Model 427 helicopters, serial numbers 56001 through 56030 with auxiliary fin assemblies, part numbers 427-035-836-101, -102, -105, or -106, installed, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (c) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent a main rotor blade from striking an auxiliary fin, loss of an upper tuning weight, impact with a tail or main rotor blade, and subsequent loss of control of the helicopter:

(a) Within 60 days, modify auxiliary fin assemblies, part numbers (P/N) 427-035-836-101, -102, -105, or -106, in accordance with the Accomplishment Instructions in Bell Helicopter Textron Alert Service Bulletin No. 427-01-07, dated November 16, 2001.

(b) After accomplishing paragraph (a) of this AD, reduce the never-exceed speed (Vne) limitation for a pedal stop failure from 80 knots indicated airspeed (KIAS) to 60 KIAS.

Note 2: Bell Helicopter Textron Rotorcraft Flight Manual BHT-427-FM-2, Revision 5, dated April 23, 2002, incorporates the reduced airspeed limitation for a pedal stop failure.

(c) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

Note 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(d) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(e) The modification shall be done in accordance with the Accomplishment Instructions in Bell Helicopter Textron Alert Service Bulletin No. 427-01-07, dated November 16, 2001. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J1R4, telephone (450) 437-2862 or (800) 363-8023, fax (450) 433-0272. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register,

800 North Capitol Street, NW., suite 700, Washington, DC.

(f) This amendment becomes effective on April 4, 2003.

Note 4: The subject of this AD is addressed in Transport Canada (Canada) AD No. CF-2001-05R1, dated February 13, 2002.

Issued in Fort Worth, Texas, on February 14, 2003.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 03-4477 Filed 2-27-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-353-AD; Amendment 39-13073; AD 2003-04-24]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; request for comments.

SUMMARY: This amendment adopts a new airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model 717-200 airplanes. This action requires a one-time inspection for cracking of the support fitting assemblies and stop pads of the main spoiler actuators, and follow-on actions. This action is necessary to find and fix cracking of the support fitting assemblies of the main spoiler actuator, which could result in damage of adjacent structure such as the rear spar or upper skin panel, and consequent reduced structural integrity of the airplane. This action is intended to address the identified unsafe condition.

DATES: Effective March 17, 2003.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 17, 2003.

Comments for inclusion in the Rules Docket must be received on or before April 29, 2003.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-353-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m.,

Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-iarcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-353-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 for Windows or ASCII text.

The service information referenced in this AD may be obtained from Boeing Commercial Aircraft Group, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5238; fax (562) 627-5210.

FOR FURTHER INFORMATION CONTACT: Maureen Moreland, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5238; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION: The FAA has received reports indicating that cracking has been found on a support fitting assembly for the main spoiler actuators on several McDonnell Douglas Model 717-200 airplanes. On one airplane, a crack completely separated a forward attachment lug from the support fitting. This allowed the lug to move forward and contact and damage the rear spar of the wing, which resulted in cracking of the spar and fuel seepage. On another airplane, the support fitting cracked laterally across the center of the fitting. Investigation revealed that the stop pad had been broken off at the pad's aft attachment hole, and contact occurred between the spoiler actuator and fitting. While the root-cause of these cracks is unknown, one possibility is improper rigging of the spoiler hold-down actuator, which could cause additional loading and fatigue in the support fitting. Cracking of a support fitting assembly for a main spoiler actuator, if not corrected, could result in damage of adjacent structure such as the rear spar or upper skin panel, and consequent reduced structural integrity of the airplane.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 717-57A0013, dated December 20, 2002. That service bulletin describes procedures for a one-time visual inspection for cracking of the support fitting assemblies and stop pads of the main spoiler actuators. For support fitting assemblies on which no cracking is found, the service bulletin describes procedures for a follow-on test of the rigging of the spoiler hold-down actuators to ensure that the actuators are rigged correctly. For cracked support fitting assemblies or stop pads, the service bulletin specifies to contact Boeing for instructions for repair and additional inspections.

Explanation of the Requirements of the Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design, this AD is being issued to find and fix cracking of the support fitting assemblies of the main spoiler actuator, which could result in damage of adjacent structure such as the rear spar or upper skin panel, and consequent reduced structural integrity of the airplane. This AD requires accomplishment of the actions specified in the service bulletin described previously, except as discussed under the heading "Differences Between This AD and the Service Bulletin." This AD also requires that operators report results of inspection findings to the FAA and to Boeing.

Interim Action

This is considered to be interim action. The inspection reports that are required by this AD will enable the manufacturer to obtain better insight into the nature, cause, and extent of the cracking, and eventually to develop final action to address the unsafe condition. Once final action has been identified, the FAA may consider further rulemaking.

Clarification of Inspection Type

The service bulletin identifies the inspection for cracking or other discrepancy as a "visual" inspection. We have determined that the inspection described in the service bulletin constitutes a "detailed" inspection. Note 2 of this AD defines such an inspection.

Differences Between This AD and the Service Bulletin

Operators should note that, although the service bulletin specifies that the