

the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

(c) For airplanes on which the modification required by paragraph (a) of this AD has been done according to Boeing Service Bulletin 757-54-0035, dated July 17, 1997: Within 15,000 flight cycles after doing the modification required by paragraph (a) of this AD, or within 3 years after the effective date of this AD, whichever is later; do a one-time detailed inspection of the middle gusset of the inboard side load fitting for proper alignment, according to Part II of the Accomplishment Instructions of Boeing Service Bulletin 757-54-0035, Revision 1, dated April 15, 1999; or Revision 2, dated June 13, 2002, excluding Evaluation Form. If the gusset is not aligned properly, before further flight, machine the gusset to the specified angle according to the service bulletin.

(d) Before further flight after doing paragraph (c) of this AD, do the actions required by paragraphs (d)(1) and (d)(2) of this AD.

(1) Remove the aft bulkhead fasteners of the lower spar fitting and do a one-time eddy current inspection of those fastener holes for cracking, according to Part V of the Accomplishment Instructions of Boeing Service Bulletin 757-54-0035, Revision 1, dated April 15, 1999; or Revision 2, dated June 13, 2002, excluding Evaluation Form.

(2) Do a detailed inspection of the 8 fasteners of the lower spar fitting for loose or missing fasteners, according to a method approved by the Manager, Seattle ACO. Before further flight, replace any loose or missing fasteners with new fasteners according to Boeing Service Bulletin 757-54-0035, Revision 1, dated April 15, 1999; or Revision 2, dated June 13, 2002, excluding Evaluation Form.

**Note 4:** The 8 fasteners are located in Panel 7 at Location 37. The number of fasteners at Location 37 has increased from 2 to 8 fasteners. Figure 30 of Boeing Service Bulletin 757-54-0035, Revision 2, dated June 13, 2002, excluding Evaluation Form, illustrates the location of the fasteners.

(e) If any cracking is found during any inspection required by this AD: Before further flight, repair according to a method approved by the Manager, Seattle ACO; or according to data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Seattle ACO, to make such findings. For a repair method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically reference this AD.

(f) If no cracking is found during any inspection required by this AD, or after repair of cracking as required by paragraph (e) of this AD, before further flight, increase the diameter of the fastener holes and install new fasteners according to Boeing Service Bulletin 757-54-0035, Revision 2, dated June 13, 2002, excluding Evaluation Form.

(g) Except as identified in Figures 3 and 5 of the Accomplishment Instructions of

Boeing Service Bulletin 757-54-0035, Revision 2, dated June 13, 2002, excluding Evaluation Form, the actions must be done using Boeing-supplied tools.

#### Alternative Methods of Compliance

(h)(1) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Seattle ACO. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Seattle ACO.

(2) Alternative methods of compliance, approved previously in accordance with AD 99-24-07, amendment 39-11431, are approved as alternative methods of compliance with paragraph (a) of this AD.

**Note 5:** Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Seattle ACO.

#### Special Flight Permit

(i) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on April 9, 2003.

**Ali Bahrami,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*  
[FR Doc. 03-9138 Filed 4-14-03; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA 2003-1407; Airspace Docket No. 03-ASO-3]

#### Proposed Establishment of Class E2 Airspace, Proposed Amendment of Class E5 Airspace; Waycross, GA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This notice proposes to establish Class E2 airspace and amend Class E5 airspace at Waycross, GA. The Ware County Airport Authority has requested Class E2 surface area airspace at Waycross-Ware County Airport to provide airport operations within controlled airspace. Jacksonville Air Route Traffic Control Center (ARTCC) would provide air traffic services at the airport and a federally commissioned automated weather observing system is in operation. In order to conduct these operations, Class E2 surface area must be established. This action would

establish Class E2 surface area airspace within a 4.1-radius of the airport.

As a result of an evaluation, it has been determined a modification should be made to the Waycross, GA, Class E5 airspace area to contain the Nondirectional Radio Beacon (NDB) Runway (RWY) 18 Standard Instrument Approach Procedure (SIAP) to Waycross-Ware County Airport. Controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to contain the SIAP. Additionally, the 7-mile radius of the Waycross-Ware County Airport would be reduced to a 6.6-mile radius.

**DATES:** Comments must be received on or before May 15, 2003.

**ADDRESSES:** Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2003-14707/ Airspace Docket No. 03-ASO-3, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. to 5 p.m., Monday through Friday, except Federal holidays. The Docket office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

An informal docket may also be examined during normal business hours at the office of the Regional Air Traffic Division, Federal Aviation Administration, Room 550, 1701 Columbia Avenue, College Park, Georgia 30337.

**FOR FURTHER INFORMATION CONTACT:** Walter R. Cochran, Manager, Airspace Branch, Air Traffic Division, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5627.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both

docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2003-14707/Airspace Docket No. 03-ASO-3." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Superintendent of Document's Web page at <http://www.access.gpo.gov/nara>. Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking, (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

#### The Proposal

The FAA is considering an amendment to Part 71 of the Federal Aviation regulations (14 CFR Part 71) to establish Class E2 airspace and amend Class E5 airspace at Waycross, GA. Class E airspace designations for airspace areas designated as surface areas and airspace areas extending upward from 700 feet or more above the surface of the earth are published in Paragraphs 6002 and 6005 respectively, of FAA Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

#### The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR Part 71 as follows:

#### PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for Part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(d); 40103, 40113, 40120, E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

##### § 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9K, Airspace Designations and Reporting Points, dated August 30, 2002, and effective September 16, 2002, is amended as follows:

##### *Paragraph 6002 Class E Airspace Designated as Surface Areas*

\* \* \* \* \*

##### **ASO GA E2 Waycross [NEW]**

Waycross—Ware County Airport, GA  
(Lat. 31°14'58" long. 82°23'43".)

Waycross VORTAC

(Lat. 31°16'10" long. 82°33'23".)

Within a 4.1-mile radius of the Waycross—Ware County Airport, within 1.2 miles each side of the 099° radial from the Waycross VORTAC, extending from the 4.1-mile radius to 4.7 miles west of the airport. This Class E airspace area is effective during the specific dates and times established in advance by a Notice to Airmen. The effective date and time

will thereafter be continuously published in the Airport/Facility Directory.

\* \* \* \* \*

##### *Paragraph 6005 Class E Airspace Areas Extending Upward from 700 feet or More Above the Surface of the Earth*

\* \* \* \* \*

##### **ASO GA E5 Waycross [Revised]**

Waycross—Ware County Airport, GA

(Lat. 31°14'58" long. 82°23'44".)

WIKET NDB

(Lat. 31°19'28" long. 82°23'58".)

That airspace extending upward from 700 feet above the surface within a 6.6-mile radius of Waycross—Ware County Airport, and within 4 miles west and 8 miles east of the 003° bearing from the WIKET NDB extending from the 6.6-mile radius to 16 miles north of the WIKET NDB; excluding that airspace within the Alma, GA, Class E airspace area.

\* \* \* \* \*

Issued in College Park, Georgia on March 31, 2003.

**Walter R. Cochran,**

*Acting Manager, Air Traffic Division,  
Southern Region.*

[FR Doc. 03-9081 Filed 4-14-03; 8:45 am]

**BILLING CODE 4910-13-M**

#### POSTAL SERVICE

##### 39 CFR Part 111

#### Delivery Confirmation and Signature Confirmation Services With First-Class Mail and Package Services Mail

**AGENCY:** Postal Service.

**ACTION:** Proposed rule.

**SUMMARY:** This proposed rule would amend the *Domestic Mail Manual* (DMM) to clarify when it is permissible to use Delivery Confirmation service and Signature Confirmation service, particularly the limitation of these services to parcel-shaped mail for First-Class Mail and Package Services mail.

**DATES:** Submit comments on or before May 15, 2003.

**ADDRESSES:** Mail or deliver written comments to the Manager, Mailing Standards, ATTN: Neil Berger, U.S. Postal Service, 1735 N. Lynn Street, Room 3025, Arlington, VA 22209-6038. Written comments may be submitted via fax to 703-292-4058. Copies of all written comments will be available for inspection and photocopying between 9 a.m. and 4 p.m., Monday through Friday, at the Postal Service Headquarters Library, 475 L'Enfant Plaza SW., 11th Floor North, Washington, DC 20260-1540.

**FOR FURTHER INFORMATION CONTACT:** Neil Berger at (703) 292-3645.