

TABLE 1.—AFFECTED TURBINE DISCS

Turbine disc serial No.	Turbine disc stage	Date when coating was applied	Turbine disc cycles—since—new when coating was applied
DETN128	HP	31. Mar 01	4356
DETN155	HP	22. Jun 99	0
DETN3541	HP	17. Apr 01	2850
DETN3542	HP	16. Jan 01	6053
LA759	HP	27. Oct 00	5858
LP219	HP	23. Nov 99	6688
LW376	HP	21. Jul 99	3302
LX484	HP	22. Feb 00	4632
LZ299	HP	23. Dec 99	5839
LZ404	HP	13. Jul 01	630
LZ555	HP	30. Aug 00	2158
LZ564	HP	15. Mar 01	4204
SG612	HP	20. Apr 00	5735
SH195	HP	16. Dec 99	5349
DETN25	IP	30. Aug 00	2158
DETN238	IP	31. Mar 01	4356
DETN240	IP	18. Apr 01	0
DETN944	IP	04. Mar 00	2200
DETN2666	IP	17. Apr 01	2850
DETN5538	IP	16. Jul 01	630
DETN6400	IP	14. Apr 99	0
LA407	IP	22. Jun 00	5736
LA858	IP	27. Oct 00	5858
LB99	IP	13. Aug 99	9093
LE284	IP	24. Dec 99	5679
LN87	IP	10. May 99	5829
LP519	IP	23. Nov 99	6688
LW517	IP	22. Dec 99	5865
LX214	IP	09. Dec 00	6498
LX379	IP	22. Feb 00	4632
LZ248	IP	23. Dec 99	5839
LZ385	IP	17. Oct 01	9072
LZ603	IP	22. Jun 99	0
SG554	IP	20. Apr 00	5735
SH863	IP	16. Dec 99	5349

Unsafe Condition

(d) This AD was prompted by reports of Sermetel coating (Omat 7/46) applied to certain turbine discs which, if allowed to remain on the discs would react adversely with the disc dry film lubricant, causing uncontained HP or IP turbine disc failure, which could result in damage to the airplane. The actions specified in this AD are intended to prevent HP or IP turbine disc failure, which could result in damage to the airplane.

Compliance

(e) Compliance with this AD is required as indicated, unless already done.

Determining if Action Is Required

(f) Within 60 days after the effective date of this AD, determine the SN of the HP turbine disc and the IP turbine disc. If none of the HP and IP turbine discs with SN's listed in Table 1 are installed in the engine, no further action is required.

(g) If one or more of the discs with SNs listed in Table 1 of this AD are installed in the engine, do the following:

(1) If the engine has had a full overhaul of the turbine after the shop visit at which the Sermetel coating (Omat 7/46) was applied, no further action is required.

(2) If only the HP turbine disc is listed in Table 1, and the engine has RRD Service Bulletin No. Da72-533, Revision 3, dated October 2001, incorporated, no further action is required.

Removal of Sermetel Coating and Disc Inspection

(3) Before accumulating 10,000 flight cycles since the coating was applied, completely remove Sermetel coating (Omat 7/46) from HP turbine discs and LP turbine discs. Information on coating removal can be found in RRD Overhaul Processes Manual, Overhaul Process 114.

(4) Visually inspect HP turbine discs and LP turbine discs, and return to service discs that pass inspection. Information on disc pass or fail inspection criteria can be found in the RRD Engine Overhaul Manual, Chapter 72-6-1.

Alternative Methods of Compliance

(h) Alternative methods of compliance must be requested in accordance with 14 CFR part 39.19, and must be approved by the Manager, Engine Certification Office.

Material Incorporated by Reference

(i) None.

Related Information

(j) The subject of this AD is addressed in LBA airworthiness directive LTA 2003-015, dated February 6, 2003.

Issued in Burlington, Massachusetts, on April 29, 2003.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. 03-10984 Filed 5-2-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2003-14656; Airspace Docket No. 03-ACE-25]

Proposed Establishment of Class E Airspace; Brookfield, MO

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking.

SUMMARY: This notice proposes to establish a Class E airspace area at Brookfield, MO. The FAA has developed Standard Instrument Approach Procedures (SIAPs) to serve the North Central Missouri Regional Airport, Brookfield, MO. Controlled airspace is needed to accommodate the SIAPs.

The intended effect of this proposal is to provide controlled Class E airspace for aircraft executing the SIAPs and to segregate aircraft using instrument approach procedures in instrument conditions from aircraft operating in visual conditions.

DATES: Comments for inclusion in the Rules Docket must be received on or before June 10, 2003.

ADDRESSES: Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify the docket number FAA-2003-14656/Airspace Docket No. 03-ACE-25, at the beginning of your comments. You may also submit comments on the Internet at <http://dms.dot.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527) is on the plaza level of the Department of Transportation NASSIF Building at the above address.

FOR FURTHER INFORMATION CONTACT: Brenda Mumper, Air Traffic Division, Airspace Branch, ACE-520A, DOT Regional Headquarters Building, Federal Aviation Administration, 901 Locust, Kansas City, MO 64106; telephone (816) 329-2524.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those

comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2003-14656/Airspace Docket No. 03-ACE-25." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRM's

An electronic copy of this document may be downloaded through the Internet at <http://dms.dot.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at <http://www.faa.gov> or the Superintendent of Document's Web page at <http://www.access.gpo.gov/nara>.

Additionally, any person may obtain a copy of this notice by submitting a request to the Federal Aviation Administration, Office of Air Traffic Airspace Management, ATA-400, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-8783. Communications must identify both docket numbers for this notice. Persons interested in being placed on a mailing list for future NPRM's should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

The Proposal

This notice proposes to amend Title 14 Code of Federal Regulations, part 71 (14 CFR part 71) by establishing a Class E airspace area at Brookfield, MO. The FAA has developed an Area Navigation (RNAV) Global Positioning System (GPS) Runway (RWY) 18, ORIGINAL SIAP and an RNAV (GPS) RWY 36, ORIGINAL SIAP to serve North Central Missouri Regional Airport, Brookfield, MO. Controlled airspace extending upward from 700 feet Above Ground Level (AGL) is needed to accommodate the SIAPs. The area would be depicted on appropriate aeronautical charts.

Class E airspace areas extending upward from 700 feet or more above the surface of the earth are published in Paragraph 6005 of FAA Order 7400.9K, dated August 30, 2002, and effective September 16, 2002, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document would be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive

Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (Air).

The Proposed Amendment

In consideration of the foregoing, the Federal Aviation Administration proposes to amend 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

§ 71.1 [Amended]

2. The incorporation by reference in 14 CFR 71.1 of Federal Aviation Administration Order 7400.9K, Airspace Designations and Reporting Points, dated August 30, 2002, and effective September 16, 2002, is amended as follows:

Paragraph 6005 Class E airspace areas extending upward from 700 feet or more above the surface of the earth.

* * * * *

ACE MO E5 Brookfield, MO

North Central Missouri Regional Airport, MO (Lat. 39°46'12"N., long. 93°00'46"W.)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of North Central Missouri Regional Airport.

* * * * *

Issued in Kansas City, MO, on April 23, 2003.

Herman J. Lyons, Jr.,

Manager, Air Traffic Division, Central Region.
[FR Doc. 03-11031 Filed 5-2-03; 8:45 am]

BILLING CODE 4910-13-M