

Rules and Regulations

Federal Register

Vol. 68, No. 180

Wednesday, September 17, 2003

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001-NM-322-AD; Amendment 39-13221; AD 2003-14-02]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model CL-600-2B19 (Regional Jet Series 100 & 440) Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule; correction.

SUMMARY: This document corrects typographical errors that appeared in airworthiness directive (AD) 2003-14-02 that was published as a final rule; correction in the **Federal Register** on August 15, 2003 (68 FR 48783). The typographical errors resulted in an incorrect AD number and effective date. This AD is applicable to certain Bombardier Model CL-600-2B19 (Regional Jet series 100 & 440) airplanes. This AD requires a one-time inspection of the aft edge of the left and right main windshields to determine whether a certain placard is installed, and corrective actions if necessary.

DATES: Effective August 14, 2003.

FOR FURTHER INFORMATION CONTACT:

Serge Napoleon, Aerospace Engineer, Airframe and Propulsion Branch, ANE-171, FAA, New York Aircraft Certification Office, 10 Fifth Street, Third Floor, Valley Stream, New York 11581; telephone (516) 256-7512; fax (516) 568-2716.

SUPPLEMENTARY INFORMATION:

Airworthiness Directive (AD) 2003-14-02, amendment 39-13221, applicable to certain Bombardier Model CL-600-2B19 (Regional Jet series 100 & 440) airplanes, was published as a final rule; correction in the **Federal Register** on August 15, 2003 (68 FR 48783). That AD

requires a one-time inspection of the aft edge of the left and right main windshields to determine whether a certain placard is installed, and corrective actions if necessary.

As published, that final rule; correction incorrectly specified the AD number as "2003-14-02 R1" instead of "2003-14-02" and the effective date as "August 11, 2003" instead of "August 14, 2003."

Since no other part of the regulatory information has been changed, the final rule is not being republished in the **Federal Register**.

The effective date of this AD remains August 14, 2003.

§ 39.13 [Corrected]

■ On page 48783, in the third column, paragraph 2 of Part 39—Airworthiness Directives is corrected to read as follows:

* * * * *

2. Section 39.13 is amended by correctly adding the following airworthiness directive (AD):

AD 2003-14-02 Bombardier, Inc. (Formerly Canadair): Amendment 39-13221. Docket 2001-NM-322-AD.

* * * * *

■ On page 48784, in the second column, paragraph (e) of AD 2003-14-02 is corrected to read as follows:

* * * * *

(e) The effective date of this amendment remains August 14, 2003.

* * * * *

Issued in Renton, Washington, on September 11, 2003.

Vi L. Lipski,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-23669 Filed 9-16-03; 8:45 am]

BILLING CODE 4910-13-U

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-NE-05-AD; Amendment 39-13309; AD 2003-19-06]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Arrius 2 B1, 2 B1A, 2 B1A 1, and 2 K1 Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Turbomeca S.A. Arrius 2 B1, 2 B1A, 2 B1A 1, and 2 K1 turboshaft engines. This AD requires replacement of the gas generator high pressure (HP) turbine disk before further flight after the engine has accumulated 5 minutes of operating time at the 2½ minute one engine inoperative (OEI) power rating. This amendment is prompted by a failure of an HP turbine blade during accelerated aging simulation tests performed by the manufacturer on an Arrius 2 B1A engine. We are issuing this AD to prevent engine failure of the only operating engine while experiencing an OEI condition.

DATES: This AD becomes effective October 22, 2003.

ADDRESSES: You may get the service information identified in this AD from Turbomeca S.A., 64511 Bordes Cedex, France; telephone 33 05 59 64 40 00, fax 33 05 59 64 60 80.

You may examine the AD docket at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA. You may examine the service information, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

FOR FURTHER INFORMATION CONTACT:

Antonio Cancelliere, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803-5299; telephone (781) 238-7751; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR part 39 with a proposed AD. The proposed AD applies to Turbomeca S.A. Arrius 2 B1, 2 B1A, 2 B1A 1, and 2 K1 turboshaft engines. We published the proposed AD in the **Federal Register** on May 20, 2003 (68 FR 27492). That action proposed to require replacement of the gas generator high pressure (HP) turbine disk before further flight after the engine has accumulated 5 minutes of operating time at the 2½ minute one engine inoperative (OEI) power rating.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no

comments on the proposal or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Changes to 14 CFR Part 39—Effect on the AD

On July 10, 2002, the FAA published a new version of 14 CFR part 39 (67 FR 47997, July 22, 2002), which governs the FAA's AD system. That regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. The material previously was included in each individual AD. Since the material is included in 14 CFR part 39, we will not include it in future AD actions.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this AD and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-05-AD" in your request.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2003-19-06 Turbomeca S.A.: Amendment 39-13309. Docket No. 2003-NE-05-AD.

Effective Date

(a) This AD becomes effective October 22, 2003.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Turbomeca S.A. Arrius 2 B1, 2 B1A, 2 B1A 1, and 2 K1 turboshaft engines. These engines are installed on, but not limited to, Eurocopter Deutschland GmbH model EC135 T1 and Agusta S.p.A. model A109 helicopters.

Unsafe Condition

(d) This AD is prompted by a failure of an HP turbine blade during accelerated aging simulation tests performed by the manufacturer on an Arrius 2 B1A engine. The actions specified in this AD are intended to prevent engine failure of the only operating engine while at one engine inoperative (OEI) condition.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

(f) After the effective date of this AD, replace the gas generator HP turbine disk before further flight after the engine has accumulated 5 minutes operating time at the 2½ minute OEI power rating.

Alternative Methods of Compliance

(g) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Material Incorporated by Reference

(h) None.

Related Information

(i) The subject of this AD is addressed in DGAC airworthiness directive 2003-098(A), dated March 5, 2003, and Turbomeca S.A. Alert Service Letters No. 2174/02/ARRIUS2B1/19 and No. 2175/02/ARRIUS2K1/3, both dated July 30, 2002.

Issued in Burlington, Massachusetts, on September 11, 2003.

Francis A. Favara,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.
[FR Doc. 03-23673 Filed 9-16-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. 29334; Amendment No. 71-35]

Airspace Designations; Incorporation By Reference

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Title 14 Code of Federal Regulations (CFR) part 71 relating to airspace designations to reflect the approval by the Director of the Federal Register of the incorporation by reference of FAA Order 7400.9L Airspace Designations and Reporting Points. This action also explains the procedures the FAA will use to amend the listings of Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points incorporated by reference.

EFFECTIVE DATE: These regulations are effective September 16, 2003. The incorporation by reference of FAA Order 7400.9L is approved by the Director of the Federal Register as of September 16, 2003, through September 15, 2004.

FOR FURTHER INFORMATION CONTACT: Christine Graves, Airspace and Rules Division (ATA-400), Office of Air Traffic Airspace Management, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

History

FAA Order 7400.9K, Airspace Designations and Reporting Points, dated September 2, 2002, and effective September 16, 2002, listed Class A, B, C, D, and E airspace areas and reporting points. Due to the length of these descriptions, the FAA requested approval from the Office of the Federal Register to incorporate the material by reference in 14 CFR 71.1 (14 CFR 71.1). The Director of the Federal Register approved the incorporation by reference of FAA Order 7400.9K in § 71.1, effective September 16, 2002, through September 15, 2003. During the incorporation by reference period, the FAA processed all proposed changes of the airspace listings in FAA Order 7400.9K in full text as proposed rule documents in the **Federal Register**. Likewise, all amendments of these listings were published in full text as final rules in the **Federal Register**. This