

effective date of AD 98-04-49, amendment 39-10360), whichever occurs later, perform an ultrasonic inspection to detect fatigue cracking in the wing/fuselage joint cruciform fittings, in accordance with Airbus Service Bulletin A320-57-1051, Revision 01, dated March 21, 1996.

(1) If no cracking is detected, repeat the inspection thereafter at intervals not to exceed 20,000 landings, until paragraph (c) of this AD is accomplished.

(2) If any crack is detected, prior to further flight, repair it in accordance with the service bulletin. Thereafter, repeat the inspection at the times specified in paragraph (a)(2)(i) or (a)(2)(ii) of this AD, as applicable.

(i) If the crack that was detected and repaired was greater than 2.5 mm: Repeat the inspection prior to the accumulation of 32,000 landings since accomplishment of the repair; and thereafter at intervals not to exceed 32,000 landings.

(ii) If the crack that was detected and repaired was less than or equal to 2.5 mm: Repeat the inspection prior to the accumulation of 28,000 landings since accomplishment of the repair; and thereafter at intervals not to exceed 20,000 landings.

New Requirements of This AD

Ultrasonic Inspection (Model A319 Series Airplanes)

(b) For Model A319 series airplanes: Perform an ultrasonic inspection to detect fatigue cracking in the wing/fuselage joint cruciform fittings, in accordance with Airbus Service Bulletin A320-57-1051, Revision 04, dated November 27, 2001. Do the initial inspection at the later of the times specified in paragraphs (b)(1) and (b)(2) of this AD. Repeat the inspection thereafter at intervals not to exceed the applicable interval specified in paragraph 1.E.(2) of the service bulletin.

(1) Prior to the accumulation of 20,000 total flight cycles or 42,000 total flight hours, whichever is first.

(2) Prior to the accumulation of 28,000 total flight cycles or within 3,500 flight cycles after the effective date of this AD, whichever is first.

Ultrasonic Inspection (Model A320 Series Airplanes)

(c) For Model A320 series airplanes: Perform an ultrasonic inspection to detect fatigue cracking in the wing/fuselage joint cruciform fittings, in accordance with Airbus Service Bulletin A320-57-1051, Revision 04, dated November 27, 2001, at the later of the times specified in paragraphs (c)(1) and (c)(2) of this AD, except as required by paragraph (f) of this AD. Accomplishment of the inspection required by this paragraph terminates the repetitive inspections required by paragraph (a) of this AD. Except as required by paragraph (e) of this AD, repeat the ultrasonic inspection at intervals not to exceed the applicable interval specified in paragraph 1.E.(2) of the service bulletin.

(1) Prior to the accumulation of 20,000 total flight cycles or 42,000 total flight hours, whichever is first.

(2) Prior to the accumulation of 28,000 total flight cycles or within 3,500 flight cycles after the effective date of this AD, whichever is first.

Cracking: Corrective Action and Repeat Inspections

(d) If any crack is found during any inspection required by paragraph (b) or (c) of this AD: Before further flight, do all applicable actions in paragraphs B.(1)(b), C.(1), D., and E. (including removing the fastener, performing a rotative probe inspection to confirm the crack or determine the size of the crack, and accomplishing applicable corrective actions) of the Accomplishment Instructions of Airbus Service Bulletin A320-57-1051, Revision 04, dated November 27, 2001, except as provided by paragraph (e) of this AD.

(e) If any crack is found during any inspection required by this AD, and the service bulletin recommends contacting Airbus for appropriate action: Before further flight, repair and perform repetitive inspections per a method and at a repetitive inspection interval approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

Model A320 Series Airplanes Repaired Previously

(f) For Model A320 series airplanes on which a crack measuring more than 2.5 mm was repaired prior to the effective date of this AD per Airbus Service Bulletin A320-57-1051, Revision 01, dated March 21, 1996: Perform repetitive inspections per a method and at an interval approved by the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

Reporting of Inspection Results Not Required

(g) Where the Accomplishment Instructions of Airbus Service Bulletin A320-57-1051, Revision 04, dated November 27, 2001, describe procedures for reporting inspection results to Airbus, this AD does not require such reporting.

Alternative Methods of Compliance

(h) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, is authorized to approve alternative methods of compliance for this AD.

Note 1: The subject of this AD is addressed in French airworthiness directive 2002-340(B), dated June 26, 2002.

Issued in Renton, Washington, on November 28, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03-30191 Filed 12-3-03; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2002-NM-233-AD]

RIN 2120-AA64

Airworthiness Directives; Dassault Model Falcon 2000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dassault Model Falcon 2000 series airplanes. This proposal would require modification of the forward ribs of the left and right engine pylons to plug holes left open during production. This action is necessary to prevent fuel leakage into a "hot" section of the engine, and consequent propagation of an uncontained engine fire. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by January 5, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-233-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-233-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington

98055-4056; telephone (425) 227-1137; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-233-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-233-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on certain Dassault Model Falcon 2000 series airplanes. The DGAC advises that during production

two 4-millimeter holes in the forward ribs of the left and right engine pylons were not plugged, reducing their capability to operate as firewalls. If there is heavy fuel leakage at the fuselage-nacelle connections, fuel could drain through the holes into "hot" zones of the engines. This condition, if not corrected, could result in propagation of an uncontained engine fire.

Explanation of Relevant Service Information

Dassault has issued Service Bulletin F2000-248, dated August 12, 2002, which describes procedures for modifying the forward ribs of the left and right engine pylons by plugging the two holes in each pylon. The modification procedures include using rivets installed with an interlay of sealing compound to plug the holes. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The DGAC classified this service bulletin as mandatory and issued French airworthiness directive 2002-413(B), dated August 7, 2002, to ensure the continued airworthiness of these airplanes in France.

FAA's Conclusions

This airplane model is manufactured in France and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Difference Between the Proposed Rule and the Service Bulletin

Although the Accomplishment Instructions of the service bulletin specify to submit information to the manufacturer, this proposed AD would not include such a requirement.

Cost Impact

The FAA estimates that 119 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$65 per work hour. The cost of required parts would be minimal. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$7,735, or \$65 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part

39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Dassault Aviation: Docket 2002–NM–233–AD.

Applicability: Model Falcon 2000 series airplanes on which Dassault Modification M2111 has not been installed, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent fuel leakage into a “hot” section of the engine, and consequent propagation of an uncontained engine fire, accomplish the following:

Modification of the Engine Pylons

(a) Within 7 months after the effective date of this AD, modify the forward ribs of the left and right engine pylons by plugging the two 4-millimeter holes in each rib in accordance with the Accomplishment Instructions of Dassault Service Bulletin F2000–248, dated August 12, 2002. Although the service bulletin specifies to submit certain information to the manufacturer, this AD does not include such a requirement.

Alternative Methods of Compliance

(b) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Note 1: The subject of this AD is addressed in French airworthiness directive 2002–413(B), dated August 7, 2002.

Issued in Renton, Washington, on November 28, 2003.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–30190 Filed 12–3–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF COMMERCE

Patent and Trademark Office

37 CFR Part 1

[Docket No.: 2003–P–029]

RIN 0651–AB71

Revision of Patent Term Extension and Patent Term Adjustment Provisions Related to Decisions by the Board of Patent Appeals and Interferences

AGENCY: United States Patent and Trademark Office, Commerce.

ACTION: Notice of proposed rule making.

SUMMARY: The patent term extension provisions of the Uruguay Round Agreements Act (URAA) and the patent term adjustment provisions of the American Inventors Protection Act of 1999 (AIPA) each provide for the possibility of patent term extension or adjustment if the issuance of the patent was delayed due to review by the Board of Patent Appeals and Interferences (BPAI) or by a Federal court and the patent was issued pursuant to or under a decision in the review reversing an adverse determination of patentability. The United States Patent and Trademark Office (Office) is proposing to revise the rules of practice in patent cases to indicate that under certain circumstances a remand by the Board of Patent Appeals and Interferences shall be considered a decision in the review reversing an adverse determination of patentability for purposes of patent term extension or patent term adjustment.

DATES: *Comment deadline date:* To be ensured of consideration, written comments must be received on or before January 5, 2004. No public hearing will be held.

ADDRESSES: Comments should be sent by electronic mail message over the Internet addressed to AB71.Comments@uspto.gov. Comments may also be submitted by mail addressed to: Box Comments—Patents, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313–1450, or by facsimile to (703) 746–3261, marked to the attention of Kery A. Fries. Although comments may be submitted by mail or facsimile, the Office prefers to receive comments via the Internet. If comments are submitted by mail, the Office prefers that the comments be submitted on a DOS formatted 3½ inch disk accompanied by a paper copy.

The comments will be available for public inspection at the Office of the Commissioner for Patents, located in Crystal Park 2, Suite 910, 2121 Crystal Drive, Arlington, Virginia, and will be

available through anonymous file transfer protocol (ftp) via the Internet (address: <http://www.uspto.gov>). Since comments will be made available for public inspection, information that is not desired to be made public, such as an address or phone number, should not be included in the comments.

FOR FURTHER INFORMATION CONTACT: Kery A. Fries, Legal Advisor, Office of Patent Legal Administration, by telephone at (703) 305–1383, by mail addressed to: Box Comments—Patents, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313–1450, or by facsimile to (703) 746–3240, marked to the attention of Kery A. Fries.

SUPPLEMENTARY INFORMATION: Section 532(a) of the URAA (Pub. L. 103–465, 108 Stat. 4809 (1994)) amended 35 U.S.C. 154 to provide that the term of a patent ends on the date that is twenty years from the filing date of the application, or the earliest filing date for which a benefit is claimed under 35 U.S.C. 120, 121, or 365(c). Public Law 103–465 also contained provisions, codified at 35 U.S.C. 154(b), for patent term extension due to certain examination delays. The Office implemented the patent term extension provisions of the URAA in a final rule published in April of 1995. *See Changes to Implement 20-Year Patent Term and Provisional Applications*, 60 FR 20195 (Apr. 25, 1995), 1174 *Off. Gaz. Pat. Office* 15 (May 2, 1995) (final rule).

The AIPA further amended 35 U.S.C. 154(b) to include additional bases for patent term extension (termed “patent term adjustment” in the AIPA). Original utility and plant patents issuing from applications filed on or after May 29, 2000, may be eligible for patent term adjustment if issuance of the patent is delayed due to one or more of the enumerated administrative delays listed in 35 U.S.C. 154(b)(1). The Office implemented the patent term adjustment provisions of the AIPA in a final rule published in September of 2000. *See Changes to Implement Patent Term Adjustment Under Twenty-Year Patent Term*, 65 FR 56365 (Sept. 18, 2000), 1239 *Off. Gaz. Pat. Office* 14 (Oct. 3, 2000) (final rule). The patent term adjustment provisions of the AIPA apply to original (*i.e.*, non-reissue) utility and plant applications filed on or after May 29, 2000. *See Changes to Implement Patent Term Adjustment Under Twenty-Year Patent Term*, 65 FR at 56367, 1239 *Off. Gaz. Pat. Office* at 14–15. The patent term extension provisions of the URAA (for delays due to secrecy order, interference or successful appellate review) continued to apply to utility and plant applications