

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39****[Docket No. 2002-NM-226-AD]****RIN 2120-AA64****Airworthiness Directives; Dornier Model 328-100 Series Airplanes****AGENCY:** Federal Aviation Administration, DOT.**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dornier Model 328-100 series airplanes. This proposal would require a one-time inspection of certain engine control cables to determine the batch number on the end fitting, and replacement of affected cables with new cables. This action is necessary to prevent failure of defective engine control cables, which could result in loss of the engine controls, and consequent reduced controllability of the airplane. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by January 5, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-226-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-226-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from AvCraft Aerospace GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA,

Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-226-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-226-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on certain Dornier Model 328-100 series airplanes.

The LBA advises that, during testing, the manufacturer of the engine control cables, SARMA, found evidence of cracking on the end fittings of two specific batches of parts, due to a manufacturing problem. Such cracking, if not corrected, could result in failure of the engine control cables, subsequent loss of the engine controls, and consequent reduced controllability of the airplane.

Explanation of Relevant Service Information

Dornier has issued Service Bulletin SB-328-76-409, Revision 1, dated May 17, 2002, which describes procedures for inspecting engine control cables having part number 001A761A1130-016 to determine the manufacturing batch number, and replacing affected engine control cables with new cables. Accomplishment of the actions specified in the service bulletin is intended to adequately address the identified unsafe condition. The LBA classified this service bulletin as mandatory and issued German airworthiness directive 2002-252, dated September 5, 2002, to ensure the continued airworthiness of these airplanes in Germany.

FAA's Conclusions

This airplane model is manufactured in Germany and is type certified for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the LBA has kept the FAA informed of the situation described above. The FAA has examined the findings of the LBA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certified for operation in the United States.

Explanation of Requirements of Proposed AD

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletin described previously, except as discussed below.

Differences Between the Service Bulletin and Proposed AD

Although the service bulletin specifies to send any engine control cable removed from the airplane to the parts manufacturer, this proposed AD does not require that action.

Clarification of Compliance Time

Operators should note that the service bulletin recommends doing the inspection at the “next scheduled maintenance event,” and replacing any affected engine control cable at “the next scheduled C-check (4,000 FH).” The German airworthiness directive recommends replacing any affected engine control cable “not later than the next scheduled C-check.” Because “C-check” schedules vary among operators, this proposed AD would require accomplishment of the inspection within 4,000 flight hours after the effective date of the AD, and replacement of any affected cable before further flight. We find that compliance within 4,000 flight hours after the effective date of this AD is appropriate for affected airplanes to continue to operate without compromising safety.

Cost Impact

We estimate that 53 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately one work hour per airplane to accomplish the proposed actions, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$3,445, or \$65 per airplane.

Replacement of an engine control cable, if required, would take approximately 8 work hours, at an average labor rate of \$65 per work hour. Parts would be provided at no cost to operators. Based on these figures, the cost impact of the proposed replacement of the engine control cables is \$520 per cable.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore,

it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Fairchild Dornier GMBH (Formerly Dornier Luftfahrt GmbH): Docket 2002-NM-226-AD.

Applicability: Model 328–100 series airplanes, as listed in Dornier Service Bulletin SB-328–76–409, Revision 1, dated May 17, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of defective engine control cables, which could result in loss of the engine controls, and consequent reduced controllability of the airplane, accomplish the following:

Identification of Manufacturing Batch Number

(a) Within 4,000 flight hours after the effective date of this AD, do a detailed inspection of the engine control cables for cables that have part number (P/N) 001A761A1130–016, engraved with manufacturing batch number (MBN) 1000125850 or 1000144210 installed. Inspect in accordance with the Accomplishment Instructions of Dornier Service Bulletin SB–328–76–409, Revision 1, dated May 17, 2002.

Note 1: For the purposes of this AD, a detailed inspection is defined as: “An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required.”

(1) If no engine control cable has a P/N and an MBN specified in paragraph (a) of this AD, no further action is required by this paragraph.

(2) If any engine control cable having the P/N or an MBN specified in paragraph (a) of this AD is found, before further flight, replace the cable in accordance with the Accomplishment Instructions of the service bulletin. Although the service bulletin specifies to send any engine control cable that has been removed from the airplane to the part manufacturer, this AD does not require that action.

Parts Installation

(b) As of the effective date of this AD, no person may install an engine control cable having P/N 001A761A1130–016, engraved with MBN 1000125850 or 1000144210, on any airplane.

Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Note 2: The subject of this AD is addressed in German airworthiness directive 2002–252, dated September 5, 2002.

Issued in Renton, Washington, on November 28, 2003.

Kevin Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 03–30225 Filed 12–4–03; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2001–NM–333–AD]

RIN 2120-AA64

Airworthiness Directives; Fokker Model F.28 Mark 1000, 2000, 3000, and 4000 Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to