

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. Section 39.13 is amended by removing amendment 39–9411 (60 FR 54421, October 24, 1995), and by adding a new airworthiness directive (AD), amendment 39–13457, to read as follows:

**2004–03–13 Bombardier, Inc. (Formerly Canadair):** Amendment 39–13457.

Docket 2003–NM–139–AD. Supersedes AD 95–22–04, Amendment 39–9411.

**Applicability:** Model CL–215–1A10 (piston) and CL–215–6B11 (turboprop) series airplanes, having serial numbers 1001 through 1125 inclusive, certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent cracking in the inner bearing surface of the main landing gear (MLG) axles, which could result in failure of an axle, subsequent separation of the wheel from the airplane, and consequent reduced controllability of the airplane during takeoff or landing, accomplish the following:

**Restatement of Certain Requirements of AD 95–22–04****Repetitive Inspections/Corrective Action**

(a) Within 60 days after November 8, 1995 (the effective date of AD 95–22–04, amendment 39–9411), perform either an eddy current inspection or a chemical inspection of the inner bearing surface area of the left and right MLG axles to determine if they have been reworked using chromium plating, in accordance with Canadair Alert Service Bulletin 215–A462, dated June 2, 1993; or Bombardier Alert Service Bulletin 215–A462, Revision 3, dated January 17, 2000. If the inner bearing surface of the MLG axle has not been reworked using chromium plating, no further action is required by this paragraph for that axle only.

(b) If the inner bearing surface of the MLG axle has been reworked using chromium plating, prior to further flight, perform an ultrasonic inspection to detect cracking in the axle, in accordance with Canadair Alert Service Bulletin 215–A462, dated June 2, 1993; or Bombardier Alert Service Bulletin 215–A462, Revision 3, dated January 17, 2000.

(1) If no crack is detected during this inspection, repeat the ultrasonic inspection at intervals not to exceed 150 landings.

(2) If any crack is detected during this inspection, prior to further flight, remove the cracked axle and replace it with a serviceable axle that does not have an inner bearing surface that has been reworked using chromium plating, in accordance with the service bulletin.

**New Requirements of This AD****Dimensional Check/Follow-on Corrective Actions**

(c) Within 150 landings after the effective date of this AD: Do a dimensional check by measuring the diameter of the left and right MLG axles to determine if they have been reworked outside the dimensions specified in Canadair CL–215 Overhaul Manual PSP 298, or if the axle has unknown rework dimensions or the service life of that axle cannot be determined, in accordance with Bombardier Alert Service Bulletin 215–A462, Revision 3, dated January 17, 2000.

(1) If any axle has been reworked outside the specified dimensions, or has unknown rework dimensions, or if the service life of that axle cannot be determined: Prior to further flight, do an ultrasonic inspection to detect cracking of the axle, in accordance with the alert service bulletin, and replace the axle with a serviceable axle before the accumulation of 1,050 total landings, in accordance with the alert service bulletin. Such replacement ends the repetitive inspections for that axle only.

(i) If no cracking is detected during the inspection required by paragraph (c)(1) of this AD, repeat the inspection at intervals not to exceed 150 landings, and replace with a serviceable axle before the accumulation of 1,050 total landings, in accordance with the alert service bulletin.

(ii) If any cracking is detected during the inspection required by paragraph (c)(1) of this AD, prior to further flight, replace the axle with a serviceable axle in accordance with the alert service bulletin.

(2) If the service life of the axle is known, and the axle has not been reworked outside the specified dimensions, no further action is required by this AD for that axle only.

**Actions Done per Previous Issues of Service Bulletin**

(d) Inspections and replacements done before the effective date of this AD in accordance with Canadair Alert Service Bulletin 215–A462, dated June 2, 1993; or Bombardier Alert Service Bulletin 215–A462, Revision 1, dated August 26, 1996; or Revision 2, dated March 3, 1999; are considered acceptable for compliance with the applicable actions specified in this AD.

**Alternative Methods of Compliance**

(e) In accordance with 14 CFR 39.19, the Manager, New York Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

**Incorporation by Reference**

(f) The actions shall be done in accordance with Canadair Alert Service Bulletin 215–A462, dated June 2, 1993; and Bombardier Alert Service Bulletin 215–A462, Revision 3, dated January 17, 2000; as applicable.

(1) The incorporation by reference of Bombardier Alert Service Bulletin 215–A462, Revision 3, dated January 17, 2000; is approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The incorporation by reference of Canadair Alert Service Bulletin 215–A462,

dated June 2, 1993; was approved previously by the Director of the Federal Register as of November 8, 1995 (60 FR 54421, October 24, 1995).

(3) Copies may be obtained from Bombardier, Inc., Canadair, Aerospace Group, P.O. Box 6087, Station Centre-ville, Montreal, Quebec H3C 3G9, Canada. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Westbury, New York; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 1:** The subject of this AD is addressed in Canadian airworthiness directive CF–1993–08R3, dated March 30, 2000.

**Effective Date**

(g) This amendment becomes effective on March 17, 2004.

Issued in Renton, Washington, on January 29, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04–2577 Filed 2–10–04; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2002–NM–116–AD; Amendment 39–13462; AD 2004–03–18]

RIN 2120–AA64

**Airworthiness Directives; Aerospatiale Model ATR42 and ATR72 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Aerospatiale Model ATR42 and ATR72 series airplanes, that requires replacement of the swinging lever spacers in the left and right leg assemblies of the main landing gear with new, improved spacers. This action is necessary to prevent propagation of fatigue cracking, which could result in failure of the spacer base and could affect the symmetrical functioning of the braking system. Asymmetrical braking could result in the airplane overrunning the runway during takeoff or landing. This action is intended to address the identified unsafe condition.

**DATES:** Effective March 17, 2004.

The incorporation by reference of certain publications listed in the

regulations is approved by the Director of the Federal Register as of March 17, 2004.

**ADDRESSES:** The service information referenced in this AD may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Tony Jopling, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2190; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Aerospatiale Model ATR42 and ATR72 series airplanes was published in the **Federal Register** on December 17, 2003 (68 FR 70208). That action proposed to require replacement of the swinging lever spacers in the left and right leg assemblies of the main landing gear with new, improved spacers.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

#### Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### Cost Impact

The FAA estimates that 133 airplanes of U.S. registry will be affected by this AD, that it will take about 16 work hours per airplane to accomplish the replacement, and that the average labor rate is \$65 per work hour. Required parts will cost between \$921 and \$4,272 per airplane. Based on these figures, the cost impact of the replacement on U.S. operators is estimated to be between \$1,961 and \$5,312 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact

figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

#### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

**2004-03-18 Aerospatiale:** Amendment 39-13462. Docket 2002-NM-116-AD.

**Applicability:** Model ATR42-200, -300, -320, and -500 series airplanes on which ATR Modification 5338 has not been done; and Model ATR72-101, -102, -201, -202, -211, -212, and -212A series airplanes on

which ATR Modification 5337 has not been done; certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the spacer base of the swinging lever spacers in the left and right leg assemblies of the main landing gear (MLG) and consequent asymmetrical braking, which could result in the airplane overrunning the runway during takeoff or landing, accomplish the following:

#### Replacement

(a) Replace the swinging lever spacers in the left and right leg assemblies of the MLG with new, improved spacers, per Avions de Transport Regional Service Bulletin ATR42-32-0094 or ATR72-32-1042, both dated November 26, 2001, as applicable. Do the replacement at the applicable time specified in paragraph (a)(1) or (a)(2) of this AD.

(1) For Model ATR42-200, -300, and -320, and Model ATR72-101, -102, -201, -202, -211, -212, and -212A series airplanes: Do the replacement at the later of the times specified in paragraphs (a)(1)(i) and (a)(1)(ii) of this AD.

(i) Before the accumulation of 15,000 total landings or 8 years in-service on new or overhauled swinging lever spacers, whichever is first.

(ii) Within 3,000 landings after the effective date of this AD.

(2) For Model ATR42-500 series airplanes: Do the replacement before the accumulation of 18,000 total landings or 9 years in-service on new or overhauled swinging lever spacers, whichever is first.

(b) Messier-Dowty Service Bulletin 631-32-166, dated November 28, 2001 (for Model ATR42 series airplanes); or 631-32-165, dated November 27, 2001 (for Model ATR72 series airplanes), may be used for accomplishment of the replacement required by paragraph (a) of this AD.

#### Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

#### Incorporation by Reference

(d) Unless otherwise specified in this AD, the actions shall be done in accordance with Avions de Transport Regional Service Bulletin ATR42-32-0094, dated November 26, 2001; or Avions de Transport Regional Service Bulletin ATR72-32-1042, dated November 26, 2001; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Aerospatiale, 316 Route de Bayonne, 31060 Toulouse, Cedex 03, France. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**Note 1:** The subject of this AD is addressed in French airworthiness directives 2001-614-089(B) and 2001-615-062(B), both dated December 26, 2001.

**Effective Date**

(e) This amendment becomes effective on March 17, 2004.

Issued in Renton, Washington, on January 30, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-2574 Filed 2-10-04; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. 2001-NM-333-AD; Amendment 39-13464; AD 2004-03-20]

**RIN 2120-AA64**

**Airworthiness Directives; Fokker Model F.28 Mark 1000, 2000, 3000, and 4000 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Fokker Model F.28 Mark 1000, 2000, 3000, and 4000 series airplanes, that requires repetitive general visual inspections, lubrication, and tests of the release mechanism for the service/emergency door; and corrective actions if necessary. This AD also provides an optional terminating action for the repetitive inspections and lubrication. This action is necessary to prevent failure of the release mechanism on the service/emergency door, which could result in the inability to open the service/emergency door during an emergency evacuation. This action is intended to address the identified unsafe condition.

**DATES:** Effective March 17, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 17, 2004.

**ADDRESSES:** The service information referenced in this AD may be obtained from Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., Suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer,

International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1137; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A

proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Fokker Model F.28 Mark 1000, 2000, 3000, and 4000 series airplanes was published in the **Federal Register** on December 5, 2003 (68 FR 67981). That action proposed to require repetitive general visual inspections, lubrication, and tests of the release mechanism for the service/emergency door; and corrective actions if necessary. That action also proposed an optional terminating action for the repetitive inspections and lubrication.

**Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

**Conclusion**

We have determined that air safety and the public interest require the adoption of the rule as proposed.

**Cost Impact**

We estimate that 6 airplanes of U.S. registry will be affected by this AD, that it will take approximately 15 work hours per airplane to accomplish the required actions, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$5,850, or \$975 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

**Regulatory Impact**

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States,

or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

**2004-03-20 Fokker Services B.V.**

Amendment 39-13464. Docket 2001-NM-333-AD.

**Applicability:** Model F.28 Mark 1000, 2000, 3000, and 4000 series airplanes; as listed in the effectivity of Fokker Service Bulletin F28/52-118, dated June 25, 2001; certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the release mechanism on the service/emergency door, which could result in the inability to open the service/emergency door during an emergency evacuation, accomplish the following:

**Inspection, Lubrication, Testing, and Corrective Actions**

(a) Within 12 months after the effective date of this AD: Do a general visual inspection (including measurement of the torque for the actuating mechanism torsion spring), lubricate, and test to verify proper