

**ACTION:** Final rule; correction.

**SUMMARY:** This document makes a correction to the correction of the final rule published in the **Federal Register** on June 25, 2003. The first correction changed assigned amendment numbers. This action makes further corrections to assigned amendment numbers.

**EFFECTIVE DATE:** This correction is effective on February 11, 2004.

**FOR FURTHER INFORMATION CONTACT:** Mike Dosert, telephone (425) 227-2132.

#### Correction

■ In correction to the final rule FR Doc. 03-16001, published on June 25, 2003 (68 FR 37735), make the following corrections:

■ 1. On page 37735, at the bottom of column 2, in the heading section, beginning on line 4, correct "Amendment. Nos. 21-83, 91-272, 121-285, 125-40, 129-35; Special Federal Aviation Regulation No. 88" to read "Amendment. Nos. 21-83, 91-277, 121-295, 125-40, 129-35; Special Federal Aviation Regulation No. 88".

**Donald P. Byrne,**

*Assistant Chief Counsel for Regulations.*

[FR Doc. 04-2878 Filed 2-10-04; 8:45 am]

**BILLING CODE 4910-13-P**

#### DEPARTMENT OF TRANSPORTATION

##### Federal Aviation Administration

##### 14 CFR Parts 25, 91, 121, 125, and 135

[Docket No. FAA-2000-7909; Amdt. Nos. 25-110, 91-279, 121-301, 125-43, 135-90]

**RIN 2120-AG91**

##### Improved Flammability Standards for Thermal/Acoustic Insulation Materials Used in Transport Category Airplanes; Correction

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; correction.

**SUMMARY:** This document makes a correction to the amendment numbers in the final rule published in the **Federal Register** on July 31, 2003. That rule adopted upgraded flammability standards for thermal and acoustic insulation materials used in transport category airplanes.

**EFFECTIVE DATE:** This correction is effective on February 11, 2004.

**FOR FURTHER INFORMATION CONTACT:** Jeff Gardlin, (425) 227-2136.

#### Correction

■ In the final rule FR Doc. 03-18612 published on July 31, 2003, (68 FR 45046), make the following corrections:

■ 1. On page 45046, in column 1, in the heading section, beginning on line 4 correct "Amdt. Nos. 25-110, 91-275, 121-289, 125-43, 135-85" to read "Amdt. Nos. 25-110, 91-279, 121-301, 125-43, 135-90".

Issued in Washington, DC, on January 30, 2004.

**Donald P. Byrne,**

*Assistant Chief Counsel for Regulations.*

[FR Doc. 04-2875 Filed 2-10-04; 8:45 am]

**BILLING CODE 4910-13-P**

#### DEPARTMENT OF TRANSPORTATION

##### Federal Aviation Administration

##### 14 CFR Part 39

[Docket No. 2002-NM-213-AD; Amendment 39-13465; AD 2004-03-21]

**RIN 2120-AA64**

##### Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model 717-200 airplanes, that requires inspection of the inboard ends of the outer skin panels of the horizontal stabilizer at Station Xh=±7.234 for material defects, and corrective action, if necessary. This action is necessary to detect material defects in the inboard ends of the outer skin panels of the horizontal stabilizer, which could lead to cracks and an associated loss of strength in the attachments, and consequent reduced structural integrity of the horizontal stabilizer. This action is intended to address the identified unsafe condition.

**DATES:** Effective March 17, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of March 17, 2004.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the Federal Aviation

Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

#### FOR FURTHER INFORMATION CONTACT:

Maureen Moreland, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5238; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model 717-200 airplanes was published in the **Federal Register** on September 18, 2003 (68 FR 54690). That action proposed to require inspection of the inboard ends of the outer skin panels of the horizontal stabilizer at Station Xh=±7.234 for material defects, and corrective action, if necessary.

#### Comments

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

#### Conclusion

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### Cost Impact

There are approximately 56 airplanes of the affected design in the worldwide fleet. The FAA estimates that 41 airplanes of U.S. registry will be affected by this AD, that it will take approximately 4 work hours per airplane to accomplish the required inspection, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the AD on U.S. operators is estimated to be \$10,660, or \$260 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include

incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions. Manufacturer warranty remedies may be available for labor costs associated with this proposed AD. As a result, the costs attributable to the proposed AD may be less than stated above.

### Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

#### 2004-03-21 McDonnell Douglas:

Amendment 39-13465. Docket 2002-NM-213-AD.

**Applicability:** Model 717-200 airplanes, as listed in Boeing Service Bulletin 717-55-0005, dated June 27, 2002; certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To detect material defects in the inboard ends of the outer skin panels of the horizontal stabilizer at Station Xh=±7.234, which could lead to cracks and an associated loss of strength in the attachments, and consequent reduced structural integrity of the horizontal stabilizer, accomplish the following:

### Inspection

(a) Prior to the accumulation of 10,000 total flight cycles, or within 15 months after the effective date of this AD, whichever occurs later, do an ultrasonic inspection of the inboard ends of the outer skin panels of the horizontal stabilizer at Station Xh=±7.234 for material defects, per the Accomplishment Instructions of Boeing Service Bulletin 717-55-0005, dated June 27, 2002.

### Corrective Action

(b) If any defects are found during the inspection required by paragraph (a) of this AD, and the service bulletin specifies contacting Boeing for appropriate action: Before further flight, repair per a method approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA; or per data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative who has been authorized by the Manager, Los Angeles ACO, to make such findings. For a repair method to be approved, as required by this paragraph, the approval letter must specifically refer to this AD.

### Alternative Methods of Compliance

(c) In accordance with 14 CFR 39.19, the Manager, Los Angeles ACO, FAA, is authorized to approve alternative methods of compliance for this AD.

### Incorporation by Reference

(d) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Service Bulletin 717-55-0005, dated June 27, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

### Effective Date

(e) This amendment becomes effective on March 17, 2004.

Issued in Renton, Washington, on January 30, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-2581 Filed 2-10-04; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2002-NM-233-AD; Amendment 39-13466; AD 2004-03-22]

**RIN 2120-AA64**

### Airworthiness Directives; Dassault Model Falcon 2000 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain Dassault Model Falcon 2000 series airplanes, that requires modification of the forward ribs of the left and right engine pylons to plug holes left open during production. This action is necessary to prevent fuel leakage into a "hot" section of the engine, and consequent propagation of an uncontained engine fire. This action is intended to address the identified unsafe condition.

**DATES:** Effective March 17, 2004.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 17, 2004.

**ADDRESSES:** The service information referenced in this AD may be obtained from Dassault Falcon Jet, P.O. Box 2000, South Hackensack, New Jersey 07606. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1137; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain Dassault Model Falcon 2000 series airplanes was