

# Proposed Rules

## Federal Register

Vol. 69, No. 38

Thursday, February 26, 2004

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-NE-59-AD]

RIN 2120-AA64

### Airworthiness Directives; General Electric Company CT58 and T58 Series Turboshaft Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for General Electric Company (GE) CT58-140-1, CT58-140-2, and T58-GE-5, -10, -100, and -402 series turboshaft engines with certain serial numbers (SNs) of stage 1 compressor disks, part number (P/N) 5001T20P01, installed. This proposed AD would require removing certain stage 1 compressor disks from service before reaching a reduced low-cycle-fatigue (LCF) life limit. This proposed AD results from two reports of low blade tip clearances in the compressor. We are proposing this AD to prevent LCF cracking and failure of the stage 1 compressor disk, an uncontained engine failure, and damage to the helicopter.

**DATES:** We must receive any comments on this proposed AD by April 26, 2004.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD:

- By mail: Federal Aviation Administration (FAA), New England Region, Office of the Regional Counsel, Attention: Rules Docket No. 2003-NE-59-AD, 12 New England Executive Park, Burlington, MA 01803-5299.
- By fax: (781) 238-7055.
- By e-mail: [9-ane-adcomment@faa.gov](mailto:9-ane-adcomment@faa.gov)

You can get the service information identified in this proposed AD from GE Aircraft Engines Customer Support Center, M/D 285, 1 Neumann Way,

Evendale, OH 45215, telephone (513) 552-3272; fax (513) 552-3329, email [GEAE.csc@ae.ge.com](mailto:GEAE.csc@ae.ge.com).

You may examine the AD docket, by appointment, at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA.

#### FOR FURTHER INFORMATION CONTACT:

Norman Brown, Senior Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park; telephone (781) 238-7181; fax (781) 238-7199.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to submit any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-59-AD" in the subject line of your comments. If you want us to acknowledge receipt of your mailed comments, send us a self-addressed, stamped postcard with the docket number written on it; we will date-stamp your postcard and mail it back to you. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. If a person contacts us verbally, and that contact relates to a substantive part of this proposed AD, we will summarize the contact and place the summary in the docket. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

##### Examining the AD Docket

You may examine the AD Docket (including any comments and service information), by appointment, between 8 a.m. and 4:30 p.m., Monday through Friday, except Federal holidays. See **ADDRESSES** for the location.

##### Discussion

On May 1, 2003, GE informed the FAA that 320 stage 1 compressor disks,

P/N 5001T20P01, have high-peak stresses. GE has identified the affected stage 1 compressor disks by SN. An investigation by GE revealed that the tangential positioning of the blade dovetail slot resulted in the high-peak stresses. This proposed AD would require removing those stage 1 compressor disks, PN 5001T20P01, from service before reaching a reduced LCF life limit of 2,100 hours time-since-new (TSN) or by December 31, 2008, whichever occurs first. This condition, if not corrected, could result in LCF cracking and failure of the stage 1 compressor disk, an uncontained engine failure, and damage to the helicopter.

##### Relevant Service Information

We have reviewed and approved the technical contents of GE Alert Service Bulletin (ASB) No. CT58 S/B 72-A0196, dated July 24, 2003, that describes the procedures for replacing the stage 1 compressor disk.

##### FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. Therefore, we are proposing this AD which would require removing certain stage 1 compressor disks from service at or before reaching a reduced LCF life limit of 2,100 hours TSN or by December 31, 2008, whichever occurs first.

##### Changes to 14 CFR Part 39—Effect on the Proposed AD

On July 10, 2002, we issued a new version of 14 CFR part 39 (67 FR 47998, July 22, 2002), which governs the FAA's AD system. This regulation now includes material that relates to altered products, special flight permits, and alternative methods of compliance. This material previously was included in each individual AD. Since this material is included in 14 CFR part 39, we will not include it in future AD actions.

##### Interim Action

These actions are interim actions and we may take further rulemaking actions in the future.

##### Costs of Compliance

There are about 320 GE CT58-140-1, CT58-140-2, and T58-GE-5, -10, -100, and -402 series turboshaft engines of

the affected design in the worldwide fleet. We estimate that 45 engines installed on helicopters of U.S. registry would be affected by this proposed AD. The proposed action does not impose any additional labor costs. A new disk would cost about \$7,965 per engine. We estimate that the prorated cost of the life reduction would be about \$4,181 per engine. Based on these figures, we estimate the total cost of the proposed AD to U.S. operators to be \$188,172.

### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a summary of the costs to comply with this proposal and placed it in the AD Docket. You may get a copy of this summary by sending a request to us at the address listed under **ADDRESSES**. Include "AD Docket No. 2003-NE-59-AD" in your request.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**General Electric Company:** Docket No. 2003-NE-59-AD.

### Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by April 26, 2004.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to General Electric Company (GE) CT58-140-1, CT58-140-2, and T58-GE-5, -10, -100, and -402 series turboshaft engines with stage 1 compressor disks, part number (P/N) 5001T20P01, that have a serial number (SN) listed in the following Table 1:

TABLE 1.—STAGE 1 COMPRESSOR DISK SNS AFFECTED BY THIS AD

GATD0PD2	GATH53GE
GATH6RWW	GATH7K4P
GATH7PR0	GATH7PRC
GATH86K2	GATH8A5P
GATH8K0P	GATH8K19
GATD0PD3	GATH53GF
GATH6T00	GATH7K4R
GATH7PR1	GATH7PRD
GATH86K3	GATH8A5T
GATH8K0R	GATH8W7H
GATD0PD5	GATH53GH
GATH6T01	GATH7K4T
GATH7PR2	GATH7PRE
GATH86K4	GATH8A5W
GATH8K0T	GATH8W7J
GATD0PD6	GATH53GJ
GATH6T02	GATH7K5G
GATH7PR3	GATH7PRF
GATH86K5	GATH8A60
GATH8K0W	GATH8W7L
GATD0PD7	GATH53GK
GATH6T03	GATH7KGH
GATH7PR4	GATH7PRG
GATH8A5G	GATH8A61
GATH8K12	GATH8W7M
GATD0PD8	GATH5T70
GATH6T04	GATH7KGK
GATH7PR5	GATH7PRH
GATH8A5H	GATH8A62
GATH8K13	GATH8W7N
GATD0PD9	GATH5T71
GATH6T05	GATH7KGL
GATH7PR6	GATH7PRJ
GATH8A5J	GATH8A63
GATH8K14	GATH8W7P
GATD0PDA	GATH5T72
GATH7K4K	GATH7KGM
GATH7PR7	GATH7PRK
GATH8A5K	GATH8A64
GATH8K15	GATH8W7R
GATD0PDC	GATH5T73
GATH7K4L	GATH7KGN
GATH7PR8	GATH7PRL
GATH8A5L	GATH8A66
GATH8K16	GATH8W7T
GATH53GC	GATH5T74
GATH7K4M	GATH7KGP
GATH7PR9	GATH7PRM
GATH8A5M	GATH8A67
GATH8K17	GATH8WD4
GATH53GD	GATH5T75
GATH7K4N	GATH7KGR
GATH7PRA	GATH7PRN
GATH8A5N	GATH8A68
GATH8K18	GATH8WD5
	GATH5T76
	GATH7KGT
	GATH7PRP
	GATH8GRG
	GATH8WD6
	GATH5T77
	GATH7KGW
	GATH7PRR
	GATH8GRH
	GATH8WD7
	GATH5T78
	GATH7KH0
	GATH7PRT
	GATH8GRK
	GATH8WD8
	GATH5T79
	GATH7KH1

TABLE 1.—STAGE 1 COMPRESSOR DISK SNS AFFECTED BY THIS AD—Continued

TABLE 1.—STAGE 1 COMPRESSOR  
DISK SNS AFFECTED BY THIS AD—  
Continued

GATH7PRW  
GATH8GRL  
GATH8WD9  
GATH5T7A  
GATH7KH2  
GATH7PT0  
GATH8GRM  
GATH8WDA  
GATH5T7C  
GATH7LAL  
GATH7RTP  
GATH8GRN  
GATH8WDC  
GATH5T7D  
GATH7LAM  
GATH7RTT  
GATH8GRP  
GATH8WDD  
GATH5T7E  
GATH7LAN  
GATH7RTT  
GATH8GRR  
GATH8WDE  
GATH5T7F  
GATH7LAP  
GATH82R8  
GATH8GRT  
GATH8WDF  
GATH5T7G  
GATH7LAR  
GATH82R9  
GATH8GRW  
GATH8WDG  
GATH5T7H  
GATH7LAT  
GATH82RA  
GATH8GT0  
GATH8WDH  
GATH6CDL  
GATH7LAW  
GATH82RD  
GATH8GT1  
GATH8WDJ  
GATH6CDM  
GATH7LC0  
GATH82RE  
GATH8GT3  
GATH8WDK  
GATH6CDN  
GATH7LC1  
GATH82RF  
GATH8GT5  
GATH8WDL  
GATH6CDP  
GATH7LC2  
GATH82RG  
GATH8GT7  
GATH94R3  
GATH6CDR  
GATH7LC3  
GATH82RH  
GATH8GT8  
GATH94R4  
GATH6CDT  
GATH7LC4  
GATH82RJ  
GATH8HGF  
GATH94R6  
GATH6CE0  
GATH7LC5  
GATH82RK  
GATH8HGG

TABLE 1.—STAGE 1 COMPRESSOR  
DISK SNS AFFECTED BY THIS AD—  
Continued

GATH94R7  
GATH6CE1  
GATH7LC6  
GATH82RL  
GATH8HGH  
GATH94R8  
GATH6CE2  
GATH7LC7  
GATH82RM  
GATH8HGJ  
GATH94R9  
GATH6CE3  
GATH7LC8  
GATH82RN  
GATH8HGK  
GATH94RA  
GATH6CE4  
GATH7M8G  
GATH82RP  
GATH8HGL  
GATH94RC  
GATH6CE5  
GATH7M8H  
GATH82RR  
GATH8HGM  
GATH94RD  
GATH6CE6  
GATH7M8J  
GATH82RT  
GATH8HGN  
GATH94RE  
GATH6CE7  
GATH7M8K  
GATH82RW  
GATH8HGP  
GATH94RF  
GATH6CE8  
GATH7M8L  
GATH82T0  
GATH8HGR  
GATH94RG  
GATH6CE9  
GATH7M8M  
GATH82T1  
GATH8HGT  
GATH94RJ  
GATH6CEA  
GATH7M8N  
GATH86JD  
GATH8HGW  
GATH94RK  
GATH6CEC  
GATH7MLK  
GATH86JE  
GATH8HH0  
GATH94RN  
GATH6CED  
GATH7MLL  
GATH86JF  
GATH8HH1  
GATH94RP  
GATH6CEE  
GATH7MLM  
GATH86JG  
GATH8HH2  
GATH94RR  
GATH6CEF  
GATH7MLN  
GATH86JH  
GATH8HH3  
GATH94RT  
GATH6RH8

TABLE 1.—STAGE 1 COMPRESSOR  
DISK SNS AFFECTED BY THIS AD—  
Continued

GATH7MLP  
GATH86JJ  
GATH8HH4  
GATH96HF  
GATH6RH9  
GATH7MLR  
GATH86JK  
GATH8HH5  
GATH96HG  
GATH6RHC  
GATH7MLT  
GATH86JL  
GATH8HH6  
GATH96HK  
GATH6RHD  
GATH7MLW  
GATH86JM  
GATH8HH7  
GATH96HL  
GATH6RHE  
GATH7MM0  
GATH86JN  
GATH8K0H  
GATH96HM  
GATH6RHF  
GATH7MM1  
GATH86JP  
GATH8K0J  
GATH96HN  
GATH6RHG  
GATH7MM2  
GATH86JR  
GATH8K0K  
GATH96HR  
GATH6RHH  
GATH7MM3  
GATH86JT  
GATH8K0L  
GATH96HT  
GATH6RHJ  
GATH7PPT  
GATH86JW  
GATH8K0M  
GATH96HW  
GATH6RWT  
GATH7PPW  
GATH86K0  
GATH8K0N  
GATH96J0

These engines are installed on, but not limited to Agusta S.p.A AS-61N, AS-61N1, Sikorsky S-61L, S-61N, S-61R, and S-61NM helicopters, and the following surplus military helicopters that have been certified in accordance with sections 21.25 or 21.27 of the Federal Aviation Regulations (14 CFR 21.25 or 21.27): Sikorsky S-61D and S-61V, Glacier CH-3E, Siller CH-3E and SH-3A, and Robinson Crane CH-3C, CH-3E, HH-3C, HH-3E, and Carson S-61L helicopters.

#### Unsafe Condition

(d) This AD results from two reports of low blade tip clearances in the compressor. We are issuing this AD to prevent low-cycle-fatigue (LCF) cracking and failure of the stage 1 compressor disk, an uncontained engine failure, and damage to the helicopter.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

**Replacement of Stage 1 Compressor Disks**

(f) If you have a stage 1 compressor disk, P/N 5001T20P01, with a SN listed in Table 1 of this AD, replace that stage 1 compressor disk at or before reaching a reduced LCF life limit of 2,100 hours time-since-new (TSN) or by December 31, 2008, whichever occurs first. GE Alert Service Bulletin (ASB) No. CT58 S/B 72-A0196, dated July 24, 2003, contains information on replacing the stage 1 compressor disk.

(g) After the effective date of this AD, do not install any stage 1 compressor disk, P/N 5001T20P01, that has a SN listed in Table 1 of this AD and has 2,100 hours TSN or more, into any engine.

**Alternative Methods of Compliance**

(h) The Manager, Engine Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

**Material Incorporated by Reference**

(i) None.

**Related Information**

(j) GE Alert Service Bulletin (ASB) No. CT58 S/B 72-A0196, dated July 24, 2003, pertains to the subject of this AD.

Issued in Burlington, Massachusetts, on February 17, 2004.

**Francis A. Favara,**

*Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.*  
[FR Doc. 04-4101 Filed 2-25-04; 8:45 am]

**BILLING CODE 4910-13-U**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. 2002-NM-310-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; Dornier Model 328-100 and -300 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Dornier Model 328-100 and -300 series airplanes. This proposal would require inspection of the metal oxide varistor (MOV) modules and transient absorption zener (TAZ) diodes to determine if those parts are outside

of tolerance limits, and replacement of MOV modules and TAZ diodes with new parts, if necessary. This action is necessary to prevent the failure of critical ice protection systems following a lightning strike, which could result in reduced controllability and degraded performance of the airplane in the event of an encounter with icing conditions. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by March 29, 2004.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-310-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: 9-anm-nprmcomment@faa.gov. Comments sent via fax or the Internet must contain "Docket No. 2002-NM-310-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from AvCraft Aerospace GmbH, P.O. Box 1103, D-82230 Wessling, Germany. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Thomas Groves, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1503; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2002-NM-310-AD." The postcard will be date stamped and returned to the commenter.

**Availability of NPRMs**

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2002-NM-310-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

The Luftfahrt-Bundesamt (LBA), which is the airworthiness authority for Germany, notified the FAA that an unsafe condition may exist on certain Dornier Model 328-100 and -300 series airplanes. The metal oxide varistor (MOV) modules protect the propeller deice system from the effects of lightning strikes. The transient absorption zener (TAZ) diodes protect other ice protection functions from the effects of lightning strikes. The LBA advises that 37% of the inspected fleet has been found with TAZ diodes and MOV modules that are out of tolerance. Further investigation revealed that the airplane maintenance manual (AMM) does not include a check of this equipment following a lightning strike. The out of tolerance condition, if not corrected, could result in the failure of critical ice protection systems following a lightning strike, which could result in reduced controllability and degraded performance of the airplane in the event of an encounter with icing conditions.