

available,” we have determined that such an imprecise compliance time would not address the identified unsafe condition in a timely manner. In developing an appropriate compliance time for this proposed AD, we considered the degree of urgency associated with the subject unsafe condition, the average utilization of the affected fleet, and the time necessary to perform the modification (1 hour). In light of all of these factors, we find that a 6-month compliance time represents an appropriate interval of time for affected airplanes to continue to operate without compromising safety.

Cost Impact

We do not know how many aircraft equipped with Apollo GX series GPS navigation units (software versions 3.0 through 3.4 inclusive) of the affected design are on the U.S. Register. However, we do know that the GPS navigation units might be installed on 1,176 aircraft worldwide. It would take approximately 1 work hour per aircraft to accomplish the proposed modification, at an average labor rate of \$65 per work hour. The parts manufacturer would provide the required parts at no cost to the operator. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$65 per aircraft.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this proposed AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions. Manufacturer warranty remedies may be available for labor costs associated with this proposed AD. As a result, the costs attributable to the proposed AD may be less than stated above.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Garmin AT (formerly UPS Aviation

Technologies, Inc.): Docket 2002–NM–254–AD.

Applicability: Aircraft equipped with Garmin AT, Apollo GX50/55/60/65 TSO–C129a global positioning system (GPS) navigation units with software versions 3.0 through 3.4 inclusive; as listed in UPS Aviation Technologies Service Bulletin 561–4002–001, dated April 19, 2002; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent the GPS navigation unit, under certain conditions, from providing erroneous cross-deviation information, which could result in the aircraft deviating from its intended course for a brief period of time; and to also prevent erroneous information from placing an excessive workload on the flightcrew while they monitor other available navigation data to avoid deviating off course; accomplish the following:

Software Modification, Testing, and Reidentification

(a) Within 6 months after the effective date of this AD, do the actions specified in paragraphs (a)(1) and (a)(2) of this AD, according to the Accomplishment

Instructions of UPS Aviation Technologies Service Bulletin 561–4002–001, dated April 19, 2002.

(1) Modify and test the software for the Apollo GX50/55/60/65 TSO–C129a GPS navigation unit by accomplishing all of the actions specified in paragraphs 3.B. and 3.C of the service bulletin.

(3) Reidentify the modified Apollo GX50/55/60/65 TSO–C129a GPS navigation unit, according to paragraph 3.D. of the service bulletin.

Alternative Methods of Compliance

(b) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office, FAA, is authorized to approve alternative methods of compliance for this AD.

Issued in Renton, Washington, on March 25, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–7288 Filed 3–31–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NM–17–AD]

RIN 2120–AA64

Airworthiness Directives; Saab Model SAAB SF340A and SAAB 340B Series Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Saab Model SAAB SF340A and SAAB 340B series airplanes. This proposal would require inspection of the main landing gear’s (MLG) separation bolt harness, corrective actions if necessary, and replacement of the MLG’s separation bolt harness. For certain airplanes, this proposal would also require modification of the MLG separation bolt’s electrical harness. These actions are necessary to prevent failure of the MLG to extend during use of the emergency backup system. These actions are intended to address the identified unsafe condition.

DATES: Comments must be received by May 3, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2003–NM–

17-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcomment@faa.gov*. Comments sent via fax or the Internet must contain "Docket No. 2003-NM-17-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Saab Aircraft AB, SAAB Aircraft Product Support, S-581.88, Linköping, Sweden. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by

interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2003-NM-17-AD." The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-17-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

Discussion

Luftfartsverket (LFV), which is the airworthiness authority for Sweden, notified the FAA that an unsafe condition may exist on certain Saab Model SAAB SF340A and SAAB 340B series airplanes. LFV advises that it has received a number of reports of broken wires and corroded connectors in the harness for the separation bolt. The cause has been attributed to repairs and installations that have not been accomplished in accordance with the type design. If the system harness is incorrectly installed or repaired, the function of the separation bolt will be inhibited, and consequently the emergency system for landing gear extension will not be fully available. This condition, if not corrected, could result in failure of the main landing gear to extend during use of the emergency backup system.

Explanation of Relevant Service Information

Saab has issued Service Bulletin 340-32-127, dated December 18, 2002; and Revision 01, dated January 23, 2003, which describes procedures for inspection of the MLG's separation bolt harness, and corrective actions, if necessary. The corrective actions involve modifications to the separation bolt harness's wires, clamps, convolex tube, and shrinkable tube, as applicable. Saab has also issued Service Bulletin 340-32-128, dated March 28, 2003, which describes procedures for replacement of the separation bolt harness of the MLGs with a new improved harness.

For certain airplanes, Saab Service Bulletin 340-32-128 recommends prior or concurrent accomplishment of the Accomplishment Instructions of Saab

Service Bulletin 340-32-041, Revision 1, dated October 9, 1987. The Accomplishment Instructions describe procedures for modification of the separation bolt harness. The modification includes the lengthening of the existing electrical harness for the explosive bolt with a new, improved electrical harness, and the rerouting and securing of the existing harness.

For certain airplanes, Saab Service Bulletin 340-32-041 recommends prior or concurrent accomplishment of the Accomplishment Instructions of Saab Service Bulletin 340-32-028, Revision 01, dated November 25, 1986. The Accomplishment Instructions describe procedures for modification of the separation bolt harness. The modification includes adding a shrink sleeve to the separation bolt squib electrical connectors, and re-routing the separation bolt ground wires at the wheel well structure.

Accomplishment of the actions specified in these service bulletins is intended to adequately address the identified unsafe condition. LFV classified these service bulletins as mandatory and issued Swedish airworthiness directives 1-186, dated December 20, 2002, and 1-189, dated April 1, 2003, to ensure the continued airworthiness of these airplanes in Sweden.

FAA's Conclusions

This airplane model is manufactured in Sweden and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, LFV has kept the FAA informed of the situation described above. The FAA has examined the findings of LFV, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously.

Cost Impact

The FAA estimates that 224 airplanes of U.S. registry would be affected by this proposed AD. The following table

shows the estimated cost impact for airplanes affected by this AD. The average labor rate is \$65 per work hour.

For certain model	Action	Number of airplanes affected	Work hours	Parts cost	Total cost
SAAB SF340A and SAAB 340B series airplanes.	Inspection of the harnesses	224	4	(¹)	58,240, or \$260 per airplane.
SAAB SF340A and SAAB 340B series airplanes.	Replacement of the harnesses	224	12	\$2,100	\$645,120, or \$2,880 per airplane.
SAAB SF340A and SAAB 340B series airplanes.	Modification of the harnesses	56	2	\$1,475	\$89,880, or \$1,605 per airplane.
SAAB SF340A and SAAB 340B series airplanes.	Modification of the harnesses	40	1	(¹)	2,500, or \$65 per airplane.

¹ None.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Saab Aircraft AB: Docket 2003–NM–17–AD.

Applicability: Model SAAB SF340A series airplanes with serial numbers 004 through 159 inclusive; and Model SAAB 340B series airplanes with serial numbers 160 through 459 inclusive; certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the main landing gear (MLG) to extend during use of the emergency backup system, accomplish the following:

Inspection and Corrective Actions

(a) Within 3 months after the effective date of this AD, perform an inspection of the MLG's separation bolt harness for broken wires and corroded connectors, and any applicable corrective actions by doing all of the actions in the Accomplishment Instructions of Saab Service Bulletin (SB) 340–32–127, dated December 18, 2002; or Revision 01, dated January 23, 2003. Perform the inspection/corrective actions in accordance with the service bulletin. Perform any applicable corrective actions before further flight.

Replacement

(b) Within 12 months after the effective date of this AD, replace the separation bolt harnesses of the MLGs with new separation bolt harnesses in accordance with the Accomplishment Instructions of Saab SB 340–32–128, dated March 28, 2003.

(c) The inspection required by paragraph (a) of this AD is not required for airplanes on which the replacement required by paragraph (b) of this AD is done within the compliance time specified in paragraph (a) of this AD.

Concurrent Service Bulletins

(d) For Model SAAB SF340A series airplanes: Prior to or concurrent with accomplishment of paragraph (b) of this AD, do the actions specified in Table 1 of this AD, as applicable.

TABLE 1.—PRIOR/CONCURRENT ACTIONS

For airplanes with serial numbers—	Accomplish all actions associated with—	According to the accomplishment instructions of—
004 through 108 inclusive	Modifying the MLG separation bolt's electrical harness.	Saab SB 340–32–041, Revision 01, dated October 9, 1987.
004 through 078 inclusive	Modifying the MLG separation bolt's electrical harness.	Saab SB 340–32–028, Revision 01, dated November 25, 1986.

Alternative Methods of Compliance

(e) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM–116,

FAA, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Note 1: The subject of this AD is addressed in Swedish airworthiness directives 1–186,

dated December 20, 2002, and 1–189, dated April 1, 2003.

Issued in Renton, Washington, on March 25, 2004.

Kevin M. Mullin,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04–7287 Filed 3–31–04; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003–NM–186–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 767–300 and 767–300F Series Airplanes Equipped With General Electric or Pratt & Whitney Engines

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 767–300 and 767–300F series airplanes equipped with General Electric or Pratt & Whitney engines. This proposal would require reworking the wing-to-strut diagonal braces and the aft pitch load fittings of the wings, and reinstalling the diagonal braces with new fuse pins and associated hardware. For certain airplanes, this proposal would require replacing the bushings of the aft pitch load fittings, installing new fuse pins, and reworking the fittings, as applicable. This action is necessary to prevent undetected loss of the diagonal brace fuse pins of the wings and consequent increased loads in other wing-to-strut joints, which could result in separation of the struts and engines from the wings. This action is intended to address the identified unsafe condition.

DATES: Comments must be received by May 17, 2004.

ADDRESSES: Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2003–NM–186–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted

via fax to (425) 227–1232. Comments may also be sent via the Internet using the following address: *9-anm-nprmcment@faa.gov*. Comments sent via fax or the Internet must contain “Docket No. 2003–NM–186–AD” in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124–2207. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

FOR FURTHER INFORMATION CONTACT: Suzanne Masterson, Aerospace Engineer, Airframe Branch, ANM–120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 917–6441; fax (425) 917–6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference to two separate issues.
- For each issue, state what specific change to the proposed AD is being requested.
- Include justification (*e.g.*, reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments

submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: “Comments to Docket Number 2003–NM–186–AD.” The postcard will be date stamped and returned to the commenter.

Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM–114, Attention: Rules Docket No. 2003–NM–186–AD, 1601 Lind Avenue, SW., Renton, Washington 98055–4056.

Discussion

The FAA has received a report that, following the loss of the upper link or midspar load paths, the fuse pin of a wing-to-strut diagonal brace of the wing for certain Boeing Model 767–300 and 767–300F series airplanes equipped with General Electric or Pratt & Whitney engines does not meet the minimum damage tolerance requirements. The fuse pin of the diagonal brace showed early fatigue cracks during damage tolerance testing. The load path of diagonal braces is part of the engine strut-to-wing load path. Early fatigue cracks of the fuse pins of the diagonal braces, if not corrected, could lead to loss of the fuse pins and consequent increased loads in other wing-to-strut joints, which could result in separation of the struts and engines from the wings.

Explanation of Relevant Service Information

The FAA has reviewed and approved Boeing Alert Service Bulletin 767–54A0096, Revision 2, dated December 18, 2003. The alert service bulletin describes procedures for removing and reworking the wing-to-strut diagonal braces of the wings, including replacing the end fittings of the braces with new fittings; reworking the aft pitch load fittings of the wings, including replacing the fitting bushings with new bushings; and reinstalling the diagonal braces with new fuse pins and associated hardware. For certain airplanes, the alert service bulletin describes procedures for replacing the bushings of the aft pitch load fittings with new bushings, reworking the aft pitch load fittings, and installing new fuse pins.

Accomplishment of the actions specified in the alert service bulletin is intended to adequately address the identified unsafe condition.

Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other products of this same