

3073013-All, installed, at the next major periodic inspection (MPI) or at next access to the LPT stage 1 nozzle assembly, after the effective date of this AD, whichever occurs first, but not to exceed 2,200 hours time-in-service (TIS) since the last LPT stage 1 nozzle assembly inspection, do the following:

(1) Measure and determine the acceptance of the LPT stage 1 nozzle assembly using paragraphs 2.A.(3) through 2.A.(5) of Honeywell International Inc. Service Bulletin (SB) No. TFE731-72-3369RWK, Revision 6, dated June 26, 2002; and

(2) If necessary, adjust the LPT stage 1 nozzle assembly using paragraph 2.B of Honeywell International Inc. SB No. TFE731-72-3369RWK, Revision 6, dated June 26, 2002 or replace with a serviceable LPT stage 1 nozzle assembly.

#### Repetitive Inspections for TFE731-2 and -2C Series Engines

(g) Thereafter, for TFE731-2 and -2C series engines, at every MPI, but not to exceed 2,200 hours time-in-service since the last LPT stage 1 nozzle assembly inspection, do the following:

(1) Measure and determine the acceptance of the LPT stage 1 nozzle assembly using paragraph 2.A.(3) through 2.A.(5) of Honeywell International Inc. SB No. TFE731-72-3369RWK, Revision 6, dated June 26, 2002; and

(2) If necessary, adjust the LPT stage 1 nozzle assembly using paragraph 2.B of Honeywell International Inc. SB No. TFE731-72-3369RWK, Revision 6, dated June 26, 2002 or replace with a serviceable LPT stage 1 nozzle assembly.

#### Disk Replacement for TFE731-3, -3A, -3AR, -3B, -3BR, and -3R Series Engines

(h) For TFE731-3, -3A, -3AR, -3B, -3BR, and -3R series engines with LPT stage 1 disk, P/N 3072351-All, 3073113-All, 3073497-All, or 3074103-All, installed, replace the LPT stage 1 disk with a serviceable disk, at next MPI or at next access to the LPT stage 1 nozzle assembly, after the effective date of this AD, or before December 31, 2011, or at disk life limit, whichever occurs first.

#### TFE731-3B and -3BR Series Engines

(i) For TFE731-3B and -3BR series engines, no replacement LPT stage 1 disk is available for disk P/N 3073497-All. Conversion from the TFE731-3B and -3BR series engines to the TFE731-3C series engine changes the turbine rotor configuration to allow installation of a serviceable LPT stage 1 disk.

#### Optional Terminating Action

(j) As optional terminating action to the repetitive inspections required by this AD, replace the applicable LPT stage 1 disk with a serviceable LPT stage 1 disk.

#### Definitions

(k) For the purposes of this AD:

(1) Next access to the LPT stage 1 nozzle assembly is defined as when the low-pressure tie-shaft is unstretched.

(2) A serviceable LPT stage 1 disk is defined as a disk having a part number not listed in this AD.

(3) A serviceable LPT stage 1 nozzle assembly is defined as an LPT stage 1 nozzle assembly that passes the acceptance referenced in paragraph (f)(1) or (g)(1) of this AD.

#### Additional Information

(l) For additional information regarding the training and tooling recommended to perform the inspection and adjustment of the LPT stage 1 nozzle assembly, contact Honeywell Engines, Systems & Services, Customer Support Center, M/S 26-06/2102-323, P.O. Box 29003, Phoenix, AZ 85038-9003. Telephone: (Domestic) 1-800-601-3099 (International) 1-602-365-3099, FAX: 1-602-365-3343.

#### Alternative Methods of Compliance

(m) The Manager, Los Angeles Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

#### Material Incorporated by Reference

(n) None.

#### Related Information

(o) None.

Issued in Burlington, Massachusetts, on June 4, 2004.

**Jay J. Pardee,**

*Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 04-13563 Filed 6-15-04; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2001-NM-381-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A330, A340-200, and A340-300 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Airbus Model A330, A340-200, and A340-300 series airplanes. This proposal would require repetitive detailed inspections for discrepancies of the grease and gear teeth of the radial variable differential transducer of the nose wheel steering gearbox; or repetitive detailed inspections for damage of the chrome on the bearing surface of the nose landing gear (NLG) main fitting barrel; as applicable. For airplanes on which any discrepancy or

damage is found, this proposal would require either an additional inspection or corrective actions, as applicable. This action is necessary to prevent incorrect operation or jamming of the nose wheel steering, which could cause reduced controllability of the airplane on the ground. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by July 16, 2004.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-381-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: [9-anm-nprmcomment@faa.gov](mailto:9-anm-nprmcomment@faa.gov). Comments sent via fax or the Internet must contain "Docket No. 2001-NM-381-AD" in the subject line and need not be submitted in triplicate. Comments sent via the Internet as attached electronic files must be formatted in Microsoft Word 97 or 2000 or ASCII text.

The service information referenced in the proposed rule may be obtained from Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Tim Backman, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2797; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this action may be changed in light of the comments received.

Submit comments using the following format:

- Organize comments issue-by-issue. For example, discuss a request to change the compliance time and a request to change the service bulletin reference as two separate issues.

- For each issue, state what specific change to the proposed AD is being requested.

- Include justification (e.g., reasons or data) for each request.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this action must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 2001-NM-381-AD." The postcard will be date stamped and returned to the commenter.

#### Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2001-NM-381-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

#### Discussion

The Direction Générale de l'Aviation Civile (DGAC), which is the airworthiness authority for France, notified the FAA that an unsafe condition may exist on all Airbus Model A330, A340-200, and A340-300 series airplanes. The DGAC advises that an operator of a Model A340 airplane reported the failure of the nose wheel steering (NWS) system. An investigation found abnormal wear of the gear teeth of the radial variable differential transducer (RVDT) gearbox, which led to incorrect driving of the command channel and monitoring-channel feedback sensors. Subsequent analyses of grease samples taken from the RVDT gearbox showed the presence of significant quantities of water in the grease, which, when frozen, could have jammed the gearboxes. The investigation also found chrome flaking and extensive corrosion of the nose landing gear (NLG) main fitting barrel under the NWS rotating sleeve.

The investigators concluded that abrasion from metallic particles in the grease caused the wear of the gear teeth.

These metallic particles came from the corroded areas of the NLG main fitting barrel, and had been carried into the system by grease that was used during the normal lubrication of the rotating sleeve. The investigators also concluded that water entered the gearbox through the seal between the steering collar and the NLG main fitting; improvement of this seal is the subject of Airbus Modification 51318 (Airbus Service Bulletins A330-32-3164 and A340-32-4204).

Wear of the gear teeth of the RVDT caused by the metallic particles from corrosion in the grease, and jamming of the gearbox caused by water freezing in the grease, could result in incorrect operation or jamming of the NWS, which could cause reduced controllability of the airplane on the ground.

The subject area on certain Model A330 series airplanes is almost identical to that on the affected Model A340-200, and A340-300 series airplanes. Therefore, those Model A330 series airplanes may be subject to the unsafe condition revealed on the Model A340-200, and A340-300 series airplanes.

#### Explanation of Relevant Service Information

Airbus has issued the following service bulletins:

- For Model A330 series airplanes: Airbus Service Bulletin A330-32-3134, Revision 02, excluding Appendix 01, dated August 8, 2003; and
- For Model A340-200 and A340-300 series airplanes: Airbus Service Bulletin A340-32-4172, Revision 02, excluding Appendix 01, dated August 8, 2003.

For certain airplanes, these service bulletins specify that operators may choose between two different inspections. Depending on the inspection choice, the service bulletins recommend different repetitive intervals. The service bulletins also state that operators may alternate between the inspection choices as long as the interval until the next inspection is the interval described for the last inspection performed.

The first inspection choice for airplanes without the Airbus Modification is repetitive inspections of the grease and gear teeth of the RVDT driving ring and the gears in the RVDT gearboxes to find discrepancies such as metallic particles in the grease, abnormal wear of the gear teeth, or missing rubber sealant at the mating face between the main fitting and the RVDT gearbox. If there are discrepancies, the service bulletins describe procedures for inspecting the chrome on the bearing surface of the

NLG main fitting barrel under the NWS rotating sleeve for damage such as flaking, corrosion, or blistering.

The second inspection choice for airplanes without the Airbus Modification is repetitive inspections of the chrome on the bearing surface of the NLG main fitting barrel under the NWS rotating sleeve for damages such as flaking, corrosion, or blistering.

For certain other airplanes, the service bulletins recommend only the inspection of the chrome on the bearing surface of the NLG main fitting barrel, which is described in the paragraph above.

For all airplanes on which discrepancies and/or damage are found, the service bulletins specify that operators should take corrective actions. The corrective actions are included in the two Messier-Dowty service bulletins listed below. These corrective actions include degreasing bare base metal and protecting the metal with cadmium Cd10 or a complete paint scheme, restoring the rubber sealant, and/or contacting Messier-Dowty for disposition.

- For certain airplanes: Messier-Dowty Special Inspection Service Bulletin D23285-32-037, dated November 8, 2001.

- For certain other airplanes: Messier-Dowty Special Inspection Service Bulletin D23285-32-044, dated January 12, 2004.

Both Airbus service bulletins refer to the Messier-Dowty service bulletins as additional sources of service information for accomplishment of the inspections and any applicable corrective actions.

The DGAC classified the Airbus service bulletins as mandatory and issued French airworthiness directives 2001-503(B) R3, dated October 1, 2003; and 2001-504(B) R4, dated October 1, 2003; to ensure the continued airworthiness of these airplanes in France.

#### FAA's Conclusions

These airplane models are manufactured in France and are type certificated for operation in the United States under the provisions of § 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the DGAC has kept the FAA informed of the situation described above. The FAA has examined the findings of the DGAC, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

### Explanation of Requirements of Proposed Rule

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design registered in the United States, the proposed AD would require accomplishment of the actions specified in the service bulletins described previously, except as discussed below.

### Differences Among the Proposed Rule, Service Bulletins, and the French Airworthiness Directive

Operators should note that, although the Messier-Dowty service bulletins specify that the manufacturer may be contacted for disposition of certain repair conditions, this proposal would require the repair of those conditions to be accomplished per a method approved by either the FAA, or the DGAC (or its delegated agent). In light of the type of repair that would be required to address the identified unsafe condition, and in consonance with existing bilateral airworthiness agreements, the FAA has determined that, for this proposed AD, a repair approved by either the FAA or the DGAC would be acceptable for compliance with this proposed AD.

Operators should also note that, although the Messier-Dowty service bulletins specify to submit reporting forms to the manufacturer, this proposed AD does not include such a requirement.

The French airworthiness directives do not give a compliance time for inspecting the chrome on the bearing surface of the NLG main fitting barrel for airplanes without Airbus Modification 51318 that have discrepancies of the grease and gear teeth of the RVDT driving ring and the gears in the RVDT gearboxes. This proposed AD would require that operators inspect the chrome within 3 months after the RVDT inspection.

The French airworthiness directives and the service bulletins do not define the type of inspections to be performed. This proposed AD calls the inspections "detailed inspections." Note 1 of this proposed AD defines this inspection.

### Cost Impact

We estimate that 16 airplanes of U.S. registry would be affected by this proposed AD.

For operators of airplanes without Airbus Modification 51318, who choose to do the inspection of the grease and gear teeth of the RVDT gearbox, we estimate that it would take approximately 2 work hours per

airplane to accomplish the proposed inspection and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of this action on U.S. operators is estimated to be \$130 per airplane, per inspection cycle.

For operators of airplanes with Airbus Modification 51381, or for operators of airplanes without Airbus Modification 51381 who choose to do the proposed inspection of the chrome on the bearing surface of the NLG main fitting barrel, we estimate that it would take approximately 8 work hours per airplane to accomplish the inspection, and that the average labor rate is \$65 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$520 per airplane, per inspection cycle.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

### Regulatory Impact

The regulations proposed herein would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the

location provided under the caption **ADDRESSES**.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

**Airbus:** Docket 2001–NM–381–AD.

*Applicability:* All Model A330, A340–200, and A340–300 series airplanes; certificated in any category.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent incorrect operation or jamming of the nose wheel steering, which could cause reduced controllability of the airplane on the ground, accomplish the following:

#### Service Bulletin Reference

(a) The following information pertains to the service bulletin referenced in this AD:

(1) The term "service bulletin," as used in this AD, means the Accomplishment Instructions of the following service bulletins, as applicable:

(i) For the inspections specified in paragraphs (c) and (d) of this AD: For Model A330 series airplanes, Airbus Service Bulletin A330–32–3134, Revision 02, excluding Appendix 01, dated August 8, 2003; and for Model A340–200 and A340–300 series airplanes, Airbus Service Bulletin A340–32–4172, Revision 02, excluding Appendix 01, dated August 8, 2003; and

(ii) For further information about the inspections required by paragraphs (c) and (d) of this AD, and for the corrective actions specified in paragraph (e) of this AD: Messier-Dowty Special Inspection Service Bulletin D23285–32–037, dated November 8, 2001 (for airplanes without Airbus Modification 51381); and Messier-Dowty Special Inspection Service Bulletin D23285–32–044, dated January 12, 2004 (for airplanes with Airbus Modification 51381).

(2) Actions accomplished before the effective date of this AD per the Airbus service bulletins listed in Table 1 of this AD are considered acceptable for compliance with the corresponding action specified in this AD.

TABLE 1.—PREVIOUS ISSUES OF SERVICE BULLETINS

Model	Service bulletin	Revision level	Date
A330 .....	A330-32-3134	Original Issue ...	September 11, 2001.
A330 .....	A330-32-3134	01 .....	November 29, 2001.
A340-200 and A340-300 .....	A340-32-4172	Original Issue ...	September 11, 2001.
A340-200 and A340-300 .....	A340-32-4172	01 .....	November 29, 2001.

### Initial Inspection and Related Investigative Action

(b) For airplanes without Airbus Modification 51381: At the latest of the times in paragraphs (b)(1), (b)(2), and (b)(3) of this AD, do the applicable initial inspection in paragraph (d) of this AD.

(1) Within 60 months after the date that the nose landing gear (NLG) was installed on the airplane.

(2) Within 60 months after the last major NLG overhaul accomplished before the effective date of this AD.

(3) Within 700 flight hours after the effective date of this AD.

(c) For airplanes with Airbus Modification 51381: At the latest of the times in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, do the applicable initial inspection in paragraph (d) of this AD.

(1) Within 60 months after the date that the NLG was installed on the airplane.

(2) Within 60 months after the last major NLG overhaul accomplished before the effective date of this AD.

(3) Within 60 months after the date that Airbus Modification 51381 was installed on the airplane.

(d) For airplanes without Airbus Modification 51318, do the inspection in either paragraph (d)(1) or (d)(2) of this AD, including any applicable related investigative action. For airplanes with Airbus Modification 51318, do the inspection in paragraph (d)(2) of this AD. Do the inspection at the applicable time in paragraph (b) or (c) of this AD, in accordance with the applicable service bulletin.

(1) Do a detailed inspection for discrepancies of the grease and gear teeth of the radial variable differential transducer (RVDT) driving ring and the gears in the RVDT gearboxes. If there are no discrepancies (such as metallic particles in the grease, abnormal wear of the gear teeth, or missing rubber sealant at the mating face between the main fitting and the RVDT gearbox), repeat the inspection per paragraph (e) of this AD. If there are discrepancies, within 3 months after the inspection, do the inspection in paragraph (d)(2) of this AD.

(2) Do a detailed inspection for damage of the chrome on the bearing surface of the NLG main fitting barrel under the NWS rotating sleeve. If there is no damage (such as flaking, corrosion, or blistering), repeat the inspection per paragraph (e) of this AD. If there is damage, do the corrective action in paragraph (f) of this AD.

**Note 1:** For the purposes of this AD, a detailed inspection is defined as: "An intensive visual examination of a specific structural area, system, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally

supplemented with a direct source of good lighting at intensity deemed appropriate by the inspector. Inspection aids such as mirror, magnifying lenses, etc., may be used. Surface cleaning and elaborate access procedures may be required."

### Repetitive Inspections

(e) Repeat the applicable inspection required by paragraph (d) of this AD at the applicable interval in paragraph (e)(1) or (e)(2) of this AD until paragraph (f) of this AD is accomplished.

(1) If the most recent inspection performed is the inspection in paragraph (d)(1) of this AD, then repeat the selected inspection at intervals not to exceed 8 months.

(2) If the most recent inspection performed is the inspection in paragraph (d)(2) of this AD, then repeat the selected inspection at intervals not to exceed 18 months.

### Corrective Actions

(f) Except as provided by paragraph (d)(1) of this AD, for airplanes on which any damage or discrepancy is found during any inspection required by paragraph (d) or (e) of this AD: Prior to further flight, do the corrective action in accordance with the applicable service bulletin. Where the service bulletin recommends contacting Messier-Dowty for appropriate action: Before further flight, repair per a method approved by either the Manager, International Branch, ANM-116, FAA, Transport Airplane Directorate; or the Direction Générale de l'Aviation Civile (DGAC) (or its delegated agent).

### No Reporting Requirements

(g) Where the Messier-Dowty service bulletins specify to submit a reporting form to the manufacturer, this AD does not include such a requirement.

### Alternative Methods of Compliance

(h) In accordance with 14 CFR 39.19, the Manager, International Branch, ANM-116, is authorized to approve alternative methods of compliance for this AD.

**Note 2:** The subject of this AD is addressed in French airworthiness directives 2001-503(B) R3, dated October 1, 2003; and 2001-504(B) R4, dated October 1, 2003.

Issued in Renton, Washington, on June 7, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-13562 Filed 6-15-04; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. 2003-NM-214-AD]

RIN 2120-AA64

### Airworthiness Directives; Boeing Model 777-200 and -300 Series Airplanes

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Boeing Model 777-200 and -300 series airplanes. This proposal would require modification of the bolt holes of the lower side of the body splice t-chord common to the paddle fitting of the lower wing panel. The modification includes performing a high frequency eddy current inspection of the fastener hole for cracks, repairing the hole if necessary, and replacing the fasteners with new inconel bolts. This action is necessary to prevent fatigue cracks in the lower t-chord at the bolt holes common to the paddle fittings that could result in fractures of one or more of the t-chord segments, which could lead to detachment of the lower wing panel and consequent loss of the wing. This action is intended to address the identified unsafe condition.

**DATES:** Comments must be received by August 2, 2004.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-114, Attention: Rules Docket No. 2003-NM-214-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9 a.m. and 3 p.m., Monday through Friday, except Federal holidays. Comments may be submitted via fax to (425) 227-1232. Comments may also be sent via the Internet using the following address: [9-anm-nprmcomment@faa.gov](mailto:9-anm-nprmcomment@faa.gov). Comments sent via fax or the Internet must contain