

Governors, however, intends to issue similar notices at least 60 days prior to the elimination of check operations at some other Reserve Bank offices, as described in the May 2003 Federal Register document.

Administrative Procedure Act

The Board has not followed the provisions of 5 U.S.C. 553(b) relating to notice and public participation in connection with the adoption of this final rule. The revisions to the appendix are technical in nature, and the routing symbol revisions are required by the statutory and regulatory definitions of "check-processing region." Because there is no substantive change on which to seek public input, the Board has determined that the § 553(b) notice and comment procedures are unnecessary.

Paperwork Reduction Act

In accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. 3506; 5 CFR 1320 Appendix A.1), the Board has reviewed the final rule under authority delegated to the Board by the Office of Management and Budget. This technical amendment to appendix A of Regulation CC will (1) delete the reference to the Columbia office of the Federal Reserve Bank of Richmond and reassign the routing symbols listed under that office to that Reserve Bank's Charlotte office and (2) delete the reference to the Louisville office of the Federal Reserve Bank of St. Louis and reassign the routing symbols listed under that office to the Cincinnati office of the Federal Reserve Bank of Cleveland. The depository institutions that are located in the affected check processing regions and that include the routing numbers in their disclosure statements would be required to notify customers of the resulting change in availability under § 229.18(e). However, because all paperwork collection procedures associated with Regulation CC already are in place, the Board anticipates that no additional burden will be imposed as a result of this rulemaking.

12 CFR Chapter II

List of Subjects in 12 CFR Part 229

Banks, Banking, Reporting and recordkeeping requirements.

Authority and Issuance

For the reasons set forth in the preamble, the Board is amending 12 CFR part 229 to read as follows:

PART 229—AVAILABILITY OF FUNDS AND COLLECTION OF CHECKS (REGULATION CC)

1. The authority citation for part 229 continues to read as follows:

Authority: 12 U.S.C. 4001 et seq.

2. The Fourth, Fifth, and Eighth Federal Reserve District routing symbol lists in appendix A are revised to read as follows:

Appendix A to Part 229—Routing Number Guide to Next-Day Availability Checks and Local Checks

* * * * *

Fourth Federal Reserve District

[Federal Reserve Bank of Cleveland]

Head Office

Table with 2 columns: routing number, symbol. Rows: 0410 2410, 0412 2412, 0430 2430, 0432 2432, 0433 2433, 0434 2434

Cincinnati Branch

Table with 2 columns: routing number, symbol. Rows: 0420 2420, 0421 2421, 0422 2422, 0423 2423, 0515 2515, 0519 2519, 0813 2813, 0830 2830, 0839 2839, 0863 2863

Columbus Office

Table with 2 columns: routing number, symbol. Rows: 0440 2440, 0441 2441, 0442 2442

Fifth Federal Reserve District

[Federal Reserve Bank of Richmond]

Baltimore Branch

Table with 2 columns: routing number, symbol. Rows: 0510 2510, 0514 2514, 0520 2520, 0521 2521, 0522 2522, 0540 2540, 0550 2550, 0560 2560, 0570 2570

Charlotte Branch

Table with 2 columns: routing number, symbol. Rows: 0530 2530, 0531 2531, 0532 2532, 0539 2539

* * * * *

Eighth Federal Reserve District

[Federal Reserve Bank of St. Louis]

Head Office

Table with 2 columns: routing number, symbol. Rows: 0810 2810, 0812 2812, 0815 2815, 0819 2819, 0865 2865

Memphis Branch

Table with 2 columns: routing number, symbol. Rows: 0820 2820, 0829 2829, 0840 2840, 0841 2841, 0842 2842, 0843 2843

* * * * *

By order of the Board of Governors of the Federal Reserve System, acting through the Secretary of the Board under delegated authority, June 22, 2004.

Jennifer J. Johnson,

Secretary of the Board.

[FR Doc. 04-14505 Filed 6-24-04; 8:45 am]

BILLING CODE 6210-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 2003-SW-38-AD; Amendment 39-13686; AD 2004-13-05]

RIN 2120-AA64

Airworthiness Directives; Eurocopter Deutschland Model MBB-BK 117 A-1, A-3, A-4, B-1, B-2, and C-1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment adopts a new airworthiness directive (AD) for the specified Eurocopter Deutschland (ECD) model helicopters that requires inspecting the vertical fin skin paneling to determine if it was manufactured with the correct wall thickness. This amendment is prompted by a report from the manufacturer that some vertical fins may have been produced with the wrong vertical fin skin thickness. The actions specified by this AD are intended to prevent failure of the vertical fin and subsequent loss of control of the helicopter.

DATES: Effective July 30, 2004.

FOR FURTHER INFORMATION CONTACT: Richard Monschke, Aviation Safety Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5116, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION: A proposal to amend 14 CFR part 39 to include an AD for the specified model helicopters was published in the Federal Register on February 10, 2004 (69 FR 6214). That action proposed to require inspecting the vertical fin skin paneling to determine if it was manufactured with the correct wall thickness.

The Luftfahrt-Bundesamt (LBA), the airworthiness authority for the Federal Republic of Germany, notified the FAA that an unsafe condition may exist on ECD Model MBB-BK117 helicopters, Model A-1 up to B-2, serial number (S/N) all, and Model C-1, S/N 7500 up to 7545. The LBA advises that during tail boom production, metal sheeting of 0.6-millimeter (mm) thickness was found instead of the specified 0.8-mm thickness for the skin paneling of several tail booms.

ECD has issued Alert Service Bulletin No. ASB-MBB-BK117-30-109, Revision 1, dated July 3, 2003, which specifies measuring the wall thickness of the skin paneling of the vertical fin to determine the thickness. The LBA classified this service bulletin as mandatory and issued AD No. 2003-219, dated August 21, 2003, to ensure the continued airworthiness of these helicopters in the Federal Republic of Germany.

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were received on the proposal or the FAA's determination of the cost to the public. The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

The FAA estimates that this AD will affect 132 helicopters of U.S. registry. The required actions will take about 1 hour per helicopter to do at an average labor rate of \$65 per work hour. Based on these figures, we estimate the total

cost impact of the AD on U.S. operators to be \$8580 assuming no vertical fins will need to be replaced.

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator,

the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

2004-13-05 Eurocopter Deutschland:

Amendment 39-13686. Docket No. 2003-SW-38-AD.

Applicability: Model MBB-BK 117 A-1, A-3, A-4, B-1, and B-2, all serial numbers (S/N), and Model C-1, S/N 7500 through 7545, certificated in any category.


Compliance: Required within 100 hours time in service, unless accomplished previously.

To prevent failure of the vertical fin and subsequent loss of control of the helicopter, do the following:

(a) Using external calipers, measure the wall thickness, including primer coating, of the skin paneling of the vertical fin at the locations shown in Figure 1 of this AD.

Note 1: Eurocopter Deutschland (ECD) Alert Service Bulletin No. ASB-MBB-BK117-30-109, Revision 1, dated July 3, 2003, pertains to the subject of this AD.

BILLING CODE 4910-13-P



△ Measurements are to be taken at at least three locations on the skin panel of the vertical fin. Care has to be taken that the external calipers are held squarely to the skin panel wall while measurements are being taken, since tilting of the calipers can lead to false results. If the panel thickness, including the primer coating, is at least 0.778 mm (0.03063 inch) at every measured location, no further action is necessary.

Vertical Fin-Skin Panelling
Figure 1

(b) If the wall thickness, including the primer coating, of the panelling is less than 0.778 millimeter (0.03063 inch) at any of the measured locations, replace the vertical fin with an airworthy part before further flight.

(c) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Safety Management Group, Rotorcraft Directorate, FAA, for information about previously approved alternative methods of compliance.

(d) This amendment becomes effective on July 30, 2004.

Note 2: The subject of this AD is addressed in Luftfahrt-Bundesamt (Federal Republic of Germany) AD 2003-219, dated August 21, 2003.

Issued in Fort Worth, Texas, on June 16, 2004.

David A. Downey,
Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 04-14318 Filed 6-24-04; 8:45 am]

BILLING CODE 4910-13-C

**DEPARTMENT OF TRANSPORTATION
Federal Aviation Administration**

14 CFR Part 39

[Docket No. 2002-NE-19-AD; Amendment 39-13693; AD 2004-13-11]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc RB211 Trent 875-17, Trent 877-17, Trent 884-17, Trent 884B-17, Trent 892-17, Trent 892B-17, and Trent 895-17 Series Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Rolls-Royce plc (RR) RB211 Trent 875-17,