

year average fresh prune production of 4,359 tons (from Committee records), and the most recent three-year average producer price of \$303 per ton as reported by the National Agricultural Statistics Service, the average annual revenue from the sale of fresh prunes is approximately \$6,143 per producer. In addition, based on Committee records and 2003 f.o.b. prices ranging from \$8.50 to \$9.50 per 30-pound container as reported by the AMS Market News Service, the entire Washington-Oregon fresh prune industry handles less than \$5,000,000 worth of prunes. In view of the foregoing, the majority of Washington-Oregon fresh prune producers and handlers may be classified as small entities.

This rule increases the assessment rate established for the Committee and collected from handlers for the 2004–2005 and subsequent fiscal periods from \$1.50 to \$1.75 per ton for prunes. The Committee unanimously recommended 2004–2005 expenditures of \$7,454 and the \$1.75 per ton assessment rate. The assessment rate of \$1.75 is \$0.25 higher than the 2003–2004 rate. With an estimated 2004–2005 prune crop of 4,500 tons, the \$1.75 rate should provide the Committee with \$7,875 in assessment income and be adequate to cover budgeted expenses. The Committee recommended the higher assessment rate to help ensure that budgeted expenses are covered and that its monetary reserve will not have to be used. Funds in the reserve (\$4,900 as of March 31, 2004), will be kept within the maximum permitted by the order of approximately one fiscal period's operational expenses (§ 924.42).

The major expenditures recommended by the Committee for the 2004–2005 fiscal period include \$3,928 for employee salaries, \$576 for rent and maintenance, \$500 for Committee travel, and \$475 for the annual financial audit. These budgeted expenses are the same as those approved for the 2003–2004 fiscal period.

The Committee discussed alternatives to this rule, including alternative expenditure levels. Lower assessment rates were considered, but not recommended because they would not have generated the income necessary to administer the program with an adequate reserve.

A review of historical information and preliminary information pertaining to the upcoming crop year indicates that the producer price for the 2004–2005 season could range from about \$273 per ton to about \$351 per ton. Therefore, the estimated assessment revenue for the 2004–2005 fiscal period as a percentage

of total producer revenue could range between 0.50 and 0.64 percent.

This action increases the assessment obligation imposed on handlers. While assessments impose some additional costs on handlers, the costs are minimal and uniform on all handlers. Some of the additional costs may be passed on to producers. However, these costs are offset by the benefits derived by the operation of the order. In addition, the Committee's meeting was widely publicized throughout the Washington-Oregon fresh prune industry and all interested persons were invited to attend and participate in the Committee's deliberations on all issues. Like all Committee meetings, the May 25, 2004, meeting was a public meeting and all entities, both large and small, were able to express views on this issue.

This rule imposes no additional reporting or recordkeeping requirements on either small or large Washington-Oregon fresh prune handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies.

USDA has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

A proposed rule concerning this action was published in the **Federal Register** on July 19, 2004 (69 FR 42899). Copies of the proposed rule were also mailed or sent via facsimile to Committee members. Finally, the proposal was made available through the Internet by USDA and the Office of the Federal Register. A 15-day comment period ending August 3, 2004, was provided for interested persons to respond to the proposal. No comments were received.

A small business guide on complying with fruit, vegetable, and specialty crop marketing agreements and orders may be viewed at: <http://www.ama.usda.gov/fv/moab.html>. Any questions about the compliance guide should be sent to Jay Guerber at the previously mentioned address in the **FOR FURTHER INFORMATION CONTACT** section.

After consideration of all relevant material presented, including the information and recommendation submitted by the Committee and other available information, it is hereby found that this rule, as hereinafter set forth, will tend to effectuate the declared policy of the Act.

Pursuant to 5 U.S.C. 553, it is also found and determined that good cause exists for not postponing the effective date of this rule until 30 days after publication in the **Federal Register** because handlers are already receiving

2004 crop fresh prunes from growers. The 2004–2005 fiscal period began on April 1, and the marketing order requires that the rate of assessment for each fiscal period apply to all assessable Washington-Oregon fresh prunes handled during such fiscal period. The Committee needs to have sufficient funds to pay for expenses which are incurred on a continuous basis. Further, handlers are aware of this action which was unanimously recommended by the Committee at a public meeting. Also, a 15-day comment period was provided for in the proposed rule, and no comments were received.

#### **List of Subjects in 7 CFR Part 924**

Plums, Prunes, Marketing agreements, Reporting and recordkeeping requirements.

- For the reasons set forth in the preamble, 7 CFR part 924 is amended as follows:

#### **PART 924—FRESH PRUNES GROWN IN DESIGNATED COUNTIES IN WASHINGTON AND IN UMATILLA COUNTY, OREGON**

- 1. The authority citation for 7 CFR part 924 continues to read as follows:

**Authority:** 7 U.S.C. 601–674.

- 2. Section 924.236 is revised to read as follows:

#### **§ 924.236 Assessment rate.**

On or after April 1, 2004, an assessment rate of \$1.75 per ton is established for the Washington-Oregon Fresh Prune Marketing Committee.

Dated: September 1, 2004.

**A.J. Yates,**  
*Administrator, Agricultural Marketing Service.*

[FR Doc. 04-20273 Filed 9-7-04; 8:45 am]

**BILLING CODE 3410-02-P**

---

#### **DEPARTMENT OF TRANSPORTATION**

##### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. 2002-NM-345-AD; Amendment 39-13789; AD 2004-18-11]**

**RIN 2120-AA64**

**Airworthiness Directives; McDonnell Douglas Model DC-9-14, DC-9-15, and DC-9-15F Airplanes; and Model DC-9-20, DC-9-30, DC-9-40, and DC-9-50 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment adopts a new airworthiness directive (AD), applicable to certain McDonnell Douglas Model DC-9-14, DC-9-15, and DC-9-15F airplanes; and Model DC-9-20, DC-9-30, DC-9-40, and DC-9-50 series airplanes. This amendment requires, among other actions, performing repetitive inspections for cracking of the counterbore of the two lower mounting holes and the lower forward edge of the outboard idler hinge fitting of the left and right wing flap at station Xw=333.148, and replacing the flap idler hinge fitting with a new or serviceable part. This action is necessary to prevent failure of the outboard idler hinge fitting of the left and right wing flap at station Xw=333.148 due to fatigue cracking, which could result in a deflected flap that may cause asymmetric lift and consequent reduced controllability and structural integrity of the airplane. This action is intended to address the identified unsafe condition.

**DATES:** Effective October 13, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of October 13, 2004.

**ADDRESSES:** The service information referenced in this AD may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

**FOR FURTHER INFORMATION CONTACT:**

Wahib Mina, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5324; fax (562) 627-5210.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an airworthiness directive (AD) that is applicable to certain McDonnell Douglas Model DC-9-14, DC-9-15, and

DC-9-15F airplanes; and Model DC-9-20, DC-9-30, DC-9-40, and DC-9-50 series airplanes; was published in the **Federal Register** on January 29, 2004 (69 FR 4259). That action proposed to require, among other actions, performing repetitive inspections for cracking of the counterbore of the two lower mounting holes and the lower forward edge of the outboard idler hinge fitting of the left and right wing flap at station Xw=333.148, and replacing the flap idler hinge fitting with a new or serviceable part.

**Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. Due consideration has been given to the comments received.

**Support for Proposed Rule**

One commenter supports the proposed rule.

**Request To Revise Cost Estimates**

The other commenter, an operator, requests that we revise the cost estimates listed in the proposed rule. The commenter states that the inspection, based on similar inspections it is currently conducting for another AD, will take four work hours per airplane (two work hours per fitting, two fittings per airplane) instead of the two work hours estimated in the proposed rule. The commenter points out that Boeing Service Bulletin DC9-57-225 (referenced as the appropriate source of service information in the proposed rule) specifies 2.7 work hours per fitting, 5.4 work hours per airplane. The commenter further states that the proposed rule does not include the cost of replacement parts required at each inspection interval, at the cost of \$1,122.20 per airplane (for Group 1 airplanes within its fleet). Therefore, the commenter declares that the proposed inspection will actually cost \$1,365 per airplane, per inspection cycle for Group 1 airplanes, and \$667 per airplane, per inspection cycle for Group 2 airplanes—not \$130 per airplane, per inspection cycle, as proposed.

The commenter also states that the replacement will take nine work hours per fitting, instead of the two work hours estimated in the proposed rule. The commenter points out that Boeing Service Bulletin DC9-57-225 specifies 7.6 work hours per fitting for the replacement. Therefore, the commenter declares the proposed replacement will cost \$6,005 per airplane for Group 1 airplanes, and \$10,397 per airplane for Group 2 airplanes—instead of between

\$2,024 and \$4,569 per airplane, as proposed.

We agree with part of the commenter's request. We have reviewed data provided by the airplane manufacturer and agree that replacement of some additional parts may be necessary during the required inspection and replacement. We do not agree, however, with the cost provided by the commenter for those parts. We have revised the cost information below to include the costs of those additional parts, based on the information provided to us by the airplane manufacturer.

We do not agree to revise the work hour estimate for the inspection or replacement. The commenter supplied no data to support its estimate of nine work hours for the replacement. The referenced service bulletin specifies two work hours per fitting for the replacement, which corresponds with the cost information below. We acknowledge that the referenced service bulletin specifies 2.7 work hours per fitting for the inspection—not two (one work hour per fitting, two fittings per airplane) as proposed. However, that figure includes costs for actions associated with access and close up. The cost information below describes only the direct costs of those specific actions required by this AD. We recognize that, in doing the actions required by an AD, operators may incur incidental costs in addition to the direct costs. As explained in the proposed rule, the cost analysis in AD rulemaking actions typically does not include incidental costs such as the time required to gain access and close up, time necessary for planning, or time necessitated by other administrative actions. Those incidental costs, which may vary significantly among operators, are almost impossible to calculate. We have not changed the work-hour estimates in this final rule.

**Conclusion**

After careful review of the available data, including the comments noted above, we have determined that air safety and the public interest require the adoption of the rule with the change previously described. We have determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

**Cost Impact**

There are approximately 708 airplanes of the affected design in the worldwide fleet. We estimate that 411 airplanes of U.S. registry will be affected by this AD, that it will take

approximately 2 work hours per airplane to accomplish the required inspection, and that the average labor rate is \$65 per work hour. The cost of certain parts required to be replaced during this inspection will be between \$212 and \$585 per airplane. Based on these figures, the cost impact of the required inspection on U.S. operators is estimated to be between \$140,562 and \$293,865, or between \$342 and \$715 per airplane, per inspection cycle.

We estimate that it will take approximately 2 work hours per fitting to accomplish the required replacement, and that the average labor rate is \$65 per work hour. The cost of each required replacement fitting will be \$1,894 per Group 1 airplane and \$4,439 per Group 2 airplane. The cost of certain other parts required to be replaced during this replacement will be \$292 per Group 1 airplane and \$106 per Group 2 airplane. Based on these figures, the cost impact of the required replacement per fitting on U.S. operators is estimated to be between \$951,876 and \$1,921,425, or \$2,316 per Group 1 airplane and \$4,675 per Group 2 airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

## Regulatory Impact

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has

been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules Docket at the location provided under the caption **ADDRESSES**.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

■ Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. Section 39.13 is amended by adding the following new airworthiness directive:

#### 2004-18-11 McDonnell Douglas:

Amendment 39-13789. Docket 2002-NM-345-AD.

**Applicability:** Model DC-9-14, DC-9-15, DC-9-15F, DC-9-21, DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, DC-9-32F (C-9A, C-9B), DC-9-41, and DC-9-51 airplanes; as listed in Boeing Service Bulletin DC9-57-225, dated December 10, 2002; certificated in any category.

**Compliance:** Required as indicated, unless accomplished previously.

To prevent failure of the outboard idler hinge fitting of the left and right wing flap at station Xw=333.148 due to fatigue cracking, which could result in a deflected flap that may cause asymmetric lift and consequent reduced controllability and structural integrity of the airplane, accomplish the following:

### Inspections

(a) Prior to the accumulation of 40,000 total landing cycles on the outboard idler hinge fitting of the left and right wing flap at station Xw=333.148, or within 8,000 landing cycles on the fitting after the effective date of this AD, whichever occurs later: Do high frequency eddy current (HFEC) inspections for cracking of the counterbore of the two lower mounting holes and the lower forward edge of the flap idler hinge fitting at station Xw=333.148, in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC9-57-225, dated December 10, 2002. Although the service bulletin specifies to report inspection findings to the airplane manufacturer, this AD does not include that requirement.

### Condition 1: No Crack Is Found

(b) If no crack is found during any inspection required by paragraph (a) of this

AD, prior to further flight, install a new nut, plain washer, and pre-load indicating (PLI) washer in accordance with the Accomplishment Instructions of Boeing Service Bulletin DC9-57-225, dated December 10, 2002. Repeat the inspections required by paragraph (a) of this AD thereafter at intervals not to exceed 1,000 landings on the fitting until the replacement required by paragraph (e) of this AD is done.

### Condition 2: Crack Is Found

(c) If any crack is found during any inspection required by this AD: Before further flight, replace the cracked flap idler hinge fitting with a new or serviceable fitting having a part number identified under the "New Part Number" column of the applicable table shown in paragraph 2.C.1. of the Material Information section of Boeing Service Bulletin DC9-57-225, dated December 10, 2002. Do the replacement in accordance with the Accomplishment Instructions of the service bulletin.

### Reinstatement of Inspections

(d) Prior to the accumulation of 40,000 total landing cycles on any new or serviceable fitting, do the HFEC inspections required by paragraph (a) of this AD. Repeat the HFEC inspections thereafter at intervals not to exceed 1,000 landing cycles on the fitting until the replacement required by paragraph (e) of this AD is done.

### Replacement

(e) Prior to the accumulation of 80,500 total landing cycles on the flap idler hinge fitting, replace the fitting with a new or serviceable fitting having a part number identified under the "New Part Number" column of the applicable table shown in paragraph 2.C.1. of the Material Information section of Boeing Service Bulletin DC9-57-225, dated December 10, 2002. Do the replacement in accordance with the Accomplishment Instructions of the service bulletin. Repeat the replacement thereafter at intervals not to exceed 80,500 total landing cycles on the fitting.

### Alternative Methods of Compliance

(f) In accordance with 14 CFR 39.19, the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

### Incorporation by Reference

(g) The actions shall be done in accordance with Boeing Service Bulletin DC9-57-225, excluding Appendix A, dated December 10, 2002. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024). Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-

0024); or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

#### **Effective Date**

(h) This amendment becomes effective on October 13, 2004.

Issued in Renton, Washington, on August 27, 2004.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-20208 Filed 9-7-04; 8:45 am]

**BILLING CODE 4910-13-P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. 2002-NM-90-AD; Amendment 39-13785; AD 2004-18-07]**

**RIN 2120-AA64**

#### **Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Final rule.

**SUMMARY:** This amendment supersedes an existing airworthiness directive (AD), applicable to certain BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes, that currently requires identifying the part numbers of discharge valves and cabin pressure controllers, and related investigative and corrective actions if necessary. This amendment requires identifying the part number of an additional cabin pressure controller, and related investigative and corrective actions if necessary. The actions specified by this AD are intended to prevent the installation of incorrect pressurization discharge valves and cabin pressure controllers, which could subject the airframe to excess stress and adversely affect the airframe fatigue life. This action is intended to address the identified unsafe condition.

**DATES:** Effective October 13, 2004.

The incorporation by reference of a certain publication listed in the regulations is approved by the Director of the Federal Register as of October 13, 2004.

The incorporation by reference of a certain other publication listed in the regulations was approved previously by

the Director of the Federal Register as of September 10, 2001 (66 FR 40864, August 6, 2001).

**ADDRESSES:** The service information referenced in this AD may be obtained from British Aerospace Regional Aircraft American Support, 13850 Mclearen Road, Herndon, Virginia 20171. This information may be examined at the Federal Aviation Administration (FAA), Transport Airplane Directorate, Rules Docket, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

#### **FOR FURTHER INFORMATION CONTACT:**

Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** A proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) by superseding AD 2001-15-23, amendment 39-12358 (66 FR 40864, August 6, 2001), which is applicable to certain BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes, was published in the **Federal Register** on June 21, 2004 (69 FR 34312). The action proposed to continue to require identifying the part numbers of discharge valves and cabin pressure controllers, and related investigative and corrective actions if necessary. The action also proposed to require identifying the part number of an additional cabin pressure controller, and related investigative and corrective actions if necessary.

#### **Comments**

Interested persons have been afforded an opportunity to participate in the making of this amendment. No comments were submitted in response to the proposal or the FAA's determination of the cost to the public.

#### **Conclusion**

The FAA has determined that air safety and the public interest require the adoption of the rule as proposed.

#### **Explanation of Change Made to Final Rule**

We inadvertently omitted a paragraph identifier in the proposed AD. We have revised this final rule to identify that paragraph as paragraph (d) of this AD,

and have reidentified subsequent paragraphs accordingly.

#### **Cost Impact**

There are approximately 20 airplanes of U.S. registry that will be affected by this AD.

The actions that are currently required by AD 2001-15-23 and continued in this AD take approximately 3 work hours per airplane to accomplish, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of the currently required actions on U.S. operators is estimated to be \$3,900, or \$195 per airplane.

The new actions that are required in this AD will take approximately 3 work hours to accomplish, at an average labor rate of \$65 per work hour. Based on these figures, the cost impact of the new requirements on U.S. operators is estimated to be \$3,900, or \$195 per airplane.

The cost impact figures discussed above are based on assumptions that no operator has yet accomplished any of the requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted. The cost impact figures discussed in AD rulemaking actions represent only the time necessary to perform the specific actions actually required by the AD. These figures typically do not include incidental costs, such as the time required to gain access and close up, planning time, or time necessitated by other administrative actions.

#### **Regulatory Impact**

The regulations adopted herein will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this final rule does not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this action (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A final evaluation has been prepared for this action and it is contained in the Rules Docket. A copy of it may be obtained from the Rules