

effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, it is determined that this proposal would not have federalism implications under Executive Order 13132.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption

ADDRESSES.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by removing amendment 39-12481 (66 FR 54416, October 29, 2001), and by adding a new airworthiness directive (AD), to read as follows:

Airbus: Docket 2003-NM-16-AD.

Supersedes AD 2002-08-13,
Amendment 39-12481.

Applicability: Model A300 B2 and B4 series airplanes, certificated in any category; except those airplanes modified by Airbus Modification 12656.

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of both spring boxes of the variable lever arm (VLA) due to corrosion damage, which could result in loss of rudder control and consequent reduced controllability of the airplane, accomplish the following:

Restatement of the Requirements of AD 2001-22-02

(a) Within 10 days after November 13, 2001 (the effective date of AD 2001-22-02, amendment 39-12481): Determine the part and amendment numbers of the VLA of the rudder control system to verify the parts were installed using the correct standard, in accordance with Airbus All Operators Telex (AOT) A300-27A0196, dated September 20, 2001; or in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-27-0196, Revision 01, dated November 13, 2002.

(1) If the part and amendment numbers shown are not correct, as specified in the AOT or the service bulletin, before further flight, do a detailed inspection of the VLA tie rod for damage (bent or ruptured rod) in accordance with the AOT or the service bulletin.

(i) If the tie rod is damaged, replace the VLA with a new VLA in accordance with the AOT or the service bulletin. Such replacement ends the requirements of this paragraph.

(ii) If the tie rod is not damaged, no further action is required by this paragraph.

(2) If the part and amendment numbers shown are correct, no further action is required by this paragraph.

Note 1: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

New Requirements of This AD

(b) For airplanes having a VLA with any part number (P/N) other than 418473-20 or 418473-200: Within 500 flight hours after the effective date of this AD, do a detailed inspection of the tie rod for damage (bent or ruptured rod), in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-27-0196, Revision 01, dated November 13, 2002. Repeat the inspection thereafter at intervals not to exceed 1,000 flight hours, until paragraph (f) of this AD has been accomplished.

Replacement or Repair

(c) If any damage is found to the VLA or the rudder control system during any inspection required by paragraph (a)(1) or (b) of this AD, before further flight, replace the VLA with a new VLA (including a follow-up test) in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-27-0196, Revision 01, dated November 13, 2002.

Actions Accomplished in Accordance With Previous Issue of the Service Bulletin

(d) Actions accomplished before the effective date of this AD in accordance with Airbus Service Bulletin A300-27-0196, dated September 20, 2002, are considered acceptable for compliance with the

corresponding actions specified in paragraphs (a), (b), and (c) of this AD.

No Reporting/Parts Return Requirements

(e) Although Airbus Service Bulletin A300-27-0196, Revision 01, dated November 13, 2002, describes procedures for submitting certain information to the manufacturer, and for returning certain parts to the manufacturer, this AD does not require those actions.

Terminating Modification

(f) Within 24 months after the effective date of this AD: Modify the applicable VLA, as required by either paragraph (f)(1) or (f)(2) of this AD, by doing all the applicable actions in accordance with the Accomplishment Instructions of Airbus Service Bulletin A300-27-0198, dated December 1, 2003. Accomplishing this modification ends the repetitive inspections required by paragraph (b) of this AD.

(1) For any VLA having a spring box with P/N 418473-20 or 418473-200: Install a new identification plate and re-identify the VLA.

(2) For any VLA having a spring box with P/N 418473 or 418473-100: Modify the spring box and re-identify the VLA.

Note 2: Airbus Service Bulletin A300-27-0198, dated December 1, 2003, references Goodrich Actuation Systems Service Bulletin 27-21-1H, Revision 3, dated December 8, 2003, as an additional source of service information for accomplishing the modification.

Alternative Methods of Compliance

(g) In accordance with 14 CFR 39.19, the Manager, International Branch, FAA, ANM-116, Transport Airplane Directorate, is authorized to approve alternative methods of compliance for this AD.

Note 3: The subject of this AD is addressed in French airworthiness directive F-2004-091(B), dated June 23, 2004.

Issued in Renton, Washington, on September 29, 2004.

Kalene C. Yanamura,

Acting Manager, , Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-22356 Filed 10-4-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION (DOT)

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19245; Directorate Identifier 2004-NM-108-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 737-300, -400, -500, -600, -700, -700C, -800 and -900 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 737-300, -400, -500, -600, -700, -700C, -800 and -900 series airplanes. This proposed AD would require modifying the wiring for the master dim and test system. For certain airplanes, this proposed AD would also require related concurrent actions as necessary. This proposed AD is prompted by a report that the master dim and test system circuit does not have wiring separation of the test ground signal for redundant equipment in the flight compartment. We are proposing this AD to prevent a single fault failure inflight from simulating a test condition and showing test patterns instead of the selected radio frequencies on the communications panels, which could inhibit communication between the flightcrew and the control tower, affecting the continued safe flight of the airplane.

DATES: We must receive comments on this proposed AD by November 19, 2004.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

sbull By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Technical information: Binh Tran, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton,

Washington 98055-4056; telephone (425) 917-6485; fax (425) 917-6590.

Plain language information: Marcia Walters, marcia.walters@faa.gov.

SUPPLEMENTARY INFORMATION:

Docket Management System (DMS)

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2004-19245; Directorate Identifier 2004-NM-108-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that website, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

We are reviewing the writing style we currently use in regulatory documents. We are interested in your comments on whether the style of this document is clear, and your suggestions to improve the clarity of our communications that affect you. You can get more information about plain language at <http://www.faa.gov/language> and <http://www.plainlanguage.gov>.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

Discussion

We have received a report indicating that the master dim and test system circuit does not have wiring separation of the test ground signal for redundant equipment in the flight compartment on certain Boeing Model 737-300, -400, -500, -600, -700, -700C, -800 and -900 series airplanes. This condition could allow a single fault to simulate a test condition in the annunciators, switches, and displays in the flight compartment. A single fault failure could also simulate a test condition on the communications panels and show test patterns instead of the selected radio frequencies. The flightcrew needs to know the selected radio frequencies so they can communicate with the control tower. In flight, if test patterns appear instead of the selected radio frequencies on the communications panels, communication between the flightcrew and the control tower could be inhibited, and the continued safe flight of the airplane could be affected.

Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 737-33-1132, Revision 1, dated March 4, 2004 (for Model 737-300, -400, and -500 series airplanes). We have also reviewed Boeing Service Bulletin 737-33-1133, Revision 2, dated December 4, 2003 (for Model 737-600, -700, -700C, -800, and -900 series airplanes). These service bulletins describe procedures for modifying the wiring for the master dim and test system. The modification includes re-routing existing wiring, creating splices, and performing operational testing.

For certain airplanes, Service Bulletin 737-33-1132 specifies prior or concurrent accomplishment of Boeing Service Bulletin 737-77-1022, currently at Revision 1, dated October 26, 1989. Service Bulletin 737-77-1022 describes procedures for installing an engine instrument system (EIS), and specifies prior or concurrent accomplishment of Boeing Service Bulletin 737-77-1023,

currently at Revision 1, dated November 9, 1989. Service Bulletin 737-77-1023 describes procedures for modifying the advisory system for the EIS. Boeing Service Bulletin 737-77-1023 references Smiths Industries Service Bulletin 311EDP-77-348 as an additional source of service information for modifying the existing EIS unit.

For certain other airplanes, Service Bulletin 737-33-1133 specifies prior or concurrent accomplishment of Boeing Service Bulletin 737-26A1083, currently at Revision 1, dated November 15, 2001; and Boeing Service Bulletin 737-33-1121, currently at Revision 1, December 19, 2002. Service Bulletin

737-26A1083 describes procedures for installing a smoke detection and fire extinguishing system in the cargo compartment. Service Bulletin 737-33-1121 describes procedures for installing wiring for the test system for the audio control panel lamp.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or

develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require modifying the wiring for the master dim and test system. The proposed AD would require you to use the service information described previously to perform these actions.

Costs of Compliance

This proposed AD would affect about 2,868 airplanes worldwide, and 1,181 airplanes of U.S. registry. The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Boeing service bulletin	Work hours	Average labor rate per hour	Parts	Cost per airplane
737-33-1132, Revision 1	14	\$65	Nominal	\$910
737-33-1133, Revision 2	3	65	Nominal	195

ESTIMATED CONCURRENT SERVICE BULLETIN COSTS

Boeing service bulletin	Work hours	Average labor rate per hour	Parts	Cost per airplane
737-26A1083, Revision 1 (Only one airplane affected).	185	\$65	Between \$30,000 and \$36,400	Between \$42,025 and \$48,425.
737-33-1121, Revision 1	Between 5 and 6	65	Between \$200 and \$340	Between \$525 and \$730.
737-77-1022, Revision 1 (Only four airplanes affected).	72	65	No charge	\$4,680.
737-77-1023, Revision 1	Between 1 and 3	65	Nominal	Between \$65 and \$195.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2004-19245; Directorate Identifier 2004-NM-108-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by November 19, 2004.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Boeing Model 737-300, -400, and -500 series airplanes listed in Boeing Special Attention Service Bulletin 737-33-1132, Revision 1, dated March 4, 2004; and Model 737-600, -700, -700C, -800, and -900 series airplanes listed in Boeing Service Bulletin 737-33-1133, Revision 2, dated December 4, 2003; certificated in any category.

Unsafe Condition

(d) This AD was prompted by a report that the master dim and test system circuit does not have wiring separation of the test ground signal for redundant equipment in the flight compartment. We are issuing this AD to prevent a single fault failure inflight from simulating a test condition and showing test patterns instead of the selected radio frequencies on the communications panels, which could inhibit communication between the flightcrew and the control tower, affecting the continued safe flight of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within

the compliance times specified, unless the actions have already been done.

Modification

(f) Within 30 months after the effective date of this AD: Modify the wiring for the master dim test system in accordance with the Accomplishment Instructions of Boeing

Special Attention Service Bulletin 737-33-1132, Revision 1, dated March 4, 2004 (for Model 737-300, -400, -500 series airplanes); and Boeing Service Bulletin 737-33-1133, Revision 2, dated December 4, 2003 (for Model 737-600, -700, -700C, -800, and -900 series airplanes); as applicable.

Actions Required To Be Accomplished Prior to or Concurrently With Paragraph (f) of This AD

(g) Prior to or concurrently with accomplishment of paragraph (f) of this AD, do the actions specified in Table 1 of this AD, as applicable.

TABLE 1—PRIOR/CONCURRENT ACTIONS

For—	Accomplish all actions associated with—	According to the Accomplishment Instructions of—
Group 57 airplanes identified in Boeing Service Bulletin 737-33-1132, Revision 1, dated March 4, 2004.	Installing an engine instrument system (EIS) and.	Boeing Service Bulletin 737-77-1022, Revision 1, dated October 26, 1989.
Group 4, 5, 7, 15, 16, 20, 24, 25, 29, 30, 33, 37, 39, 40, 41, and 46 airplanes identified in Boeing Service Bulletin 737-33-1133, Revision 2, dated December 4, 2003.	Modifying the advisory system for the EIS	Boeing Service Bulletin 737-77-1023, Revision 1, dated November 9, 1989.
Group 2 airplanes identified in Boeing Service Bulletin 737-33-1121, Revision 1, dated December 19, 2002.	Installing wiring for the test system for the audio control panel lamp.	Boeing Service Bulletin 737-33-1121, Revision 1, dated December 19, 2002.
Group 39 airplanes identified in Boeing Service Bulletin 737-33-1133, Revision 2, dated December 4, 2003.	Installing splice SP896	Boeing Service Bulletin 737-26A1083, Revision 1, dated November 15, 2001.
	Installing a smoke detection and fire extinguishing system in the cargo compartment.	Boeing Service Bulletin 737-26A1083, Revision 1, dated November 15, 2001.

Actions Accomplished per Previous Issue of Service Bulletins

(h) Actions accomplished before the effective date of this AD in accordance with Boeing Special Attention Service Bulletin 737-33-1132, dated March 20, 2003; Boeing Service Bulletin 737-33-1133, dated December 19, 2002; or Boeing Service Bulletin 737-33-1133, Revision 1, dated April 17, 2003, as applicable, are considered acceptable for compliance with the corresponding actions specified in this AD.

Alternative Methods of Compliance (AMOCs)

(i) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on September 27, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-22355 Filed 10-4-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Bureau of Customs and Border Protection

19 CFR 133

RIN 1505-AB51

Recordation of Copyrights and Enforcement Procedures To Prevent the Importation of Piratical Articles

AGENCY: Bureau of Customs and Border Protection, Department of Homeland Security.

ACTION: Proposed rule.

SUMMARY: As a result of technological advances available to those pirating copyrighted works, there has been a global increase in the importation of piratical works. Because of this increased risk to owners of protected copyrighted works and because most owners of copyrights in non-U.S. works do not register their copyrights as a matter of course, the Bureau of Customs and Border Protection (CBP) is proposing regulations that allow CBP to be more responsive to claims of piracy.

The CBP Regulations currently require that in order to be eligible for border protection all claims to copyright, foreign and domestic, be registered with the U.S. Copyright Office. This document proposes to allow sound recordings and motion pictures or similar audio-visual works to be recorded with CBP while pending registration with the U.S. Copyright

Office. This document also proposes to amend the CBP Regulations to enhance the protection of all non-U.S. works by allowing recordation without requiring registration with the U.S. Copyright Office. Lastly, the proposed regulations set forth changes to CBP's enforcement procedures, including, among other things, enhanced disclosure provisions, protection for live musical performances and provisions to enforce the Digital Millennium Copyright Act.

DATES: Written comments must be submitted on or before November 4, 2005.

ADDRESSES: You may submit comments, identified by RIN 1505-AB51, by either of the following methods:

- Federal eRulemaking Portal: <http://www.regulations.gov>. Follow the instructions for submitting comments.

- Mail: Regulations Branch, Office of Regulations and Rulings, Bureau of Customs and Border Protection, 1300 Pennsylvania Avenue, NW. (Mint Annex), Washington, DC 20229.

Comments submitted may be inspected at the Regulations Branch, Office of Regulations and Rulings, Bureau of Customs and Border Protection, 799 9th Street, NW., 5th Floor, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Paul Pizzeck, Esq. or George F. McCray, Esq., Intellectual Property Rights Branch, Office of Regulations and Rulings, (202) 572-8710.

SUPPLEMENTARY INFORMATION: