

Model	Serial Nos.	What Is the Unsafe Condition Presented in This AD?	by improper lockwire security, which could result in engine failure. This failure could lead to a forced landing of the airplane.
Bombardier (Otter) DHC-3.	All serial numbers powered by radial engines.	(d) This AD is the result of mandatory continuing airworthiness information (MCAI) issued by the airworthiness authority for Canada. We are issuing this AD to prevent loss of ignition systems during flight caused	What Must I Do To Address This Problem? (e) To address this problem, you must do the following:
Actions		Compliance	Procedures
(1) Inspect the following: (i) connector plugs on the fore side of the firewall for security; (ii) the connector plug lockwire to ensure it is intact and the holes in the plugs are not broken out or cracked.		Initially inspect within the next 100 hours time-in-service (TIS) after December 6, 2004 (the effective date of this AD). Repetitively inspect thereafter at intervals not to exceed 100 hours TIS.	Follow deHavilland Beaver Alert Service Bulletin Number A2/53, Revision B, dated May 28, 2004; and deHavilland Otter Alert Service Bulletin Number A3/53, Revision B, dated May 28, 2004, as applicable.
(2) If during any inspection required in paragraph (e)(1)(i) and (e)(1)(ii) of this AD: (i) the lockwire holes are found damaged, replace the connector plug with a new part of the same number; and (ii) the lockwire is damaged, replace the lockwire.		Prior to further flight after any inspection required by paragraphs (e)(1)(i) and (e)(1)(ii) of this AD.	Follow deHavilland Beaver Alert Service Bulletin Number A2/53, Revision B, dated May 28, 2004; and deHavilland Otter Alert Service Bulletin Number A3/53, Revision B, dated May 28, 2004, as applicable.
(3) When the connector plugs are replaced, do an operational check of the magnetos and correct as appropriate.		Prior to further flight after any replacement required by paragraph (e)(2)(i) this AD.	Follow the applicable maintenance manual procedures.

Note: We recommend you insert de Havilland Inc. Temporary Revision No. 2-24, dated August 24, 2001, and Temporary Revision No. 14, dated August 24, 2001, into the applicable maintenance manual.

May I Request an Alternative Method of Compliance?

(f) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, New York Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Mazdak Hobbi, Aerospace Engineer, New York ACO, FAA, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: (516) 228-7330; facsimile: (516) 794-5531.

Does This AD Incorporate Any Material by Reference?

(g) You must do the actions required by this AD following the instructions in deHavilland Beaver Alert Service Bulletin Number A2/53, Revision B, dated May 28, 2004; and deHavilland Otter Alert Service Bulletin Number A3/53, Revision B, dated May 28, 2004. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from Bombardier Commercial Service Center, Plant 9, C.P. 6087 Succurale Centre-ville, Montreal QC H3C 3G9, Canada. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/

code_of_federal_regulations/ibr_locations.html

Issued in Kansas City, Missouri, on October 12, 2004.

Dorenda D. Baker,

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-23365 Filed 10-20-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2004-17738; Airspace Docket No. 04-AWP-5]

Establishment of Class D Airspace; Riverside March Field, CA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes a Class D surface area at Riverside March Field, CA, within a 5-mile radius of the airport from the surface up to and including 4,000 feet mean sea level (MSL). The continuous hours of operation of March Airport Traffic Control Tower (ATCT), combined with a part-time Class C airspace area for Riverside March Field, has made this action necessary.

EFFECTIVE DATE: 0901 UTC, November 25, 2004.

FOR FURTHER INFORMATION CONTACT: Debra Trindle, Airspace Specialist, Airspace Branch, Air Traffic Division, Federal Aviation Administration, 15000

Aviation Boulevard, Lawndale, California; telephone (310) 725-6613.

SUPPLEMENTARY INFORMATION:

History

On Monday, August 2, 2004, the FAA proposed to amend 14 CFR part 71 to establish Class D airspace at Riverside March Field, CA (69 FR 46116). The proposal was to establish a Class D surface area within a 5-mile radius of the airport from the surface up to and including 4,000 feet mean sea level (MSL). Riverside March Field currently has Class C airspace that is effective only when the March Ground Control Approach (GCA) is open, usually 2300 local to 0700 local; however the March ATCT is open continuously. Class D airspace is necessary when the ATCT is open, and the GCA is closed, to contain and protect Standard Instrument Approach Procedures (SIAPs) and other Instrument Flight Rules (IFR) operations at the airport. Interested parties were invited to participate in this rulemaking proceeding by submitting written comments on the proposal to the FAA. No comments objecting to the proposal were received. Class D airspace designations are published in paragraph 5000 of FAA Order 7400.9M dated August 30, 2004, and effective September 16, 2004, which is incorporated by reference in 14 CFR 71.1. The Class D airspace designation listed in this document will be published subsequently in the Order.

The Rule

This amendment to 14 CFR part 71 establishes Class D airspace at Riverside

March Field, CA, to accommodate aircraft executing instrument flight procedures into and out of Riverside March Field. The airspace description and effective times of use will be published in appropriate aeronautical publications. The area will not be charted due to the existing, already charted, Class C airspace area.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a Regulatory Evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 71

Airspace, Incorporation by reference, Navigation (air).

Adoption of the Amendment

■ In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

PART 71—DESIGNATION OF CLASS A, CLASS B, CLASS C, CLASS D, AND CLASS E AIRSPACE AREAS; AIRWAYS; ROUTES; AND REPORTING POINTS

■ 1. The authority citation for part 71 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40103, 40113, 40120; E.O. 10854, 24 FR 95665, 3 CFR, 1959–1963 Comp., p. 389.

§ 71.1 [Amended]

■ 2. The incorporation by reference in 14 CFR 71.1 of the Federal Aviation Administration Order 7400.9M, Airspace Designations and Reporting Points, dated August 30, 2004, and effective September 16, 2004, is amended as follows:

Paragraph 5000 Class D airspace.

* * * * *

AWP CA D Riverside March Field, CA [New]

Riverside March Field, CA
(Lat. 33°52'50" N, long. 117°15'34" W)

That airspace extending upward from the surface to and including 4,000 feet MSL within a 5-mile radius of the Riverside March Field. This Class D airspace area is effective during the specific days and times established in advance by a Notice to Airmen. The effective days and times will thereafter be continuously published in the Airport/Facility Directory.

* * * * *

Issued in Los Angeles, California, on September 29, 2004.

John Clancy,

Area Director, Terminal Operations, Western Service Area.

[FR Doc. 04-23548 Filed 10-20-04; 8:45 am]

BILLING CODE 4910-13-M

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 529

Certain Other Dosage Form New Animal Drugs

CFR Correction

In Title 21 of the Code of Federal Regulations, parts 500 to 599, revised as of April 1, 2004, on page 331, in § 529.1940, paragraph (e)(2)(ii) is corrected beginning in the fourth line, by removing (1) and (2).

[FR Doc. 04-55522 Filed 10-20-04; 8:45 am]

BILLING CODE 1505-01-D

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[TD 9141]

RIN 1545-AX88

Application of Section 904 to Income Subject to Separate Limitations; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correcting amendment.

SUMMARY: This document contains corrections to final regulations that were published in the **Federal Register** on July 20, 2004 (69 FR 43304). This regulation relates to the section 904(d) foreign tax credit limitation and to the exclusion of certain export financing interest from foreign personal holding company income.

DATES: These corrections are effective July 20, 2004.

FOR FURTHER INFORMATION CONTACT:

Bethany A. Ingwalson at (202) 622-3850 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The final regulations that are the subject of these corrections are under section 904(d) of the Internal Revenue Code.

Need for Correction

As published, TD 9141 contains errors that may prove to be misleading and are in need of clarification.

List of Subjects in 26 CFR Part 1

Income taxes, Reporting and recordkeeping requirements.

Correction of Publication

■ Accordingly, 26 CFR Part 1 is corrected by making the following correcting amendment:

PART 1—INCOME TAXES

■ **Paragraph 1.** The authority citation for part 1 continues to read in part as follows:

Authority: 26 U.S.C. 7805 * * *

§ 1.904(b)-1 [Corrected]

■ **Par. 2.** Section 1.904(b)-1(g) *Example 3 (v)*, the introductory text is amended by removing the language “\$424.87/ \$2571.42, computed as follows;” and adding the language “\$412/\$2571.42, computed as follows;” in its place.

■ **Par. 3.** Section 1.904(b)-1(g) *Example 4 (iii)*, the second sentence is amended by removing the language “paragraph (c)(1) of this section. Under Step 1, the U.S. long-term capital loss adjustment amount is \$50 (\$80–\$30). Under Step 2, the” and adding the language “paragraph (c)(1) of this section. Under Step 1, the U.S. long-term capital loss adjustment amount is \$50 (\$80–\$30). Under Step 2, the” in its place.

■ **Par. 4.** Section 1.904-(b)-1(g) *Example 5 (iii)*, the second sentence is amended by removing the language “Under Step 1, the U.S. long-term capital loss adjustment amount is \$50 (\$150–\$100). Under Step 2,” and adding the language “to a rate differential adjustment. Under Step 1, the U.S. long-term capital loss adjustment amount is \$50 (\$150–\$100). Under Step 2,” in its place.

§ 1.904(b)-2 [Corrected]

■ **Par. 5.** Section 1.904(b)-2, paragraph (c), the second sentence is amended by removing the language “apply § 1.904(b)-1(i) and this” and adding the