

(1) Place a suitable container under the fuel strainer drain outlet prior to operating the strainer drain control for at least 4 seconds. Check strainer to ensure drain is closed.(2) Inspect the fluid drained from the fuel strainer and each wing tank quick drain for evidence of fuel contamination in the form of water, rust, sludge, ice, or any other substance not compatible with fuel. Also check for proper fuel grade before the first flight of each day and after each refueling. If any contamination is detected, comply with paragraph (f)(4) of this AD.

(3) Repeat steps in paragraph (f)(1) and (f)(2) of this AD on each wing tank quick drain.

(4) If the airplane has been exposed to rain, sleet, or snow, or if the wing fuel tanks or fuel strainer drains produce water or other contamination, you must purge the airplane fuel system to the extent necessary to ensure that there is no water, ice, or other fuel contamination.

#### May I Request Another AMOC for This AD?

(g) You may request a different method of compliance or a different compliance time for this AD by following the procedures in 14 CFR 39.19. Unless FAA authorizes otherwise, send your request to your principal inspector. The principal inspector may add comments and will send your request to the Manager, Wichita Aircraft Certification Office (ACO), FAA. For information on any already approved alternative methods of compliance, contact Paul O. Pendleton, Aerospace Engineer, FAA, Wichita ACO, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4143; facsimile: (316) 946-4107.

#### Does This AD Incorporate Any Material by Reference?

(h) You must do the actions required by this AD following the instructions in O & N Aircraft Modifications Inc. Mandatory Service Bulletin No. ON-100, dated February 1, 1998. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. You may get a copy from O & N Aircraft Modifications Inc., 210 Windsock Lane, Seamans Airport, Factoryville, PA 18419. You may review copies at FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on December 1, 2004.

**David A. Downey,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-26915 Filed 12-8-04; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2004-19228; Directorate Identifier 2004-NM-77-AD; Amendment 39-13897; AD 2004-25-09]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Boeing Model 707 Airplanes and Model 720 and 720B Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Boeing Model 707 airplanes and Model 720 and 720B series airplanes. This AD requires repetitive inspections of the left and right support ribs for the main landing gear (MLG) trunnion, related investigative/corrective actions if necessary, and other specified actions. This AD is prompted by reports of in-service cracking of the support ribs for the MLG trunnion. We are issuing this AD to detect and correct corrosion and cracking of the support ribs for the MLG trunnion, which could result in collapse of the MLG.

**DATES:** This AD becomes effective January 13, 2005.

The incorporation by reference of a certain publication listed in the AD is approved by the Director of the Federal Register as of January 13, 2005.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. You can examine this information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

**FOR FURTHER INFORMATION CONTACT:**

*Technical information:* Candice Gerretsen, Aerospace Engineer,

Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6428; fax (425) 917-6590.

*Plain language information:* Marcia Walters, [marcia.walters@faa.gov](mailto:marcia.walters@faa.gov).

#### Examining the Docket

The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section.

**SUPPLEMENTARY INFORMATION:** The FAA proposed to amend 14 CFR part 39 with an AD for all Boeing Model 707 airplanes and Model 720 and 720B series airplanes. That action, published in the **Federal Register** on October 4, 2004 (69 FR 59151), proposed to require repetitive inspections of the left and right support ribs for the main landing gear (MLG) trunnion, related investigative/corrective actions if necessary, and other specified actions.

#### Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comment that was submitted on the proposed AD. The commenter, the manufacturer, supports the proposed AD.

#### Conclusion

We have carefully reviewed the available data, including the comment that has been submitted, and determined that air safety and the public interest require adopting the AD as proposed.

#### Costs of Compliance

There are about 227 airplanes of the affected design worldwide. The following table provides the estimated costs for U.S. operators to comply with this AD.

## ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Inspection, per inspection cycle.	6	\$65	None .....	\$390, per inspection cycle.	32	\$12,480, per inspection cycle.

**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, the FAA is charged with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

**Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2004-25-09 Boeing:** Amendment 39-13897. Docket No. FAA-2004-19228; Directorate Identifier 2004-NM-77-AD.

**Effective Date**

(a) This AD becomes effective January 13, 2005.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to all Boeing Model 707-100 long body, -200, -100B long body, and -100B short body series airplanes; and Model 707-300, -300B, -300C, and -400 airplanes; and Model 720 and 720B series airplanes; certificated in any category.

**Unsafe Condition**

(d) This AD was prompted by reports of in-service cracking of the support ribs for the main landing gear (MLG) trunnion. We are issuing this AD to detect and correct corrosion and cracking of the support ribs for the MLG trunnion, which could result in collapse of the MLG.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Service Bulletin References**

(f) The term "alert service bulletin," as used in this AD, means the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3510, dated January 15, 2004.

**Repetitive Detailed Inspection and Corrective Action**

(g) Within 6 months after the effective date of this AD: Do a detailed inspection for corrosion and cracking of the left and right support ribs of the MLG trunnion. Do the

inspection in accordance with all of the actions in Part I of the alert service bulletin. Repeat the inspection thereafter at intervals not to exceed 6 months.

(h) If any corrosion or cracking is found during any inspection required by paragraph (g) of this AD: Before further flight, do all applicable related investigative and corrective actions, and the other specified actions, in accordance with the alert service bulletin; except, where the alert service bulletin specifies to contact Boeing, before further flight, repair in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA; or in accordance with data meeting the type certification basis of the airplane approved by a Boeing Company Designated Engineering Representative (DER) who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically refer to this AD.

**Repetitive High Frequency Eddy Current (HFEC) Inspection and Corrective Action**

(i) Within 12 months after the effective date of this AD: Do a HFEC inspection for cracking of the left and right support ribs of the MLG trunnion. Do the inspection in accordance with all of the actions in Part II of the alert service bulletin. Repeat the inspection thereafter at intervals not to exceed 12 months.

(j) If cracking is found during any inspection required by paragraph (i) of this AD: Before further flight, repair the cracked area in accordance with a method approved by the Manager, Seattle ACO; or in accordance with data meeting the type certification basis of the airplane approved by a Boeing Company DER who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically refer to this AD.

**Alternative Methods of Compliance (AMOCs)**

(k)(1) The Manager, Seattle ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by a Boeing Company DER who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the approval must specifically refer to this AD.

**Material Incorporated by Reference**

(l) You must use Boeing 707 Alert Service Bulletin A3510, dated January 15, 2004, to

perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. For copies of the service information, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. For information on the availability of this material at the National Archives and Records Administration (NARA), call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html). You may view the AD docket at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC.

Issued in Renton, Washington, on November 30, 2004.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 04-26794 Filed 12-8-04; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2004-19811; Directorate Identifier 2004-NM-201-AD; Amendment 39-13893; AD 2004-25-05]

RIN 2120-AA64

#### **Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SP, and 747SR Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-200C, 747-200F, 747-300, 747SP, and 747SR series airplanes. This AD requires repetitive inspections to detect cracks and fractures of the strut front spar chord assembly at each strut location, and repair if necessary. This AD is prompted by a report of a fractured front spar chord assembly for strut No. 3, which resulted in the loss of the strut upper link load path. We are issuing this AD to prevent loss of the strut upper link load path and consequent fracture of the diagonal brace, which could result in in-flight separation of the strut and engine from the airplane.

**DATES:** Effective December 27, 2004.

The incorporation by reference of certain publications listed in the AD is

approved by the Director of the Federal Register as of December 27, 2004.

We must receive comments on this AD by February 7, 2005.

**ADDRESSES:** Use one of the following addresses to submit comments on this AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, PO Box 3707, Seattle, Washington 98124-2207. You can examine this information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2004-19811; the directorate identifier for this docket is 2004-NM-201-AD.

#### **Docket Management System (DMS)**

The FAA has implemented new procedures for maintaining AD dockets electronically. As of May 17, 2004, new AD actions are posted on DMS and assigned a docket number. We track each action and assign a corresponding directorate identifier. The DMS AD docket number is in the form "Docket No. FAA-2004-99999." The Transport Airplane Directorate identifier is in the form "Directorate Identifier 2004-NM-999-AD." Each DMS AD docket also lists the directorate identifier ("Old Docket Number") as a cross-reference for searching purposes.

#### **Examining the Dockets**

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in

person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

#### **FOR FURTHER INFORMATION CONTACT:**

Technical information: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6437; fax (425) 917-6590. *Plain language information:* Marcia Walters, [marcia.walters@faa.gov](mailto:marcia.walters@faa.gov).

**SUPPLEMENTARY INFORMATION:** We have received a report indicating that the front spar chord assembly for strut No. 3 fractured on a Boeing Model 747-200B series airplane that had accumulated a total of 16,604 flight cycles and 79,013 flight hours. The front spar chord assembly fractured 4.37 inches forward of the upper link attach lug. The manufacturer's analysis showed that the fitting fractured as the result of fatigue at a critical stress area. Fracture of the front spar chord assembly will result in the loss of the strut upper link load path. Loss of the upper link load path would result in the transfer of additional loads to the diagonal brace load path, which could result in fracture of the diagonal brace. This condition, if not corrected, could result in in-flight separation of the strut and engine from the airplane.

#### **Relevant Service Information**

We have reviewed Boeing Alert Service Bulletin (ASB) 747-54A2224, dated September 30, 2004. The ASB describes procedures for accomplishing detailed and high frequency eddy current (HFEC) inspections of the strut front spar chord assembly for cracks and fractures at each strut location. The ASB also specifies, if any crack or fracture is found, to contact the manufacturer for additional instructions and repair. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

#### **FAA's Determination and Requirements of This AD**

The unsafe condition described previously is likely to exist or develop on other airplanes of the same type design. Therefore, we are issuing this AD to prevent loss of the strut upper link load path and consequent fracture