

Compliance: Required as indicated, unless accomplished previously.

To prevent failure of the main deck floor stanchions and consequent collapse of the main floor during an emergency landing, which could result in passenger injury and impede passenger evacuation from the airplane, accomplish the following:

Replacement and Related Investigative and Corrective Actions and Retrofit Action

(a) Within 18 months after the effective date of this AD: Replace the four tie rods for the waste tank cradle with new tie rods and do all applicable related investigative actions, corrective actions, and special retrofit actions by accomplishing all the actions in the Accomplishment Instructions of Boeing Alert Service Bulletins 767-38A0062 (for Model 767-300 series airplanes) and 767-38A0063 (for Model 767-400ER series airplanes), both dated August 15, 2002; as applicable. Do the actions in accordance with the applicable service bulletin except as provided by paragraph (b) of this AD. Accomplish any related investigative, corrective, or special retrofit action before further flight.

(b) If any deformation, crack, or other damage is found during any related investigative action required by paragraph (a) of this AD, and the bulletin specifies contacting Boeing for appropriate action: Before further flight, perform the special retrofit action per a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. For a retrofit method to be approved by the Manager, Seattle ACO, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

Parts Installation

(c) As of the effective date of this AD, no person may install any tie rod for the waste tank cradle having part number 251T0100-1401, 251T0100-1402, 251T0100-1403, or 251T0100-1404, on any airplane to which this AD applies.

Alternative Methods of Compliance

(d) In accordance with 14 CFR 39.19, the Manager, Seattle ACO, FAA, is authorized to approve alternative methods of compliance (AMOCs) for this AD.

Incorporation by Reference

(e) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 767-38A0062, dated August 15, 2002; and Boeing Alert Service Bulletin 767-38A0063, dated August 15, 2002; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, PO Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/

[code_of_federal_regulations/ibr_locations.html](http://www.archives.gov/federal_regulations/ibr_locations.html).

Effective Date

(f) This amendment becomes effective on January 13, 2005.

Issued in Renton, Washington, on November 30, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-26917 Filed 12-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2004-19023; Directorate Identifier 2004-NM-123-AD; Amendment 39-13899; AD 2004-25-11]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A318, A319, A320, and A321 series airplanes. This AD requires removing two maintenance lights in the hydraulics bay, disconnecting the wiring for the lights, and modifying the switches. This AD is prompted by underlying safety issues involved in fuel tank explosions on several large transport airplanes. We are issuing this AD to prevent an ignition source for fuel vapor in the hydraulics bay, which could result in fire or explosion in the adjacent center wing fuel tank.

DATES: This AD becomes effective January 13, 2005.

The incorporation by reference of certain publications listed in the AD is approved by the Director of the Federal Register as of January 13, 2005.

ADDRESSES: For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. You can examine this information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or at the Docket

Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Technical information: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

Plain language information: Marcia Walters, marcia.walters@faa.gov.

Examining the Docket

The AD docket contains the proposed AD, comments, and any final disposition. You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section.

SUPPLEMENTARY INFORMATION: The FAA proposed to amend 14 CFR Part 39 with an AD for certain Airbus Model A318, A319, A320, and A321 series airplanes. The proposed AD was published in the **Federal Register** on September 7, 2004 (69 FR 54055), to require removing two maintenance lights in the hydraulics bay, disconnecting the wiring for the lights, and modifying the switches.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments that have been submitted on the proposed AD.

Request To Include a Terminating Action

One commenter states that it has no objection to the proposed AD but requests that we revise the proposed AD to include a terminating action that includes installation of an explosion-proof lighting system.

We acknowledge the commenter's request but do not concur. The commenter's request did not include any technical information about an explosion-proof lighting system, nor did it describe the procedures associated with installing such a system. Further, we do not know of any service information at this time that provides procedures for installing this type of system. Once such service information is available and approved, we may consider approving a request for an alternative method of compliance

(AMOC) for the requirements of this AD. No change has been made to the final rule.

Request To Provide Option of Deactivating Power

One commenter requests that we revise the proposed AD to include an option that would allow an operator to deactivate the power to the subject maintenance lights by modifying certain switch wiring. The commenter notes that this modification would reduce the cost of deactivating the existing lights and allow easier installation when

replacement lights are available. The commenter states that this modification “would equally address the unsafe condition.”

We do not concur with the commenter’s request. The commenter did not provide any information on how it plans to modify the wiring to deactivate power to the subject maintenance lights. We may approve a request for an AMOC for the requirements of this AD if the commenter submits this request with technical data supporting its request. No change has been made to the final rule.

Conclusion

We have carefully reviewed the available data, including the comments that have been submitted, and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Remove lights, disconnect wires, and modify switches	3	\$65	\$70	\$265	648	\$171,720

Authority for This Rulemaking

The FAA’s authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs describes in more detail the scope of the agency’s authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, the FAA is charged with promoting safety flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this AD.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2004–25–11 Airbus: Amendment 39–13899. Docket No. FAA–2004–19023; Directorate Identifier 2004–NM–123–AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective January 13, 2005.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Airbus Model A318, A319, A320, and A321 series airplanes; certificated in any category; except those airplanes on which Airbus Modification 33518 has been accomplished in production.

Unsafe Condition

(d) This AD was prompted by underlying safety issues involved in fuel tank explosions on several large transport airplanes. We are issuing this AD to prevent an ignition source for fuel vapor in the hydraulics bay, which could result in fire or explosion in the center wing fuel tank.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification

(f) Within 19 months after the effective date of this AD, remove maintenance lights 9LL and 10LL from the hydraulics bay, disconnect the wiring for the lights, and modify the 12LL switches. Do the actions in accordance with Airbus Service Bulletin A320–92–1032, dated March 8, 2004.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(h) French airworthiness directive F–2004–073, dated May 26, 2004, also addresses the subject of this AD.

Material Incorporated by Reference

(i) You must use Airbus Service Bulletin A320–92–1032, dated March 8, 2004, to perform the actions that are required by this AD, unless the AD specifies otherwise. The

Director of the Federal Register approves the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. For copies of the service information, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. For information on the availability of this material at the National Archives and Records Administration (NARA), call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html. You may view the AD docket at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC.

Issued in Renton, Washington, on November 30, 2004.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 04-26916 Filed 12-8-04; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-64-AD; Amendment 39-13891; AD 2004-25-04]

RIN 2120-AA64

Airworthiness Directives; Mooney Aircraft Corporation Models M20B, M20C, M20D, M20E, M20F, M20G, and M20J Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA adopts a new airworthiness directive (AD) for all Mooney Aircraft Corporation (Mooney) Models M20B, M20C, M20D, M20E, M20F, M20G, and M20J airplanes equipped with an O & N Bladder Fuel Cell installed per Supplemental Type Certificate (STC) SA2277CE or STC SA2350CE. The STCs apply to all the affected airplane models except for Model M20B airplanes. Model M20B airplanes could have one of the STCs incorporated by field approval. This AD requires you to inspect the drain valve to assure that it is inserted fully into the drain nipple and modify any drain valve found not to be inserted fully into the drain nipple. This AD also requires certain modifications and replacements on the affected fuel cells to reduce the chances of water/ice contamination. This AD is the result of reports of rainwater entering the fuel bladders and the information from the subsequent evaluation of the fuel systems. The actions specified by this AD are intended to assist in preventing water

from entering the fuel bladders, which could result in rough engine operation or complete loss of engine power.

DATES: This AD becomes effective on January 21, 2005.

As of January 21, 2005, the Director of the Federal Register approved the incorporation by reference of certain publications listed in the regulation.

ADDRESSES: You may get the service information identified in this AD from O & N Aircraft Modifications Inc., 210 Windsock Lane, Seamans Airport, Factoryville, PA 18419; telephone: (717) 945-3769; facsimile: (717) 945-7282.

You may view the AD docket at FAA, Central Region, Office of the Regional Counsel, Attention: Rules Docket No. 98-CE-64-AD, 901 Locust, Room 506, Kansas City, Missouri 64106. Office hours are 8 a.m. to 4 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Paul O. Pendleton, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4143; facsimile: (316) 946-4107.

SUPPLEMENTARY INFORMATION:

Discussion

What events have caused this AD?

The FAA has received a report of water being trapped in the fuel bladders on Mooney Models M20C, M20D, M20E, M20F, M20G, and M20J airplanes that are equipped with an O & N Bladder Fuel Cell installed per Supplemental Type Certificate (STC) SA2277CE or STC SA2350CE. The STCs apply to all of the above-referenced airplane models except for the Mooney Model M20B airplanes; the Model M20B airplanes could have one of the STCs incorporated by field approval.

Evaluation of this problem shows that improper installation of the fuel bladder drains and fuel caps could allow rainwater to enter the fuel bladders if the fuel cap was defective.

The evaluation also revealed additional installation problems and design deficiencies, including:

- Inadequate installation of the foam filler that supports the fuel bladders;
- Inadequate engine crankcase breather vent and primary fuel vent ice protection; and
- Fuel caps that have the sealing surface below the fuel tank opening.

What is the potential impact if FAA took no action? If not prevented, water entering the fuel bladders could result in rough engine operation or complete loss of engine power.

Has FAA taken any action to this point? We issued a proposal to amend

part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all Mooney Aircraft Corporation (Mooney) Models M20B, M20C, M20D, M20E, M20F, M20G, and M20J airplanes equipped with an O & N Bladder Fuel Cell installed per Supplemental Type Certificate (STC) SA2277CE or STC SA2350CE. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on October 9, 1998 (63 FR 54401). The NPRM proposed to require you to inspect the drain valve to assure that it was inserted fully into the drain nipple and modify any drain valve found not fully inserted into the drain nipple. The NPRM also proposed to require you to incorporate the design changes specified in O & N Aircraft Modifications Inc. Mandatory Service Bulletin No. ON-100, dated February 1, 1998.

Comments

Was the public invited to comment?

We provided the public the opportunity to participate in developing this AD. The following presents the comments received on the proposal and FAA's response to each comment:

Comment Issue No. 1: Remove the Requirement To Replace the Flush Style Fuel Cap With a Raised Style Fuel Cap

What is the commenter's concern?

The FAA received 18 comments with each commenter stating that requiring replacement of the flush style fuel caps with raised style fuel caps is unnecessary.

Most commenters, which are owners and operators of the affected model airplanes, state that they have never experienced getting a single drop of water in the fuel tanks with the O&N flush style fuel caps. Many of these airplanes are washed frequently with high-pressure hoses and are parked outside in the rain, sleet, and snow.

The commenters express no problems with the flush style fuel caps because of proper maintenance and proper operating procedures.

Several commenters state that all high performance airplanes have flush style fuel caps. They further comment that, if the FAA wants these fuel caps replaced on the affected Mooney airplanes because they pose an unsafe condition, then the FAA should mandate this on all airplanes with flush style fuel caps.

The commenters also communicate that this replacement would cause a financial burden with no gain in safety.

The commenters want the fuel cap replacement requirement removed from the AD.