

**Regulatory Findings**

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Airbus:** Docket No. FAA-2005-20453; Directorate Identifier 2004-NM-270-AD.

**Comments Due Date**

(a) The Federal Aviation Administration must receive comments on this AD action by April 4, 2005.

**Affected ADs**

- (b) None.

**Applicability**

(c) This AD applies to Airbus Model A318, A319, A320, and A321 series airplanes, certificated in any category, as listed in Table 1 of this AD.

TABLE 1.—APPLICABILITY

Airbus model—	Having the following Airbus modification installed in production—	Or the following Airbus service bulletin incorporated in service—	But not having the following Airbus modification installed in production—
A318 series airplanes .....	Not applicable .....	Not applicable .....	33232
A319 series airplanes .....	25642 or 26213 .....	A320-52-1088 .....	33232
A320 series airplanes .....	26213 or 26603 .....	A320-52-1088 .....	33232
A321 series airplanes .....	26213 or 26603 .....	A320-52-1088 .....	33232

**Unsafe Condition**

(d) This AD was prompted by a report indicating that, during a test of the fire extinguishing system, air leakage through the water drain valves in the forward and aft cargo doors reduced the concentration of fire extinguishing agent to below the level required to suppress a fire. We are issuing this AD to prevent air leakage through the water drain valves, which, in the event of a fire in the forward or aft cargo compartment, could result in an insufficient concentration of fire extinguishing agent and consequent inability of the fire extinguishing system to suppress the fire.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Replacement of Water Drain Valves**

(f) Within 6 months after the effective date of this AD, replace the water drain valves in the forward and aft cargo doors with new valves that close at a lower differential pressure, by doing all of the applicable actions specified in the Accomplishment Instructions of Airbus Service Bulletin A320-52-1124, dated May 6, 2004.

**Alternative Methods of Compliance (AMOCs)**

(g) The Manager, International Branch, ANM-116, Transport Airplane Directorate,

FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

**Related Information**

(h) French airworthiness directive F-2004-172, dated October 27, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on February 22, 2005.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-4079 Filed 3-2-05; 8:45 am]

**BILLING CODE 4910-13-P**

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 757-200, -200PF, and -300 series airplanes. This proposed AD would require inspecting for damage of the ground brackets, ground wires, and terminal lugs of the auxiliary power unit (APU) battery and the APU start transformer rectifier unit (TRU) as applicable; and corrective and related investigative actions. This proposed AD is prompted by reports indicating that, during inspections on two airplanes, the ground brackets for the APU battery were found damaged. We are proposing this AD to detect and correct a damaged electrical bonding surface of the APU battery and APU start TRU ground connections, which could cause overheating of the ground connections and lead to possible consequent ignition of the adjacent insulating blankets.

**DATES:** We must receive comments on this proposed AD by April 18, 2005.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2005-20473; Directorate Identifier 2004-NM-156-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; Boeing Model 757-200, -200PF, and -300 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- By fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, PO Box 3707, Seattle, Washington 98124-2207.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-20473; the directorate identifier for this docket is 2004-NM-156-AD.

#### FOR FURTHER INFORMATION CONTACT:

Elias Natsiopoulos, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6478; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-20473; Directorate Identifier 2004-NM-156-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments submitted by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual

who sent the comment (or signed the comment on behalf of an association, business, labor union, *etc.*). You can review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

#### Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the DMS receives them.

#### Discussion

We have received reports indicating that, during inspections on two Boeing Model 757-200 airplanes, the ground brackets for the auxiliary power unit (APU) battery were found damaged. Manufacturer analysis found that the bonding surface of the ground brackets had an anodized finish, which reduces electrical conductivity. Further manufacturer investigation of airplanes in production revealed that the method used to clean the ground brackets didn't remove the anodized finish from the bonding surface before the ground wires were installed. This condition, if not corrected, could cause overheating of the ground connections and lead to possible consequent ignition of the adjacent insulating blankets.

#### Similar Models

The subject ground brackets on certain Boeing Model 757-200PF and -300 airplanes are almost identical to those on the affected Model 757-200 airplanes. Therefore, all of these models may be subject to the same unsafe condition.

#### Relevant Service Information

We have reviewed Boeing Alert Service Bulletin 757-24A0099 (for Model 757-200 and -200PF series airplanes), and Alert Service Bulletin 757-24A0100 (for Model 757-300 series airplanes); both dated March 25, 2004. The service bulletins describe procedures for inspecting the ground brackets, ground wires, and terminal lugs of the APU battery and the APU start transformer rectifier unit (TRU) ground connections; and corrective and related investigative actions. Corrective actions include cleaning the bonding

surfaces of the ground brackets and terminal lugs; and replacing the ground brackets, ground wires, and terminal lugs if necessary. Investigative actions include measuring the electrical resistance between the ground brackets and the terminal lugs and between the ground brackets and the station frame. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

#### FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. Therefore, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

#### Clarification of Inspection Terminology

The Boeing alert service bulletins specify inspecting for damage to certain ground connections, but do not specify the type of inspection to be performed. Paragraph (f) of this proposed AD identifies this inspection as a "general visual inspection," and Note 1 of this proposed AD defines this inspection.

#### Costs of Compliance

There are about 251 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 159 airplanes of U.S. registry.

For about 95 Group 1 and Group 3 airplanes: The proposed inspection and cleaning of the ground connections would take about 2 work hours per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$12,350, or \$130 per airplane.

For about 64 Group 2 airplanes: The proposed inspection and cleaning of the ground connection would take about 1 work hour per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$4,160, or \$65 per airplane.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII,

Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### **§ 39.13 [Amended]**

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Boeing:** Docket No. FAA-2005-20473; Directorate Identifier 2004-NM-156-AD.

### Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this AD action by April 18, 2005.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to Boeing Model 757-200, -200PF, and -300 series airplanes, certificated in any category; as identified in Boeing Alert Service Bulletin 757-24A0099, and Boeing Alert Service Bulletin 757-24A0100; both dated March 25, 2004.

### Unsafe Condition

(d) This AD was prompted by reports indicating that during inspections on two airplanes, the ground brackets for the auxiliary power unit (APU) battery were found damaged. We are issuing this AD to detect and correct a damaged electrical bonding surface of the APU battery and APU start transformer rectifier unit (TRU) ground connections, which could cause overheating of the ground connections and lead to possible consequent ignition of the adjacent insulating blankets.

### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Inspection of Ground Connections

(f) Within 18 months after the effective date of this AD, perform a general visual inspection for damage of the ground brackets, ground wires, and terminal lugs of the APU battery and APU start transformer rectifier unit (TRU), and do any corrective and related investigative actions; by doing all the actions specified in the Accomplishment Instructions of Boeing Alert Service Bulletin 757-24A0099 (for Model 757-200 and -200PF series airplanes), or Boeing Alert Service Bulletin 757-24A0100 (for Model 757-300 series airplanes); both dated March 25, 2004; as applicable.

**Note 1:** For the purposes of this AD, a general visual inspection is "a visual examination of an interior or exterior area, installation or assembly to detect obvious damage, failure or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normal available lighting conditions such as daylight, hangar lighting, flashlight or drop-light and may require removal or opening of access panels or doors. Stands, ladders or platforms may be required to gain proximity to the area being checked."

### Alternative Methods of Compliance (AMOCs)

(g) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Issued in Renton, Washington, on February 18, 2005.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-4080 Filed 3-2-05; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2005-20246; Airspace Docket No. 04-ASO-15]

RIN 2120-AA66

### Proposed Establishment of Area Navigation Instrument Flight Rules Terminal Transition Routes (RITTR); Charlotte, NC

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This action proposes to establish four Area Navigation (RNAV) Instrument Flight Rules (IFR) Terminal Transition Routes (RITTR) in the Charlotte, NC, terminal area. RITTR's are low altitude Air Traffic Service (ATS) routes, based on RNAV, for use by aircraft having IFR-approved Global Positioning System (GPS)/Global Navigation Satellite System (GNSS) equipment. The purpose of RITTR is to expedite the handling of IFR overflight traffic through busy terminal airspace areas. The FAA is proposing this action to enhance safety and to improve the efficient use of the navigable airspace in the Charlotte, NC, terminal area.

**DATES:** Comments must be received on or before April 18, 2005.

**ADDRESSES:** Send comments on this proposal to the Docket Management System, U.S. Department of Transportation, Room Plaza 401, 400 Seventh Street, SW., Washington, DC 20590-0001. You must identify FAA Docket No. FAA-2005-20246 and Airspace Docket No. 04-ASO-15, at the beginning of your comments. You may also submit comments through the Internet at <http://dms.dot.gov>.

**FOR FURTHER INFORMATION CONTACT:** Paul Gallant, Airspace and Rules, Office of System Operations and Safety, Federal Aviation Administration, 800 Independence Avenue, SW., Washington, DC 20591; telephone: (202) 267-8783.

**SUPPLEMENTARY INFORMATION:**