

should be done in accordance with the service bulletin.

For Model 757-300 Series Airplanes: Repetitive Overhauls

(f) For Model 757-300 series airplanes: Prior to the accumulation of 30,000 total flight hours, overhaul the primary brake and differential assembly of the HSTA in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757-27A0143, Revision 1, dated October 23, 2003. Repeat the overhaul thereafter at intervals not to exceed 30,000 flight hours.

Actions Accomplished Per Previous Issues of Service Bulletins

(g) Overhauls of the primary brake and tests of the secondary brakes accomplished before the effective date of this AD in accordance with Boeing Alert Service Bulletin 757-27A0142, dated February 13, 2003; or Revision 1, dated April 10, 2003; and overhauls of the primary brake accomplished before the effective date of this AD in accordance with Boeing Alert Service Bulletin 757-27A0143, dated February 13, 2003; are considered acceptable for compliance with the overhaul of the primary brake only and tests of the secondary brakes specified in this AD.

Alternative Methods of Compliance (AMOCs)

(h) In accordance with 14 CFR 39.19, the Manager, Seattle Aircraft Certification Office (ACO), FAA, is authorized to approve AMOCs for this AD.

Incorporation by Reference

(i) Unless otherwise specified in this AD, the actions shall be done in accordance with Boeing Alert Service Bulletin 757-27A0142, Revision 2, dated October 23, 2003; or Boeing Alert Service Bulletin 757-27A0143, Revision 1, dated October 23, 2003; as applicable. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207. Copies may be inspected at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Effective Date

(j) This amendment becomes effective on July 22, 2005.

Issued in Renton, Washington, on June 3, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-11793 Filed 6-16-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2005-21469; Directorate Identifier 2005-NM-124-AD; Amendment 39-14133; AD 2005-12-17]

RIN 2120-AA64

Airworthiness Directives; Bombardier Model DHC-8-400 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Bombardier Model DHC-8-400 series airplanes. This AD requires inspecting the electrical connectors of the fire extinguisher bottles for the forward and aft baggage compartments and for the auxiliary power unit and engine nacelles to determine if they are connected correctly; and doing related investigative and corrective actions, if necessary. This AD is prompted by reports of the electrical connectors for the fire bottles in the forward and aft baggage compartments being cross connected. We are issuing this AD to detect and correct cross connection of the fire extinguisher bottles, which could result in failure of the fire bottles to discharge and consequent inability to extinguish a fire in the affected areas.

DATES: Effective July 5, 2005.

The incorporation by reference of a certain publication listed in the AD is approved by the Director of the Federal Register as of July 5, 2005.

We must receive comments on this AD by August 16, 2005.

ADDRESSES: Use one of the following addresses to submit comments on this AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.
- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada.

You can examine the contents of this AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., room PL-401, on the plaza level of the Nassif Building, Washington, DC. This docket number is FAA-2005-21469; the directorate identifier for this docket is 2005-NM-124-AD.

Examining the Docket

You can examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System (DMS) receives them.

FOR FURTHER INFORMATION CONTACT: Ezra Sasson, Aerospace Engineer, Systems and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, suite 410, Westbury, New York 11590; telephone (516) 228-7320; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION: Transport Canada Civil Aviation (TCCA), which is the airworthiness authority for Canada, notified the FAA that an unsafe condition may exist on certain Bombardier Model DHC-8-400 series airplanes. TCCA advises that it has received three reports of the electrical connectors for the fire extinguisher bottles in the forward and aft baggage compartments being cross connected. Investigation has revealed that similar conditions could exist in the fire extinguisher bottles for the auxiliary power unit (APU) and engine nacelles. Cross connection of the fire extinguisher bottles, if not corrected, could result in failure of the fire bottles to discharge and consequent inability to extinguish a fire in the affected areas.

Relevant Service Information

Bombardier has issued Alert Service Bulletin A84-26-06, dated May 12, 2005. The service bulletin describes procedures for inspecting the electrical connectors of the fire extinguisher bottles for the forward and aft baggage compartments and for the APU and engine nacelles to determine if they are

connected correctly; and doing related investigative and corrective actions if necessary. For certain fire extinguisher bottles, the related investigative action includes inspecting the connector pins for damage if the electrical connectors have been cross connected. The corrective actions include replacing any damaged electrical connectors with new electrical connectors and correcting any incorrect electrical connections, if necessary. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. TCCA mandated the service bulletin and issued Canadian airworthiness directive CF-2005-14, dated May 16, 2005, to ensure the continued airworthiness of these airplanes in Canada.

FAA's Determination and Requirements of This AD

This airplane model is manufactured in Canada and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the TCCA has kept the FAA informed of the situation described above. We have examined the TCCA's findings, evaluated all pertinent information, and determined that we need to issue an AD for products of this type design that are certificated for operation in the United States.

Therefore, we are issuing this AD to detect and correct cross connection of the fire extinguisher bottles, which could result in failure of the fire bottles to discharge and consequent inability to extinguish a fire in the affected areas. This AD requires accomplishing the actions specified in the service information described previously, except as discussed under "Difference Between the AD, Canadian Airworthiness Directive, and Service Bulletin."

Difference Between the AD, Canadian Airworthiness Directive, and Service Bulletin

Operators should note that, although Canadian airworthiness directive CF-2005-14 and the Accomplishment Instructions of the referenced service bulletin describe procedures for submitting inspection results to the airplane manufacturer, this AD does not require that action. We do not need this information from operators.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD; therefore, providing notice and opportunity for public comment before the AD is issued is impracticable, and good cause exists to make this AD effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements that affect flight safety and was not preceded by notice and an opportunity for public comment; however, we invite you to submit any relevant written data, views, or arguments regarding this AD. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2005-21469; Directorate Identifier 2005-NM-124-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the AD. We will consider all comments received by the closing date and may amend the AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this AD. Using the search function of our docket Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You can review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you can visit <http://dms.dot.gov>.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2005-12-17 Bombardier, Inc. (Formerly de Havilland, Inc.): Amendment 39-14133. Docket No. FAA-2005-21469; Directorate Identifier 2005-NM-124-AD.

Effective Date

(a) This AD becomes effective July 5, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier Model DHC-8-400 series airplanes, certificated in any category; as identified in Bombardier

Alert Service Bulletin A84-26-06, dated May 12, 2005.

Unsafe Condition

(d) This AD was prompted by reports of the electrical connectors for the fire bottles in the forward and aft compartments being cross connected. The FAA is issuing this AD to detect and correct cross connection of the fire extinguisher bottles, which could result in failure of the fire bottles to discharge and consequent inability to extinguish a fire in the affected areas.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective Action

(f) Within 14 days after the effective date of this AD, inspect the electrical connectors of the fire extinguisher bottles for the forward and aft baggage compartments and for the auxiliary power unit and engine nacelles to determine if they are connected correctly; and, before further flight, do the related investigative and corrective actions, as applicable; by doing all of the applicable actions specified in the Accomplishment Instructions of Bombardier Alert Service Bulletin A84-26-06, dated May 12, 2005. Although the service bulletin referenced in this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

Alternative Methods of Compliance (AMOCs)

(g) The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

Related Information

(h) Canadian airworthiness directive CF-2005-14, dated May 16, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(i) You must use Bombardier Alert Service Bulletin A84-26-06, dated May 12, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get copies of the service information, contact Bombardier, Inc., Bombardier Regional Aircraft Division, 123 Garratt Boulevard, Downsview, Ontario M3K 1Y5, Canada. To view the AD docket, go to the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC. To review copies of the service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on June 7, 2005.

Michael J. Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-11792 Filed 6-16-05; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 510

New Animal Drugs; Change of Sponsor's Name

AGENCY: Food and Drug Administration, HHS.

ACTION: Final rule.

SUMMARY: The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect a change of sponsor's name from Rhodia Limited to Rhodia UK Limited.

DATES: This rule is effective June 17, 2005.

FOR FURTHER INFORMATION CONTACT:

David R. Newkirk, Center for Veterinary Medicine (HFV-100), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, 301-827-6967, e-mail: david.newkirk@fda.gov.

SUPPLEMENTARY INFORMATION: Rhodia Limited, P.O. Box 46, St. Andrews Rd., Avonmouth, Bristol BS11 9YF, England, UK, has informed FDA of a change of sponsor's name to Rhodia UK Limited. Accordingly, the agency is amending the regulations in 21 CFR 510.600(c) to reflect the change.

This rule does not meet the definition of "rule" in 5 U.S.C. 804(3)(A) because it is a rule of "particular applicability." Therefore, it is not subject to the congressional review requirements in 5 U.S.C. 801-808.

List of Subjects in 21 CFR Part 510

Administrative practice and procedure, Animal drugs, Labeling, Reporting and recordkeeping requirements.

■ Therefore, under the Federal Food, Drug, and Cosmetic Act and under authority delegated to the Commissioner of Food and Drugs and redelegated to the Center for Veterinary Medicine, 21 CFR part 510 is amended as follows:

PART 510—NEW ANIMAL DRUGS

■ 1. The authority citation for 21 CFR part 510 continues to read as follows:

Authority: 21 U.S.C. 321, 331, 351, 352, 353, 360b, 371, 379e.

§510.600 [Amended]

■ 2. Section 510.600 is amended in the table in paragraph (c)(1) in the entry for "Rhodia Limited" by removing "Rhodia Limited" and by adding in its place "Rhodia UK Limited", and in the table in paragraph (c)(2) in the entry for "059258" by removing "Rhodia Limited" and by adding in its place "Rhodia UK Limited".

Dated: June 8, 2005.

Steven D. Vaughn,

Director, Office of New Animal Drug Evaluation, Center for Veterinary Medicine.

[FR Doc. 05-11928 Filed 6-16-05; 8:45 am]

BILLING CODE 4160-01-S

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 300

[FRL-7924-5]

National Oil and Hazardous Substances Pollution Contingency Plan National Priorities List

AGENCY: Environmental Protection Agency.

ACTION: Direct final notice of deletion of Metropolitan Mirror and Glass (MM&G) Superfund Site from the National Priorities List.

SUMMARY: The Environmental Protection Agency (EPA) Region 3 is publishing a direct final notice of deletion of the MM&G, Superfund Site (Site), located in Frackville, Schuylkill County, Commonwealth of Pennsylvania, from the National Priorities List (NPL).

The NPL, promulgated pursuant to section 105 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) of 1980, as amended, is appendix B of 40 CFR part 300, which is the National Oil and Hazardous Substances Pollution Contingency Plan (NCP). This direct final deletion is being published by EPA with concurrence of the Commonwealth of Pennsylvania, through the Pennsylvania Department of Environmental Protection (PADEP), because EPA has determined that all appropriate response actions under CERCLA have been completed and, therefore, further remedial action pursuant to CERCLA is not appropriate.

DATES: This direct final deletion will be effective August 16, 2005 unless EPA receives adverse comments by July 18, 2005. If adverse comments are received, EPA will publish a timely withdrawal of the direct final deletion in the **Federal**