

circuit as of the effective date of this AD: Within 3 days or 20 flight hours after performing any maintenance that would normally require bleeding of the blue hydraulic circuit (as instructed by the related AMM procedure), bleed the blue hydraulic circuit by accomplishing all the actions specified in Airbus AOT A320-29A1112, Revision 01, dated April 8, 2004.

#### Replacement of AGCM and Reducer

(h) Within 35 months after the effective date of this AD, replace the AGCM with a modified and reidentified AGCM; and replace the reducer with a new reducer if applicable; in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320-29-1111, dated June 29, 2004. Replacing the AGCM, and the reducer if applicable, ends the actions required by paragraphs (f) and (g) of this AD.

**Note 1:** Airbus Service Bulletin A320-29-1111 refers to Hamilton Sundstrand Service Bulletin ERPS13GCM-29-5, dated June 29, 2004, as an additional source of service information for modifying and reidentifying the AGCM.

#### Alternative Methods of Compliance (AMOCs)

(i) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

#### Related Information

(j) French airworthiness directive F-2004-150, dated September 1, 2004, also addresses the subject of this AD.

#### Material Incorporated by Reference

(k) You must use All Operators Telex (Airbus) A320-29A1112, Revision 01, dated April 8, 2004; and Airbus Service Bulletin A320-29-1111, dated June 29, 2004; as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approves the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. To get copies of the service information, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France. To view the AD docket, go to the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL-401, Nassif Building, Washington, DC. To review copies of the service information, go to the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 8, 2005.

#### Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-14087 Filed 7-20-05; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2005-21598; Directorate Identifier 2005-NM-121-AD; Amendment 39-14159; AD 2005-13-22]

RIN 2120-AA64

#### Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 Airplanes, and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting a typographical error in an existing airworthiness directive (AD) that was published in the *Federal Register* on June 22, 2005 (70 FR 36011). The error resulted in an incomplete listing of the affected airplanes. This AD applies to all EMBRAER Model EMB-135 airplanes, and all Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. This AD requires repetitive inspections of the electrical connectors of the electric fuel pumps to detect discrepancies, application of anti-corrosion spray, replacement of all fuel pumps with improved fuel pumps, repetitive inspections after all six fuel pumps are replaced, and applicable corrective actions.

**DATES:** Effective July 7, 2005.

**ADDRESSES:** The AD docket contains the proposed AD, comments, and any final disposition. You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Washington, DC. This docket number is FAA-2005-21598; the directorate identifier for this docket is 2005-NM-121-AD.

**FOR FURTHER INFORMATION CONTACT:** Todd Thompson, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-1175; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** On June 15, 2005, the FAA issued AD 2005-13-22, amendment 39-14159 (70 FR 36011, June 22, 2005), for all EMBRAER Model EMB-135 airplanes, and all Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. The AD requires repetitive inspections of the electrical connectors of the electric fuel pumps to detect discrepancies, application of anti-corrosion spray, replacement of all fuel pumps with improved fuel pumps, repetitive inspections after all six fuel pumps are replaced, and applicable corrective actions.

As published, the AD includes an incomplete applicability. Paragraph (c) of the AD omits Models EMB-145XR, -145MP, and -145EP airplanes, although those three models were included in all other references to the applicability throughout the preamble and regulatory language of the AD.

No other part of the regulatory information has been changed; therefore, the final rule is not republished in the *Federal Register*.

The effective date of this AD remains July 7, 2005.

#### PART 39—[AMENDED]

##### § 39.13 [Corrected]

■ In the *Federal Register* of June 22, 2005, on page 36012, in the 3rd column, paragraph (c) of AD 2005-13-22 is corrected to read as follows:

\* \* \* \* \*

(c) This AD applies to all EMBRAER Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes.

\* \* \* \* \*

Issued in Renton, Washington, on July 11, 2005.

#### Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05-14169 Filed 7-20-05; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2005-21103; Airspace Docket No. 05-AEA-10]

#### Amendment of Class E Airspace; Blairstown, NJ

**AGENCY:** Federal Aviation Administration (FAA) DOT.