

under sections 13(d) and 13(e) of the Exchange Act shall be followed as codified at 17 CFR 240.13d-1 through 240.13e-102 and 240.13k-1.

■ 9. Section 335.801 is amended by revising paragraph (a) to read as follows:

**§ 335.801 Inapplicable SEC regulations; FDIC substituted regulations; additional information.**

(a) *Filing fees.* Filing fees will not be charged relative to any filings or submissions of materials made with the FDIC pursuant to the cross reference to regulations of the SEC issued under sections 10A(m), 12, 13, 14, and 16 of the Securities Exchange Act of 1934 (15 U.S.C. 78), sections 302, 303, 304, 306, 401(b), 404, 406, and 407 of the Sarbanes-Oxley Act of 2002 (15 U.S.C. 7241, 7242, 7243, 7244, 7261, 7262, 7264, and 7265), and this part.

\* \* \* \* \*

■ 10. Section 335.901 is amended by revising the section heading and paragraph (a) as follows:

**§ 335.901 Delegation of authority to act on matters with respect to disclosure laws and regulations.**

(a) Except as provided in paragraph (b) of this section, authority is delegated to the Director, Division of Supervision and Consumer Protection (DSC), and where confirmed in writing by the director, to a deputy director or an associate director, or to the appropriate regional director or deputy regional director or area director, to act on disclosure matters under and pursuant to sections 10A(m), 12, 13, 14(a), 14(c), 14(d), 14(f) and 16 of the Securities Exchange Act of 1934 (15 U.S.C. 78), sections 302, 303, 304, 306, 401(b), 404, 406, and 407 of the Sarbanes-Oxley Act of 2002 (15 U.S.C. 7241, 7242, 7243, 7244, 7261, 7262, 7264, and 7265), and this part.

\* \* \* \* \*

Dated at Washington, DC, this 19th day of July, 2005.

By order of the Board of Directors.  
Federal Deposit Insurance Corporation.

**Robert E. Feldman,**

*Executive Secretary.*

[FR Doc. 05-15107 Filed 8-1-05; 8:45 am]

**BILLING CODE 6714-01-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2005-20111; Directorate Identifier 2004-NM-154-AD; Amendment 39-14207; AD 2005-16-02]

RIN 2120-AA64

#### **Airworthiness Directives; Raytheon Model HS.125 Series 700A Airplanes, Model BAe.125 Series 800A Airplanes, and Model Hawker 800 and Hawker 800XP Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Raytheon Model HS.125 series 700A airplanes, Model BAe.125 series 800A airplanes, and Model Hawker 800 and Hawker 800XP airplanes. This AD requires inspecting to determine the current rating of the circuit breakers of certain cockpit ventilation and avionics cooling system blowers; and replacing the circuit breakers and modifying the blower wiring, as applicable. This AD results from a report indicating that a blower motor seized up and gave off smoke. We are issuing this AD to prevent smoke and fumes in the cockpit in the event that a blower motor seizes and overheats due to excessive current draw.

**DATES:** Effective September 6, 2005.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of September 6, 2005.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:**

Philip Petty, Aerospace Engineer, Electrical Systems Branch, ACE-119W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4139; fax (316) 946-4107.

**SUPPLEMENTARY INFORMATION:**

### Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

### Discussion

The FAA issued a supplemental notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Raytheon Model HS.125 series 700A airplanes, Model BAe.125 series 800A airplanes, and Model Hawker 800 and Hawker 800XP airplanes. That supplemental NPRM was published in the **Federal Register** on May 9, 2005 (70 FR 24341). That supplemental NPRM proposed to require inspecting to determine the current rating of the circuit breakers of certain cockpit ventilation and avionics cooling system blowers; and replacing the circuit breakers and modifying the blower wiring, as applicable.

### Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

### Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

### Costs of Compliance

There are about 350 airplanes of the affected design in the worldwide fleet. This AD will affect about 250 airplanes of U.S. registry. The required inspection will take about 1 work hour per airplane, at an average labor rate of \$65 per work hour. Based on these figures, the estimated cost of this AD on U.S. operators is \$16,250, or \$65 per airplane.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2005-16-02 Raytheon Aircraft Company:** Amendment 39-14207. Docket No.

FAA-2005-20111; Directorate Identifier 2004-NM-154-AD.

### Effective Date

(a) This AD becomes effective September 6, 2005.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to Raytheon Model HS.125 series 700A airplanes, BAe.125 series 800A airplanes, and Model Hawker 800 and Hawker 800XP airplanes; certificated in any category; equipped with Brailsford TBL-2.5 blowers; as identified in Raytheon Service Bulletin SB 24-3272, Revision 1, dated October 2000.

### Unsafe Condition

(d) This AD results from a report indicating that a cockpit ventilation and avionics cooling system blower motor seized up and gave off smoke. We are issuing this AD to prevent smoke and fumes in the cockpit in the event that a blower motor seizes and overheats due to excessive current draw.

### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Inspection and Corrective Actions

(f) Within 600 flight hours or 6 months after the effective date of this AD, whichever occurs first, inspect to determine the current rating of the circuit breakers of certain cockpit ventilation and avionics cooling system blowers; and, before further flight, replace the circuit breakers and modify the blower wiring, as applicable; by doing all the actions in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 24-3272, Revision 1, dated October 2000; except as provided by paragraphs (g) and (h) of this AD.

### Contacting the Manufacturer

(g) Where the service bulletin specifies contacting the manufacturer for information if any difficulties are encountered while accomplishing the service bulletin, this AD requires you to contact the Manager, Wichita Aircraft Certification Office (ACO), FAA.

### No Reporting Requirement

(h) Although the service bulletin referenced in this AD specifies to submit certain information to the manufacturer, this AD does not include this requirement.

### Alternative Methods of Compliance (AMOCs)

(i) The Manager, Wichita ACO, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

### Material Incorporated by Reference

(j) You must use Raytheon Service Bulletin SB 24-3272, Revision 1, dated October 2000, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved

the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Raytheon Aircraft Company, Department 62, P.O. Box 85, Wichita, Kansas 67201-0085, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on July 21, 2005.

**Kevin M. Mullin,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-15011 Filed 8-1-05; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2005-20595; Directorate Identifier 2004-NM-149-AD; Amendment 39-14208; AD 2005-16-03]**

**RIN 2120-AA64**

### Airworthiness Directives; Bombardier Model DHC-7-100, DHC-7-101, DHC-7-102, and DHC-7-103 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Bombardier Model DHC-7-100, DHC-7-101, DHC-7-102, and DHC-7-103 airplanes. This AD requires revising the Airworthiness Limitations section of the Instructions of Continued Airworthiness to include a new, lower life limit for lower wing skins. This AD results from the discovery that, during the manufacture of the lower wing skins, score marks may have been accidentally inscribed around the edge of the lower wing skin doublers. We are issuing this AD to prevent fatigue cracks from developing at the score marks in the lower wing skins, which could result in the structural failure of the wing.

**DATES:** Effective September 6, 2005.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of September 6, 2005.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://>