

## Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per air-plane	Number of U.S.-registered airplanes	Fleet cost
Rivet installation .....	1	\$65	Operator-supplied .....	\$65	108	\$7,020

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

## The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**Empresa Brasileira de Aeronautica S.A. (EMBRAER):** Docket No. FAA-2005-22871; Directorate Identifier 2005-NM-191-AD.

#### Comments Due Date

(a) The FAA must receive comments on this AD action by December 9, 2005.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to EMBRAER Model EMB-120, -120ER, -120FC, -120QC, and -120RT airplanes, certificated in any category; as identified in EMBRAER Service Bulletin 120-53-0080, dated November 30, 2004.

#### Unsafe Condition

(d) This AD results from a report indicating that, during production, a pinhole was left open at the upper frame of the auxiliary power unit (APU) firewall. We are issuing this AD to ensure that the APU compartment is isolated from the rest of the airplane in the event of an APU fire.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

## Rivet Installation

(f) Within 4,000 flight hours or 24 months, whichever occurs first after the effective date of this AD: Install a rivet and washer in the hole of the upper frame of the APU firewall, in accordance with EMBRAER Service Bulletin 120-53-0080, dated November 30, 2004.

## Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

## Related Information

(h) Brazilian airworthiness directive 2005-08-03, dated September 5, 2005, also addresses the subject of this AD.

Issued in Renton, Washington, on October 26, 2005.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-22304 Filed 11-8-05; 8:45 am]

**BILLING CODE 4910-13-U**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2005-22875; Directorate Identifier 2005-NM-179-AD]

RIN 2120-AA64

### Airworthiness Directives; Short Brothers Model SD3-60 SHERPA, SD3-SHERPA, and SD3-60 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to supersede an existing airworthiness

directive (AD) that applies to all Short Brothers Model SD3-60 and SD3-SHERPA airplanes. The existing AD currently requires an inspection of the fork end of the rear pintle pin on each main landing gear (MLG) to verify that sealant is properly applied and is undamaged, and related investigative/corrective actions if necessary. This proposed AD would add an inspection for correctly applied sealant on the MLG rear pintle pin assemblies, and related investigative/corrective actions if necessary. This proposed AD would also expand the applicability of the existing AD. This proposed AD results from a new report of a cracked pintle pin fork end. We are proposing this AD to prevent stress-corrosion cracking and subsequent failure of the MLG.

**DATES:** We must receive comments on this proposed AD by December 9, 2005.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Short Brothers, Airworthiness & Engineering Quality, P.O. Box 241, Airport Road, Belfast BT3 9DZ, Northern Ireland, for service information identified in this proposed AD.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 227-2125; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "Docket No. FAA-2005-22875; Directorate Identifier 2005-NM-179-AD" at the beginning of your comments. We specifically invite comments on the

overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

**Examining the Docket**

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

**Discussion**

On January 25, 1993, we issued AD 93-02-03, amendment 39-8485 (58 FR 7983, February 11, 1993), for all Short Brothers Model SD3-60 and SD3-SHERPA airplanes. That AD requires an inspection of the fork end of the rear pintle pin on each main landing gear (MLG) to verify that sealant is properly applied and is undamaged; removal of the bushings and an inspection to detect faults of the bores in the fork end, if necessary; and repair of the fork end of the pintle pin, if necessary. That AD resulted from a report of a cracked fork end of the MLG rear pintle pin. We issued that AD to prevent stress-corrosion cracking and subsequent failure of the MLG.

**Actions Since Existing AD Was Issued**

Since we issued AD 93-02-03, we have learned about another incident of a cracked pintle pin fork end on a Model SD3 airplane.

**Relevant Service Information**

Shorts has issued Service Bulletins SD360 Sherpa-32-4 (for Model SD3-60 SHERPA airplanes), SD3 Sherpa-32-5 (for Model SD3-SHERPA airplanes), and SD360-32-37 (for Model SD3-60 airplanes), all dated July 2004. The service bulletins describe procedures for an inspection to determine whether sealant has been properly applied on the MLG rear pintle pin assemblies, and related investigative/corrective actions for missing or damaged sealant. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition. The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, mandated the service information and issued British airworthiness directive G-2004-0022, dated August 25, 2004, to ensure the continued airworthiness of these airplanes in the United Kingdom.

The service bulletins refer to Messier Dowty Service Bulletin 32-70SD, Revision 1, dated July 3, 1995, as an additional source of service information for the inspection and related investigative/corrective actions.

**FAA's Determination and Requirements of the Proposed AD**

These airplane models are manufactured in the United Kingdom and are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. We have examined the CAA's findings, evaluated all pertinent information, and determined that AD action is necessary for airplanes of this type design that are certificated for operation in the United States.

This proposed AD would supersede AD 93-02-03 and would retain the requirements of the existing AD. This proposed AD would also expand the applicability for the actions specified in service information described previously, except as discussed below.

**Difference Between the Proposed AD and Service Information**

The service information specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions using a method that we or the CAA (or its delegated agent) approve. In light of the type of repair that would be required to address the unsafe condition, and

consistent with existing bilateral airworthiness agreements, we have determined that, for this proposed AD, a repair we or the CAA approve would be acceptable for compliance with this proposed AD.

### Clarification of Inspection Terminology

In this proposed AD, the inspection specified in the service bulletins is referred to as a "general visual inspection." Note 1 in this proposed AD defines this type of inspection.

### Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this proposed AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per air-plane	Number of U.S.-registered airplanes	Fleet cost
Inspection (required by AD 93-02-03) ....	1	\$65	None	\$65	42	\$2,730
Inspection (new proposed action) .....	1	65	None	65	42	2,730

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section

for a location to examine the regulatory evaluation.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-8485 (58 FR 7983, February 11, 1993) and adding the following new airworthiness directive (AD):

**Short Brothers PLC:** Docket No. FAA-2005-22875; Directorate Identifier 2005-NM-179-AD.

#### Comments Due Date

(a) The FAA must receive comments on this AD action by December 9, 2005.

#### Affected ADs

(b) This AD supersedes AD 93-02-03.

#### Applicability

(c) This AD applies to all Shorts Model SD3-60 SHERPA, SD3-SHERPA, and SD3-60 airplanes, certificated in any category.

#### Unsafe Condition

(d) This AD results from a new report of a cracked pintle pin fork end. We are issuing this AD to prevent stress-corrosion cracking and subsequent failure of the main landing gear (MLG).

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Restatement of Requirements of AD 93-02-03

#### Inspection

(f) For Model SD3-60 and SD3-SHERPA airplanes: Within 300 hours' time-in-service or 30 days after March 18, 1993 (the effective date of AD 93-02-03), whichever occurs first, perform a visual inspection of the fork end of the rear pintle pin on each MLG to verify that an undamaged fillet of sealant is properly applied around the flanges of the bronze bushings, in accordance with Shorts SD3-60 Service Bulletin SD360-32-33, dated August 7, 1992.

(1) If an undamaged fillet of properly applied sealant is found: No further action is required by this AD.

(2) If no fillet of sealant is found at the joint line, or if a damaged fillet of sealant is found: Prior to the accumulation of 1,200 hours' time-in-service or 120 days after accomplishing the inspection required by paragraph (f) of this AD, whichever occurs first, remove the bushings and perform a magnetic non-destructive testing (NDT) inspection to detect faults of the bores in the fork end, in accordance with the service bulletin. If faults are found as a result of the NDT inspection, prior to further flight, repair the fork end of the rear pintle pin in a manner approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA.

### New Requirements of This AD

#### Inspection

(g) For all airplanes: Within 3 months after the effective date of this AD, do a general visual inspection of the MLG rear pintle pin assemblies for correctly applied sealant, in accordance with Shorts Service Bulletin SD360-32-37, SD3 SHERPA-32-5, or SD360 SHERPA 32-4, all dated July 2004, as applicable.

(1) If the sealant is applied correctly: This AD requires no further work.

(2) If the sealant is applied incorrectly: Within 12 months after the effective date of this AD, do a magnetic flaw detection inspection to detect cracks of the rear pintle pin fork ends, in accordance with the service bulletin. If any cracked pintle pin fork end is found: Replace it before further flight with a serviceable part that has been inspected in accordance with the requirements of this AD.

**Note 1:** For the purposes of this AD, a general visual inspection is: "A visual

examination of an interior or exterior area, installation, or assembly to detect obvious damage, failure, or irregularity. This level of inspection is made from within touching distance unless otherwise specified. A mirror may be necessary to ensure visual access to all surfaces in the inspection area. This level of inspection is made under normally available lighting conditions such as daylight, hangar lighting, flashlight, or droplight and may require removal or opening of access panels or doors. Stands, ladders, or platforms may be required to gain proximity to the area being checked.”

**Note 2:** The service bulletins identified in paragraph (g) of this AD refer to Messier Dowty Service Bulletin 32-70SD, Revision 1, dated July 3, 1995, as an additional source of service information for the inspection and corrective actions.

(h) If any crack is detected during any inspection required by this AD and the service information specifies to contact the manufacturer for repair instructions: Before further flight, repair using a method approved by either the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the Civil Aviation Authority (CAA) (or its delegated agent).

#### *Alternative Methods of Compliance (AMOCs)*

(i)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

#### *Related Information*

(j) British airworthiness directive G-2004-0022, dated August 25, 2004, also addresses the subject of this AD.

Issued in Renton, Washington, on October 28, 2005.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 05-22305 Filed 11-8-05; 8:45 am]

**BILLING CODE 4910-13-P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

[Docket No. FAA-2005-22874; Directorate Identifier 2005-NM-173-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Boeing Model 777-200 and -300 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 777-200 and -300 series airplanes. This proposed AD would require inspecting the lower web of the aft fairing of engine struts for any discoloration and doing any related investigative and corrective action if necessary; inspecting the heat shield castings for any damage and doing any corrective action if necessary; installing gap cover strips; and replacing insulation blankets with new insulation blankets. This proposed AD results from a report that several discolored fairing lower webs and some damaged/deteriorated insulation blankets were found in the aft fairings of engine struts. We are proposing this AD to prevent cracking of lower webs of the aft fairings, which could result in flammable hydraulic fluid leaking onto or near an ignition source, and possibly result in an uncontrollable fire in the engine strut area.

**DATES:** We must receive comments on this proposed AD by December 27, 2005.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
  - Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.
  - Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.
  - Fax: (202) 493-2251.
  - Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

**FOR FURTHER INFORMATION CONTACT:** John Vann, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6513; fax (425) 917-6590.

#### **SUPPLEMENTARY INFORMATION:**

##### **Comments Invited**

We invite you to submit any relevant written data, views, or arguments

regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number “FAA-2005-22874; Directorate Identifier 2005-NM-173-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT’s complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

#### **Examining the Docket**

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

#### **Discussion**

We have received a report indicating that damaged/deteriorated thermal insulation blankets and discolored fairing lower webs were found in the aft fairings of engine struts on several Model 777-200 and -300 series airplanes. Gaps in the segmented heat shield in the strut aft fairings allow engine primary/main exhaust to enter the heat shield cavity in the strut aft fairing. The temperature of the exhaust that leaks into the heat shield cavity exceeds the insulation blankets’ maximum design tolerance. Since the insulation blankets provide thermal protection for the aluminum fairing lower web, degradation of an insulation blanket allows thermal distress of the lower web and eventually, cracking of the lower web. A cracked lower web is