

airplanes; and Model A340–211, –212, –213, –311, –312, and –313 airplanes; certificated in any category.

Unsafe Condition

(d) This AD results from reports of elevator servo control failures due to broken guides. We are issuing this AD to ensure proper functioning of the elevator servo controls. Failure of the elevator servo controls during certain phases of takeoff could result in an unannounced loss of elevator control and consequent reduced controllability of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Service Information

(f) The term "AOT," as used in this AD, means section 4.2. "Description" of the following service information, as applicable:

(1) For Model A330–200 and –300 series airplanes: Airbus All Operators Telex A330–27A3138, Revision 01, dated October 3, 2005; and

(2) For Model A340–200 and –300 series airplanes: Airbus All Operators Telex A340–27A4137, Revision 01, dated October 3, 2005.

Initial and Repetitive Elevator Servo-Loop Tests

(g) Within 200 flight hours after the effective date of this AD: Test the elevator servo-loops, in accordance with the AOT. If the test of the elevator servo-loops passes, repeat the test at intervals not to exceed 140 flight hours or 8 days, whichever occurs first.

Failed Tests

(h) If any test of the elevator servo-loops required by paragraph (g) of this AD fails: Before further flight, troubleshoot the cause of the test failure, and do the applicable corrective actions; in accordance with the AOT. Thereafter, repeat the test at the times specified in paragraph (g) of this AD.

Reporting Requirement

(i) Following each test required by paragraph (g) of this AD, submit a report of the findings of only failed elevator servo-loop tests to Airbus Customer Services, Engineering and Technical Support, Attention: Mr. J. Laurent, SEE53, fax +33/(0)5.61.93.44.25; at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD. The report must include the description of the failure experienced during the test, the identified cause of the failure, and the number of flight hours and flight cycles on the airplane. Under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120–0056.

(1) If the test was done after the effective date of this AD: Submit the report within 10 days after the test.

(2) If the test was done prior to the effective date of this AD: Submit the report within 10 days after the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(k) French airworthiness directive UF–2005–171, dated October 3, 2005, also addresses the subject of this AD.

Material Incorporated by Reference

(l) You must use Airbus All Operators Telex A330–27A3138, Revision 01, dated October 3, 2005; or Airbus All Operators Telex A340–27A4137, Revision 01, dated October 3, 2005; as applicable, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL–401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on October 31, 2005.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05–22213 Filed 11–10–05; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2005–22120; Directorate Identifier 2004–NM–92–AD; Amendment 39–14360; AD 2005–23–02]

RIN 2120–AA64

Airworthiness Directives; Airbus Model A319–100 Series Airplanes, Model A320–111 Airplanes, Model A320–200 Series Airplanes, and Model A321–100 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A319–100 series airplanes, Model A320–111 airplanes, Model A320–200 series airplanes, and Model A321–100 series airplanes equipped with any additional center tank (ACT). This AD requires identifying the part number of the ACT and, for certain ACTs, replacing the outer ACT manhole cover and seal. This AD results from reports of an ACT fuel transfer failure due to air leakage around the seal of the outer manhole covers of the ACTs. We are issuing this AD to prevent this leakage, which could result in fuel or fuel vapor leaking into the cargo compartment, and consequent increased risk of a fire in the cargo compartment.

DATES: This AD becomes effective December 19, 2005.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of December 19, 2005.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL–401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Tim Dulin, Aerospace Engineer, International Branch, ANM–116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055–4056; telephone (425) 227–2141; fax (425) 227–1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647–5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Airbus Model A319–100 series airplanes, Model A320–111 airplanes, Model A320–200 series

airplanes, and Model A321-100 series airplanes equipped with certain additional center tanks (ACT). That NPRM was published in the **Federal Register** on August 17, 2005 (70 FR 48336). That NPRM proposed to require identifying the part number (P/N) of the ACT and, for certain ACTs, replacing the outer ACT manhole cover and seal.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the single comment received. The commenter supports the NPRM.

Additional Service Bulletin Information

After the NPRM was issued Airbus released Revision 02 of service bulletin A321-28-1105, dated March 11, 2005. We have reviewed it, and it is substantially similar to Revision 01, which was referred to in the NPRM as the acceptable source of service information. We have revised paragraph (g) of this AD to refer to Revision 02 of the service bulletin as the acceptable source of service information, and to give credit for doing Revision 01 before the effective date of this AD.

Clarification of Alternative Method of Compliance (AMOC) Paragraph

We have revised this action to clarify the appropriate procedure for notifying

the principal inspector before using any approved AMOC on any airplane to which the AMOC applies.

Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD with the change described previously. We have determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average hourly labor rate	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
P/N identification	1	\$65	\$0	\$65	28	\$1,820

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866;

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2005-23-02 Airbus: Amendment 39-14360. Docket No. FAA-2005-22120; Directorate Identifier 2004-NM-92-AD.

Effective Date

(a) This AD becomes effective December 19, 2005.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Airbus Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes; Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, and -131 airplanes; certificated in any category; which are equipped with any additional center tank (ACT).

Unsafe Condition

(d) This AD was prompted by reports of an ACT fuel transfer failure due to air leakage around the seal of the outer manhole covers of the ACTs. We are requiring this AD to prevent this leakage, which could result in fuel or fuel vapor leaking into the cargo compartment, and consequent increased risk of a fire in the cargo compartment.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Part Number Identification

(f) Within 30 days (for Model A319-111, -112, -113, -114, -115, -131, -132, and -133 airplanes) or 12 months (for Model A320-111, -211, -212, -214, -231, -232, and -233 airplanes; and Model A321-111, -112, and -131 airplanes) after the effective date of this AD: Determine whether the part number (P/N) of each ACT installed on the airplane is included in Table 1 of this AD. If no ACT installed on the airplane has a P/N included

in Table 1 of this AD, no further work is required by this paragraph.

TABLE 1.—AFFECTED ACT P/Ns

D2827091100000
D2827091100200
D2827091100600
D2827091300000
D2827091300200
D2827091300400
D2827105100000
D2827105100200
D2827105100400
D2827105200000
D2827105200200
D2827105200400
D2827105300000
D2827105300200
D2827105300400
D2827105400000
D2827105400200
D2827105400400
D2827105400600
D2827105400800
D2827105500000
D2827105500200
D2827105500400
D2827105600000
D2827105600200
D2827105600400
D2827107500000
D2827107500200

Manhole Cover/Seal Replacement

(g) Within 30 days (for Model A319–111, –112, –113, –114, –115, –131, –132, and –133 airplanes) or 12 months (for Model A320–111, –211, –212, –214, –231, –232, and –233 airplanes; and Model A321–111, –112, and –131 airplanes) after the effective date of this AD: For each ACT P/N listed in Table 1 of this AD: Before further flight, replace the outer ACT manhole cover with a reinforced manhole cover and replace the outer manhole cover seal with a new seal, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A320–28–1105, Revision 02, dated March 11, 2005. Replacements are also acceptable if done before the effective date of this AD in accordance with Airbus Service Bulletin A320–28–1105, Revision 01, dated March 18, 2003; and Airbus Service Bulletin A320–28–1105, dated October 22, 2002.

Parts Installation

(h) As of the effective date of this AD, no person may install an ACT having any P/N listed in Table 1 of this AD, unless the actions required by paragraph (g) of this AD have been done for that ACT.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(j) French airworthiness directive F–2004–038, dated March 17, 2004, also addresses the subject of this AD.

Material Incorporated by Reference

(k) You must use Airbus Service Bulletin A320–28–1105, Revision 02, dated March 11, 2005, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., room PL–401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741–6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington on October 26, 2005.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 05–22219 Filed 11–10–05; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2005–22169; Directorate Identifier 2005–NM–094–AD; Amendment 39–14361; AD 2005–23–03]

RIN 2120–AA64

Airworthiness Directives; Learjet Model 23, 24, 24A, 24B, 24B–A, 24C, 24D, 24D–A, 24E, 24F, 24F–A, 25, 25A, 25B, 25C, 25D, and 25F Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Learjet Model 23, 24, 24A, 24B, 24B–A, 24C, 24D, 24D–A, 24E, 24F, 24F–A, 25, 25A, 25B, 25C, 25D, and 25F airplanes. This AD requires replacement of the spherical accumulator for the main hydraulic system with a new cylindrical accumulator. For certain airplanes, this AD also requires modification of the accumulator pressure gauge. This AD results from reports of the failure of two thrust reverser accumulators (which are similar to the main hydraulic system's

spherical accumulator) and fatigue cracks found on four thrust reverser accumulators. We are issuing this AD to prevent failure of the spherical accumulator for the main hydraulic system, due to fatigue cracking on the threads, which could result in the loss of hydraulic power, damage to the surrounding airplane structure, and loss of airplane control. The failure of the accumulator could also result in injury to any persons in the surrounding area. The loss of hydraulic fluid could also leak onto a potential source of ignition and result in a consequent fire.

DATES: This AD becomes effective December 19, 2005.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of December 19, 2005.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, room PL–401, Washington, DC.

Contact Learjet, Inc., One Learjet Way, Wichita, Kansas 67209–2942, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT:

Robert Busto, Aerospace Engineer, Systems and Propulsion Branch, ACE–116W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946–4157; fax (316) 946–4107.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647–5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Learjet Model 23, 24, 24A, 24B, 24B–A, 24C, 24D, 24D–A, 24E, 24F, 24F–A, 25, 25A, 25B, 25C, 25D, and 25F airplanes. That NPRM was published in the **Federal Register** on August 23, 2005 (70 FR 49210). That NPRM proposed to require replacement of the spherical accumulator for the main hydraulic system with a new cylindrical accumulator. For certain