

17. Should part 715 require credit unions that obtain a financial statement audit and/or an "attestation on internal controls" (whether as required or voluntarily) to forward a copy of the auditor's report to NCUA? If so, how soon after the audit period-end? If not, why not?

18. Should part 715 require credit unions to provide NCUA with a copy of any management letter, qualification, or other report issued by its external auditor in connection with services provided to the credit union? If so, how soon after the credit union receives it? If not, why not?

19. If credit unions were required to forward external auditors' reports to NCUA, should part 715 require the auditor to review those reports with the Supervisory Committee before forwarding them to NCUA?

20. Existing part 715 requires a credit union's engagement letter to prescribe a target date of 120 days after the audit period-end for delivery of the audit report. Should this period be extended or shortened? What sanctions should be imposed against a credit union that fails to include the target delivery date within its engagement letter?

21. Should part 715 require credit unions to notify NCUA in writing when they enter into an engagement with an auditor, and/or when an engagement ceases by reason of the auditor's dismissal or resignation? If so in cases of dismissal or resignation, should the credit union be required to include reasons for the dismissal or resignation?

22. NCUA recently joined in the final *Interagency Advisory on the Unsafe and Unsound Use of Limitation of Liability Provisions in External Audit Engagement Letters*, 71 FR 6847 (Feb. 9, 2006). Should credit union Supervisory Committees be prohibited by regulation from executing engagement letters that contain language limiting various forms of auditor liability to the credit union? Should Supervisory Committees be prohibited from waiving the auditor's punitive damages liability?

By the National Credit Union Administration Board on February 16, 2006.

Mary F. Rupp,

Secretary of the Board.

[FR Doc. E6-2531 Filed 2-22-06; 8:45 am]

BILLING CODE 7535-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-23704; Directorate Identifier 2006-NE-02-AD]

RIN 2120-AA64

Airworthiness Directives; Honeywell International Inc. TPE331 Series Turboprop, and TSE331-3U Model Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Honeywell International Inc. TPE331 series turboprop, and TSE331-3U model turboshaft engines. This proposed AD would require implementing a new flight cycle counting method for first, second, and third-stage turbine rotors used in aircraft that make multiple takeoffs and landings without an engine shutdown, and removing turbine rotors from service that have reached or exceeded their cycle life limits. This new flight cycle counting method would require determining total equivalent cycles accrued. This proposed AD results from several reports of uncontained turbine rotor separation on engines used in special-use operations. We are proposing this AD to prevent uncontained failure of the turbine rotor due to low-cycle-fatigue (LCF), and damage to the aircraft.

DATES: We must receive any comments on this proposed AD by April 24, 2006.

ADDRESSES: Use one of the following addresses to comment on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You can get the service information identified in this proposed AD from Honeywell Engines, Systems & Services, Technical Data Distribution, M/S 2101-201, P.O. Box 52170, Phoenix, AZ 85072-2170; telephone: (602) 365-2493 (General Aviation); (602) 365-5535 (Commercial); fax: (602) 365-5577 (General Aviation and Commercial).

You may examine the comments on this proposed AD in the AD docket on the Internet at <http://dms.dot.gov>.

FOR FURTHER INFORMATION CONTACT:

Joseph Costa, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712-4137; telephone (562) 627-5246; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send us any written relevant data, views, or arguments regarding this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2006-23704; Directorate Identifier 2006-NE-02-AD" in the subject line of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of the DOT Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78) or you may visit <http://dms.dot.gov>.

Examining the AD Docket

You may examine the docket that contains the proposal, any comments received and, any final disposition in person at the DOT Docket Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5227) is located on the plaza level of the Department of Transportation Nassif Building at the street address stated in

ADDRESSES. Comments will be available in the AD docket shortly after the Docket Management Facility receives them.

Discussion

We received several reports of turbine rotor separations on Honeywell International Inc. TPE331 turboprop series engines, resulting in metal fragments either penetrating the engine case or exiting the tail pipe. These engines were in special-use operations that typically include minor cycles (aircraft that make multiple takeoffs and landings without an engine shutdown).

We found that as minor cycles on these engines accumulate, so does LCF damage to the turbine rotors, just like LCF damage does from a major cycle (engine start, takeoff, landing, shutdown). Further, the manufacturer's major life cycle calculations do not address special-use operations (aircraft that make multiple takeoffs and landings without an engine shutdown). Special-use operations typically include agricultural, skydiving, and certain cargo flight operations, where the number of minor cycles generally ranges between five and twenty takeoffs-and-landings (to ground idle) per major cycle.

This proposed AD is related to the recent FAA safety evaluation on Mitsubishi MU-2B series airplanes. This condition, if not corrected, could result in LCF damage to the turbine rotors, resulting in uncontained turbine rotor failure and damage to the aircraft.

Relevant Service Information

We have reviewed the technical contents of Honeywell International Inc. Alert Service Bulletins (ASBs) No. TPE331-A72-2111, dated November 12, 2002; No. TPE331-A72-2123, dated February 8, 2006; No. TPE331-A72-2130, dated September 27, 2005; and TPE331-A-72-2131, dated September 27, 2005, that describe procedures for determining total equivalent cycles (major cycles plus minor cycles) for first, second, and third-stage turbine rotors used in special-use operations

and procedures for removing over-limit turbine rotors from service.

We have also reviewed and approved the technical contents of Honeywell International Inc. Service Bulletins (SBs) No. TPE331-72-0019, Revision 22, dated May 16, 2001; SB No. TPE331-72-0180, Revision 31, dated November 7, 2003; and SB No. TP331-72-0476, Revision 27, dated September 17, 2003, and AlliedSignal Inc. SB No. TP331-72-0117, Revision 11, dated November 13, 1997, that describe procedures for recording total equivalent cycles.

Differences Between the Proposed AD and the Manufacturer's Service Information

The proposed AD would allow special-use operators to remove over-limit turbine rotors either according to Table 1 of the removal schedule in the applicable ASBs, or within nine months after the effective date of the proposed AD, whichever occurs later. This would allow high-utilization agricultural operators more time to comply with the proposed AD within their spraying season.

Also, the compliance time stated in compliance paragraph 1.D. of the applicable Honeywell ASBs is different from the proposed AD. Also, although the Honeywell and AlliedSignal ASBs and SBs address only the TPE331 series, and TSE331-3U model engines in service, the applicability of the proposed AD includes all certified TPE331-1 through -12 series engines and TSE331-3U model engines. Also, the proposed AD provides actions for used rotors installed on or after the effective date of this AD.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other products of this same type design. We are proposing this AD, which would require:

- Determining and recording the total equivalent cycles for turbine rotors

currently installed in engines that were or are in special-use operations; and

- Removing from service, turbine rotors that were or are in special-use operations that have reached or exceeded their cycle life limits; and
- Using the new flight cycle counting method that counts major and minor cycles as accrued for all new turbine rotors.

The proposed AD would require you to use the service information described previously to perform these actions.

Costs of Compliance

We estimate that this proposed AD would affect 200 TPE331 series turboprop, and TSE331-3U model turboshaft engines installed on airplanes and helicopters of U.S. registry. We also estimate that it would take about two work hours per engine to perform the proposed total equivalent cycles determination and recording. We also estimate that to perform a proposed turbine engine removal it would take 40 work hours per engine when done at an unscheduled turbine section inspection, and one work hour per engine when done at a scheduled engine turbine section inspection. We estimate the average labor rate to be \$65 per work hour. Required parts would cost about \$20,000 per engine. The costs associated with this proposed AD are dependent on the engine mission cycle. Operators accruing many minor and major cycles might replace first and second stage turbine rotors every two years. For the purpose of this proposed AD, we estimate the costs for an eight-year period with moderate usage to be 10 minor cycles each flight and 200 flights each year, and the effective use of the first and second turbine rotors to be equivalent to 2,600 cycles. Based on these figures, we estimate the total cost to U.S. operators to be \$9,350,630.

This is one of several actions that FAA is evaluating for unsafe conditions on the MU-2B airplanes. We estimate that 10 percent of the affected engines are used on MU-2B airplanes. To date, we have proposed the following actions:

Docket	Unsafe condition	Date NPRM published	Cost impact
FAA-2006-23578	Wing attach barrel nuts, bolts, and retainers for cracks, corrosion, and fractures.	January 25, 2006 (71 FR 4072).	\$65 per airplane for the inspection and \$1,195 per airplane if all 8 barrel nuts needed replacement. Total airplane cost is \$1,260 per airplane. If all 397 airplanes needed all 8 barrel nuts replaced, the total cost on U.S. operators for this proposed action would be \$500,220.
FAA-2006-23644	An asymmetric thrust situation in certain flight conditions, which could result in airplane controllability problems.	February 9, 2006 (71 FR 6685).	\$390 per airplane to change the blade angle. The total cost to U.S. operators for this proposed action would be \$57,720.

Total proposed cost impact to date (including this NPRM) for the affected airplanes is \$47,113 per airplane. This does not account for the following:

- The cost of any repairs or replacements based upon the results of inspections by the proposed actions; and
- The loss of revenue due to the airplane being down for work associated with any proposed AD action.

The total cost to date on all U.S. operators (including this NPRM) would be \$18,703,940. This is based on the presumption that 10 airplanes would need the actions performed as specified by Docket No. FAA-2006-23704.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Under the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Honeywell International Inc. (formerly AlliedSignal Inc., Garrett Engine Division; Garrett Turbine Engine Company; and AiResearch Manufacturing Company of Arizona): Docket No. FAA-2006-23704; Directorate Identifier 2006-NE-02-AD.

Comments Due Date

(a) The Federal Aviation Administration (FAA) must receive comments on this airworthiness directive (AD) action by April 24, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Honeywell International Inc. TPE331-1, -1U, -1UA, -2, -2UA, -3U, -3UW, -3W, -5, -5A, -5AB, -5B, -5U, -6, -6A, -6U, -8, -8A, -9, -9U, -10, -10A, -10AV, -10B, -10G, -10GP, -10GR, -10GT, -10J, -10N, -10P, -10R, -10T, -10U, -10UA, -10UF, -10UG, -10UGR, -10UJ, -10UK, -10UR, -11U, -11UA, -12, -12B, -12JR, -12UA, -12UAR, -12UER, and -12UHR series turboprop and TSE331-3U model turboshaft engines. These engines are installed on, but not limited to, the following aircraft:

Manufacturer	Airplane model
AERO PLANES, LLC (formerly McKinnon Enterprises)	G-21G.
ALLIED AG CAT PRODUCTIONS (formerly Schweizer)	G-164 SERIES.
AYRES	S-2R SERIES.
BRITISH AEROSPACE LTD (formerly Jetstream)	3201 SERIES, AND HP.137 JETSTREAM MK.1.
CESSNA AIRCRAFT COMPANY	441 CONQUEST.
CONSTRUCCIONES AERONAUTICAS, S.A. (CASA)	C-212 SERIES.
DEHAVILLAND	DH104 SERIES 7AXC (DOVE).
DORNIER	228 SERIES.
FAIRCHILD	SA226 AND SA227 SERIES (SWEARINGEN MERLIN AND METRO SERIES).
GRUMMAN AMERICAN	G-164 SERIES.
MITSUBISHI	MU-2B SERIES (MU-2 SERIES).
PILATUS	PC-6 SERIES (FAIRCHILD PORTER AND PEACEMAKER).
POLSKIE ZAKLADY LOTNICZE SPOLKA (formerly Wytownia Sprzetu Komunikacyjnego).	PZL M18, PZL M18A, PZL M18B.
PROP-JETS, INC.	400.
RAYTHEON AIRCRAFT (formerly Beech)	C45G, TC-45G, C-45H, TC-45H, Tc-45J, G18S, E18S-9700, D18S, D18C, H18, RC-45J, JRB-6, UC-45J, 3N, 3NM, 3TM, B100, C90 AND E90.
SHORTS BROTHERS AND HARLAND, LTD	SC7 (SKYVAN) SERIES.
THRUSH (ROCKWELL COMMANDER)	S-2R.
TWIN COMMANDER (JETPROP COMMANDER)	680 AND 690 SERIES.

Manufacturer	Helicopter model
SIKORSKY	S-55 SERIES (HELITEC CORP. S55T).

Unsafe Condition

(d) This AD results from several reports of uncontained turbine rotor separation on engines used in special-use operations. We are issuing this AD to prevent uncontained failure of the turbine rotor due to low-cycle-fatigue (LCF), and damage to the aircraft.

Compliance

(e) You are responsible for having the actions required by this AD performed

within the compliance times specified unless the actions have already been done.

Used Turbine Rotors Installed Before the Effective Date of This AD

(f) For used turbine rotors installed before the effective date of this AD, and currently or previously used in special-use operations:

(1) Within 100 major cycles-in-service after the effective date of this AD, or

upon removal of the turbine rotor(s) from the engine, whichever occurs first, do the following:

(i) Determine the total equivalent cycles accrued for turbine rotors. Use paragraph 2.A. of the Accomplishment Instructions of the applicable Honeywell Alert Service Bulletin (ASB) for your model engines listed in the following Table A., to make the determination.

TABLE A.—HONEYWELL ASBs FOR DETERMINING TOTAL EQUIVALENT CYCLES

For engines	Use ASB No.	Turbine rotor removal schedule
(A) TPE331-1 through -6 series and TSE331-3U model	TPE331-A72-2111, dated November 12, 2002	Use ASB Table 1.
(B) TPE331-8 through -9 series	TPE331-A72-2123, dated February 8, 2006	Use ASB Table 1.
(C) TPE331-10 through -11 series	TPE331-A72-2130, dated September 27, 2005	Use ASB Table 1.
(D) TPE331-12 series	TPE331-A72-2131, dated September 27, 2005	Use ASB Table 1.

(ii) If you are unable to determine equivalent cycles for prior special-use operations, you must use a takeoff-to-engine shutdown ratio of six to estimate

prior special-use equivalent cycles for turbine rotors.

(iii) For each turbine rotor affected on the Life Limited Part Log Card, record the total equivalent cycles accrued, as

determined in paragraphs (f)(1)(i) and (f)(1)(ii) of this AD, by complying with the recording requirements for your model engine listed in the following Table B.:

TABLE B.—SBs FOR RECORDING TOTAL EQUIVALENT CYCLES

For engines	Record using
(A) TPE331-1 through -6 series and TSE331-3U model	Honeywell SB No. TPE331-72-0019, Revision 22, dated May 16, 2001.
(B) TPE331-8 through -9 series	AlliedSignal SB No. TPE331-72-0117, Revision 11, dated November 13, 1997.
(C) TPE331-10 through -11 series	Honeywell SB No. TPE331-72-0180, Revision 31, dated November 7, 2003.
(D) TPE331-12 series	Honeywell SB No. TPE331-72-0476, Revision 27, dated September 17, 2003.

(2) Remove from service turbine rotors affected by paragraph (f) of this AD using the applicable Turbine Rotor Removal Schedule in Table A of this AD, or, within nine months after the effective date of this AD, whichever occurs later.

Used Turbine Rotors Installed On or After the Effective Date of This AD

(g) For used turbine rotors installed on or after the effective date of this AD, and currently or previously used in special-use operations:

(1) Before further flight, determine and record total equivalent cycles using paragraphs (f)(1)(i) through (f)(1)(iii) of this AD.

(2) Remove from service, turbine rotors affected by paragraph (g) of this

AD using the applicable Turbine Rotor Removal Schedule in Table A of this AD.

New (Zero Cycles) Turbine Rotors Installed On or After the Effective Date of This AD

(h) For all new (zero cycles) turbine rotors installed on or after the effective date of this AD:

(1) Use the new counting method by counting and recording minor and major cycles when accrued, and determine equivalent cycles by the method described in paragraph (f) of this AD.

(2) The use of the ratio of six takeoffs to one engine shutdown per major cycle for unknown cycle history is not permitted.

Definitions

(i) Engines used in special-use operations are engines installed in aircraft that make multiple takeoffs and landings without engine shutdown.

(j) Total equivalent cycles is the combination of major and minor cycles as specified in the Honeywell ASBs listed in Table A of this AD.

(k) Total equivalent cycle life limits listed in the ASBs are the same as the cycle life limits specified in the SBs listed in Table B of this AD.

(l) The recording of total equivalent cycles on the Life Limited Part Log Card is the same procedure specified for “accumulated cycles” or “total cycles” in the SBs listed in Table B of this AD.

(m) Turbine rotors includes first, second, and third stage seal plates, air seals, rotor disks, wheels, and assemblies that have part numbers specified in the ASBs listed in Table A of this AD.

(n) A major cycle is an engine start, takeoff, landing, and shutdown.

(o) A minor cycle is multiple takeoffs and landings without an engine shutdown.

(p) A used turbine rotor is a turbine rotor whose cycles-since-new are more than zero.

Alternative Methods of Compliance

(q) The Manager, Los Angeles Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Related Information

(r) None.

Issued in Burlington, Massachusetts, on February 15, 2006.

Ann C. Mollica,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-2574 Filed 2-22-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Office of the Secretary

14 CFR Part 382

RIN 2105-AD41

[OST Docket No. 2006-23999]

Accommodations for Individuals Who Are Deaf, Hard of Hearing, or Deaf-Blind

AGENCY: Office of the Secretary, Department of Transportation (DOT).

ACTION: Notice of Proposed Rulemaking (NPRM).

SUMMARY: This notice of proposed rulemaking (NPRM) proposes to amend a previously published proposed rule that implements the Air Carrier Access Act (ACAA), to provide for additional accommodations for air travelers who are deaf, hard of hearing or deaf-blind. This proposed rule applies to U.S. air carriers, to foreign air carriers for their flights into and out of the United States, to airport facilities located in the U.S. that are owned, controlled or leased by carriers, and to aircraft that serve a U.S. airport. It proposes to require U.S. and certain foreign air carriers to provide prompt access for individuals who identify themselves as requiring hearing

or visual assistance to the same information provided to other passengers in the terminal and on the aircraft; caption safety and informational videos, DVDs and other audio-visual displays shown on new and existing aircraft; caption entertainment videos, DVDs and other audio-visual displays on new aircraft; ensure that individuals calling a carrier's TTY line for information or reservations receive equal response time and level of service (including queuing or other automated response service) as that provided to individuals calling a non-TTY information or reservation line; enable captioning on televisions and audio-visual equipment located in those portions of U.S. airports that are owned, leased or controlled by carriers and open to public access to the extent that such equipment has captioning capability on the effective date of this rule; replace non-caption capable televisions and audio-visual displays with captioning capable technology in the normal course of operations or when relevant airport facilities undergo substantial renovation or expansion; and train carrier personnel to proficiency on recognizing requests for communication accommodations and communicating with individuals who have visual or hearing impairments.

DATES: Interested persons are invited to submit comments regarding this proposal. Comments must be received on or before April 24, 2006.

ADDRESSES: Comments on this notice of proposed rulemaking must refer to the docket and notice numbers cited at the beginning of this notice and be submitted to the Docket Management Facility of the Office of the Secretary (OST), located on the Plaza Level of the Nassif Building at the U.S. Department of Transportation, Room PL-401, 400 Seventh Street, SW., Washington, DC 20590-0001. The DOT Docket Facility is open to the public from 10 a.m. to 5 p.m., Monday through Friday. Commenters may also submit comments electronically. Instructions appear on the Dockets Management System (DMS) pages of the Department's Web site (<http://dms.dot.gov>).

FOR FURTHER INFORMATION CONTACT: Omar Guerrero or Blane A. Workie, Office of the General Counsel, Department of Transportation, 400 7th Street, SW., Room 4116, Washington, DC 20590, 202-366-9342 (voice), (202) 366-0511 (TTY), 202-366-7152 (fax), omar.guerrero@dot.gov or blane.workie@dot.gov (e-mail). Arrangements to receive this notice in an alternative format may be made by contacting the above named individuals.

SUPPLEMENTARY INFORMATION:

Background

This NPRM concerns the issue of accommodations for deaf, hard of hearing and deaf-blind individuals. The Department of Transportation (hereinafter "Department" or "DOT") first considered such an NPRM in 1996. At that time, DOT issued an NPRM on seating accommodations and stowage of collapsible wheelchairs in which it also requested comments on suggestions the Department had received regarding accommodations for deaf and hard of hearing persons. See 61 FR 56484 (Nov. 1, 1996). Specifically, the 1996 NPRM sought comments on the need for, technical feasibility of, and cost of the following accommodations: (1) The captioning of video material shown on aircraft (e.g., movies and other entertainment features); (2) the availability of telecommunications devices for the deaf where air phone service is provided to other passengers; (3) the provision of assistive listening technology for public address announcements in the aircraft; and (4) the provision of electronic messaging or assistive listening technology in gate areas. In the preamble of the final rule that resulted from the November 1996 proposed rulemaking, however, the Department deferred a decision on whether to require additional accommodations for deaf and hard of hearing passengers. See 63 FR 10528 (March 4, 1998).

In January 2000, DOT reopened consideration of this issue by convening a public meeting to discuss whether the Department should commence a rulemaking to require certain additional accommodations for deaf and hard of hearing passengers under the ACAA. See 62 FR 63279 (Nov. 19, 1999); 64 FR 66590 (Nov. 29, 1999). Later that year, the Department determined to institute a rulemaking on additional accommodations for deaf and hard of hearing individuals through the use of a regulatory negotiation. However, resource issues delayed the formation and progress of a regulatory negotiation on this issue.

Representatives from the deaf and hard of hearing community, during the May 2001 DOT forum regarding air travel for people with disabilities, asked that DOT follow-up on these early efforts to address deaf and hard of hearing accommodations with a rulemaking. In response to this request, DOT indicated that collaboration among air carriers, airports and the disability community would accelerate the initiation of rulemaking addressing these issues.