

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this supplemental NPRM and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding the following new airworthiness directive:

Gulfstream Aerospace Corporation: Docket 96–NM–143–AD.

Applicability: All Model G–159 airplanes, certificated in any category.

Compliance: Required as indicated, unless accomplished previously.

To detect and correct corrosion and cracking of the spot-welded skins of the lower wing plank splices and certain structural assemblies, which could result in reduced controllability of the airplane, accomplish the following:

Note 1: A note in the Accomplishment Instructions of the Gulfstream customer bulletin instructs operators to contact Gulfstream if any difficulty is encountered in accomplishing the customer bulletin. However, any deviation from the instructions provided in the service bulletin must be approved as an alternative method of compliance (AMOC) under paragraph (h) of this AD.

Non-Destructive Testing Inspections of the Fuselage, Empennage, and Flight Controls

(a) Within 9 months after the effective date of this AD, perform a non-destructive test (NDT) to detect corrosion of the skins of the elevators, ailerons, rudder and rudder trim tab, flaps, aft lower fuselage, and vertical and horizontal stabilizers; in accordance with Gulfstream GI Customer Bulletin (CB) No. 337B, including Appendix A, dated August 17, 2005. The corrosion criteria must be determined by the Manager, Atlanta Aircraft Certification Office (ACO), FAA. Gulfstream Tool ST905–377 is also an acceptable method of determining the corrosion criteria.

(1) If no corrosion or cracking is detected, repeat the inspection thereafter at intervals not to exceed 18 months.

(2) If all corrosion is detected that meets the criteria of “light” or “mild” corrosion, repeat the NDT inspections of that component thereafter at intervals not to exceed 12 months.

(3) If any corrosion is detected that meets the criteria of “moderate” corrosion, repeat the NDT inspection of that component thereafter at intervals not to exceed 9 months.

(4) If any corrosion is detected that meets the criteria of “severe” corrosion, before further flight, replace the component with a serviceable component in accordance with the CB.

Existing Repairs

(b) If any existing repairs are found during the inspections required by paragraph (a) of this AD, before further flight, ensure that the repairs are in accordance with a method approved by the Manager, Atlanta ACO, FAA.

Inspections of the Lower Wing Plank

(c) Except as provided in paragraph (f) of this AD: Within 9 months after the effective date of this AD, perform NDT inspections to detect corrosion and cracking of the lower wing plank splices in accordance with Gulfstream GI CB 337B, including Appendix A, dated August 17, 2005.

(1) If no corrosion or cracking is detected, repeat the NDT inspection at intervals not to exceed 18 months.

(2) If any corrosion or cracking is detected, before further flight, perform all applicable investigative actions and corrective actions in accordance with the customer bulletin.

Repair Removal Threshold

(d) For repairs specified in Appendix A of Gulfstream GI CB 337B, dated August 17, 2005: Within 144 months after the date of the repair installation, remove the repaired component and replace it with a new or serviceable component, in accordance with Gulfstream GI CB 337B, including Appendix A, dated August 17, 2005.

Prior Blending in the Riser Areas

(e) If, during the performance of the inspections required by paragraph (c) or (f) of this AD, the inspection reveals that prior blending has been performed on the riser areas: Before further flight, perform an eddy current or fluorescent penetrant inspection, as applicable, to evaluate the blending, and accomplish appropriate corrective actions, in accordance with Gulfstream GI CB 337B, including Appendix A, dated August 17, 2005. If any blend-out is outside the limits specified in the CB, before further flight, repair in a manner approved by the Manager, Atlanta ACO.

For Airplanes With New Lower Wing Planks

(f) For airplanes with new lower wing planks, as defined by paragraphs (f)(1) and (f)(2) of this AD: Within 144 months after replacement of the lower wing planks with new lower wing planks, or within 9 months after the effective date of this AD, whichever occurs later, perform all of the actions, including any other related investigative actions and corrective actions, specified in paragraph (c) of this AD.

Reporting Requirement

(g) Within 30 days of performing the inspections required by this AD: Submit a report of inspection findings (both positive and negative) to Gulfstream Aerospace Corporation; Attention: Technical Operations—Mail Station D–10, P. O. Box 2206, Savannah, Georgia 31402–0080. Information collection requirements contained in this regulation have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120–0056.

Alternative Methods of Compliance

(h)(1) The Manager, Atlanta ACO, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on March 9, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6–4050 Filed 3–20–06; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2006–24173; Directorate Identifier 2005–NM–262–AD]

RIN 2120–AA64

Airworthiness Directives; Boeing Model 777 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Boeing Model 777 airplanes. This proposed AD would require a one-time inspection of the first bonding jumper aft of the bulkhead fitting to detect damage or failure and to determine the mechanical integrity of its electrical bonding path, and repair if necessary; measuring the bonding resistance between the fitting for the fuel feed tube and the front spar in the left and right main fuel tanks, and repairing the bonding if necessary; and applying additional sealant to completely cover the bulkhead fittings inside the fuel tanks. This proposed AD

results from fuel system reviews conducted by the manufacturer. We are proposing this AD to prevent arcing or sparking during a lightning strike at the interface between the bulkhead fittings of the engine fuel feed tube and the front spar inside the fuel tank. This arcing or sparking could provide a potential ignition source inside the fuel tank, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

DATES: We must receive comments on this proposed AD by May 5, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket Web site: Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- Government-wide rulemaking Web site: Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- Mail: Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, room PL-401, Washington, DC 20590.

- Fax: (202) 493-2251.

- Hand Delivery: Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for the service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: John L. Vann, Aerospace Engineer, Propulsion Branch, ANM-140S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6513; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2006-24173; Directorate Identifier 2005-NM-262-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://>

dms.dot.gov, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

We have examined the underlying safety issues involved in fuel tank explosions on several large transport airplanes, including the adequacy of existing regulations, the service history of airplanes subject to those regulations, and existing maintenance practices for fuel tank systems. As a result of those findings, we issued a regulation titled "Transport Airplane Fuel Tank System Design Review, Flammability Reduction and Maintenance and Inspection Requirements" (67 FR 23086, May 7, 2001). In addition to new airworthiness standards for transport airplanes and new maintenance requirements, this rule included Special Federal Aviation Regulation No. 88 ("SFAR 88," Amendment 21-78, and subsequent Amendments 21-82 and 21-83).

Among other actions, SFAR 88 requires certain type design (*i.e.*, type certificate (TC) and supplemental type certificate (STC)) holders to substantiate that their fuel tank systems can prevent ignition sources in the fuel tanks. This requirement applies to type design holders for large turbine-powered transport airplanes and for subsequent modifications to those airplanes. It requires them to perform design reviews and to develop design changes and maintenance procedures if their designs do not meet the new fuel tank safety standards. As explained in the preamble

to the rule, we intended to adopt airworthiness directives to mandate any changes found necessary to address unsafe conditions identified as a result of these reviews.

In evaluating these design reviews, we have established four criteria intended to define the unsafe conditions associated with fuel tank systems that require corrective actions. The percentage of operating time during which fuel tanks are exposed to flammable conditions is one of these criteria. The other three criteria address the failure types under evaluation: Single failures, single failures in combination with another latent condition(s), and in-service failure experience. For all four criteria, the evaluations included consideration of previous actions taken that may mitigate the need for further action.

We have determined that the actions identified in this AD are necessary to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

We have received a report indicating that, on certain Boeing Model 747 airplanes, the sealant at the fitting for the fuel feed tube at the front spar bulkhead may be insufficient to protect against a spark between the bulkhead fitting and the spar in the event of a lightning strike. In SFAR 88-related testing, the manufacturer determined that a lightning strike can cause a spark even if the fitting is bonded. This condition, if not corrected, could result in a potential ignition source inside the fuel tank, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

The affected area on certain Boeing Model 747 airplanes is similar in design to that on the affected Boeing Model 777 airplanes. Therefore, all of these models may be subject to the same unsafe condition.

Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 777-28-0044, Revision 1, dated December 20, 2005. The service bulletin describes procedures for:

- Doing a general visual inspection of the first bonding jumper aft of the bulkhead fitting to detect damage or failure and to determine the mechanical integrity of its electrical bonding path.
- Measuring the bonding resistance between the fitting for the fuel feed tube and the front spar in the left main fuel tank, and repairing the bonding if it

exceeds certain limits defined in the service bulletin.

- Applying additional sealant to completely cover the bulkhead fitting inside the fuel tank.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously, except as discussed under "Difference Between the Proposed AD and the Service Bulletin."

Difference Between the Proposed AD and the Service Bulletin

Although the service bulletin does not give repair instructions if any damage or failure is found during the general visual inspection, or if the mechanical integrity of the bonding path is compromised, this proposed AD would require doing the repair according to a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Chapter 28-00-00 of the Boeing 777 Aircraft Maintenance Manual is one approved method.

Costs of Compliance

There are about 497 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 131 airplanes of U.S. registry. The proposed actions would take about 8 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$83,840, or \$640 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2006-24173; Directorate Identifier 2005-NM-262-AD.

Comments Due Date

- (a) The FAA must receive comments on this AD action by May 5, 2006.

Affected ADs

- (b) None.

Applicability

(c) This AD applies to Boeing Model 777-200, -300, and -300ER series airplanes, certificated in any category; as identified in Boeing Special Attention Service Bulletin 777-28-0044, Revision 1, dated December 20, 2005.

Unsafe Condition

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent arcing or sparking during a lightning strike at the interface between the bulkhead fittings of the engine fuel feed tube and the front spar inside the fuel tank. This arcing or sparking could provide a potential ignition source inside the fuel tank, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection and Corrective Actions

(f) Within 60 months after the effective date of this AD, do the actions in paragraphs (f)(1), (f)(2), and (f)(3) of this AD for the bulkhead fittings of the engine fuel feed tube for the left and right main fuel tanks. Do all actions in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 777-28-0044, Revision 1, dated December 20, 2005.

(1) Do a general visual inspection of the first bonding jumper aft of the bulkhead fitting to detect damage or failure and to determine the mechanical integrity of its electrical bonding path. If any damage or failure is found during this inspection or if the mechanical integrity of the bonding path is compromised: Before further flight, repair according to a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA, Chapter 28-00-00 of the Boeing 777 Aircraft Maintenance Manual is one approved method.

(2) Measure the bonding resistance between the fitting for the fuel feed tube and the front spar in the left main fuel tank. If the bonding resistance exceeds 0.001 ohm: Before further flight, repair the bonding in accordance with the service bulletin.

(3) Apply additional sealant to completely cover the bulkhead fitting inside the fuel tank.

Actions Accomplished in Accordance With Previous Revision of Service Bulletin

(g) Actions done before the effective date of this AD in accordance with Boeing Special Attention Service bulletin 777-28-0044, dated February 3, 2005, are acceptable for compliance with the requirements of paragraph (f) of this AD.

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on March 10, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-4051 Filed 3-20-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Financial Crimes Enforcement Network

31 CFR Part 103

RIN 1506-AA84

Proposed Amendments to Bank Secrecy Act Regulations Regarding Casino Recordkeeping and Reporting Requirements

AGENCY: Financial Crimes Enforcement Network, Department of the Treasury.

ACTION: Notice of proposed rulemaking.

SUMMARY: We are proposing to amend the Bank Secrecy Act regulations relating to currency transaction reporting by casinos. Specifically, we are proposing to exclude, as reportable transactions in currency, jackpots from slot machines and video lottery terminals. We are also proposing to exclude certain transactions between casinos and currency dealers or exchangers and casinos and check cashers as reportable transactions in currency. Finally, we are proposing several other amendments that would update or clarify the “cash in” and “cash out” examples of transactions that are set forth in our currency transaction reporting regulations.

DATES: Written comments on all aspects of the proposal are welcome and may be submitted on or before May 22, 2006.

ADDRESSES: You may submit comments identified by Regulatory Information Number (RIN) 1506-AA84, by any of the following methods:

- Federal E-rulemaking Portal: <http://www.regulations.gov>. Follow the instructions for submitting comments. Include 1506-AA84 in the submission.
- E-mail: regcomments@fincen.treas.gov. Include 1506-AA84 in the subject line of the message.
- Mail: Financial Crimes Enforcement Network, P.O. Box 39, Vienna, VA 22183. Include 1506-AA84 in the body of the text.

Instructions: Electronic comments are preferred because paper mail in the

Washington, DC, area may be delayed. Please submit comments by one method only. Any submissions received must include the agency name and the RIN for this rulemaking. All comments received will be posted without change to <http://www.fincen.gov>, including any personal information provided. Comments may be inspected in the Financial Crimes Enforcement Network reading room between 10 a.m. and 4 p.m. in Washington, DC. Persons wishing to inspect the comments submitted must request an appointment by telephone at (202) 354-6400 (not a toll-free number).

FOR FURTHER INFORMATION CONTACT: Regulatory Policy and Programs Division, Financial Crimes Enforcement Network, (800) 949-2732 (toll-free number) or (202) 354-6400 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

I. Background

A. Statutory and Regulatory Background

The Director of the Financial Crimes Enforcement Network is the delegated administrator of the Bank Secrecy Act.¹ The Act authorizes the Director to issue regulations to require all financial institutions defined as such in the Act to maintain or file certain reports or records that have been determined to have a high degree of usefulness in criminal, tax, or regulatory investigations or proceedings, or in the conduct of intelligence or counter-intelligence activities, including analysis, to protect against international terrorism, and to implement anti-money laundering programs and compliance procedures.²

Casinos are cash-intensive businesses that offer a broad array of financial services. These services include customer deposit or credit accounts, facilities for transmitting and receiving funds transfers directly from other financial institutions, and check cashing and currency exchange services. Consequently, these services offered by casinos are similar to and may serve as substitutes for services ordinarily provided by depository institutions and

¹ The statute generally referred to as the “Bank Secrecy Act,” Titles I and II of Public Law 91-508, as amended, is codified at 12 U.S.C. 1829b, 12 U.S.C. 1951-1959, and 31 U.S.C. 5311-5314, 5316-5332.

² Language expanding the scope of the Bank Secrecy Act to intelligence or counter-intelligence activities to protect against international terrorism was added by section 358 of the Uniting and Strengthening America by Providing Appropriate Tools Required to Intercept and Obstruct Terrorism (“USA PATRIOT”) Act of 2001, Public Law 107-56 (October 26, 2001). In pertinent part, regulations implementing Title II of the Bank Secrecy Act appear at 31 CFR part 103.

certain non-bank financial institutions. As such, casinos are vulnerable to abuse by money launderers, terrorist financiers, and tax evaders.

In general, state-licensed casinos were made subject to the Bank Secrecy Act by regulation in 1985.³ The 1985 rulemaking was based on the authority of the Secretary of the Treasury to designate as financial institutions for Bank Secrecy Act purposes: (i) Businesses that engage in activities that are “similar to, related to, or a substitute for” the activities of covered businesses listed in the Bank Secrecy Act and (ii) other businesses “whose cash transactions have a high degree of usefulness in criminal, tax, or regulatory matters.”⁴ Congress later explicitly added casinos and other gaming establishments to the list of financial institutions regulated pursuant to the Bank Secrecy Act.⁵

Casinos authorized to conduct business under the Indian Gaming Regulatory Act became subject to the Bank Secrecy Act by regulation in 1996,⁶ and card clubs became subject to the Bank Secrecy Act by regulation in 1998.⁷

B. Casino Currency Transaction Reporting Requirements

Regulations under the Bank Secrecy Act define a “transaction in currency” as any transaction “involving the physical transfer of currency from one person to another.”⁸ Casinos must report each transaction in currency involving cash in or cash out of more

³ See 50 FR 5065 (February 6, 1985). Casinos whose gross annual gaming revenue did not exceed \$1 million were, and continue to be, excluded from Bank Secrecy Act requirements otherwise applicable to casinos and card clubs.

⁴ See 31 U.S.C. 5312(a)(2)(Y) and (Z).

⁵ See section 409 of the Money Laundering Suppression Act of 1994, Title IV of the Riegle Community Development and Regulatory Improvement Act of 1994, Public Law 103-325. The current statutory specification reads:

(2) Financial institution means—

* * * * *

(X) A casino, gambling casino, or gaming establishment with an annual gaming revenue of more than \$1,000,000 which—

(i) Is licensed as a casino, gambling casino, or gaming establishment under the laws of any State or any political subdivision of any State; or

(ii) Is an Indian gaming operation conducted under or pursuant to the Indian Gaming Regulatory Act other than an operation which is limited to class I gaming (as defined in section 4(6) of such Act); * * * 31 U.S.C. 5312(a)(2)(X).

⁶ See 61 FR 7054 (February 23, 1996).

⁷ See 63 FR 1919 (January 13, 1998). Card clubs generally are subject to the same rules as casinos, unless a different treatment for card clubs is explicitly stated in 31 CFR part 103. Therefore, for purposes of this Notice of Proposed Rulemaking, and unless the context indicates otherwise, the term “casino” refers to both casinos and to card clubs.

⁸ See 31 CFR 103.11(ii)(2).