

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2006-25326; Directorate Identifier 2006-NM-081-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by August 28, 2006.

Affected ADs

(b) None.

Applicability

(c) This AD applies to the Boeing airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Model 757-200 series airplanes, as identified in Boeing Service Bulletin 757-24-0093, dated August 14, 2003.

(2) Model 757-300 series airplanes, as identified in Boeing Service Bulletin 757-24-0094, dated April 17, 2003.

Unsafe Condition

(d) This AD results from an in-flight entertainment (IFE) systems review. We are issuing this AD to ensure that the flightcrew is able to turn off electrical power to the IFE system through utility bus switches in the flight compartment. The flightcrew's inability to turn off power to the IFE system during a non-normal or emergency situation could result in the inability to control smoke or fumes in the airplane flight deck or cabin.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Installation of Circuit Breakers, Relays, and Wiring

(f) Within 60 months after the effective date of this AD, do the applicable actions specified in paragraphs (f)(1) through (f)(6) of this AD, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757-24-0093, dated August 14, 2003 (for Model 757-200 series airplanes); or Boeing Service Bulletin 757-24-0094, dated April 17, 2003 (Model 757-300 series airplanes), as applicable.

(1) For all airplanes: Change the wiring at the P5 and P11 panel assemblies in the flight compartment, at the P36 panel assembly in the forward cargo compartment, and at the P37 and P70 panel assemblies in the main electronics compartment. Install a new relay and relay connector, if applicable, at the P36 panel assembly and at the P37 panel assembly.

(2) For Model 757-200 series airplanes identified as Group 1 in Boeing Service Bulletin 757-24-0093, dated August 14, 2003: Install new circuit breakers C3090 and C3089 at the P37 and P70 panel assemblies, respectively, in the main electronics compartment.

(3) For Model 757-200 series airplanes identified as Groups 21 and 22 in Boeing Service Bulletin 757-24-0093, dated August 14, 2003: Replace circuit breaker C311 at the P31 panel assembly in the main electronics compartment with a higher-rated circuit breaker.

(4) For Model 757-200 series airplanes identified as Groups 1 through 20 inclusive and 23 through 40 inclusive in Boeing Service Bulletin 757-24-0093, dated August 14, 2003: Replace circuit breakers C311 and C315 at the P31 and P32 panel assemblies, respectively, in the main electronics compartment with higher-rated circuit breakers.

(5) For Model 757-300 series airplanes identified as Groups 1 and 4 in Boeing Service Bulletin 757-24-0094, dated April 17, 2003: Replace circuit breakers C311 and C315 at the P31 and P32 panel assemblies, respectively, in the main electronics compartment with higher-rated circuit breakers.

(6) For Model 757-300 series airplanes identified as Groups 1, 2, and 3 in Boeing Service Bulletin 757-24-0094, dated April 17, 2003: Install new wires between the P5 panel assembly in the flight compartment and the P36 and P37 panel assemblies in the main electronics compartment.

Concurrent Requirement for Certain Airplanes

(g) For the Model 757-200 series airplanes identified as Groups 8, 9, 12, 15, 20, 21 through 32 inclusive, and 34 through 40 inclusive in Boeing Service Bulletin 757-24-0093, dated August 14, 2003: Prior to or concurrently with accomplishing the actions specified in paragraph (f) of this AD, modify the wiring of the control module assembly for the electrical systems, by accomplishing all of the actions specified in the Accomplishment Instructions of Boeing Component Service Bulletin 233N3209-24-04, Revision 1, dated August 14, 2003, as applicable.

Credit for Accomplishment of Previous Service Bulletin

(h) Modification of the control module assembly done before the effective date of this AD in accordance with Boeing Component Service Bulletin 233N3209-24-04, dated April 10, 2003, is acceptable for compliance with the requirements of paragraph (g) of this AD.

Alternative Methods of Compliance (AMOCs)

(i)(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Issued in Renton, Washington, on July 3, 2006.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E6-11020 Filed 7-12-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25327; Directorate Identifier 2006-NM-116-AD]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747-400, 747-400D, and 747SR Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to revise an existing airworthiness directive (AD) that applies to certain Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747-400, 747-400D, and 747SR series airplanes. The existing AD currently requires repetitive inspections to detect cracking of certain lower lobe fuselage frames, and repair if necessary. This proposed AD would specify appropriate service information for certain corrective actions. This proposed AD results from reports indicating that fatigue cracks were found in lower lobe frames on the left side of the fuselage. We are proposing this AD to detect and correct fatigue cracking of certain lower lobe fuselage

frames, which could lead to fatigue cracks in the fuselage skin, and consequent rapid decompression of the airplane.

DATES: We must receive comments on this proposed AD by August 28, 2006.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street SW., Nassif Building, Room PL-401, Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207, for service information identified in this proposed AD.

FOR FURTHER INFORMATION CONTACT: Ivan Li, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (425) 917-6437; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include docket number "Docket No. FAA-2006-25327; Directorate Identifier 2006-NM-116-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that Web site, anyone can find and read the comments in a docket, including the name of the individual who sent the

comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

Discussion

On April 20, 2006, we issued AD 2006-09-06, amendment 39-14576 (71 FR 25926, May 3, 2006), for certain Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747-400, 747-400D, and 747SR series airplanes. That AD requires repetitive inspections to detect cracking of certain lower lobe fuselage frames, and repair if necessary. That AD resulted from reports indicating that fatigue cracks were found in lower lobe frames on the left side of the fuselage. We issued that AD to detect and correct fatigue cracking of certain lower lobe fuselage frames, which could lead to fatigue cracks in the fuselage skin, and consequent rapid decompression of the airplane.

Actions Since Existing AD Was Issued

Since we issued AD 2006-09-06, an operator questioned the addition of a reference to Boeing Service Bulletin 747-53A2349, Revision 2, dated April 3, 2003, in paragraph (h)(1) of that AD. A service bulletin reference in that paragraph was not included in the Notice of Proposed Rulemaking (NPRM) for AD 2006-09-06, but was added in the final rule to clarify the requirements of that paragraph. However, the service bulletin referenced in that paragraph should be Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002, rather than Boeing Service Bulletin 747-53A2349, Revision 2. Therefore, we have revised paragraph (h)(1) of this NPRM to refer to the correct service bulletin.

FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe

condition that is likely to exist or develop on other airplanes of this same type design. For this reason, we are proposing this AD, which would revise AD 2006-09-06 and would retain the requirements of the existing AD. This proposed AD would revise the service information referenced in paragraph (h)(1).

Explanation of Editorial Change

We have revised the reference to the Boeing 747-400 Structural Repair Manual in paragraph (h)(1)(i) of this proposed AD. The paragraph applies to Group 1 airplanes and should refer to the Boeing 747 Structural Repair Manual because Boeing 747-400 series airplanes are not in Group 1.

Costs of Compliance

There are about 681 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 99 airplanes of U.S. registry. The new requirements of this proposed AD add no additional economic burden. The current costs for this AD are repeated for the convenience of affected operators, as follows:

The actions in this proposed AD take about 2 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of both the retained and proposed actions for U.S. operators is \$15,840, or \$160 per airplane, per inspection cycle.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the

States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and place it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-14576 (71 FR 25926, May 3, 2006) and adding the following new airworthiness directive (AD):

Boeing: Docket No. FAA-2006-25327; Directorate Identifier 2006-NM-116-AD.

Comments Due Date

(a) The FAA must receive comments on this AD action by August 28, 2006.

Affected ADs

(b) This AD revises AD 2006-09-06.

Applicability

(c) This AD applies to Boeing Model 747-100, 747-100B, 747-100B SUD, 747-200B, 747-300, 747-400, 747-400D, and 747SR series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002.

Unsafe Condition

(d) This AD results from reports indicating that fatigue cracks were found in lower lobe frames on the left side of the fuselage. We are issuing this AD to detect and correct fatigue

cracking of certain lower lobe fuselage frames, which could lead to fatigue cracks in the fuselage skin, and consequent rapid decompression of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Restatement of the Requirements of AD 99-07-12, With Additional Information for Group 2 Airplanes

Initial Inspections

(f) For airplanes on which the initial detailed internal inspection of the Section 46 lower lobe frames required by paragraph (f)(2) or (i)(2) of AD 2005-20-30, amendment 39-14327, has not been accomplished: Perform a detailed visual inspection to detect cracking of the lower lobe fuselage frames from Body Station 1820 to Body Station 2100, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-53A2408, dated April 25, 1996; or Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002; as applicable; at the later of the applicable times specified in paragraph (f)(1), (f)(2), or (f)(3) of this AD.

(1) For all airplanes: Prior to the accumulation of 15,000 total flight cycles; or

(2) For Group 1 airplanes identified in Revision 1 of the service bulletin: Within 1,500 flight cycles or 18 months after May 5, 1999 (the effective date of AD 99-07-12), whichever occurs first.

(3) For Group 2 airplanes identified in Revision 1 of the service bulletin: Within 1,500 flight cycles or 18 months after June 7, 2006, whichever occurs first.

Note 1: Paragraphs (f)(2) and (i)(2) of AD 2005-20-30 require a detailed inspection to detect cracks in the Section 46 lower lobe frames, in accordance with Boeing Service Bulletin 747-53A2349, Revision 2, dated April 3, 2003. The initial inspection is required prior to the accumulation of 22,000 total flight cycles; or within 1,000 flight cycles after June 11, 1993 (the effective date of AD 93-08-12, amendment 39-8559), or November 16, 2005 (the effective date of AD 2005-20-30), depending on previous inspections accomplished; whichever occurs later.

Note 2: For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

Repetitive Inspections

(g) If no cracking is detected during the inspection required by paragraph (f) of this AD, repeat the inspection thereafter at intervals not to exceed 3,000 flight cycles.

Corrective Actions

(h) If any cracking is detected during any inspection required by paragraph (f) of this AD, prior to further flight, accomplish paragraphs (h)(1) and (h)(2) of this AD:

(1) Within 20 inches of the crack location on the frame, perform a detailed inspection of the adjacent structure to detect cracking. As of the effective date of this AD, the detailed inspection must be done in accordance with Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002. If any cracking is detected during any detailed inspection done in accordance with paragraph (f) or (h)(1) of this AD, prior to further flight, repair in accordance with paragraph (h)(1)(i) or (h)(1)(ii) of this AD, as applicable.

(i) For Group 1 airplanes: Using a method approved in accordance with the procedures specified in paragraph (j) of this AD. The Boeing 747 Structural Repair Manual, Subject 53-10-04, Figure 67 or 90, is one approved method.

(ii) For Group 2 airplanes: Using a method approved in accordance with the procedures specified in paragraph (j) of this AD. The Boeing 747-400 Structural Repair Manual, Subject 53-60-07, Repair 1 or 2, is one approved method.

(2) Repeat the inspection required by paragraph (f) of this AD thereafter at intervals not to exceed 3,000 flight cycles.

Optional Terminating Inspection

(i) Accomplishment of the initial detailed inspection of the Section 46 lower lobe frames required by paragraph (f)(2) or (i)(2) of AD 2005-20-30 constitutes terminating action for the requirements of this AD only for airplanes identified in Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002, as Group 1 airplanes. Accomplishment of the initial detailed inspection of the Section 46 lower lobe frames required by paragraph (f) of AD 2006-05-02 constitutes terminating action for the requirements of this AD only for airplanes identified in Boeing Alert Service Bulletin 747-53A2408, Revision 1, dated April 4, 2002, as Group 2 airplanes.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane.

(4) AMOCs approved previously in accordance with AD 99-07-12, amendment

39-11097, are approved as AMOCs for the corresponding provisions of this AD.

Issued in Renton, Washington, on July 5, 2006.

Ali Bahrami,

*Manager, Transport Airplane Directorate,
Aircraft Certification Service.*

[FR Doc. E6-11019 Filed 7-12-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Parts 740, 742, 748, 754, and 772

[Docket No. 030425102-6179-03]

RIN 0694-AC20

Mandatory Use of Simplified Network Application Processing System

AGENCY: Bureau of Industry and Security, Commerce.

ACTION: Proposed rule—withdrawal.

SUMMARY: The Bureau of Industry and Security (BIS) is withdrawing a proposed rule that would have made use of the Simplified Network Application Process (SNAP) mandatory and that would have comprehensively revised the provisions of the Export Administration Regulations (EAR) that govern electronic filing. BIS is continuing to work on improvements to its on-line application system and will issue new rules as needed to implement those improvements.

DATES: The proposed rule is withdrawn as of July 13, 2006.

FOR FURTHER INFORMATION CONTACT: William Arvin, Office of Exporter Services, Regulatory Policy Division; e-mail warvin@bis.doc.gov, telephone (202) 482-2440.

SUPPLEMENTARY INFORMATION:

Background

On November 12, 2003 (68 FR 64009), the Bureau of Industry and Security published a proposed rule that would have required that all applications for export licenses, reexport licenses, license exception AGR submissions, classification requests and encryption review requests be submitted via a to-be-instituted revised Simplified Network Application Process unless certain enumerated exceptions applied, and that would have extensively revised the requirements for electronic filing of certain applications (the November 2003 proposed rule). The November 2003 proposed rule would also have allowed organizations that use the system, once

registered, to add, remove and adjust the authority level of individual users authorized to file applications and notices on behalf of that organization. The November 2003 proposed rule would have permitted the electronic filing of attachments, and required that all attachments to applications and notices be in text searchable pdf format.

The original comment period expired on January 12, 2004, but was extended to February 12, 2004 (69 FR 1685, January 12, 2004). BIS received 16 comments on the proposed rule. Although a number of commenters generally favored expanded electronic filing in principle, many were opposed to the requirement that attachments be in text searchable pdf format, generally citing the cost of producing such documents, particularly if the source documents had to be scanned from poor quality, oversized or bound originals. Other commenters opposed making electronic filing mandatory, and still others, although not opposed to mandatory electronic filing in principle, stated that no mandatory filing rule should be imposed until after the improved system had been deployed and was operating reliably.

Since the publication of the November 2003 proposed rule, BIS has reassessed its efforts to improve electronic filing of license applications and as a result of that reassessment, determined to release improvements and modifications to its electronic filing system in small installments rather than in the single complete restructuring that the November 2003 proposed rule contemplated. BIS may at times find it necessary to amend the Export Administration Regulations to conform with some of those installments. However, BIS has concluded that a single rule comprehensively rewriting the EAR provisions relating to electronic filing as it proposed in the November 2003 proposed rule no longer is consistent with the manner in which it plans to modernize its electronic filing process. In addition, BIS agrees with the commenters to the November 2003 proposed rule who stated that any revised electronic system should be put into place and be operating reliably before any rule making its use mandatory is published.

Accordingly, BIS is withdrawing the November 2003 proposed rule. BIS is continuing to work on improvements to its on-line application system and will issue new rules as needed to implement those improvements.

Dated: June 30, 2006.

Matthew S. Borman,

Deputy Assistant Secretary for Export Administration.

[FR Doc. E6-11056 Filed 7-12-06; 8:45 am]

BILLING CODE 3510-33-P

DEPARTMENT OF ENERGY

Federal Energy Regulatory Commission

18 CFR Parts 366, 367, 368, 369 and 375

[Docket No. RM06-11-000]

Financial Accounting, Reporting and Records Retention Requirements Under the Public Utility Holding Company Act of 2005

Issued June 30, 2006.

AGENCY: Federal Energy Regulatory Commission.

ACTION: Notice of Proposed Rulemaking; Notice of agenda, panelists and questions for July 18, 2006 Technical Conference.

SUMMARY: On April 21, 2006, the Federal Energy Regulatory Commission issued a Notice of Proposed Rulemaking in the above-docketed proceeding concerning Financial Accounting, Reporting and Records Retention Requirements Under the Public Utility Holding Company Act of 2005, 71 FR 28464, May 16, 2006. The Commission is convening a technical conference on July 18, 2006, to identify issues associated with the proposed Uniform System of Accounts for Centralized Service Companies, the proposed records retention requirements for holding companies and service companies, and the Revised Form 60. By this notice, the Commission is providing the agenda, panelists and a list of questions that will be addressed by the panelists at this conference.

DATES: Conference will be held on July 18, 2006.

FOR FURTHER INFORMATION CONTACT: Julia A. Lake (Legal Information), Office of the General Counsel—Energy Markets, Federal Energy Regulatory Commission, 888 First Street, NE., Washington, DC 20426. Telephone: (202) 502-8370. E-mail: julia.lake@ferc.gov.

SUPPLEMENTARY INFORMATION:

Notice of Agenda, Panelists and Questions

As announced on April 21 and June 16, 2006, the Federal Energy Regulatory Commission (Commission) will hold a technical conference and workshop in