

(i) Business name, address, telephone number, signature, and the date the form was signed;

(ii) The date of peeling, chopping, or slicing;

(iii) Inspection certificate number;

(iv) The quantity of onions; and

(v) Such other information as may be required by the committee.

(2) Handlers who peel, chop, or slice onions produced outside the production area must provide the committee with documentation showing that the onions so prepared were produced outside the production area.

(e) *Special purpose shipments.* The minimum grade, size, maturity, assessment, and inspection requirements of this section shall not be applicable to shipments of onions for any of the following purposes:

(1) Planting,

(2) Livestock feed,

(3) Charity,

(4) Dehydration,

(5) Canning,

(6) Freezing,

(7) Extraction,

(8) Pickling, and

(9) Disposal.

In addition, the minimum grade, size, and maturity requirements set forth in paragraph (a) of this section shall not be applicable to shipments of pearl onions, but the maximum size requirement in paragraph (h) of this section and the assessment and inspection requirements shall be applicable to shipments of pearl onions.

(f) *Safeguards.* Each handler making shipments of onions outside the production area for dehydration, canning, freezing, extraction, or pickling pursuant to paragraph (e) of this section shall:

(1) Furnish "Application to Make Special Purpose Shipments—Certificate of Privilege" and such other information to the committee as required. The committee will review and verify each "Application to Make Special Purpose Shipments—Certificate of Privilege" and notify the handler of approval or disapproval. The committee may contact the receiver or receiver's agent of the special purpose shipment for verification and request the receiver or receiver's agent to complete a "Special Purpose Shipment Receiver Certification";

(2) Bill or consign each shipment directly to the applicable receiver or receiver's agent of the special purpose shipment;

(3) Furnish "Onion Diversion Report" and such other information to the committee as required. Failure of the handler to furnish such report and information as required to the

committee may be cause for cancellation of such handlers' Certificate of Privilege. Upon cancellation of any such Certificate of Privilege the handler may appeal to the committee for reconsideration. The committee may audit a receiver or receiver's agent of the special purpose shipment to verify reports and information submitted by handlers. Failure of a receiver or receiver's agent of a special purpose shipment to comply with the committee may be cause for cancellation of the receiver's or receiver agent's eligibility to receive further special purpose shipments from the production area. Upon cancellation of any such Certificate of Privilege the receiver or the receiver's agent may appeal to the committee for reconsideration.

* * * * *

Dated: November 3, 2006.

Lloyd C. Day,

Administrator, Agricultural Marketing Service.

[FR Doc. 06-9112 Filed 11-3-06; 11:11 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26102; Directorate Identifier 2006-NE-36-AD; Amendment 39-14820; AD 2006-23-08]

RIN 2120-AA64

Airworthiness Directives; Societe de Motorisations Aeronautiques (SMA) SR305-230 and SR305-230-1 Reciprocating Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: "Over a period of time, the alteration of one electronic control unit (ECU) electronic component can cause a rapid uncontrolled power increase. Several occurrences have already been reported during engine start or during engine warm-up."

The event can also occur in flight which can result in loss of control of the airplane.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective November 22, 2006.

We must receive comments on this AD by November 22, 2006.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7175; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct

unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Discussion

The European Aviation Safety Agency (EASA), which is the aviation authority for the European community, has issued Emergency Airworthiness Directive No. 2006-0312-E, dated October 13, 2006 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states that:

Over a period of time, the alteration of one ECU electronic component can cause a rapid uncontrolled power increase. Several occurrences have already been reported during engine start or during engine warm-up.

The event can also occur in flight which can result in loss of control of the airplane. You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

SMA has issued Service Bulletin No. SB-01-76-004, dated October 10, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all the information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information

provided in the MCAI and related service information.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because of the several occurrences that have already been reported during engine start or during engine warm-up. The event can also occur in flight which can result in loss of control of the airplane. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2006-26102; Directorate Identifier 2006-NE-36-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2006-23-08 Societe de Motorisations Aeronautiques (SMA): Amendment 39-14820; Docket No. FAA-2006-26102; Directorate Identifier 2006-NE-36-AD.

Effective Date

- (a) This airworthiness directive (AD) becomes effective November 22, 2006.

Affected ADs

- (b) None.

Applicability

- (c) This AD applies to SMA SR305-230 and SR305-230-1 reciprocating engines. These engines are installed on, but not limited to, Cessna 182, Maule M-7, and Piper PA-34 airplanes.

Reason

(d) European Aviation Safety Agency, (EASA), Emergency Airworthiness Directive No. 2006-0312-E, dated October 13, 2006 states:

Over a period of time, the alteration of one electronic control unit (ECU) electronic component can cause a rapid uncontrolled power increase. Several occurrences have already been reported during engine start or during engine warm-up.

The event described in the EASA AD can also occur in flight which can result in loss of control of the airplane.

Actions and Compliance

(e) Unless already done, do the following actions before further flight.

(1) Determine the serial number (SN) of the ECU installed on the aircraft. Do not operate the engine if the ECU SN is 131 and below, except SN 70, 71, 83, and 88.

(2) If the ECU SN is 131 and below, except 70, 71, 83, and 88, remove and replace the ECU with an ECU having a SN of 132 and above.

FAA AD Differences

(f) None.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Engine Certification Office, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to mandatory continuing airworthiness information (MCAI) EASA Airworthiness Directive No. 2006-0312-E, dated October 13, 2006, and SMA Service Bulletin No. SB-01-76-004, dated October 10, 2006, for related information.

Material Incorporated by Reference

(i) None.

Issued in Burlington, Massachusetts, on October 31, 2006.

Francis A. Favara,

Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-18666 Filed 11-6-06; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2006-25855; Directorate Identifier 2006-NE-29-AD; Amendment 39-14819; AD 2006-23-07]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce plc Trent 768-60, Trent 772-60, and Trent 772B-60 Turbofan Engines.

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Rolls-Royce plc Trent 768-60, Trent 772-60, and Trent 772B-60 turbofan engines. This AD requires removing from service certain sets of fan blade annulus fillers at a new life limit. This AD results from six reports of fan annulus filler release into the engine. We are issuing this AD to prevent a dual-engine shutdown on twin-engine airplanes.

DATES: Effective November 22, 2006.

We must receive any comments on this AD by January 8, 2007.

ADDRESSES: Use one of the following addresses to comment on this AD:

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* Docket Management Facility; U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building, 400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT:

Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone: (781) 238-7175, fax: (781) 238-7199.

SUPPLEMENTARY INFORMATION: The European Aviation Safety Agency (EASA), which is the airworthiness authority for the European community, recently notified us that an unsafe condition may exist on Rolls-Royce plc

Trent 768-60, Trent 772-60, and Trent 772B-60 turbofan engines. EASA advises that six occurrences of the release of a fan annulus filler into the engine have occurred in 2005. Because of the number of events, there is a risk of a dual-engine shutdown on twin-engine airplanes.

Bilateral Airworthiness Agreement

These Rolls-Royce plc Trent 768-60, Trent 772-60, and Trent 772B-60 turbofan engines are manufactured in the United Kingdom. They are type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Under this bilateral airworthiness agreement, EASA kept the FAA informed of the situation described above. We have examined the findings of EASA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

FAA's Determination and Requirements of This AD

Although no airplanes that are registered in the United States use these engines, the possibility exists that the engines could be used on airplanes that are registered in the United States in the future. The unsafe condition described previously is likely to exist or develop on other Rolls-Royce plc Trent 768-60, Trent 772-60, and Trent 772B-60 turbofan engines of the same type design. We are issuing this AD to prevent a dual-engine shutdown on twin-engine airplanes. This AD requires the following:

- On or before December 31, 2006, if an airplane has fan annulus fillers, part number (P/N) FK21226, installed in both engines or has fan annulus fillers, P/N FK21226, in one engine and P/N FK22974, in the other engine, then the accumulated life of the fan annulus fillers on at least one engine must not exceed 7,500 cycles-in-service (CIS). Replace one of the engines, or one set of fan annulus fillers before further flight to comply with this requirement.

- After December 31, 2006, remove sets of fan annulus fillers, P/N FK21226, before exceeding the life limit of 6,500 CIS.

FAA's Determination of the Effective Date

Since there are currently no domestic operators of this engine model, notice and opportunity for public comment before issuing this AD are unnecessary.