

Note 1: Sikorsky Aircraft Corporation issued an All Operators Letter (AOL) CCS-61-AOL-04-0005, dated May 18, 2004, with an example and additional information about tracking cycles and the moving average procedure. You can obtain this AOL from the manufacturer at the address stated in the ADDRESSES portion of this AD.

(c) For each REL IFWU assembly, at intervals not to exceed 500 hours TIS or 7500 lift cycles, whichever occurs first, since the last IFWU assembly inspection:

(1) Inspect for wear, surface distress, and endplay by following paragraphs B.(1) through B.(6) of the Accomplishment Instructions of Sikorsky Aircraft Corporation Alert Service Bulletin No. 61B35-67B, Revision B, dated August 11, 2003 (ASB). Record all the information specified in Figures 1 through 3 attached to the ASB. You may record this information on any suitable maintenance record, or you may use the Sikorsky evaluation forms provided in the ASB. This AD does not require you to contact Sikorsky.

(2) Replace any IFWU assembly part whose average wear, wear marks, surface distress, or endplay exceeds the limits stated in paragraph B.(1) through B.(6) of the Accomplishment Instructions of the ASB with an airworthy IFWU assembly part.

Note 2: Sikorsky S-61 Overhaul Manual, Number SA 4045-83, Revision 20, dated August 15, 2003, as revised by Temporary Revisions 65-193, -194, -195, and -196, contains the overhaul procedures for the IFWU assembly.

(d) For each REL IFWU assembly, permanently mark IFWU camshafts, P/N S6135-20611, S6135-20614 and S6137-23075, and IFWU gear housings, P/N S6135-20695 and S6137-23057, with the letters "REL". Mark the camshafts by applying etching ink on the surface of the part that is 0.5 inch square with the depth of the letters not to exceed 0.001 inch. After etching, neutralize the etched surface and oil to prevent corrosion.

(e) For the next 24 months and within 10 days after completing the requirements of paragraph (c)(1) of this AD, provide a copy of the recorded information to the Manager of the Boston Aircraft Certification Office, Engine and Propeller Directorate, FAA, 12 New England Executive Park, Burlington, MA 01803.

Note 3: In the ASB, Sikorsky requests copies of the completed inspection forms, Figures 1 through 3 to their ASB. This AD does not require you to provide these forms to Sikorsky.

(f) Information collection requirements contained in this AD have been approved by the Office of Management and Budget (OMB) under the provisions of the Paperwork Reduction Act of 1980 (44 U.S.C. 3501 *et seq.*) and have been assigned OMB Control Number 2120-0056.

(g) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Boston Aircraft Certification Office, Engine and Propeller Directorate, FAA, ATTN: Kirk Gustafson, Aviation Safety Engineer, 12 New England

Executive Park, Burlington, MA 01803, telephone (781) 238-7190, fax (781) 238-7170, for information about previously approved alternative methods of compliance.

(h) The inspections shall be done by following the specified portions of Sikorsky Aircraft Corporation Alert Service Bulletin No. 61B35-67B, Revision B, dated August 11, 2003. The Director of the Federal Register approved this incorporation by reference in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Sikorsky Aircraft Corporation, Attn: Manager, Commercial Tech Support, 6900 Main Street, Stratford, Connecticut 06614, phone (203) 386-3001, fax (203) 386-5983. Copies may be inspected at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

(i) This amendment becomes effective on February 14, 2007.

Appendix I

Section I: The first moving average of lift cycles per hour TIS.

The first moving average calculation is performed on the IFWU assembly when the external lift component history card record reflects that the IFWU assembly has reached its first 250 hours TIS. To perform the calculation, divide the total number of lift cycles performed during the first 250 hours TIS by 250. The result will be the first moving average calculation of lift cycles per hour TIS.

Section II: Subsequent moving average of lift cycles per hour TIS.

Subsequent moving average calculations are performed on the IFWU assembly at intervals of 50 hour TIS after the first moving average calculation. Subtract the total number of lift cycles performed during the first 50-hour TIS interval used in the previous moving average calculation from the total number of lift cycles performed on the IFWU assembly during the previous 300 hours TIS. Divide this result by 250. The result will be the next or subsequent moving average calculation of lift cycles per hour TIS.

Section III: Sample calculation for subsequent 50 hour TIS intervals.

Assume the total number of lift cycles for the first 50 hour TIS interval used in the previous moving average calculation = 450 lift cycles and the total number of lift cycles for the previous 300 hours TIS = 2700 lift cycles. The subsequent moving average of lift cycles per hour TIS = (2700-450) divided by 250 = 9 lift cycles per hour TIS.

Issued in Fort Worth, Texas, on December 26, 2006.

David A. Downey,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. E7-40 Filed 1-9-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26128; Directorate Identifier 2006-NE-34-AD; Amendment 39-14875; AD 2007-01-04]

RIN 2120-AA64

Airworthiness Directives; Turbomeca Artouste III B and III B1 Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

3 cases of cracking due to exfoliation corrosion on the unions of fuel pipes P/N 0 202 12 800 0, connecting the Fuel Control Unit to the start electrovalve, were reported. These cases of cracking, if they had not previously been detected, could have caused a loss of integrity of the union conveying fuel under pressure. A fuel leakage could then have happened and would have led to an uncommanded loss of power and to a fire hazard. This AD requires the fuel pipe to be inspected for cracking.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

DATES: This AD becomes effective January 25, 2007.

The Director of the Federal Register approved the incorporation by reference of Turbomeca Mandatory Service Bulletin No. A218 73 0803, dated May 2, 2006, listed in the AD as of January 25, 2007.

We must receive comments on this AD by February 9, 2007.

ADDRESSES: You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC 20590-0001.

- *Hand Delivery:* Room PL-401 on the plaza level of the Nassif Building,

400 Seventh Street, SW., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

• *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7175; fax (781) 238-7199.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Discussion

The European Aviation Safety Agency (EASA), which is the aviation authority for the European Union, has issued Airworthiness Directive No. 2006-0154, dated June 1, 2006, (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

3 cases of cracking due to exfoliation corrosion on the unions of fuel pipes P/N 0 202 12 800 0, connecting the Fuel Control Unit to the start electrovalve, were reported. These cases of cracking, if they had not previously been detected, could have caused

a loss of integrity of the union conveying fuel under pressure. A fuel leakage could then have happened and would have led to an uncommanded loss of power and to a fire hazard. This AD requires the fuel pipe to be inspected for cracking.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Turbomeca has issued Mandatory Service Bulletin No. A218 73 0803, dated May 2, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA's Determination and Requirements of This AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all the information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Differences Between the AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the AD. These requirements take precedence over the actions copied from the MCAI.

FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because undetected cracking could cause loss of integrity of the union conveying fuel under pressure. This could result in a fuel leak and an uncommanded loss of power and a fire hazard. Therefore, we determined

that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2006-26128; Directorate Identifier 2006-NE-34-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-01-04 Turbomeca: Amendment 39-14875. Docket No. FAA-2006-26128; Directorate Identifier 2006-NE-34-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective January 25, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Artouste III B and III B1 turboshaft engines fitted with a fuel pipe, part number 0 202 12 800 0. These engines are installed on SA 315 B LAMA and SA 316 B Alouette III helicopters.

Reason

(d) European Aviation Safety Agency, (EASA), Airworthiness Directive No. 2006-0154, dated June 1, 2006, states:

3 cases of cracking due to exfoliation corrosion on the unions of fuel pipes P/N 0 202 12 800 0, connecting the Fuel Control Unit to the start electrovalve, were reported. These cases of cracking, if they had not previously been detected, could have caused a loss of integrity of the union conveying fuel under pressure. A fuel leakage could then have happened and would have led to an uncommanded loss of power and to a fire hazard. This AD requires the fuel pipe to be inspected for cracking.

FAA AD Differences

(e) None.

Actions and Compliance

(f) At the next maintenance action on the engine or airframe, but no later than 30 days after the effective date of this AD, unless already done, do the following action.

(1) Inspect for cracks in the lower union of the flexible fuel pipe between the electric fuel cock and the start valve.

(2) Use the instructions contained in paragraph 2 of Turbomeca Mandatory Service Bulletin No. A218 73 0803, dated May 2, 2006, to do the inspection.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Engine Certification Office, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to the EASA Airworthiness Directive 2006-0154, dated June 1, 2006, and Turbomeca Mandatory Service Bulletin A218 73 0803, dated May 2, 2006, for related information.

(i) Contact Christopher Spinney, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; telephone (781) 238-7175; fax (781) 238-7199, for more information about this AD.

Material Incorporated by Reference

(j) You must use Turbomeca Mandatory Service Bulletin No. A218 73 0803, dated May 2, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Turbomeca, 40220 Tarnos, France; telephone (33) 05 59 74 40 00; fax (33) 05 59 74 45 15.

(3) You may review copies at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on December 27, 2006.

Ann C. Mollica,

Acting Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E6-22533 Filed 1-9-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25089; Directorate Identifier 2006-NM-091-AD; Amendment 39-14873; AD 2007-01-02]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model MD-11 and -11F Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to certain McDonnell Douglas Model MD-11 and -11F airplanes. That AD currently requires an initial general visual inspection of the power feeder cables of the integrated drive generator (IDG) and the fuel feed lines of engine pylons No. 1 and No. 3 on the wings for proper clearance and damage; corrective actions if necessary; and repetitive general visual inspections and a terminating action for the repetitive inspections. This new AD requires the existing actions, and for certain airplanes, this AD requires installation of new clamps on the power feeder cables of the IDG of engine pylons No. 1 and No. 3. This AD results from reports of IDG power feeder cables riding against structure and fuel lines in the No. 1 and No. 3 pylons. We are issuing this AD to prevent potential chafing of the power feeder cables of the IDG in engine pylons No. 1 and No. 3 on the wings, and consequent arcing on the fuel lines in the engine pylons and possible fuel fire.

DATES: This AD becomes effective February 14, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of February 14, 2007.

On February 24, 2004 (69 FR 2657, January 20, 2004), the Director of the Federal Register approved the incorporation by reference of Boeing Alert Service Bulletin MD11-54A011, Revision 02, dated May 31, 2002.