

thereafter at intervals not to exceed 2,500 flight cycles.

**Note 1:** For the purposes of this AD, a detailed inspection is: "An intensive examination of a specific item, installation, or assembly to detect damage, failure, or irregularity. Available lighting is normally supplemented with a direct source of good lighting at an intensity deemed appropriate. Inspection aids such as mirror, magnifying lenses, etc., may be necessary. Surface cleaning and elaborate procedures may be required."

#### Corrective Actions

(g) If any damaged, missing or incorrectly installed wiper rings, rubber gaiters, or straps are found during any inspection required by paragraph (f) of this AD: Within 400 flight cycles after accomplishing the inspection, replace the applicable component with a serviceable component in accordance with the Accomplishment Instructions of Airbus Service Bulletin A310-27-2099, dated February 17, 2006.

#### Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

#### Related Information

(i) The European Aviation Safety Agency's airworthiness directive 2006-0111, dated May 12, 2006, also addresses the subject of this AD.

#### Material Incorporated by Reference

(j) You must use Airbus Service Bulletin A310-27-2099, dated February 17, 2006, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr/locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr/locations.html).

Issued in Renton, Washington, on January 16, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-1080 Filed 1-25-07; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2006-25219; Directorate Identifier 2005-NM-259-AD; Amendment 39-14907; AD 2007-02-20]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Fokker Model F27 Mark 050 and F.28 Mark 0070 and 0100 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Fokker Model F27 Mark 050 and F.28 Mark 0070 and 0100 airplanes. This AD requires repetitively removing the two existing escape rope assemblies in the flight compartment and installing new escape rope assemblies. This AD results from reports of findings of small cracks in the polyester assembly block in which the cotton escape rope is stored. A test revealed that the escape ropes had deteriorated over time, and the load capability was considerably reduced. We are issuing this AD to ensure that flightcrew members safely reach the ground after exiting the flight compartment window during an emergency evacuation.

**DATES:** This AD becomes effective March 2, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 2, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601

Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149.

#### **SUPPLEMENTARY INFORMATION:**

##### **Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

##### **Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Fokker Model F27 Mark 050 and Model F.28 Mark 0070 and 0100 airplanes. That NPRM was published in the **Federal Register** on June 30, 2006 (71 FR 37510). That NPRM proposed to require repetitively removing the two existing escape rope assemblies in the flight compartment and installing new escape rope assemblies.

##### **Comments**

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

##### **Request To Change Incorporation of Certain Service Information**

The Modification and Replacement Parts Association (MARPA) states that, typically, airworthiness directives are based on service information originating with the type certificate holder or its suppliers. MARPA adds that manufacturer service documents are privately authored instruments generally having copyright protection against duplication and distribution. MARPA notes that when a service document is incorporated by reference into a public document, such as an airworthiness directive, it loses its private, protected status and becomes a public document. MARPA adds that if a service document is used as a mandatory element of compliance, it should not simply be referenced, but should be incorporated into the regulatory document; by definition, public laws must be public, which means they cannot rely upon private writings. MARPA adds that incorporated by reference service documents should be made available to the public by publication in the Docket Management System (DMS), keyed to

the action that incorporates them. MARPA notes that the stated purpose of the incorporation by reference method is brevity, to keep from expanding the **Federal Register** needlessly by publishing documents already in the hands of the affected individuals; traditionally, "affected individuals" means aircraft owners and operators, who are generally provided service information by the manufacturer. MARPA adds that a new class of affected individuals has emerged, since the majority of aircraft maintenance is now performed by specialty shops instead of aircraft owners and operators. MARPA notes that this new class includes maintenance and repair organizations, component servicing and repair shops, parts purveyors and distributors, and organizations manufacturing or servicing alternatively certified parts under section 21.303 ("Replacement and modification parts") of the Federal Aviation Regulations (14 CFR 21.303). MARPA adds that the concept of brevity is now nearly archaic as documents exist more frequently in electronic format than on paper. Therefore, MARPA asks that the service documents deemed essential to the accomplishment of the NPRM be incorporated by reference into the regulatory instrument, and published in the DMS.

We understand MARPA's comment concerning incorporation by reference. The Office of the Federal Register (OFR) requires that documents that are necessary to accomplish the requirements of the AD be incorporated by reference during the final rule phase of rulemaking. This final rule incorporates by reference the document necessary for the accomplishment of the actions required by this AD. Further, we point out that while documents that are incorporated by reference do become public information, they do not lose their copyright protection. For that reason, we advise the public to contact the manufacturer to obtain copies of the referenced service information. We agree that incorporation by reference was authorized to reduce the volume of material published in the **Federal Register** and the Code of Federal Regulations. However, as specified in the Federal Register Document Drafting Handbook, the Director of the Office of the Federal Register (OFR) decides when an agency may incorporate material by reference. As the commenter is aware, the OFR files documents for public inspection on the workday before the date of publication of the rule at its office in Washington, DC. As stated in the Federal Register Document Drafting

Handbook, when documents are filed for public inspection, anyone may inspect or copy filed documents during the OFR's hours of business. Further questions regarding publication of documents in the **Federal Register** or incorporation by reference should be directed to the OFR.

In addition, regarding the commenter's request to post service bulletins on the Department of Transportation's DMS, we are currently in the process of reviewing issues surrounding the posting of service bulletins on the DMS as part of an AD docket. Once we have thoroughly examined all aspects of this issue and have made a final determination, we will consider whether our current practice needs to be revised. No change to the AD is necessary in response to this comment.

#### Conclusion

We have carefully reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD as proposed.

#### Costs of Compliance

This AD affects about 2 airplanes of U.S. registry. The removal and installation take about 2 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts cost between \$387 and \$425 per airplane, depending on airplane configuration. Based on these figures, the estimated cost of the AD for U.S. operators is between \$1,094 and \$1,170, or between \$547 and \$585 per airplane, per removal and installation.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2007-02-20 Fokker Services B.V.:**  
Amendment 39-14907. Docket No. FAA-2006-25219; Directorate Identifier 2005-NM-259-AD.

#### Effective Date

- (a) This AD becomes effective March 2, 2007.

#### Affected ADs

- (b) None.

#### Applicability

- (c) This AD applies to Fokker Model F27 Mark 050 and F.28 Mark 0070 and 0100 airplanes, certificated in any category; with escape rope assemblies in the flight compartment.

**Unsafe Condition**

(d) This AD results from reports of findings of small cracks in the polyester assembly block in which the cotton escape rope is stored. A test revealed that the escape ropes had deteriorated over time, and the load capability was considerably reduced. We are issuing this AD to ensure that flightcrew members safely reach the ground after exiting the flight compartment window during an emergency evacuation.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Replacement**

(f) Within 12 months after the effective date of this AD: Remove the two existing escape rope assemblies in the flight compartment and install new escape rope assemblies in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF50-25-059 (for Model F27 Mark 050 airplanes); and Fokker Service Bulletin SBF100-25-099 (for Model F.28 Mark 0070 and 0100 airplanes); both dated June 28, 2004. Repeat the removal and installation thereafter at intervals not to exceed 72 months.

**Alternative Methods of Compliance (AMOCs)**

(g)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

**Related Information**

(h) Dutch airworthiness directive 2004-159, dated December 24, 2004, also addresses the subject of this AD.

**Material Incorporated by Reference**

(i) You must use Fokker Service Bulletin SBF50-25-059, dated June 28, 2004; or Fokker Service Bulletin SBF100-25-099, dated June 28, 2004; as applicable; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Fokker Services B.V., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands, for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401, Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Renton, Washington, on January 17, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-1078 Filed 1-25-07; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2006-25891; Directorate Identifier 2006-NM-186-AD; Amendment 39-14908; AD 2007-02-21]**

**RIN 2120-AA64**

**Airworthiness Directives; Airbus Model A300 Airplanes; and Model A300 B4-600, B4-600R, and F4-600R Series Airplanes, and Model C4-605R Variant F Airplanes (Collectively Called A300-600 Series Airplanes)**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain Airbus Model A300 airplanes; and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model C4-605R Variant F airplanes (collectively called A300-600 series airplanes). This AD requires replacing the pressure limiter of the parking brake system with a new or modified pressure limiter. This AD results from a report indicating that failure of the parking brake system occurred on a Model A300-600 airplane. We are issuing this AD to prevent failure of the parking brake system and interference with emergency use of the brake pedals, which could lead to airplane collision with surrounding objects or departure from the runway.

**DATES:** This AD becomes effective March 2, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 2, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for service information identified in this AD.

**FOR FURTHER INFORMATION CONTACT:** Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Examining the Docket**

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

**Discussion**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain Airbus Model A300 and A310 airplanes; and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model C4-605R Variant F airplanes (collectively called A300-600 series airplanes). That NPRM was published in the **Federal Register** on September 26, 2006 (71 FR 56054). That NPRM proposed to require replacing the pressure limiter of the parking brake system with a new or modified pressure limiter.

**Comments**

We provided the public the opportunity to participate in the development of this AD. We have considered the comments received.

**Request To Refer To Revised Service Information**

Airbus has informed us that the applicable service bulletins identified in the NPRM have all been reissued at Revision 01, and requests that we revise the NPRM to refer to Airbus Service Bulletins A300-32-0448 and A300-32-6094, both Revision 01, both dated October 26, 2006. However, Airbus has determined that the subject modification is incompatible with Model A310 airplanes and informed the European Aviation Safety Agency (EASA) of this situation. Airbus states that:

- EASA intends to revise EASA airworthiness directive 2006-0178, dated June 26, 2006, to remove Model A310 airplanes from the effectivity;
- Airbus intends to issue a new revision of Service Bulletin A310-32-2133 with a revised modification for Model A310 airplanes; and