

(f) The Australian AD allows an appropriately trained pilot to perform the visual inspections of the canard inboard flap hinge support brackets. Although the Malaysian AD does not specifically state this, it does refer to the Australian AD. Regardless, the Federal Aviation Regulations (14 CFR 43.3) only allow the pilot to perform preventive maintenance as described in 14 CFR part 43, App. A, paragraph (c). These visual inspections are not considered preventive maintenance under 14 CFR part 43, App. A, paragraph (c). Therefore, an appropriately-rated mechanic must perform all actions of this AD.

Special Flight Permit

(g) Special flight permits are not allowed for this AD. Part 39 of the Federal Aviation Regulations (14 CFR part 39) provides that FAA may issue special flight permits for ADs, unless otherwise specified in the individual AD. The FAA has determined that the safety issue is severe enough that failure of the canard inboard flap hinge support brackets must be prevented and cracks in this area must be detected before further operation.

Alternative Methods of Compliance (AMOCs)

(h) The Manager, Standards Staff, FAA, ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(i) AMOCs approved for AD 2004-11-04 are approved for this AD.

Related Information

(j) Malaysian AD No. CAM AD 001-01-2004 R1, dated December 23, 2005; and Australian AD No. CASA AD/X-TS/5, dated August 21, 2003, revised April 2, 2004, also address the subject of this AD.

Material Incorporated by Reference

(k) You must use Eagle Aircraft Mandatory Service Bulletin SB 1120, Original, Effective Date June 3, 2005; and Eagle Aircraft Mandatory Service Bulletin SB 1109, Revision Original, Effective Date August 29, 2003 to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Eagle Aircraft Mandatory Service Bulletin SB 1120, Original, Effective Date June 3, 2005, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) On June 4, 2004 (69 FR 30189, May 27, 2004), the Director of the Federal Register previously approved the incorporation by reference of Eagle Aircraft Mandatory Service Bulletin SB 1109, Revision Original, Effective Date August 29, 2003.

(3) For service information identified in this AD, contact CTRM Aviation Sdn. Bhd. (formerly known as Eagle Aircraft Sdn. Bhd.), Locked Bag 1028, Pejabat Pos Besar Melaka, 75150 Melaka, Malaysia; telephone: 06 317 1007; fax: 06 317 7023.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Kansas City, Missouri

64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Kansas City, Missouri, on February 5, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-2319 Filed 2-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26285; Directorate Identifier 2006-CE-69-AD; Amendment 39-14932; AD 2007-04-01]

RIN 2120-AA64

Airworthiness Directives; Pacific Aerospace Corporation Ltd Model 750XL Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as possible installation of undersize rivets in the fuselage roof at STN 180.85, BL 19.67, WL 86.2. We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective March 21, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 21, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Streamlined Issuance of AD

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. The streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on December 11, 2006 (71 FR 71499). That NPRM proposed to require that you inspect the rivets in the fuselage roof at STN 180.85, BL 19.67, WL 86.2, and replace undersize rivets.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable in a U.S. court of law. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the AD. These requirements, if any, take precedence over the actions copied from the MCAI.

Costs of Compliance

We estimate that this AD will affect 7 products of U.S. registry. We also

estimate that it will take about 16 work-hours per product to comply with this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$100 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$9,660, or \$1,380 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5227) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

* * * **Pacific Aerospace Corporation Ltd:**
Amendment 39-14932; Docket No.
FAA-2006-26285; Directorate Identifier
2006-CE-69-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective March 21, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Model 750XL airplanes, serial numbers 102, 104 through 120, 122, and 125, certificated in any category.

Reason

(d) The mandatory continuing airworthiness information (MCAI) states the finding of the possible installation of undersize rivets in the fuselage roof at STN 180.85, BL 19.67, WL 86.2.

Actions and Compliance

(e) Unless already done, within the next 150 hours time-in-service after the effective date of this AD, inspect the rivets in the fuselage roof at STN 180.85, BL 19.67, WL 86.2, and replace undersize rivets, following PAC Pacific Aerospace Corporation Mandatory Service Bulletin PACSB/XL/019, Date Issued: April 21, 2006.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows:
No differences.

Other FAA AD Provisions

(f) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Staff, FAA, ATTN: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et. seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(g) Refer to MCAI New Zealand Civil Aviation Authority AD DCA/750XL/8, Drafted: May 9, 2006; Effective Date: August 31, 2006; and PAC Pacific Aerospace Corporation Mandatory Service Bulletin PACSB/XL/019, Date Issued: April 21, 2006, for related information.

Material Incorporated by Reference

(h) You must use PAC Pacific Aerospace Corporation Mandatory Service Bulletin PACSB/XL/019, Date Issued: April 21, 2006, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Pacific Aerospace Corporation Ltd., Hamilton Airport, Private Bag HN 3027, Hamilton, New Zealand; telephone: 011 64 7 843 6144; fax: 011 64 7 843 6134.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on February 5, 2007.

David R. Showers,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-2318 Filed 2-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-25925; Directorate Identifier 2006-NM-167-AD; Amendment 39-14934; AD 2007-04-03]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135 Airplanes and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to all EMBRAER Model EMB-135 airplanes and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. That AD currently requires repetitive inspections of the pitot static heating relay K0057 and corrective actions if necessary. That AD also requires doing a terminating modification, which ends the repetitive inspections. This new AD removes the existing repetitive inspections and instead requires a one-time detailed inspection for damage of the relay, relay socket, and silicone gasket; applicable corrective actions; and a new action to modify and re-identify the relay socket. This AD also revises the existing terminating modification—replacing/rerouting the windowsill drain hoses—into two parts, each with a different, reduced compliance time. This AD results from a report of smoke in the cockpit. We are issuing this AD to prevent ignition of a windowsill drain hose by an overheated relay, which could cause fire and smoke in the cockpit.

DATES: This AD becomes effective March 21, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 21, 2007.

ADDRESSES: You may examine the AD docket on the Internet at [http://](http://dms.dot.gov)

dms.dot.gov or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343-CEP 12.225, Sao Jose dos Campos-SP, Brazil, for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the

ADDRESSES section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 2006-04-02, amendment 39-14483 (71 FR 9434, February 24, 2006). The existing AD applies to all EMBRAER Model EMB-135 airplanes, and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. That NPRM was published in the **Federal Register** on September 28, 2006 (71 FR 56900). That NPRM proposed to remove the existing repetitive inspections and instead to require a one-time detailed inspection for damage of the relay, relay socket, and silicone gasket; applicable corrective actions; and a new action to modify and re-identify the relay socket. That NPRM also proposed to revise the existing terminating modification—replacing/rerouting the windowsill drain hoses—into two parts, each with a different, reduced compliance time.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments that have been received on the NPRM.

Request To Allow Use of Existing Alternative Method of Compliance (AMOC)

One commenter, ExpressJet Inc., requests that we allow for termination of certain repetitive inspections described in the NPRM. The commenter states that it has received AMOC number ANM-116-06-244 to AD 2006-04-02, which allows ending the repetitive relay inspections described in EMBRAER Service Bulletin 145-30-0042 once EMBRAER Alert Service Bulletin 145-30-A050 is accomplished; and, further, that doing EMBRAER Service Bulletin 145-30-0041 also provides terminating action for the repetitive inspections. The commenter states that paragraph (f) of the NPRM proposes to require repetitive inspections as described in EMBRAER Alert Service Bulletin 145-30-A050 until EMBRAER Service Bulletin 145-30-0041 is accomplished, and requests that we revise the NPRM to allow those inspections to be terminated if the modification described in either EMBRAER Alert Service Bulletin 145-30-A050 or EMBRAER Service Bulletin 145-30-0041 is accomplished in accordance with the AMOC.

We find that clarification is necessary. This AD cancels the repetitive inspections required by AD 2006-04-02, which cites EMBRAER Service Bulletins 145LEG-30-0012 and 145-30-0042, both dated April 18, 2005, as the appropriate sources of service information for doing the repetitive inspections. EMBRAER Alert Service Bulletins 145LEG-30-A017 and 145-30-A050, both dated May 31, 2006, supersede Service Bulletins 145LEG-30-0012 and 145-30-0042, respectively, and replace the repetitive inspections with a one-time only inspection. Therefore, as of the effective date of this AD, the repetitive inspections are no longer required. No change is needed to the AD in this regard.

Request To Change Incorporation of Certain Information

One commenter, the Modification and Replacement Parts Association (MARPA), requests that we revise our procedures for incorporation by reference (IBR) of service information in ADs. MARPA asserts that ADs are frequently derived from privately-authored, copyright-protected manufacturer service documents, but that when such a document is incorporated by reference into a public document like an AD, it loses its private, protected status and becomes itself a public document. MARPA continues that public laws by definition must be public and cannot rely for