

(2) As an option, the service bulletin allows repairs specified in an approved BAE Systems repair scheme. This AD instead requires any repair using this option to be done in accordance with a method approved by either the Manager, International Branch, ANM-116, FAA; or the European Aviation Safety Agency (or its delegated agent).

Alternative Methods of Compliance (AMOCs)

(h)(1) The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Related Information

(i) The subject of this AD is also addressed in European Aviation Safety Agency emergency airworthiness directive 2006-0091-E, dated April 20, 2006.

Material Incorporated by Reference

(j) You must use BAE Systems (Operations) Limited Alert Inspection Service Bulletin ISB.57-a071, dated April 12, 2006, to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of this document in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact British Aerospace Regional Aircraft American Support, 13850 Mclearn Road, Herndon, Virginia 20171, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 5, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. E7-2414 Filed 2-13-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2006-26084; Directorate Identifier 2006-NM-063-AD; Amendment 39-14937; AD 2007-04-06]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model DC-8-62, DC-8-63, DC-8-62F, and DC-8-63F Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain McDonnell Douglas Model DC-8-62, DC-8-63, DC-8-62F, and DC-8-63F airplanes. This AD requires revising the wiring for the engine thrust brake circuit and indicating circuit and other specified actions, or rerouting the wiring at plug P1-1762A on the electrical power center generator control panel, as necessary. This AD results from the determination that the thrust reverser systems on these airplanes do not adequately preclude inadvertent deployment of the thrust reversers. We are issuing this AD to prevent inadvertent deployment of the thrust reversers during takeoff or landing, which could result in loss of control of the airplane.

DATES: This AD becomes effective March 21, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of March 21, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Nassif Building, Room PL-401, Washington, DC.

Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for service information identified in this AD.

FOR FURTHER INFORMATION CONTACT: William Bond, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5253; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Examining the Docket

You may examine the airworthiness directive (AD) docket on the Internet at <http://dms.dot.gov> or in person at the Docket Management Facility office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Management Facility office (telephone (800) 647-5227) is located on the plaza level of the Nassif Building at the street address stated in the **ADDRESSES** section.

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to certain McDonnell Douglas Model DC-8-62, DC-8-63, DC-8-62F, and DC-8-63F airplanes. That NPRM was published in the **Federal Register** on October 19, 2006 (71 FR 61690). That NPRM proposed to require revising the wiring for the engine thrust brake circuit and indicating circuit and other specified actions, or rerouting the wiring at plug P1-1762A on the electrical power center generator control panel, as necessary.

Comments

We provided the public the opportunity to participate in the development of this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We have carefully reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Costs of Compliance

There are about 70 airplanes of the affected design in the worldwide fleet. This AD affects about 45 airplanes of U.S. registry. The required actions take between 1 and 5 work hours per airplane, depending on airplane configuration, at an average labor rate of \$80 per work hour. For a certain airplane configuration, required parts cost about \$9 per airplane. For a certain other airplane configuration, required parts cost about \$2,825 per airplane. Based on these figures, the estimated cost of this AD for U.S. operators is between \$4,005 and \$145,125, or between \$89 and \$3,225 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more

detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

2007-04-06 McDonnell Douglas:
Amendment 39-14937. Docket No. FAA-2006-26084; Directorate Identifier 2006-NM-063-AD.

Effective Date

(a) This AD becomes effective March 21, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas Model DC-8-62 and DC-8-63 airplanes and Model DC-8-62F and DC-8-63F airplanes, certificated in any category; as identified in McDonnell Douglas DC-8 Service Bulletin 78-95, Revision 2, dated March 10, 1971.

Unsafe Condition

(d) This AD results from the determination that the thrust reverser systems on McDonnell Douglas Model DC-8-62, DC-8-63, DC-8-62F, and DC-8-63F airplanes do not adequately preclude inadvertent deployment of the thrust reversers. We are issuing this AD to prevent inadvertent

deployment of the thrust reversers during takeoff or landing, which could result in loss of control of the airplane.

Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Modification of Engine Thrust Brake Circuitry

(f) Within 27 months after the effective date of this AD, do the applicable action specified in paragraph (f)(1) or (f)(2) of this AD, by accomplishing all of the applicable actions specified in the Accomplishment Instructions of McDonnell Douglas DC-8 Service Bulletin 78-95, Revision 2, dated March 10, 1971; or Revision 1, dated December 29, 1970.

(1) Revise the wiring for the engine thrust brake circuit and indicating circuit, and do all other specified actions before further flight after revising the wiring.

(2) Reroute the wiring at plug P1-1762A on the electrical power center generator control panel.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) Before using any AMOC approved in accordance with § 39.19 on any airplane to which the AMOC applies, notify the appropriate principal inspector in the FAA Flight Standards Certificate Holding District Office.

Material Incorporated by Reference

(h) You must use McDonnell Douglas DC-8 Service Bulletin 78-95, Revision 2, dated March 10, 1971; or McDonnell Douglas DC-8 Service Bulletin 78-95, Revision 1, dated December 29, 1970; to perform the actions that are required by this AD, unless the AD specifies otherwise. McDonnell Douglas DC-8 Service Bulletin 78-95, Revision 2, dated March 10, 1971, contains the following effective pages:

Page number	Revision level shown on page	Date shown on page
1, 2, 16, 17	2	March 10, 1971.
3-15, 18-23	1	December 29, 1970.

The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846, Attention: Data and Service Management, Dept. C1-L5A (D800-0024), for a copy of this service information. You may review copies at the Docket Management Facility, U.S. Department of Transportation, 400 Seventh Street, SW., Room PL-401,

Nassif Building, Washington, DC; on the Internet at <http://dms.dot.gov>; or at the National Archives and Records Administration (NARA). For information on the availability of this material at the NARA, call (202) 741-6030, or go to http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 2, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-2416 Filed 2-13-07; 8:45 am]

BILLING CODE 4910-13-P