

# Proposed Rules

Federal Register

Vol. 72, No. 153

Thursday, August 9, 2007

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-28883; Directorate Identifier 2007-NM-106-AD]

RIN 2120-AA64

#### Airworthiness Directives; Hawker Beechcraft Model 400A Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Hawker Beechcraft Model 400A series airplanes. This proposed AD would require inspecting the galley cabinets to determine if a certain part number is installed or if a certain size of wire already exists, and doing related investigative/corrective actions if necessary. This proposed AD results from reports of undersized, and consequently unprotected, wire in the galley cabinets. We are proposing this AD to prevent overheating of wire insulation and consequent fire or smoke in the airplane cabin.

**DATES:** We must receive comments on this proposed AD by September 24, 2007.

**ADDRESSES:** Use one of the following addresses to submit comments on this proposed AD.

- *DOT Docket Web site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Government-wide rulemaking Web site:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Fax:* (202) 493-2251.

- *Hand Delivery:* Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Contact Hawker Beechcraft Corporation, 9709 East Central, Wichita, Kansas 67206, for the service information identified in this proposed AD.

#### FOR FURTHER INFORMATION CONTACT:

Philip Petty, Aerospace Engineer, Electrical Systems and Avionics, ACE-119W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Mid-Continent Airport, Wichita, Kansas 67209; telephone (316) 946-4139; fax (316) 946-4107.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to submit any relevant written data, views, or arguments regarding this proposed AD. Send your comments to an address listed in the **ADDRESSES** section. Include the docket number "FAA-2007-28883; Directorate Identifier 2007-NM-106-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD. Using the search function of that web site, anyone can find and read the comments in any of our dockets, including the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78), or you may visit <http://dms.dot.gov>.

#### Examining the Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>, or in person at the Docket Operations office

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located on the ground level of the West Building at the DOT street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after the Docket Management System receives them.

#### Discussion

We have received reports of undersized, and consequently unprotected, wire in the galley cabinets, on Hawker Beechcraft Model 400A series airplanes. The electrical current-carrying capacity of the main bus power wiring installed in the galley cabinet(s) is not capable of supporting the trip rating of the airframe 50 amp galley power (50A) circuit breaker. This condition, if not corrected, could result in overheating of wire insulation and consequent fire or smoke in the airplane cabin.

#### Relevant Service Information

We have reviewed Raytheon Service Bulletin SB 25-3758, dated June 2006. The service information describes procedures for inspecting the galley cabinets to determine if Precision Pattern galley cabinet, part number (P/N) 20917, 20918, or 20921, is installed, or if 8AWG (American Wire Gauge) wire already exists; and doing any related investigative and applicable corrective actions, if necessary. The related investigative action is a visual inspection of the galley power wire for presence of 10AWG wire. The corrective action is replacing the undersized 10AWG wire with 8AWG wire in the gallery power circuit. Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

Raytheon Service Bulletin SB 25-3758, dated June 2006, refers to Raytheon Kit 128-3068-0001, Revision 3, dated April 18, 2006, as an additional source of service information for replacing the undersized 10AWG wire with 8AWG wire in the gallery power circuit.

#### FAA's Determination and Requirements of the Proposed AD

We have evaluated all pertinent information and identified an unsafe condition that is likely to exist or develop on other airplanes of this same

type design. For this reason, we are proposing this AD, which would require accomplishing the actions specified in the service information described previously.

#### Differences Between the Proposed AD and Service Information

Raytheon Service Bulletin SB 25–3758 does not specify a compliance time for accomplishing the related investigative and applicable corrective actions after inspecting the galley cabinets. This proposed AD would require those applicable actions within 20 flight hours or 30 days after inspecting the galley cabinets. In developing an appropriate compliance time, we considered the safety implications, the time necessary to perform the related investigative and applicable corrective actions, and normal maintenance schedules for timely accomplishment of those actions. In light of these items, we have determined that a compliance time of 20 flight hours or 30 days after inspecting the galley cabinet is appropriate. We have coordinated this difference with Hawker Beechcraft.

#### Costs of Compliance

There are about 285 airplanes of the affected design in the worldwide fleet. This proposed AD would affect about 214 airplanes of U.S. registry. The proposed inspection would take about 1 work hour per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the proposed AD for U.S. operators is \$17,120, or \$80 per airplane.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended].

2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**Hawker Beechcraft Corporation:** Docket No. FAA–2007–28883; Directorate Identifier 2007–NM–106–AD.

#### Comments Due Date

(a) The FAA must receive comments on this AD action by September 24, 2007.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to Hawker Beechcraft Model 400A series airplanes, certificated in any category; as identified in Raytheon Service Bulletin SB 25–3758, dated June 2006.

#### Unsafe Condition

(d) This AD results from reports of undersized, and consequently unprotected, wire in the galley cabinets. We are issuing this AD to prevent overheating of wire insulation and consequent fire or smoke in the airplane cabin.

#### Compliance

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

#### Inspection and Related Investigative/Corrective Actions

(f) Within 200 flight hours or 12 months after the effective date of this AD, whichever occurs first, inspect the galley cabinets to determine if Precision Pattern galley cabinet, part number (P/N) 20917, 20918, or 20921, is installed, or if 8 American Wire Gauge (AWG) wire already exists, and within 20 flight hours or 30 days after the inspection, do all applicable related investigative and corrective actions, if necessary. The actions must be done in accordance with the Accomplishment Instructions of Raytheon Service Bulletin SB 25–3758, dated June 2006.

**Note 1:** Raytheon Service Bulletin SB 25–3758, dated June 2006, refers to Raytheon Kit 128–3068–0001, Revision 3, dated April 18, 2006, as an additional source of service information for replacing the undersized 10AWG wire with 8AWG wire in the gallery power circuit.

#### Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Issued in Renton, Washington, on July 30, 2007.

#### Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7–15424 Filed 8–8–07; 8:45 am]

**BILLING CODE 4910–13–P**