

compliance with the corresponding actions of this AD.

#### Alternative Methods of Compliance (AMOCs)

(k)(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) AMOCs approved previously in accordance with AD 2006-10-04, are approved as AMOCs for the corresponding provisions of this AD.

(3) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(4) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD, if it is approved by an Authorized Representative for the Boeing Commercial Airplanes Delegation Option Authorization Organization who has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

Issued in Renton, Washington, on July 30, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-16121 Filed 8-15-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-28922; Directorate Identifier 2007-NM-132-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A310 Series Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

An incident occurred on one A300-600 aircraft at parking brake application. Both

engines were running, the aircraft started moving again despite parking brake application. Captain tried to stop the aircraft via the pedals but, as the parking brake selector valve was selected, the aircraft could not be stopped (as per design, activation of the parking brake inhibits the other braking modes, and consequently prevents the recovery of the normal braking through the pedals). As part of the investigation, the pressure limiter was removed and examined. The expertise revealed a metallic wire aimed at reducing the section of one port of this equipment was found broken. A part of this wire partially obstructed the hole receiving this wire, thus delaying the build up of parking brake pressure.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by September 17, 2007.

**ADDRESSES:** You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-28922; Directorate Identifier 2007-NM-132-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://dms.dot.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2007-0151, dated May 22, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

An incident occurred on one A300-600 aircraft at parking brake application. Both engines were running, the aircraft started moving again despite parking brake application. Captain tried to stop the aircraft via the pedals but, as the parking brake selector valve was selected, the aircraft could not be stopped (as per design, activation of the parking brake inhibits the other braking modes, and consequently prevents the recovery of the normal braking through the pedals). As part of the investigation, the pressure limiter was removed and examined. The expertise revealed a metallic wire aimed at reducing the section of one port of this equipment was found broken. A part of this wire partially obstructed the hole receiving this wire, thus delaying the build up of parking brake pressure. In order to avoid recurrence of the failure mode described above, EASA issued Airworthiness Directive (AD) 2006-0178 to require the replacement of the parking brake pressure limiter (FIN 323292).

During embodiment of SB (Service Bulletin) 32-2133 on an A310 as per AD 2006-0178 (EASA AD 2006-0178 corresponds to FAA AD 2007-02-21, amendment 39-14908), an operator reported that the modified pressure limiter could not be fitted. Subsequent investigation concluded that A310 installation being slightly different from A300-600 aircraft, the approved solution was not directly adaptable to A310 aircraft.

\* \* \* This new AD, dealing with the same subject, requires the replacement of the brake pressure limiter by accomplishment of Airbus SB A310-32-2133, which has been

revised to include the adaptation kit for A310 aircraft.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Airbus has issued Service Bulletin A310-32-2133, Revision 02, dated February 26, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 68 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Labor costs may be covered under warranty as described in the service information. Required parts would cost about \$0 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties,

some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$32,640, or \$480 per product.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**AIRBUS:** Docket No. FAA-2007-28922; Directorate Identifier 2007-NM-132-AD.

#### Comments Due Date

(a) We must receive comments by September 17, 2007.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to Airbus Model A310 series airplanes, certificated in any category, except airplanes on which Airbus Service Bulletin A310-32-2133, Revision 02, dated February 26, 2007, has been embodied in service.

#### Subject

(d) Air Transport Association (ATA) of America Code 32: Landing gear.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states: An incident occurred on one A300-600 aircraft at parking brake application. Both engines were running, the aircraft started moving again despite parking brake application. Captain tried to stop the aircraft via the pedals but, as the parking brake selector valve was selected, the aircraft could not be stopped (as per design, activation of the parking brake inhibits the other braking modes, and consequently prevents the recovery of the normal braking through the pedals). As part of the investigation, the pressure limiter was removed and examined. The expertise revealed a metallic wire aimed at reducing the section of one port of this equipment was found broken. A part of this wire partially obstructed the hole receiving this wire, thus delaying the build up of parking brake pressure. In order to avoid recurrence of the failure mode described above, EASA (European Aviation Safety Agency), issued Airworthiness Directive (AD) 2006-0178 to require the replacement of the parking brake pressure limiter (FIN 323292).

During embodiment of SB (Service Bulletin) 32-2133 on an A310 as per AD 2006-0178 [EASA AD 2006-0178 corresponds to FAA AD 2007-02-21, amendment 39-14908], an operator reported that the modified pressure limiter could not be fitted. Subsequent investigation concluded that A310 installation being slightly different from A300-600 aircraft, the approved solution was not directly adaptable to A310 aircraft.

\* \* \* This new AD, dealing with the same subject, requires the replacement of the brake pressure limiter by accomplishment of Airbus SB A310-32-2133, which has been revised to include the adaptation kit for A310 aircraft.

**Actions and Compliance**

(f) Unless already done, do the following actions.

(1) Within 10 months after the effective date of this AD, replace the parking brake pressure limiter (FIN 323292), in accordance with the instructions given in Airbus Service Bulletin A310-32-2133, Revision 02, dated February 26, 2007.

**FAA AD Differences**

**Note:** This AD differs from the MCAI and/or service information as follows: No difference.

**Other FAA AD Provisions**

(g) The following provisions also apply to this AD:

(1) **Alternative Methods of Compliance (AMOCs):** The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

**Related Information**

(h) Refer to MCAI EASA Airworthiness Directive 2007-0151, dated May 22, 2007; Airbus Service Bulletin A310-32-2133, Revision 02, dated February 26, 2007; and Messier-Bugatti Service Bulletin C24264-32-848, dated February 15, 2006, for related information.

Issued in Renton, Washington, on July 30, 2007.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-16109 Filed 8-15-07; 8:45 am]

**BILLING CODE** 4910-13-P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-28944; Directorate Identifier 2006-NM-239-AD]

RIN 2120-AA64

**Airworthiness Directives; Airbus Model A300 Series Airplanes and Airbus Model A300-600 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

[T]he detection of cracks on multiple aircraft in lower skin panel No. 2 forward of access panel 575FB/675FB held on the rear dummy spar, inboard of rib 9, fuselage side, aft of the rear spar.

This area of structure has been subjected to several repairs and modifications in previous years.

The AIRBUS Service Bulletins (SB) A300-57-0177 at Revision 3 and A300-57-6029 at Revision 4 define the various configurations for the mandatory inspections to be conducted in order to control or correct the development of cracks which could affect the structural integrity of the aircraft.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by September 17, 2007.

**ADDRESSES:** You may send comments by any of the following methods:

- *DOT Docket Web Site:* Go to <http://dms.dot.gov> and follow the instructions for sending your comments electronically.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* Room W12-140 on the ground floor of the West Building, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- *Federal eRulemaking Portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://dms.dot.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:****Streamlined Issuance of AD**

The FAA is implementing a new process for streamlining the issuance of ADs related to MCAI. This streamlined process will allow us to adopt MCAI safety requirements in a more efficient manner and will reduce safety risks to the public. This process continues to follow all FAA AD issuance processes to meet legal, economic, Administrative Procedure Act, and **Federal Register** requirements. We also continue to meet our technical decision-making responsibilities to identify and correct unsafe conditions on U.S.-certificated products.

This proposed AD references the MCAI and related service information that we considered in forming the engineering basis to correct the unsafe condition. The proposed AD contains text copied from the MCAI and for this reason might not follow our plain language principles.

**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2007-28944; Directorate Identifier 2006-NM-239-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.