

of the times specified in paragraphs (f)(1) and (f)(2) of this AD, and the repetitive inspections must be accomplished thereafter at the intervals specified in Section 1 of Document 95A.1930/05, except as provided by paragraph (g) of this AD.

(1) The effective date of this AD.

(2) The date of issuance of the original French standard airworthiness certificate or the date of issuance of the original French export certificate of airworthiness.

Note 2: Airbus Operator Information Telex SE 999.0079/07, Revision 01, dated August 14, 2007, identifies the applicable sections of the Airbus A310 airplane maintenance manual necessary for accomplishing the tasks specified in Section 1 of Document 95A.1930/05.

Initial Compliance Time for Task 28-18-00-03-1

(g) For Task 28-18-00-03-1 identified in Section 1 of Document 95A.1930/05, "Maintenance/Inspection Tasks," of Airbus A310 Fuel Airworthiness Limitations, Document 95A.1930/05, Issue 2, dated May 11, 2007 (approved by the EASA on July 6, 2007): The initial compliance time is the later of the times specified in paragraphs (g)(1) and (g)(2) of this AD. Thereafter, Task 28-18-00-03-1 must be accomplished at the repetitive interval specified in Section 1 of Document 95A.1930/05.

(1) Prior to the accumulation of 40,000 total flight hours.

(2) Within 72 months or 20,000 flight hours after the effective date of this AD, whichever occurs first.

Revise ALS To Incorporate CDCCLs

(h) Within 12 months after the effective date of this AD, revise the ALS of the Instructions for Continued Airworthiness to incorporate Airbus A310 ALS Part 5—Fuel Airworthiness Limitations, dated May 31, 2006, as defined in Airbus A310 Fuel Airworthiness Limitations, Document 95A.1930/05, Issue 2, dated May 11, 2007 (approved by the EASA on July 6, 2007), Section 2, "Critical Design Configuration Control Limitations."

No Alternative Inspections, Inspection Intervals, or CDCCLs

(i) Except as provided by paragraph (j) of this AD: After accomplishing the actions specified in paragraphs (f) and (h) of this AD, no alternative inspections, inspection intervals, or CDCCLs may be used.

Alternative Methods of Compliance (AMOCs)

(j)(1) The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Related Information

(k) EASA airworthiness directive 2007-0096 R1, dated May 2, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(l) You must use Airbus A310 ALS Part 5—Fuel Airworthiness Limitations, dated May 31, 2006; and Airbus A310 Fuel Airworthiness Limitations, Document 95A.1930/05, Issue 2, dated May 11, 2007; to perform the actions that are required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference of these documents in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France, for a copy of this service information. You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 5, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-20221 Filed 10-15-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28909; Directorate Identifier 2007-NM-135-AD; Amendment 39-15230; AD 2007-21-12]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-135BJ Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found cases in which some wiring harnesses were not protected in accordance with SFAR-88 (Special Federal Aviation Regulation No. 88) requirements.

The potential of ignition sources, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane. We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective November 20, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 20, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on August 8, 2007 (72 FR 44435). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been found cases in which some wiring harnesses were not protected in accordance with SFAR-88 (Special Federal Aviation Regulation No. 88) requirements.

The potential of ignition sources, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane. The corrective action includes installing heat shrinkable sleeves on the inspection and refueling panel illumination lights wiring, and installing nipples on the terminal lugs to protect the wire terminals. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the

public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect about 8 products of U.S. registry. We also estimate that it will take about 6 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$32 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$4,096, or \$512 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2007-21-12 Empresa Brasileira de Aeronautica S.A. (EMBRAER): Amendment 39-15230. Docket No. FAA-2007-28909; Directorate Identifier 2007-NM-135-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective November 20, 2007.

Affected ADs

(b) None.

Applicability

(c) This AD applies to EMBRAER Model EMB-135BJ airplanes, certificated in any category; as identified in EMBRAER Service Bulletin 145LEG-28-0016, Revision 01, dated June 27, 2005.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: It has been found cases in which some wiring harnesses were not protected in accordance with SFAR-88 (Special Federal Aviation Regulation No. 88) requirements. The potential of ignition sources, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane. The corrective action includes installing heat shrinkable sleeves on the inspection and refueling panel illumination lights wiring, and installing nipples on the terminal lugs to protect the wire terminals.

Actions and Compliance

(f) Unless already done, do the following actions.

(1) Within 5,000 flight hours after the effective date of this AD, install heat shrinkable sleeves on the inspection and refueling panel illumination lights wiring, and install nipples on the terminal lugs to protect the wire terminals, in accordance with the detailed instructions and procedures in EMBRAER Service Bulletin 145LEG-28-0016, Revision 01, dated June 27, 2005.

(2) Actions done before the effective date of this AD in accordance with EMBRAER Service Bulletin 145LEG-28-0016, dated March 8, 2004, are acceptable for compliance with the corresponding actions of this AD.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2125; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the

FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI Brazilian Airworthiness Directive 2006-07-02, effective August 21, 2006, and EMBRAER Service Bulletin 145LEG-28-0016, Revision 01, dated June 27, 2005, for related information.

Material Incorporated by Reference

(i) You must use EMBRAER Service Bulletin 145LEG-28-0016, Revision 01, dated June 27, 2005, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Empresa Brasileira de Aeronautica S.A. (EMBRAER), P.O. Box 343—CEP 12.225, Sa~o Jose dos Campos—SP, Brazil.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 5, 2007.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E7-20222 Filed 10-15-07; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2007-28663; Directorate Identifier 2006-NM-223-AD; Amendment 39-15221; AD 2007-21-03]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300-600 Series Airplanes; and Model A310 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

* * * * *

* * * the FAA set-up in January 1999 an Ageing Transport Systems Rulemaking Advisory Committee (ATSRAC) to investigate the potential safety issues in aging aircraft as a result of wear and degradation in their operating systems.

Under this plan, all Holders of type Certificates aircraft are required to conduct a design review, to preclude the occurrence of potential unsafe conditions as the aircraft aged.

* * * * *

The unsafe condition is degradation of the fuel system, which could result in loss of the airplane. We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective November 20, 2007.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of November 20, 2007.

ADDRESSES: You may examine the AD docket on the Internet at <http://dms.dot.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building, Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on July 10, 2007 (72 FR 37472). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

* * * the FAA issued in July 1996 an Aging Non-structural Systems plan to address the White House Commission an Aviation Safety and Security (WHCSS) report.

To help fulfill the actions specified in this Aging Systems plan, the FAA set-up in January 1999 an Ageing Transport Systems Rulemaking Advisory Committee (ATSRAC) to investigate the potential safety issues in aging aircraft as a result of wear and degradation in their operating systems.

Under this plan, all Holders of type Certificates aircraft are required to conduct a design review, to preclude the occurrence of potential unsafe conditions as the aircraft aged.

Further to AIRBUS investigations on this subject, corrected measures intended to improve the design of A310 and A300-600 fleet against potential unsafe conditions as the aircraft aged, are rendered mandatory by this AD.

The unsafe condition is degradation of the fuel system, which could result in loss of the airplane. The corrective actions include:

- Modify emergency power electrical routing.
- Inspect certain wire routes and do necessary corrective action (repair chafed or burned wiring, damaged clamps, and introduce self-vulcanizing silicone tape for wrapping the cable bundle at each clamping position).
- Secure electrical routing.
- Relocate temperature sensors and modify wires.

You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in