

economic cost on small entities. Moreover, we did not receive any comments regarding the small entity impact of this part of the NPRM. Therefore as the Acting FAA Administrator, I certify that this rule will not have a significant economic impact on a substantial number of small entities.

*International Trade Impact Assessment*

The Trade Agreements Act of 1979 (Pub. L. 96-39) prohibits Federal agencies from establishing any standards or engaging in related activities that create unnecessary obstacles to the foreign commerce of the United States. Legitimate domestic objectives, such as safety, are not considered unnecessary obstacles. The statute also requires consideration of international standards and, where appropriate, that they be the basis for U.S. standards. The FAA has assessed the potential effect of this final rule and determined it would promote international trade by reducing the cost of export airworthiness approvals for Class II products (major components) and Class III products (parts and components).

*Unfunded Mandates Assessment*

Title II of the Unfunded Mandates Reform Act of 1995 (Pub. L. 104-4) requires each Federal agency to prepare a written statement assessing the effects of any Federal mandate in a proposed or final agency rule that may result in an expenditure of \$100 million or more (adjusted annually for inflation with the base year 1995) in any one year by State, local, and tribal governments, in the aggregate, or by the private sector; such a mandate is deemed to be a "significant regulatory action." The FAA currently uses an inflation-adjusted value of \$128.1 million.

This final rule does not contain such a mandate. The requirements of Title II do not apply.

**Executive Order 13132, Federalism**

The FAA has analyzed this final rule under the principles and criteria of Executive Order 13132, Federalism. We determined that this action will not have a substantial direct effect on the States, or the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government, and, therefore, does not have federalism implications.

**Environmental Analysis**

FAA Order 1050.1E identifies FAA actions that are categorically excluded from preparation of an environmental

assessment or environmental impact statement under the National Environmental Policy Act in the absence of extraordinary circumstances. The FAA has determined this rulemaking action qualifies for the categorical exclusion identified in paragraph 308(b) and involves no extraordinary circumstances.

**Regulations That Significantly Affect Energy Supply, Distribution, or Use**

The FAA has analyzed this final rule under Executive Order 13211, Actions Concerning Regulations that Significantly Affect Energy Supply, Distribution, or Use (May 18, 2001). We have determined that it is not a "significant energy action" under the executive order because it is not a "significant regulatory action" under Executive Order 12866, and it is not likely to have a significant adverse effect on the supply, distribution, or use of energy.

**Availability of Rulemaking Documents**

You can get an electronic copy of rulemaking documents using the Internet by—  
 1. Searching the Federal eRulemaking portal at <http://www.regulations.gov>;  
 2. Visiting the FAA's Regulations and Policies Web page at [http://www.faa.gov/regulations\\_policies/](http://www.faa.gov/regulations_policies/); or  
 3. Accessing the Government Printing Office's Web page at <http://www.gpoaccess.gov/fr/index.html>.

You can also get a copy by sending a request to the Federal Aviation Administration, Office of Rulemaking, ARM-1, 800 Independence Avenue, SW., Washington, DC 20591, or by calling (202) 267-9680. Make sure to identify the amendment number or docket number of this rulemaking.

Anyone is able to search the electronic form of all comments received into any of our dockets by the name of the individual submitting the comment (or signing the comment, if submitted on behalf of an association, business, labor union, etc.). You may review DOT's complete Privacy Act statement in the **Federal Register** published on April 11, 2000 (Volume 65, Number 70; Pages 19477-78) or you may visit <http://DocketsInfo.dot.gov>.

**Small Business Regulatory Enforcement Fairness Act**

The Small Business Regulatory Enforcement Fairness Act (SBREFA) of 1996 requires FAA to comply with small entity requests for information or advice about compliance with statutes and regulations within its jurisdiction. If you are a small entity and you have a question regarding this document, you

may contact your local FAA official, or the person listed under the **FOR FURTHER INFORMATION CONTACT** heading at the beginning of the preamble. You can find out more about SBREFA on the Internet at [http://www.faa.gov/regulations\\_policies/rulemaking/sbre\\_act/](http://www.faa.gov/regulations_policies/rulemaking/sbre_act/).

**List of Subjects in 14 CFR Part 21**

Aircraft, Certification procedures for products and parts, Export airworthiness approvals.

**The Amendment**

■ In consideration of the foregoing, the Federal Aviation Administration amends Chapter I of Title 14, Code of Federal Regulations as follows:

**PART 21—CERTIFICATION PROCEDURES FOR PRODUCTS AND PARTS**

■ 1. The authority citation for part 21 continues to read as follows:

**Authority:** 42 U.S.C. 7572; 49 U.S.C. 106(g), 40105, 40113, 44701-44702, 44707, 44709, 44711, 44713, 44715, 45303.

■ 2. Amend § 21.325 by adding new paragraph (b)(4) to read as follows:

**§ 21.325 Export airworthiness approvals.**

\* \* \* \* \*  
 (b)\* \* \*

(4) Class II and III products located outside of the United States if the FAA finds no undue burden in administering the applicable requirements of Title 49 U.S.C. and this subchapter.

\* \* \* \* \*

Issued in Washington, DC, on November 6, 2007.

**Robert A. Sturgell,**  
*Acting Administrator.*  
 [FR Doc. E7-22111 Filed 11-9-07; 8:45 am]  
**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2007-28828; Directorate Identifier 2007-NM-010-AD; Amendment 39-15258; AD 2007-23-12]

RIN 2120-AA64

**Airworthiness Directives; Boeing Model 707 Airplanes and Model 720 and 720B Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for all Boeing Model 707 airplanes and Model 720 and 720B series airplanes. This AD requires accomplishing an airplane survey to define the configuration of certain system installations, and repair of any discrepancy found. This AD also requires modifying the fuel system by installing lightning protection for the fuel quantity indication system (FQIS), ground fault relays for the fuel boost pumps, and additional power relays for the center tank fuel pumps and uncommanded on-indication lights at the flight engineer's panel. This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent certain failures of the fuel pumps or FQIS, which could result in a potential ignition source inside the fuel tank, which, in combination with flammable fuel vapors, could result in a fuel tank explosion and consequent loss of the airplane.

**DATES:** This AD becomes effective December 18, 2007.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Kathrine Rask, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6505; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to all Boeing Model 707 airplanes and Model 720 and 720B series airplanes. That NPRM was published in the **Federal Register** on August 1, 2007 (72 FR 41958). That NPRM proposed to

require accomplishing an airplane survey to define the configuration of certain system installations, and repair of any discrepancy found. That NPRM proposed to also require modifying the fuel system by installing lightning protection for the fuel quantity indication system, ground fault relays for the fuel boost pumps, and additional power relays for the center tank fuel pumps and uncommanded on-indication lights at the flight engineer's panel.

#### Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the single comment received. The commenter, Boeing, supports the NPRM.

#### Conclusion

We have carefully reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

#### Costs of Compliance

There are about 185 airplanes of the affected design in the worldwide fleet. This AD affects about 52 airplanes of U.S. registry.

The required survey takes about 20 work hours per airplane, at an average labor rate of \$80 per work hour. Based on these figures, the estimated cost of the survey for U.S. operators is \$83,200, or \$1,600 per airplane.

Because the manufacturer has not yet developed a modification commensurate with the actions specified by this AD, we cannot provide specific information regarding the required number of work hours or the cost of parts to do the required modification. In addition, modification costs will likely vary depending on the operator and the airplane configuration. The compliance time of 72 months should provide ample time for the development, approval, and installation of an appropriate modification.

Based on similar modifications accomplished previously on other airplane models, however, we can reasonably estimate that the modification may require as many as 420 work hours per airplane, at an average labor rate of \$80 per work hour. Required parts may cost up to \$185,000 per airplane. Based on these figures, the estimated cost of the modification for U.S. operators may cost up to \$11,367,200, or \$218,600 per airplane.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

■ 2. The Federal Aviation Administration (FAA) amends § 39.13 by adding the following new airworthiness directive (AD):

**2007-23-12 Boeing:** Amendment 39-15258. Docket No. FAA-2007-28828; Directorate Identifier 2007-NM-010-AD.

**Effective Date**

(a) This AD becomes effective December 18, 2007.

**Affected ADs**

(b) None.

**Applicability**

(c) This AD applies to all Boeing Model 707-100 long body, -200, -100B long body, and -100B short body series airplanes; and Model 707-300, -300B, -300C, and -400 series airplanes; and Model 720 and 720B series airplanes; certificated in any category.

**Unsafe Condition**

(d) This AD results from fuel system reviews conducted by the manufacturer. We are issuing this AD to prevent certain failures of the fuel pumps or fuel quantity indication system (FQIS), which could result in a potential ignition source inside the fuel tank, which, in combination with flammable fuel vapors, could result in fuel tank explosion and consequent loss of the airplane.

**Compliance**

(e) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

**Airplane Survey**

(f) Within 12 months after the effective date of this AD: Conduct an airplane survey that defines the configuration of system installations for the wing leading edges, wing-to-body area, electrical equipment bay, flight deck, and FQIS using a method approved in accordance with the procedures specified in paragraph (h)(1) of this AD. If any discrepancy is detected, repair before further flight using a method approved in accordance with the procedures specified in paragraph (h)(1) of this AD. Submit the survey results to the Manager, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356, at the applicable time specified in paragraph (f)(1) or (f)(2) of this AD. The report must include the survey results (e.g., photographs and sketches, part numbers of FQIS components and fuel pumps, and the actual configuration of FQIS and the fuel pump control systems), a description of any discrepancy found, the airplane serial number, and the number of landings and flight hours on the airplane. Under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements contained in this AD and has assigned OMB Control Number 2120-0056.

(1) If the survey was done after the effective date of this AD: Submit the report within 30 days after the survey.

(2) If the survey was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

**Note 1:** For the purposes of this AD, “discrepancy” is defined as any wear or deterioration (e.g., damage, fluid leaks,

corrosion, cracking, or system failures) that might prevent the airplane from being in an airworthy condition.

**Modification of Fuel System**

(g) Within 72 months after the effective date of this AD: Modify the fuel system as specified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, using a method approved in accordance with the procedures specified in paragraph (h)(1) of this AD.

(1) Replace the FQIS wire bundle along the leading edge of the left and right wings with a new wire bundle that has a lightning shield that is separated from other wiring.

(2) Replace each fuel pump relay with a ground fault interrupter relay.

(3) Install redundant power relays for the center tank fuel pumps and uncommanded on-indication lights at the flight engineer's panel.

**Alternative Methods of Compliance (AMOCs)**

(h)(1) The Manager, Seattle ACO has the authority to approve AMOCs for this AD, if requested in accordance with the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

**Material Incorporated by Reference**

(i) None.

**BILLING CODE 4910-13-P**

## Appendix 1. 707 SFAR 88 Survey Areas


## 707 SFAR-88 Survey

Boeing and the FAA have identified the following changes to the 707/720 fuel systems to support SFAR-88. Boeing is in the process of developing Service Bulletins for these system changes:

- FQIS Wire Shielding and Separation
- Ground Fault Interrupt (GFI) Relay
- Pump Un-Commanded On (PUO) system
- Potential solution for FQIS Center Tank Hot Short Protection

To support the development of these Service Bulletins, Boeing requires a photographic survey of the airplane. Because these airplanes are now rare,

Boeing needs operator assistance with the required SFAR-88 design changes. Boeing needs digital videos or digital photographs of the following areas of the aircraft:

**707 SFAR 88 SURVEY  
AREAS****1) Flight Deck**

New circuit breakers will be installed on the P1, P2, P3, P4 and/or P5 panels. Two new indication lights are installed in the lower P11 panel. Provide photographs of these panels.

Provide photos of the Flight Deck area above and below the Engineer's panel and on the opposite side showing the existing wire bundle routing with the ceiling and side panels removed. This will be used to route additional wire bundles separated from the existing power wires that will be routed to the EE Bay.

Verify the part number(s) of the FQIS indicators installed in the P11 panel. Verify if a remote trimmer is installed for this indicator.

## Appendix 1. 707 SFAR 88 Survey Areas

### 2) E/E-Bay

Provide photos of any location within the E/E-Bay where there is enough space to install a J-box. A J-box is a 22 inch by 12 inch by 4.0 inch tall avionics box that contains control relays. A new J-box must be installed in order to add the Ground Fault Interrupt relays and the Pump Un-commanded ON relays. Possible locations are along the body structure and beneath the cabin floor.

### 3) Mix Bay

Provide photos showing the tubing and duct routing from the wing section. Provide photos of the current wire bundles in the mix bay. Boeing intends to add 18 new splices for the FQIS wire harness. Provide photos for the installation of a box which is 9 x 6 x 6 inches tall which may be required for FQIS Center Tank Hot Short Protection. Boeing requests photos from both inside the aircraft fuselage showing the wire routing and pressure vessel penetration.

### 4) Leading Edge

Provide photos of the Fuel Quantity Indication system connectors on the front for all fuel tanks. Provide photographs of the front spar every 3 feet from the reserve tank to the center tank. Photos should show tubing installations, existing wire harnesses, pneumatic ducts, etc. Photograph areas between the engine struts, outboard of engine 1 and 4, and between the inboard strut and side of body with a free 9 X 3 X 5 inch accessible areas. These photos will help Boeing engineering develop new FQIS wire routing that has a minimum of 2 inch separation from existing wires, or possibly to install new FQIS spar penetration connectors. Provide photos of the front spar and seal ribs with in the strut area with the access panels removed. These photos will also be used in the development of the FQIS wire shielding and separation.

### 5) Wing to Body (Un-pressurized wire penetrations)

Photos of the existing wire bundle penetrations through the pressure vessel and a 3 foot radius area around the existing wire bundle penetrations in the wing to body fairing (view from the front spar looking inboard).

### 6) Fuel Tanks

Provide photographs of the fuel quantity indication probes and the wiring for the probes. Photograph along the wiring to the spar penetration. Provide photographs of the internal tank structure and plumbing. Note that non-explosion proof equipment is generally not allowed inside fuel tanks.

NOTE: To photograph inside the fuel tanks, ensure that the Lower Explosion Limit of the fuel tank is below 10%, and tape the battery compartment on the camera closed. Tapping the battery compartment closed will ensure that the battery will not suddenly eject if the camera is dropped, which will prevent a potential spark.

### General notes on taking pictures

- 1) Preferably, use a digital camera that has a close-up feature and a built in or external flash. A camera with 4 mega pixels or more is preferred. Photos should be in JPEG format.
- 2) Close up photos should also show a scale in inches or centimeters. In other words, please put a ruler in the shot. After the photos are taken, use any digital photography software to add text (in English) as necessary. Please indicate where on the aircraft the close-up photos were taken (body stations and or wing stations).
- 3) Digital Video is also an acceptable way to complete this survey. With video, make sure there is enough lighting, especially in the confined areas such as the fuel tanks or EE Bay. With video, please provide sweeps of the areas indicated above. For example, focus on the front spar and slowly walk outboard to inboard to provide an overview of the entire spar. Then, provide the detailed shots of each of the items indicated above. Boeing prefers the videos to be in an AVI or a WMV format.
- 4) Store the photos or video on CDs or DVDs media. Provide separate CDs or DVDs for each aircraft. Label the media with the aircraft tail number, registry and or serial number. Submit the media to the FAA.

Issued in Renton, Washington, on October 12, 2007.

**Stephen P. Boyd,**

*Assistant Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 07-5635 Filed 11-9-07; 8:45 am]

BILLING CODE 4910-13-C

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-0073; Directorate Identifier 2007-NM-229-AD; Amendment 39-15240; AD 2007-22-04]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A330 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule; correction.

**SUMMARY:** The FAA is correcting a typographical error in an existing airworthiness directive (AD) that was published in the **Federal Register** on October 24, 2007 (72 FR 60238). The error resulted in an inadvertent omission of the deadline for submitting comments. This AD applies to all Airbus Model A330 airplanes. This AD requires revising the Procedures and Emergency sections of the Airbus A330 Airplane Flight Manual.

**DATES:** This correction is effective November 13, 2007. The AD published at 72 FR 60238 remains effective November 8, 2007. Comments on the AD at 72 FR 60238 must be received by December 17, 2007.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Tim Backman, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2797; fax (425) 227-1149.

**SUPPLEMENTARY INFORMATION:** On October 12, 2007, the FAA issued AD 2007-22-04, amendment 39-15240 (72 FR 60238, October 24, 2007), for all Airbus Model A330 airplanes. The AD requires revising the Procedures and Emergency sections of the Airbus A330 Airplane Flight Manual.

As published, that AD did not include the sentence that contains the deadline for submitting comments.

No part of the regulatory information has been changed; therefore, the final rule is not republished in the **Federal Register**.

The effective date of this AD remains November 8, 2007.

In the **Federal Register** of October 24, 2007, on page 60238, in the second column, the **DATES** section of AD 2007-22-04 is corrected to read as follows:

“**DATES:** This AD becomes effective November 8, 2007.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of November 8, 2007.

We must receive comments on this AD by December 17, 2007.”

Issued in Renton, Washington, on November 2, 2007.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E7-21996 Filed 11-9-07; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF HOMELAND SECURITY

### Bureau of Customs and Border Protection

#### 19 CFR Part 123

[CBP Dec. 07-84]

#### Advance Electronic Presentation of Cargo Information for Truck Carriers Required To Be Transmitted Through ACE Truck Manifest at Ports in the State of Alaska

**AGENCY:** Customs and Border Protection, Department of Homeland Security.

**ACTION:** Final rule.

**SUMMARY:** Pursuant to section 343(a) of the Trade Act of 2002 and implementing regulations, truck carriers and other eligible parties are required to transmit advance electronic truck cargo information to Customs and Border Protection (CBP) through a CBP-approved electronic data interchange. In a previous document, CBP designated the Automated Commercial Environment (ACE) Truck Manifest

System as the approved interchange and announced that the requirement that advance electronic cargo information be transmitted through ACE would be phased in by groups of ports of entry. This document announces that at all land border ports in the state of Alaska truck carriers will be required to file electronic manifests through the ACE Truck Manifest System.

**DATES:** Trucks entering the United States through land border ports of entry in the state of Alaska will be required to transmit the advance information through the ACE Truck Manifest system effective February 11, 2008.

**FOR FURTHER INFORMATION CONTACT:** Mr. James Swanson, via e-mail at [james.d.swanson@dhs.gov](mailto:james.d.swanson@dhs.gov).

#### SUPPLEMENTARY INFORMATION:

##### Background

Section 343(a) of the Trade Act of 2002, as amended (the Act; 19 U.S.C. 2071 note), required that CBP promulgate regulations providing for the mandatory transmission of electronic cargo information by way of a CBP-approved electronic data interchange (EDI) system before the cargo is brought into or departs the United States by any mode of commercial transportation (sea, air, rail or truck). The cargo information required is that which is reasonably necessary to enable high-risk shipments to be identified for purposes of ensuring cargo safety and security and preventing smuggling pursuant to the laws enforced and administered by CBP.

On December 5, 2003, CBP published in the **Federal Register** (68 FR 68140) a final rule to effectuate the provisions of the Act. In particular, a new section 123.92 (19 CFR 123.92) was added to the regulations to implement the inbound truck cargo provisions. Section 123.92 describes the general requirement that, in the case of any inbound truck required to report its arrival under section 123.1(b), if the truck will have commercial cargo aboard, CBP must electronically receive certain information regarding that cargo through a CBP-approved EDI system no later than 1 hour prior to the carrier's reaching the first port of arrival in the United States. For truck carriers arriving with shipments qualified for clearance under the FAST (Free and Secure Trade) program, section 123.92 provides that CBP must electronically receive such cargo information through the CBP-approved EDI system no later than 30 minutes prior to the carrier's reaching the first port of arrival in the United States.