

Bulletin A300-28-6064, dated July 28, 2005, for aircraft under configuration 05, as defined in the service bulletin, are considered acceptable for compliance with the requirements of paragraph (f)(2) of this AD.

(5) Actions done before the effective date of this AD in accordance with Airbus Service Bulletin A300-28-6077, dated July 25, 2005, for aircraft under configuration 05, as defined in the service bulletin, are considered acceptable for compliance with the requirements of paragraph (f)(3) of this AD.

**FAA AD Differences**

**Note:** This AD differs from the MCAI and/or service information as follows: The applicability of the MCAI does not address Airbus Modification 12490. We have added this Modification number to the applicability of this AD, as requested by Airbus and coordinated with the European Aviation Safety Agency (EASA).

**Other FAA AD Provisions**

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from

a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

**Related Information**

(h) Refer to MCAI EASA Airworthiness Directive 2007-0233, dated August 27, 2007, and the service information listed in Table 1 of this AD, for related information.

**TABLE 1.—SERVICE INFORMATION**

Airbus Service Bulletin	Revision level	Date
A300-28-6064 .....	01 .....	April 3, 2007.
A300-28-6068 .....	Original .....	July 20, 2005.
A300-28-6077 .....	01 .....	October 26, 2006.

**Material Incorporated by Reference**

(i) You must use the service information specified in Table 2 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of

this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind

Avenue SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**TABLE 2.—MATERIAL INCORPORATED BY REFERENCE**

Airbus Service Bulletin	Revision level	Date
A300-28-6064 .....	01 .....	April 3, 2007.
A300-28-6068 .....	Original .....	July 20, 2005.
A300-28-6077 .....	01 .....	October 26, 2006.

Issued in Renton, Washington, on January 18, 2008.

**Ali Bahrami,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-1462 Filed 1-30-08; 8:45 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2008-0105; Directorate Identifier 2008-CE-001-AD; Amendment 39-15355; AD 2008-03-06]

**RIN 2120-AA64**

**Airworthiness Directives; Stemme GmbH & Co. KG Model S10-VT Powered Sailplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results

from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

A leakage in the area of a plastic T-connector was found during a daily pre-flight check. The investigation has shown a crack in the centre part of this connector.

This AD requires actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** This AD becomes effective February 20, 2008.

On February 20, 2008, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

We must receive comments on this AD by March 3, 2008.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Gregory Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued Emergency AD No. 2007-0315-E, dated December 21, 2007 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A leakage in the area of a plastic T-connector was found during a daily pre-flight check. The investigation has shown a crack in the centre part of this connector.

This proposed AD would require you to inspect all plastic connectors in the area of the fuel pumps and the connection point of the pressure lines to the fuel shut-off valve for possible leakage and replace the plastic connectors in the fuel system with metal connectors if leaks are found.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

STEMME F & D has issued Service Bulletin A31-10-082, Am.-Index: 01.a, dated November 30, 2007. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of the AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are issuing this AD because we evaluated all information provided by the State of Design Authority and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might have also required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are described in a separate paragraph of the AD. These requirements take precedence over those copied from the MCAI.

#### FAA's Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because a leak in the area of a fuel line plastic T-connector was found, which could result in the possibility of fuel leaking into the engine compartment. Therefore, we determined that notice and opportunity for public comment before issuing this AD are impracticable and that good cause exists for making this amendment effective in fewer than 30 days.

#### Comments Invited

This AD is a final rule that involves requirements affecting flight safety, and we did not precede it by notice and

opportunity for public comment. We invite you to send any written relevant data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-0105; Directorate Identifier 2008-CE-001-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**2008-03-06 Stemme GmbH & Co. KG:**  
Amendment 39-15355; Docket No. FAA-2008-0105; Directorate Identifier 2008-CE-001-AD.

#### Effective Date

(a) This airworthiness directive (AD) becomes effective February 20, 2008.

#### Affected ADs

(b) None.

#### Applicability

(c) This AD applies to Model S10-VT powered sailplanes, serial numbers 11-001 through 11-112, except 11-036, 11-067, 11-068, and 11-090, certificated in any category.

#### Subject

(d) Air Transport Association of America (ATA) Code 28: Fuel.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

A leakage in the area of a plastic T-connector was found during a daily pre-flight check. The investigation has shown a crack in the centre part of this connector.

This AD requires you to inspect all plastic connectors in the area of the fuel pumps and the connection point of the pressure lines to the fuel shut-off valve for possible leakage and replace the plastic connectors in the fuel system with metal connectors if leaks are found.

#### Actions and Compliance

(f) Unless already done, do the following actions.

(1) Before the first flight of each day after February 20, 2008 (the effective date of this AD) until the replacement required in paragraph (f)(3) of this AD is done, inspect all plastic connectors in the area of the fuel pumps and the connection point of the pressure lines to the fuel shut-off valve

(behind the rear bulkhead of the front fuselage) for possible leakage. Do the inspection following STEMME F & D Service Bulletin A31-10-082, Am.-Index: 01.a, dated November 30, 2007.

(2) Before further flight after the inspection required in paragraph (f)(1) of this AD, replace the plastic T- and Y-connectors in the fuel system with metal connectors if leaks are found. Do the replacements following STEMME F & D Service Bulletin A31-10-082, Am.-Index: 01.a, dated November 30, 2007. This replacement terminates the repetitive inspections required in paragraph (f)(1) of this AD.

(3) Within the next 30 days after February 20, 2008 (the effective date of this AD), replace all plastic T- and Y-connectors in the fuel system with metal connectors. Do the replacements following STEMME F & D Service Bulletin A31-10-082, Am.-Index: 01.a, dated November 30, 2007. This replacement terminates the repetitive inspections required in paragraph (f)(1) of this AD.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Gregory Davison, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4130; fax: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI European Aviation Safety Agency (EASA), Emergency AD 2007-0315-E, dated December 21, 2007, and STEMME F & D Service Bulletin A31-10-082, Am.-Index: 01.a, dated November 30, 2007, for related information.

#### Material Incorporated by Reference

(i) You must use STEMME F & D Service Bulletin A31-10-082, Am.-Index: 01.a, dated November 30, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact STEMME GmbH & Co. KG, Flugplatzstraße F 2, Nr. 7, 15344 Strausberg, Federal Republic of Germany; telephone: 49.33.41.3612.0; facsimile: 49.33.41.3612.30.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri on January 24, 2008.

**John Colomy,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-1679 Filed 1-30-08; 8:45 am]

**BILLING CODE 4910-13-P**

#### DEPARTMENT OF TRANSPORTATION

#### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2007-27891; Directorate Identifier 2007-NE-14-AD; Amendment 39-15349; AD 2008-02-19]

RIN 2120-AA64

#### Airworthiness Directives; Honeywell International Inc. TFE731-2C, -3B, -3BR, -3C, -3CR, -3D, -3DR, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, -40AR, -40R, and -60 Series Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for Honeywell International Inc. (Honeywell) TFE731-2C, -3B, -3BR, -3C, -3CR, -3D, -3DR, -4R, -5AR, -5BR, -5R, -20R, -20AR, -20BR, -40, -40AR, -40R, and -60 series turbofan engines. This AD requires removal from service of certain high pressure (HP) turbine rotor assemblies with part numbers (P/Ns) 3075772-1 and 3060841-1 using a drawdown schedule, and returning them to Honeywell for curvic root radius inspection. This AD results from the manufacturer's report