

# Rules and Regulations

Federal Register

Vol. 73, No. 127

Tuesday, July 1, 2008

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents. Prices of new books are listed in the first FEDERAL REGISTER issue of each week.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-0368 Directorate Identifier 2008-CE-007-AD; Amendment 39-15532; AD 2008-11-10]

RIN 2120-AA64

#### Airworthiness Directives; Viking Air Limited Models DHC-6-1, DHC-6-100, DHC-6-200, and DHC-6-300 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

There have been reports of inter-rivet cracking on several wing front spar adapter assemblies (P/N C6WM1027-1) on the horizontal and vertical flanges. It was determined that the cracking was caused by stress corrosion in the short transverse grain initiated by local riveting induced stresses.

We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective August 5, 2008.

On August 5, 2008, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket

Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Pong Lee, Aerospace Engineer, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: (516) 228-7324; fax: (516) 794-5531.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on March 31, 2008 (73 FR 16782). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

There have been reports of inter-rivet cracking on several wing front spar adapter assemblies (P/N C6WM1027-1) on the horizontal and vertical flanges. It was determined that the cracking was caused by stress corrosion in the short transverse grain initiated by local riveting induced stresses. This directive mandates modification and inspection of the wing front spar adapter fitting and replacement of cracked fittings.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

**Differences Between This AD and the MCAI or Service Information**

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies.

Any such differences are highlighted in a NOTE within the AD.

**Costs of Compliance**

We estimate that this AD will affect 157 products of U.S. registry. We also estimate that it will take about 18 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of this AD on U.S. operators to be \$226,080 or \$1,440 per product.

In addition, we estimate that any necessary follow-on actions will take about 200 work-hours and require parts costing \$3,696 for a cost of \$19,696 per product. We have no way of determining the number of products that may need these actions.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD Docket.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

##### 2008-11-10 Viking Air Limited:

Amendment 39-15532; Docket No. FAA-2008-0368; Directorate Identifier 2008-CE-007-AD.

##### Effective Date

(a) This airworthiness directive (AD) becomes effective August 5, 2008.

##### Affected ADs

(b) None.

##### Applicability

(c) This AD applies to Models DHC-6-1, DHC-6-100, DHC-6-200, and DHC-6-300 airplanes, all serial numbers, that are:

(1) Equipped with wing boxes, part numbers (P/Ns) C6W1002-1, C6W1002-3, WR6-1002-59, or WR6-1002-61, that incorporate a P/N C6WM1027-1 front spar adapter assembly with 10 or more years of service; and

(2) Certificated in any category.

#### Subject

(d) Air Transport Association of America (ATA) Code 57: Wings.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

There have been reports of inter-rivet cracking on several wing front spar adapter assemblies (P/N C6WM1027-1) on the horizontal and vertical flanges. It was determined that the cracking was caused by stress corrosion in the short transverse grain initiated by local riveting induced stresses. This directive mandates modification and inspection of the wing front spar adapter fitting and replacement of cracked fittings.

#### Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within the next 180 days after August 5, 2008 (the effective date of this AD), install inspection holes in the left-hand (LH) and right-hand (RH) lower wing skins following Viking DHC-6 Twin Otter Service Bulletin Number V6/541, dated October 1, 2007.

(2) Before further flight after installing the inspection holes required in paragraph (f)(1) of this AD, inspect the LH and RH front spar adapter assemblies for cracks. For wing box P/Ns C6W1002-1 and C6W1002-3, inspect following Viking DHC-6 Twin Otter Service Bulletin Number V6/540, dated October 1, 2007. For wing box P/Ns WR6-1002-59 and WR6-1002-61, inspect following R.W. Martin, Inc. Service Bulletin No. 00160/2, Revision A, dated November 15, 2007. Repetitively inspect all affected wing box P/Ns thereafter at intervals not to exceed 1,200 hours time-in-service or 12 months, whichever occurs first, until the replacement required in paragraph (f)(3) of this AD is done.

(3) Before further flight after doing any inspection required in paragraph (f)(2) of this AD where cracks are found, replace the cracked front spar adapter assembly with a front spar adapter assembly, P/N C6WM1027-3. Do the replacement following Viking DHC-6 Twin Otter Service Bulletin Number V6/542, dated October 1, 2007. This replacement terminates the repetitive inspections required in paragraph (f)(2) of this AD for the replaced front spar adapter assembly.

(4) As a terminating action for the repetitive inspections required in paragraph (f)(2) of this AD, at any time after the initial inspection required in paragraph (f)(2) of this AD, you may replace P/N C6WM1027-1 with P/N C6WM1027-3.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: (1) MCAI Transport Canada AD No. CF-2007-31, dated December 17, 2007, requires incorporating task C57-10-18 of the DHC-6 Corrosion Prevention and Control Manual (CPCM), PSM 1-6-5, within 90 days after the effective date of this AD.

(2) We are not incorporating task C57-10-18 of the DHC-6 CPCM, PSM 1-6-5, into this AD because we are currently examining Transport Canada AD No. CF-94-12R1,

dated April 13, 1999, and AD No. CF-99-11, dated May 28, 1999. Transport Canada issued these ADs to incorporate a Corrosion Prevention and Control Program that identifies specific areas that must be inspected to ensure the structural integrity of the DHC-6 fleet.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Pong Lee, Aerospace Engineer, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: (516) 228-7324; fax: (516) 794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI Transport Canada AD No. CF-2007-31, dated December 17, 2007; Viking DHC-6 Twin Otter Service Bulletins No. V6/540, dated October 1, 2007; No. V6/541, dated October 1, 2007; and No. V6/542, dated October 1, 2007; and R.W. Martin, Inc. Service Bulletin No. 00160/2, Revision A, dated November 15, 2007, for related information.

#### Material Incorporated by Reference

(i) You must use Viking DHC-6 Twin Otter Service Bulletin No. V6/540, dated October 1, 2007; Viking DHC-6 Twin Otter Service Bulletin No. V6/541, dated October 1, 2007; Viking DHC-6 Twin Otter Service Bulletin No. V6/542, dated October 1, 2007; and R.W. Martin, Inc. Service Bulletin No. 00160/2, Revision A, dated November 15, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Viking Air Limited, 9574 Hampden Road, Sidney, B.C., Canada V8L 5V5 or R.W. Martin, Inc., 37552 Winchester Road, Hangar 20, Murrieta, California 92563.

(3) You may review copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri 64106; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 15, 2008.

**David R. Showers,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-13844 Filed 6-30-08; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-0367 Directorate Identifier 2007-CE-089-AD; Amendment 39-15574; AD 2008-13-11]

RIN 2120-AA64

#### **Airworthiness Directives; Viking Air Limited Models DHC-6-1, DHC-6-100, DHC-6-200, and DHC-6-300 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

Service experience indicates that as aircraft become older, they are more likely to exhibit indications of corrosion.

Additionally, the FAA has reviewed the service experience and finds this action to be necessary based upon that service experience. We are issuing this AD to require actions to correct the unsafe condition on these products.

**DATES:** This AD becomes effective August 5, 2008.

On August 5, 2008, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building

Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Richard Beckwith, Aerospace Engineer, FAA, New York Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: (516) 228-7302; fax: (516) 568-2716.

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on March 31, 2008 (73 FR 16779). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Service experience indicates that as aircraft become older, they are more likely to exhibit indications of corrosion. Transport Canada, in conjunction with other airworthiness authorities, has committed itself to ensuring that additional maintenance programs for older aircraft are developed and implemented to minimize and control corrosive deterioration that could jeopardize airworthiness. Bombardier Inc., as manufacturer of the DHC-6 aircraft, has developed a Corrosion Prevention and Control Program which identifies specific areas that must be inspected to ensure the structural integrity of the DHC-6 fleet.

##### **Comments**

We gave the public the opportunity to participate in developing this AD. We have considered the comment received.

The Aircraft Owners and Pilots Association (AOPA) states that:

AOPA opposes broad-based fleet-wide airworthiness directives to address corrosion related issues such as this one. Instead AOPA supports a more focused approach that takes aircraft maintenance and usage into account; instead of an AD based solely on age.

In general, the FAA agrees that broad-based fleet-wide ADs are not always appropriate. However, in this case, the FAA has determined an AD should be issued because an unsafe condition exists in the product and the condition is likely to exist or develop in other products of the same type design.

The FAA is issuing this AD for two reasons, both of which are stated in the NPRM. First, service experience indicates that as aircraft become older, they are more likely to exhibit indications of corrosion. Second, we have performed a review of the relevant service experience, including a review of the Corrosion Prevention and Control Program inspection reports that were made by operators to the manufacturer. This service experience supports the issuance of an AD.

The FAA agrees in principle that based upon maintenance history, type of usage, etc., some operators may be in the position to address this unsafe condition using alternative methods to those proposed in the NPRM. However, it is not possible for the FAA to know all operators' specific conditions and write a different AD for each operator. Operators are encouraged to provide supporting evidence regarding their maintenance and operations in support of an alternative method of compliance (AMOC) when appropriate and should follow the procedures in 14 CFR 39.19 and this AD for requesting an AMOC.

We are not changing the final rule AD action based on this comment.

##### **Conclusion**

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

##### **Differences Between This AD and the MCAI or Service Information**

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to assure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the AD.

##### **Costs of Compliance**

Based on the service information, we estimate that this AD will affect 162 products of U.S. registry. We also estimate that it will take about 40 work-hours per product to comply with basic requirements of this AD. The average labor rate is \$80 per work-hour.

Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$518,400 or \$3,200 per product.

##### **Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: