

Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to European Aviation Safety Agency (EASA) Airworthiness Directive 2007-0302, dated December 14, 2007; and Airbus Mandatory Service Bulletins A330-53-3174 and A340-53-4177, both dated October 10, 2007; for related information.

Material Incorporated by Reference

(i) You must use Airbus Mandatory Service Bulletin A330-53-3174, including Appendix 01, dated October 10, 2007; or Airbus Mandatory Service Bulletin A340-53-4177, including Appendix 01, dated October 10, 2007; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France.

(3) You may review copies at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on August 18, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-19720 Filed 9-5-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-0407; Directorate Identifier 2008-NM-002-AD; Amendment 39-15662; AD 2008-18-05]

RIN 2120-AA64

Airworthiness Directives; McDonnell Douglas Model 717-200 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain McDonnell Douglas Model 717-200 airplanes. This AD requires inspecting the drive assembly of the aft elevator standby loop of the elevator standby cable system for interference between the clevis and bolt of the bellcrank assembly, correct orientation of the pull-pull cable clevis bolt, and excessive freeplay of the bellcrank assembly bearing, and corrective actions if necessary. This AD also requires modifying the pull-pull cable clevis in the drive assembly of the aft elevator standby loop for certain airplanes. This AD results from a report of an aborted takeoff due to a control column disconnect. We are issuing this AD to prevent binding of the bolt that connects the cable 264A clevis to the bellcrank assembly against the adjacent (upper) clevis of the pull-pull cable assembly. This binding condition could result in slow airplane rotation or a control column disconnect during takeoff and a runway excursion if takeoff must be aborted.

DATES: This AD is effective October 14, 2008.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 14, 2008.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846; Attention: Data and Service Management, Dept. C1-L5A (D800-0024).

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory

evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

David Rathfelder, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5229; fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to certain McDonnell Douglas Model 717-200 airplanes. That NPRM was published in the **Federal Register** on April 7, 2008 (73 FR 18725). That NPRM proposed to require inspecting the drive assembly of the aft elevator standby loop for interference between the clevis and bolt of the bellcrank assembly, correct orientation of the pull-pull cable clevis bolt, and excessive freeplay of the bellcrank assembly bearing, and corrective actions if necessary. That NPRM also proposed to require modifying the pull-pull cable clevis in the drive assembly of the aft elevator standby loop for certain airplanes.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Request To Change Summary Section for Clarification

Boeing asks that the second sentence of the Summary section in the NPRM, which describes what is to be inspected, be changed as follows: "This proposed AD would require inspecting the aft elevator standby loop drive assembly of the elevator standby cable system for interference between the clevis and bolt of this bellcrank assembly, correct orientation of the pull-pull cable clevis bolt, and excessive freeplay of the bellcrank assembly bearing, and corrective actions if necessary." Boeing states that this would more accurately describe the drive assembly being inspected since there are two drive assemblies in the elevator standby cable system.

We agree that the description in the Summary section of the AD should be clarified. Therefore, we have changed the Summary section and all other

relevant sections in the AD to meet the commenter's intent.

Requests To Extend Compliance Time

Midwest Airlines asks that the compliance time in the NPRM be changed to one of the following: "Complete the inspection and modification within 27 months of the effective date of the AD," or "Complete the inspection and modification within 3,000 flight hours or 27 months, whichever occurs later from the effective date of the AD." Midwest Airlines states that it currently has a utilization of 3,450 flight hours per year, and if the compliance time is not changed, it would require compliance for all its airplanes in less than one year. Midwest Airlines also states that it checked some of its airplanes for the interference and none was found.

Air Tran proposes that the inspection and clevis replacement specified in the NPRM be done concurrently at 27 months after the effective date of the AD, rather than the inspection being limited to 3,000 flight hours. Air Tran states that since similar access is required for both the inspection and clevis replacement, it is more practical to accomplish the clevis replacement at the same time as the inspection. Twenty-seven months aligns with the Model 717 maintenance program heavy maintenance visits, but 3,000 flight hours does not.

We agree to extend the compliance time for performing the inspection for the reasons provided by the commenters. We have determined that a compliance time of within 3,000 flight hours or 27 months after the effective date of the AD, whichever occurs later, is appropriate and will ensure an acceptable level of safety. We have changed paragraph (f)(1) of this AD accordingly. The compliance time for doing the clevis modification specified in paragraph (f)(2) of this AD remains the same. Changing the compliance time for the inspection provides the opportunity to do the inspection and modification at the same time.

Request To Change Cost Section

Midwest Airlines states that the work-hour estimate specified in the Costs of Compliance section of the NPRM is underestimated. Midwest Airlines notes that the NPRM specifies 1 work-hour for the inspection and the referenced service bulletin specifies 2.4 to 11.9 work hours. Midwest Airlines adds that the NPRM specifies 4 work-hours for the modification and the referenced service bulletin specifies 5.4 work-hours. Midwest Airlines believes the service

bulletin is more accurate than the NPRM.

From this comment, we infer that Midwest Airlines would like us to increase the work-hour estimate given in the NPRM. We do not agree. The cost information below describes only the direct costs of the specific actions required by this AD. Based on the best data available, the manufacturer provided the number of work hours (1 for the inspection, 4 for the modification) necessary to do the required actions, as specified in the service bulletin. We recognize that, in doing the actions required by an AD, operators might incur incidental costs in addition to the direct costs. The cost analysis in AD rulemaking actions, however, typically does not include incidental costs such as the time required to gain access and close up, time necessary for planning, or time necessitated by other administrative actions. Those incidental costs, which might vary significantly among operators, are almost impossible to calculate. We have made no change to the AD in this regard.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously. We also determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

Costs of Compliance

We estimate that this AD will affect 123 airplanes of U.S. registry.

It will take about 1 work-hour per product to do the inspection. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of the inspection required by this AD to the U.S. operators to be \$9,840, or \$80 per product.

It will take about 4 work-hours per product to do the modification. Required parts will cost about \$163 per product. Based on these figures, we estimate the cost of the modification required by this AD to the U.S. operators to be \$59,409, or \$483 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979), and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

You can find our regulatory evaluation and the estimated costs of compliance in the AD Docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2008-18-05 McDonnell Douglas:

Amendment 39-15662. Docket No. FAA-2008-0407; Directorate Identifier 2008-NM-002-AD.

Effective Date

(a) This airworthiness directive (AD) is effective October 14, 2008.

Affected ADs

(b) None.

Applicability

(c) This AD applies to McDonnell Douglas Model 717-200 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 717-27A0039, dated December 6, 2007.

Unsafe Condition

(d) This AD results from a report of an aborted takeoff due to a control column disconnect. We are issuing this AD to prevent binding of the bolt that connects the cable 264A clevis to the bellcrank assembly against the adjacent (upper) clevis of the pull-pull cable assembly. This binding condition could result in slow airplane rotation or a control column disconnect during takeoff and a runway excursion if takeoff must be aborted.

Compliance

(e) Comply with this AD within the compliance times specified, unless already done.

Inspection/Corrective Actions

(f) Do the applicable actions specified in paragraphs (f)(1) and (f)(2) of this AD at the time specified, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 717-27A0039, dated December 6, 2007.

(1) For all airplanes: Do a general visual inspection of the drive assembly of the aft elevator standby loop of the elevator standby cable system for interference between the clevis and bolt of the bellcrank assembly, correct orientation of the pull-pull cable clevis bolt, and excessive freeplay of the bellcrank assembly bearing. Do the inspection within 3,000 flight hours or 27 months after the effective date of this AD, whichever occurs later. Do all applicable corrective actions before further flight.

(2) For airplanes identified in the service bulletin as Group 1, Configuration 1: Modify the pull-pull cable clevis in the drive assembly of the aft elevator standby loop of the elevator standby cable system. Do the modification at the applicable time specified in paragraph 1.E., "Compliance," of the service bulletin; except, where the service bulletin specifies a compliance time after the date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

Alternative Methods of Compliance (AMOCs)

(g)(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, ATTN: David Rathfelder, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, California 90712-4137; telephone (562) 627-5229; fax (562) 627-5210; has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

(2) To request a different method of compliance or a different compliance time

for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

Material Incorporated by Reference

(h) You must use Boeing Alert Service Bulletin 717-27A0039, dated December 6, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Long Beach Division, 3855 Lakewood Boulevard, Long Beach, California 90846; Attention: Data and Service Management, Dept. C1-L5A (D800-0024).

(3) You may review copies of the service information incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 18, 2008.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E8-19721 Filed 9-5-08; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0562; Directorate Identifier 2008-NM-010-AD; Amendment 39-15658; AD 2008-18-01]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model ERJ 170 and ERJ 190 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found cases where the pressure equalization valve was not installed in the left-hand bulkhead blowout panel, on the forward and/or aft cargo compartments, thus affecting the effectiveness of fire detection, containment and suppression.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective October 14, 2008.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of October 14, 2008.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Kenny Kaulia, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2848; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on May 20, 2008 (73 FR 29085). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

It has been found cases where the pressure equalization valve was not installed in the left-hand bulkhead blowout panel, on the forward and/or aft cargo compartments, thus affecting the effectiveness of fire detection, containment and suppression.

Corrective actions include inspecting for the presence of pressure equalization valves and, if necessary, installing pressure equalization valves. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.