

biofuels in commercially significant quantities not later than three years of the date that bidding closes on the reverse auction in which the predecessor entity submitted a successful bid.

[FR Doc. E8-30500 Filed 12-22-08; 8:45 am]

BILLING CODE 6450-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-1327; Directorate Identifier 2008-NM-161-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Model A318, A319, A320, and A321 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

An A320 aircraft experienced an event where it was not possible to open the reinforced cockpit door, even after power had been removed from the aircraft. Investigation has identified that the cockpit door latch/striker assembly may have overheated, causing permanent internal damage prior to being electrically isolated by the internal thermal fuse. This condition, in case of a rapid decompression in the cockpit, would prevent the necessary unlocking/opening of the door, which may lead to failure of the airplane structure.

\* \* \* \* \*

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by January 22, 2009.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus, Airworthiness Office—EAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; fax +33 5 61 93 44 51; e-mail: [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-2141; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1327; Directorate Identifier 2008-NM-161-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2008-0151, dated August 5, 2008 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

An A320 aircraft experienced an event where it was not possible to open the reinforced cockpit door, even after power had been removed from the aircraft. Investigation has identified that the cockpit door latch/striker assembly may have overheated, causing permanent internal damage prior to being electrically isolated by the internal thermal fuse. This condition, in case of a rapid decompression in the cockpit, would prevent the necessary unlocking/opening of the door, which may lead to failure of the airplane structure.

To prevent this, an improved strike package/door bolting system, including a Polymer Positive Temperature Coefficient (PPTC) element (overheat protection) was introduced by Airbus Modification 35219 in production and modification 35218 (Service Bulletin A320-25-1444) in-service. The PPTC is a resettable thermistor and is installed on the frame of the electrically-operated cockpit door latch/striker assembly.

The in-service implementation of this modification was originally managed by an Airbus campaign but the rate of installation by operators has not met the expected timescales, making mandatory action necessary to address this.

For the reasons described above, this AD requires the installation of improved cockpit door latch/striker assemblies.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

Airbus has issued Service Bulletin A320-25-1444, Revision 02, dated August 1, 2006. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 620 products of U.S. registry. We also estimate that it would take about 6 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$0 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$297,600, or \$480 per product.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**Airbus:** Docket No. FAA-2008-1327; Directorate Identifier 2008-NM-161-AD.

#### Comments Due Date

- (a) We must receive comments by January 22, 2009.

#### Affected ADs

- (b) None.

#### Applicability

- (c) This AD applies to Airbus Model A318-111, -112, -121, and -122; A319-111, -112, -113, -114, -115, -131, -132, and -133; A320-111, -211, -212, -214, -231, -232, -233; and A321-111, -112, -131, -211, -212, -213, -231, and -232 series airplanes; certificated in any category; equipped with a cockpit door latch/striker assembly having part number AR4714-1 or AR4714-3.

### Subject

- (d) Air Transport Association (ATA) of America Code 25: Equipment/furnishings.

### Reason

- (e) The mandatory continuing airworthiness information (MCAI) states:

An A320 aircraft experienced an event where it was not possible to open the reinforced cockpit door, even after power had been removed from the aircraft. Investigation has identified that the cockpit door latch/striker assembly may have overheated, causing permanent internal damage prior to being electrically isolated by the internal thermal fuse. This condition, in case of a rapid decompression in the cockpit, would prevent the necessary unlocking/opening of the door, which may lead to failure of the airplane structure.

To prevent this, an improved strike package/door bolting system, including a Polymer Positive Temperature Coefficient (PPTC) element (overheat protection) was introduced by Airbus Modification 35219 in production and modification 35218 (Service Bulletin A320-25-1444) in-service. The PPTC is a resettable thermistor and is installed on the frame of the electrically-operated cockpit door latch/striker assembly.

The in-service implementation of this modification was originally managed by an Airbus campaign but the rate of installation by operators has not met the expected timescales, making mandatory action necessary to address this.

For the reasons described above, this AD requires the installation of improved cockpit door latch/striker assemblies.

### Actions and Compliance

- (f) Unless already done, do the following actions.

- (1) Within 8 months after the effective date of this AD: Replace all cockpit door latch/striker assemblies having part number AR4714-1 or AR4714-3 with modified units in accordance with Airbus Service Bulletin A320-25-1444, Revision 02, dated August 1, 2006 (Airbus Modification 35218).

- (2) Previous accomplishment of the replacement before the effective date of this AD in accordance with Airbus Service Bulletin A320-25-1444, dated April 29, 2005, or Revision 01, dated July 19, 2005, meets the requirements of paragraph (f)(1) of this AD.

### FAA AD Differences

**Note 1:** This AD differs from the MCAI and/or service information as follows: No differences.

### Other FAA AD Provisions

- (g) The following provisions also apply to this AD:

- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tim Dulin, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington

98057-3356; telephone (425) 227-2141; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) **Reporting Requirements:** For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2008-0151, dated August 5, 2008, and Airbus Service Bulletin A320-25-1444, Revision 02, dated August 1, 2006, for related information.

Issued in Renton, WA, on December 12, 2008.

**Michael J. Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E8-30478 Filed 12-22-08; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2008-1326; Directorate Identifier 2008-NM-141-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Boeing Model 747 Airplanes; and Boeing Model 757-200, -200PF, and -300 Series Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Boeing Model 747 series airplanes and certain Boeing Model 757-200, -200PF, and -300 series airplanes. This proposed AD would require replacing the control switches of the forward, aft, and nose cargo doors of Model 747 airplanes; and would require replacing the control switches of cargo doors 1 and 2 of Model 757 airplanes. This proposed AD results from reports of problems associated with the

uncommanded operation of cargo doors. We are proposing this AD to prevent injuries to persons and damage to the airplane and equipment.

**DATES:** We must receive comments on this proposed AD by February 6, 2009.

**ADDRESSES:** You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Boeing Commercial Airplanes, P.O. Box 3707, Seattle, Washington 98124-2207; fax 206-766-5682; e-mail [DDCS@boeing.com](mailto:DDCS@boeing.com); Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Patrick Gillespie, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 917-6429; fax (425) 917-6590.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments

to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2008-1326; Directorate Identifier 2008-NM-141-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

We received several reports of problems associated with the uncommanded operation of the forward, aft, and nose cargo doors of Boeing Model 747 airplanes that had accumulated between 9,390 and 22,529 total flight cycles; and cargo doors 1 and 2 of Boeing Model 757 airplanes that had accumulated between 4,300 and 30,000 total flight cycles. Tests of the cargo door control switches have shown that the control switches remained in the closed position after they were released, which caused the cargo doors to continue moving. The cause of the switch failure is related to the rated switch operation life cycle. This condition, if not corrected, could result in injuries to persons and damage to the airplane and equipment.

#### Relevant Service Information

We have reviewed Boeing Special Attention Service Bulletin 747-52-2286, dated September 28, 2007 (for Model 747 airplanes). This service bulletin describes procedures for replacing the control switches of the forward, aft, and nose cargo doors with new control switches.

We have also reviewed Boeing Special Attention Service Bulletin 757-52-0090, dated September 21, 2007 (for Model 757 airplanes). This service bulletin describes procedures for replacing the control switches of cargo doors 1 and 2 with new control switches.

Accomplishing the actions specified in the service information is intended to adequately address the unsafe condition.

#### FAA's Determination and Requirements of This Proposed AD

We are proposing this AD because we evaluated all relevant information and determined the unsafe condition