

TABLE 1—CYCLIC LIFE BY PART NUMBER AND MISSION—Continued

High Pressure (HP) Compressor Rotor Front Disc Assembly					
Part No.	Serial No.	A1-30 design	B1-30 and C1-30 designs	A1-30 Hawaiian	C1-30 Tropical and derated
BRR21918 .....	1292	7,300	5,100	7,300	4,300

**Other FAA AD Provisions**

(f) *Alternative Methods of Compliance (AMOCs)*: The Manager, Engine Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19.

**Related Information**

(g) Refer to MCAI Emergency Airworthiness Directive 2007-0050-E, dated February 26, 2007, and Rolls-Royce Deutschland Ltd & Co KG Alert Service Bulletin SB-BR700-72-A900437, Revision 1, dated April 18, 2007, for related information. Contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, Dahlewitz, 15827 Blankenfelde-Mahlow, Germany; telephone 49 (0) 33-7086-1768; fax 49 (0) 33-7086-3356, or go to: <http://www.rolls-royce.com/deutschland/en/default.htm>, for a copy of this service information.

(h) Contact Jason Yang, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; e-mail: [jason.yang@faa.gov](mailto:jason.yang@faa.gov); telephone (781) 238-7747; fax (781) 238-7199, for more information about this AD.

Issued in Burlington, Massachusetts, on January 21, 2009.

**Peter A. White,**

*Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.*

[FR Doc. E9-3017 Filed 2-11-09; 8:45 am]

BILLING CODE 4910-13-P

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2009-0119; Directorate Identifier 2008-CE-068-AD]

RIN 2120-AA64

**Airworthiness Directives; M7 Aerospace LP Models SA226-AT, SA226-T, SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, and SA227-DC (C-26B) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2008-12-

16, which applies to certain M7 Aerospace LP SA226 and SA227 series airplanes. AD 2008-12-16 currently requires you to inspect wires and tube assemblies for chafing, arcing, or insufficient clearance between components. If chafing, arcing, or insufficient clearance between components is found, AD 2008-12-16 requires you to clear, repair, and/or replace all chafed wires, components, and tube assemblies. AD 2008-12-16 also requires you to cover the four-gauge wires leaving the battery box with firesleaving and secure them with a clamp. Since we issued AD 2008-12-16, M7 Aerospace LP has notified us that Model SA227-BC (C-26A) was inadvertently left out of the Applicability section of the AD and they updated some of the service information due to parts availability. Operators have also identified issues with model applicability that needed clarification. Consequently, this proposed AD would retain the actions of AD 2008-12-16, add Model SA227-BC (C-26A) to the Applicability section, and regroup the models for clarification. We are proposing this AD to detect and correct chafing of electrical wires, components, and tube assemblies. This condition could result in arcing of exposed wires with consequent burning of a hole in a hydraulic line or the bleed air line. This failure could lead to a hydraulic fluid leak and a possible fire in the engine nacelle compartment.

**DATES:** We must receive comments on this proposed AD by April 13, 2009.

**ADDRESSES:** Use one of the following addresses to comment on this proposed AD:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact M7 Aerospace Repair Station, 10823 NE Entrance Road, San Antonio, Texas 78216; telephone: (210) 824-9421; fax: (210) 804-7766; Internet: <http://www.m7aerospace.com>.

**FOR FURTHER INFORMATION CONTACT:**

Werner Koch, Aerospace Engineer, ASW-150, Fort Worth Airplane Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone: (817) 222-5133; fax: (817) 222-5960.

**SUPPLEMENTARY INFORMATION:****Comments Invited**

We invite you to send any written relevant data, views, or arguments regarding this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number, "FAA-2009-0119; Directorate Identifier 2008-CE-068-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive concerning this proposed AD.

**Discussion**

Five reports of chafing between the bleed air tube assembly and the electrical starter cables on M7 Aerospace LP SA226 and SA227 series airplanes, with one incident resulting in a fire, caused us to issue AD 2008-12-16, Amendment 39-15560 (73 FR 34615, June 18, 2008). AD 2008-12-16 currently requires the following on M7 Aerospace LP SA226 and SA227 series airplanes:

- Inspect electrical wires and components, hydraulic tube assemblies, and bleed air tube assemblies, for sufficient clearance between components or any evidence of chafing or arcing;

- Clear, repair, and/or replace all chafed electrical wires and components, chafed hydraulic tube assemblies, and chafed bleed air tube assemblies; and

- Cover the four-gauge wires leaving the battery box with firesleeving and secure them with a clamp.

Since we issued AD 2008-12-16, M7 Aerospace LP has notified us that Model SA227-BC (C-26A) was inadvertently left out of the Applicability section of the AD and they updated some of the

service information due to parts availability. Operators have also identified issues with the model applicability that needed clarification. Consequently, this proposed AD would retain the actions of AD 2008-12-16, add the Model SA227-BC (C-26A) to the Applicability section, and regroup the models for clarification. We are proposing this AD to detect and correct chafing of electrical wires, components, and tube assemblies.

This condition could result in arcing of the exposed wires with consequent burning of a hole in a hydraulic line or the bleed air line. This failure could lead to a hydraulic fluid leak and a possible fire in the engine nacelle compartment.

**Relevant Service Information**

We have reviewed the following service bulletins and procedures:

Service bulletin	Applicable models	Procedures described
Fairchild Aircraft Corporation SA226 Series Service Bulletin 226-24-019, revised: November 21, 2008.	SA226-AT, SA226-T, and SA226-TC .....	Inspecting the battery cables and covering the four-gauge wires leaving the battery box with firesleeving and securing them with a clamp.
Fairchild Aircraft Corporation SA227 Series Service Bulletin No. SB227-24-001, revised: November 21, 2008.	SA227-AC, SA227-AT, and SA227-BC (C-26A).	Rerouting the hydraulic tube assemblies in the right wing leading edge, rerouting the battery cables and 22-gauge wire bundle, and installing a new access panel forward of the battery box.
M7 Aerospace SA226 Series Service Bulletin No. 226-24-020, revised: August 4, 2008.	SA226-AT and SA226-TC .....	
M7 Aerospace SA227 Series Service Bulletin No. 227-24-002, revised: November 21, 2008.	SA227-AC and SA227-AT.	
M7 Aerospace SA226 Series Service Bulletin No. 226-24-036, revised: November 21, 2008.	SA226AT, SA226-T, and SA226TC .....	Inspecting electrical wires and components, hydraulic tube assemblies, and bleed air tube assemblies at the inboard wing leading edge/battery box areas, wing stations 51.167 to 81.174, and the feed-through locations into the inboard keelson.
M7 Aerospace SA227 Series Service Bulletin No. 227-24-019, revised: November 21, 2008.	SA227-AC (C-26A), SA227-BC (C-26A), and SA227-AT.	
M7 Aerospace SA227 Series Commuter Category Service Bulletin No. CC7-24-010, revised: November 21, 2008.	SA227-CC and SA227-DC (C-26B).	

**FAA's Determination and Requirements of the Proposed AD**

We are proposing this AD because we evaluated all information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design. This proposed AD would

supersede AD 2008-12-16 with a new AD that would retain the actions of AD 2008-12-16, add Model SA227-BC (C26A) to the Applicability section, and regroup the models for clarification. We are proposing this AD to detect and correct chafing of electrical wires, components, and tube assemblies. This proposed AD would require you to use

the service information described previously to perform these actions.

**Costs of Compliance**

We estimate that this proposed AD would affect 268 airplanes in the U.S. registry.

We estimate the following costs to do the proposed inspection:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
4 work-hours × \$80 per hour = \$320 .....	Not Applicable .....	\$320	\$85,760

We estimate the following costs to do any necessary modifications for certain Models SA226-AT, SA226-T, SA226-TC, SA227-AC, and SA227-AT

airplanes referenced in M7 Aerospace SA226 Series Service Bulletin 226-24-019, revised: November 21, 2008; or M7 Aerospace SA227 Series Service

Bulletin 227-24-001, revised: November 21, 2008. We estimate 88 airplanes may need this modification:

Labor cost	Parts cost	Total cost per airplane	Total cost on U.S. operators
13 work-hours × \$80 per hour = \$1,040 .....	\$7	\$1,047	\$92,136

We estimate the following costs to do any necessary repairs for certain Models SA226-AT, SA226-TC, SA227-AC, and SA227-AT referenced in M7 Aerospace

SA226 Series Service Bulletin 226-24-020, revised: August 4, 2008; or M7 Aerospace SA227 Series Service Bulletin 227-24-002, revised:

November 21, 2008. We have no way of determining the number of airplanes that may need this repair:

Labor cost	Parts cost	Total cost per airplane
50 work-hours × \$80 per hour = \$4,000 .....	\$3,000	\$7,000

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

### Examining the AD Docket

You may examine the AD docket that contains the proposed AD, the regulatory evaluation, any comments received, and other information on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone (800) 647-5527) is located at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2008-12-16, Amendment 39-15560 (73 FR 34615, June 18, 2008), and adding the following new AD:

**M7 Aerospace LP:** Docket No. FAA-2009-0119; Directorate Identifier 2008-CE-068-AD.

### Comments Due Date

(a) We must receive comments on this airworthiness directive (AD) action by April 13, 2009.

### Affected ADs

(b) This AD supersedes AD 2008-12-16, Amendment 39-15560.

### Applicability

(c) This AD applies to Models SA226-AT, SA226-T, SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, and SA227-DC (C-26B) airplanes, all serial numbers, that are certificated in any category.

### Unsafe Condition

(d) This AD results from five reports of chafing between the bleed air tube assembly and the electrical starter cables on M7 Aerospace LP SA226 and SA227 series airplanes with one incident resulting in a fire. We are proposing this AD to detect and correct chafing of electrical wires and components, hydraulic tube assemblies, and bleed air tube assemblies. This condition could result in arcing of the exposed wires with consequent burning of a hole in a hydraulic line or the bleed air line. This failure could lead to a possible hydraulic fluid leak and fire in the engine nacelle compartment.

### Compliance

(e) To address this problem, you must do the following, unless already done:

Actions	Compliance	Procedures
<p>(1) For airplanes with the following Model Numbers (M/N) and Serial Numbers (S/N), inspect the main battery leads running forward from the battery compartment for deterioration, cover the four-gauge wires leaving the battery box with firesleeving, and secure them with a clamp:</p> <ul style="list-style-type: none"> <li>(i) M/N SA226-AT, S/N AT-001 through AT-419;</li> <li>(ii) M/N SA226-T, S/N T-201 through T-248;</li> <li>(iii) M/N SA226-TC, S/N TC-201 through TC-419;</li> <li>(iv) M/N SA227-AC (C-26A), S/N AC-420 through AC-539, AC-541, AC-543, AC-544, AC-547 through AC-551; and</li> <li>(v) M/N SA227-AT, S/N AT-423 through AT-551.</li> </ul>	<p>Within 250 hours time-in-service (TIS) after July 23, 2008 (the effective date of AD 2008-12-16).</p>	<p>Use the following service information as applicable:</p> <ul style="list-style-type: none"> <li>(A) For Models SA226-AT, SA226-T, and SA226-TC airplanes: Follow M7 Aerospace SA226 Series Service Bulletin No. 226-24-019, revised: November 21, 2008; or Fairchild Aircraft Corporation SA226 Series Service Bulletin No. SB 24-019, revised: May 17, 1983; or</li> <li>(B) For Models SA227-AC (C-26A) and SA227-AT airplanes: Follow M7 Aerospace SA227 Series Service Bulletin No. 227-24-001, revised: November 21, 2008; or Fairchild Aircraft Corporation SA227 Series Service Bulletin No. SB24-001, revised: May 17, 1983.</li> </ul>
<p>(2) For airplanes with the following M/Ns and S/Ns, reroute the hydraulic tube assemblies in the right wing leading edge, reroute the battery cables and 22-gauge wire bundle, and install a new access panel forward of the battery box:</p> <ul style="list-style-type: none"> <li>(i) M/N SA226-AT, S/N AT-001 through AT-074;</li> <li>(ii) M/N SA226-TC, S/N TC-201 through TC-419;</li> <li>(iii) M/N SA227-AC (C-26A), S/N AC-420 through AC-539, AC-541, AC-543, AC-544, AC-547 through AC-550; and</li> <li>(iv) M/N SA227-AT, S/N AT-423 through AT-551.</li> </ul>	<p>Before further flight after the modification required in paragraph (e)(1) of this AD and you were not able to obtain a minimum 0.50-inch clearance between the bleed air line and the tubing on the battery cables.</p>	<p>Use the following service information as applicable:</p> <ul style="list-style-type: none"> <li>(A) For Models SA226-AT, and SA226-TC airplanes: Follow M7 Aerospace SA226 Series Service Bulletin No. 226-24-020, revised: August 4, 2008; or Fairchild Aircraft Corporation SA226 Series Service Bulletin No. SB 24-020, revised: February 15, 1984; or</li> <li>(B) For Models SA227-AC (C-26A) and SA227-AT, airplanes: Follow M7 Aerospace SA227 Series Service Bulletin No. 227-24-002, revised: November 21, 2008; or Fairchild Aircraft Corporation SA227 Series Service Bulletin No. SB24-002, revised: February 15, 1984.</li> </ul>
<p>(3) For airplane Models SA226-AT, SA226-T, SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-CC, and SA227-DC (C-26B): Inspect electrical wires and components, hydraulic tube assemblies, and bleed air tube assemblies at the left hand and right hand (LH/RH) inboard wing leading edge/battery box areas, LH/RH wing stations 51.167 to 81.174, and at all feed-through locations into the LH/RH inboard keelson for any evidence of chafing or arcing.</p>	<p>Within 250 hours TIS after July 23, 2008 (the effective date of AD 2008-12-16). Repetitively thereafter inspect at intervals not to exceed 12 months.</p>	<p>Use the following service information as applicable:</p> <ul style="list-style-type: none"> <li>(i) For Models SA226-AT, SA226-T, and SA226-TC airplanes: Follow M7 Aerospace SA226 Series Service Bulletin No. 226-24-036, revised November 21, 2008; or M7 Aerospace SA226 Series Service Bulletin No. 226-24-036, issued: September 19, 2007;</li> <li>(ii) For Models SA227-AC (C-26A) and SA227-AT, airplanes: Follow M7 Aerospace SA227 Series Service Bulletin No. 227-24-019, revised: November 21, 2008; or M7 Aerospace SA227 Series Service Bulletin No. 227-24-019, issued: September 19, 2007; or</li> <li>(iii) For Models SA227-CC and SA227-DC (C-26B) airplanes: Follow SA227 Series Commuter Category Service Bulletin No. CC7-24-010, revised November 21, 2008; or SA227 Series Commuter Category Service Bulletin No. CC7-24-010, issued September 19, 2007.</li> </ul>
<p>(4) For airplane Model SA227-BC (C-26A): Inspect the main battery leads running forward from the battery compartment for any evidence of insulation deterioration.</p>	<p>Within 250 hours TIS after the effective date of this AD.</p>	<p>Follow M7 Aerospace SA227 Series Service Bulletin No. 227-24-001, revised: November 21, 2008.</p>
<p>(5) For airplane Model SA227-BC (C-26A): Inspect electrical wires and components, hydraulic tube assemblies, and bleed air tube assemblies at LH/RH inboard wing leading edge/battery box areas, LH/RH wing stations 51.167 to 81.174, and at all feed-through locations into the LH/RH inboard keelson for any evidence of insulation deterioration, chafing, or arcing.</p>	<p>Within 250 hours TIS after the effective date of this AD. Repetitively thereafter inspect at intervals not to exceed 12 months.</p>	<p>Follow M7 Aerospace SA227 Series Service Bulletin No. 227-24-019, revised: November 21, 2008.</p>

Actions	Compliance	Procedures
(6) For all airplane Models: Clear, repair, and/or replace all electrical wires and components, hydraulic tube assemblies, and bleed air tube assemblies, in the inspection area and feed-through locations that show any sign of insulation deterioration, chafing, or arcing, as required.	Before further flight after any inspection required in paragraphs (e)(1), (e)(3), (e)(4), and (e)(5) of this AD where any evidence of insulation deterioration, chafing, or arcing was found.	Use the service information from paragraphs (e)(1), (e)(3), (e)(4), and (e)(5) of this AD, as applicable.

**Note:** Although not a requirement of this AD, you may incorporate Swearingen Aviation Corporation SA226 Series Service Bulletin No. 57-010, revised: December 5, 1975, on those airplanes that have not installed the access panel. Installation of the access panel will simplify the incorporation of the service bulletins referenced in this AD and future inspections of the areas of concern.

#### Alternative Methods of Compliance (AMOCs)

(f) The Manager, Fort Worth Airplane Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Werner Koch, Aerospace Engineer, ASW-150, Fort Worth Airplane Certification Office, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone: (817) 222-5133; fax: (817) 222-5960. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

#### Related Information

(g) To get copies of the service information referenced in this AD, contact M7 Aerospace Repair Station, 10823 NE Entrance Road, San Antonio, Texas 78216; telephone: (210) 824-9421; fax: (210) 804-7766; Internet: <http://www.m7aerospace.com>. To view the AD docket, go to U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, or on the Internet at <http://www.regulations.gov>.

Issued in Kansas City, Missouri, on February 6, 2009.

**Kim Smith,**

Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-3012 Filed 2-11-09; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2008-1253; Airspace Docket No. 08-ANE-103]

#### Establishment of Class E Airspace; Nantucket, MA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** This action proposes to modify Class E Airspace at Nantucket, MA. The development of new Standard Instrument Approach Procedures (SIAPs) and the evaluation of current procedures are requiring the establishment of Class E Surface airspace designated as an extension to Class D airspace. This action would encompass the SIAPs and enhance the safety and airspace management around the Nantucket Memorial Airport, MA.

**DATES:** Comments must be received on or before March 16, 2009.

**ADDRESSES:** Send comments on this rule to: U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590-0001; Telephone: 1-800-647-5527; Fax: 202-493-2251. You must identify the Docket Number FAA-2008-1253; Airspace Docket No. 08-ANE-103, at the beginning of your comments. You may also submit and review received comments through the Internet at <http://www.regulations.gov>.

You may review the public docket containing the rule, any comments received, and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9 a.m. and 5 p.m., Monday through Friday, except Federal Holidays.

An informal docket may also be examined during normal business hours at the office of the Eastern Service Center, Federal Aviation Administration, Room 210, 1701 Columbia Avenue, College Park, Georgia 30337.

#### FOR FURTHER INFORMATION CONTACT:

Daryl Daniels, Airspace Specialist, Operations Support Group, Eastern Service Center, Air Traffic Organization, Federal Aviation Administration, P.O. Box 20636, Atlanta, Georgia 30320; telephone (404) 305-5581.

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

Interested persons are invited to comment on this rule by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Those wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2008-1253; Airspace Docket No. 08-ANE-103." The postcard will be date/time stamped and returned to the commenter. All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

#### Availability of NPRMs

An electronic copy of this document may be downloaded from and comments submitted through <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at [http://www.faa.gov/airports/airtraffic/air\\_traffic/publications/airspace\\_amendments/](http://www.faa.gov/airports/airtraffic/air_traffic/publications/airspace_amendments/). Persons interested in being placed on a mailing list for future NPRMs should