

Material Incorporated by Reference

(i) You must use Bombardier Service Bulletin 601R-27-153, Revision A, dated December 16, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Quebec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on February 5, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-3262 Filed 2-19-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2008-0613; Directorate Identifier 2008-NM-066-AD; Amendment 39-15794; AD 2009-02-04]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300-600 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

One operator experienced failures of four Fuel Level Sensor-Amplifier (FLSA) and

Multi Tank Indicators (MTI) units. FLSA and MTI failures have been identified as having been caused by incorrect connector sleeves material fitted to the MTI units.

Degradation of the electrical insulation sleeves of the Low-level indication lamps on the MTI on the flight deck can cause a short circuit that might result in high voltage being conveyed to the high and low level sensors in the outer tanks. This might cause the level sensor to heat above acceptable limits.

* * * * *

This action is necessary to prevent overheating of the fuel level sensors, which could result in a fuel tank explosion and consequent loss of the airplane. We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective March 27, 2009.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 27, 2009.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1138; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on June 6, 2008 (73 FR 32250). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

One operator experienced failures of four Fuel Level Sensor-Amplifier (FLSA) and Multi Tank Indicators (MTI) units. FLSA and MTI failures have been identified as having been caused by incorrect connector sleeves material fitted to the MTI units.

Degradation of the electrical insulation sleeves of the Low-level indication lamps on the MTI on the flight deck can cause a short circuit that might result in high voltage being conveyed to the high and low level sensors in the outer tanks. This might cause the level sensor to heat above acceptable limits.

For the reasons stated above, this Airworthiness Directive (AD) requires the accomplishment of wiring modifications to protect the FLSA and the Flight Warning

Computers from 115V AC and 28V DC short circuits within the MTI.

This action is necessary to prevent overheating of the fuel level sensors, which could result in a fuel tank explosion and consequent loss of the airplane. You may obtain further information by examining the MCAI in the AD docket.

Actions Since NPRM Was Issued

Since we issued the NPRM, Airbus has issued Mandatory Service Bulletin A300-28A6096, Revision 02, dated July 4, 2008. In the NPRM, we referred to Airbus Mandatory Service Bulletin A300-28A6096, Revision 01, dated April 16, 2008, as the source of service information for doing the modification. The procedures in Airbus Mandatory Service Bulletin A300-28A6096, Revision 02, dated July 4, 2008, are essentially the same as those in Airbus Mandatory Service Bulletin A300-28A6096, Revision 01, dated April 16, 2008. Therefore, we have revised paragraph (f) of this AD to refer to Airbus Mandatory Service Bulletin A300-28A6096, Revision 02, dated July 4, 2008, as the appropriate source of service information for doing the modification, and to give credit for using Airbus Mandatory Service Bulletin A300-28A6096, Revision 01, dated April 16, 2008, for accomplishing the modification before the effective date of the AD.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Request To Delay Issuance of AD

Air Transport Association (ATA), on behalf of its member American Airlines (AA), and UPS and FedEx ask that we delay issuance of the AD until the master minimum equipment list (MMEL) can be revised to support the low-level warning configuration. AA, UPS, and FedEx state that disconnection of the low-level warning for the left and right outer fuel tanks requires significant changes to the Airbus A300-600 MMEL. AA, UPS, and FedEx add that the current MMEL available to U.S. operators cannot support the disconnected low-level warning configuration; therefore, the AD should not be released until the MMEL has been revised.

We disagree with the commenter's request and rationale for delaying issuance of the AD. Revision 16 of the MMEL, dated October 2008, has been released and is available to U.S. operators. Revision 16 of the MMEL supports the low-level warning

configuration. Therefore, we have made no change to the AD in this regard.

Request To Extend Compliance Time

ATA, on behalf of its member AA, and UPS and FedEx ask that we revise the compliance time specified in the NPRM from 90 to 180 days to allow FAA approval of the air carrier's customized MEL after it has been revised, and to facilitate distribution.

We disagree with the commenters. As stated above, the revised MMEL has been released and is available to air carriers. We have determined that the 3-month compliance time specified in this AD is adequate to address the unsafe condition in a timely manner. We have made no change to the AD in this regard.

Request To Include Alternate Terminating Action

ATA on behalf of its member AA, and UPS and FedEx ask that the AD include alternative terminating action for operators that install multi-task indicators (MTIs) that have been modified per Smiths Service Bulletin 1410KID-28-468, and installed per Airbus Mandatory Service Bulletin A300-28-6101, dated June 4, 2008. AA and FedEx state that once the MTI is modified the unsafe condition specified in the NPRM will be addressed. UPS states that the improved sleeve installed per Airbus Mandatory Service Bulletin A300-28-6101, dated June 4, 2008, addresses the concerns in the NPRM.

We disagree with the commenters. Based on information provided by Airbus, Airbus Mandatory Service Bulletin A300-28-6101, dated June 4, 2008, does not contain a final fix for the unsafe condition specified in the AD. Airbus is currently developing two modifications that provide the final solution to address the unsafe condition identified in this AD. Once these modifications are developed, approved, and available, we might consider additional rulemaking which would terminate the AD requirements. We have made no change to the AD in this regard.

Conclusion

We reviewed the available data, including the comments received, and determined that air safety and the public interest require adopting the AD with the change described previously. We determined that this change will not increase the economic burden on any operator or increase the scope of the AD.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect 151 products of U.S. registry. We also estimate that it will take about 5 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$0 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$60,400, or \$400 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on

the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2009-02-04 Airbus: Amendment 39-15794. FAA-2008-0613; Directorate Identifier 2008-NM-066-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective March 27, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to all Airbus Model A300–600 airplanes, certificated in any category; all certified models, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

One operator experienced failures of four Fuel Level Sensor-Amplifier (FLSA) and Multi Tank Indicators (MTI) units. FLSA and MTI failures have been identified as having been caused by incorrect connector sleeves material fitted to the MTI units.

Degradation of the electrical insulation sleeves of the Low-level indication lamps on the MTI on the flight deck can cause a short circuit that might result in high voltage being conveyed to the high and low level sensors in the outer tanks. This might cause the level sensor to heat above acceptable limits.

For the reasons stated above, this Airworthiness Directive (AD) requires the accomplishment of wiring modifications to protect the FLSA and the Flight Warning Computers from 115V AC and 28V DC short circuits within the MTI.

This action is necessary to prevent overheating of the fuel level sensors, which could result in a fuel tank explosion and consequent loss of the airplane.

Actions and Compliance

(f) Unless already done, within 3 months after the effective date of this AD: Modify the wiring in the right-hand electronics rack in accordance with the Accomplishment Instructions of Airbus Mandatory Service Bulletin A300–28A6096, Revision 02, dated July 4, 2008. Previous accomplishment of the modification before the effective date of this AD in accordance with Airbus Mandatory Service Bulletin A300–28A6096, dated October 19, 2007; or Revision 01, dated April 16, 2008; meets the requirements in this paragraph.

FAA AD Differences

Note: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM–116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–1138; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008–0055, dated March 5, 2008, and Airbus Mandatory Service Bulletin A300–28A6096, Revision 02, dated July 4, 2008, for related information.

Material Incorporated by Reference

(i) You must use Airbus Mandatory Service Bulletin A300–28A6096, Revision 02, dated July 4, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information that is incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221 or 425–227–1152.

(4) You may also review copies of the service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on December 28, 2008.

Linda Navarro,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. E9–3277 Filed 2–19–09; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2007–0219; Directorate Identifier 2007–NE–46–AD; Amendment 39–15806; AD 2009–03–05]

RIN 2120–AA64

Airworthiness Directives; Pratt & Whitney Canada PW206A, PW206B, PW206B2, PW206C, PW206E, PW207C, PW207D, and PW207E Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

PW206 and PW207 compressor turbine (CT) disc bore areas may experience impact damage resulting from bending or fracture of the CT disc retaining nut. Damage of the CT disc bore area can reduce LCF capabilities of the CT disc, resulting in disc fracture.

We are issuing this AD to prevent damage to the CT disc bore area, which could result in possible uncontained failure of the engine and damage to the helicopter.

DATES: This AD becomes effective March 27, 2009. The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 27, 2009.

ADDRESSES: The Docket Operations office is located at Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue, SE., West Building Ground Floor, Room W12–140, Washington, DC 20590–0001.

FOR FURTHER INFORMATION CONTACT: Ian Dargin, Aerospace Engineer, Engine Certification Office, FAA, Engine and Propeller Directorate, 12 New England Executive Park; Burlington, MA 01803; e-mail: ian.dargin@faa.gov; telephone (781) 238–7178; fax (781) 238–7199.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That