

(2) If any incorrect fit, damage, or wear is found, before next flight, do related investigative actions and applicable corrective actions in accordance with the Accomplishment Instructions of the service bulletin.

New Requirements of This AD: Actions and Compliance

(g) Unless already done: Within 12 months after the effective date of this AD, inspect for deviations of the aerodynamic seal of the wing-to-fuselage fairings and the fuselage skin, do all applicable related investigative and corrective actions, and apply a fillet seam between the fairings and the fuselage skin, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-53-107, dated February 26, 2008. Do all applicable related investigative and corrective actions before further flight. Accomplishment of this inspection terminates the actions required by paragraph (f) of this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows:
No differences.

Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, ANM-116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 227-1137; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(i) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0079, dated April 24, 2008; Fokker Service Bulletin SBF100-53-101, dated September 30, 2005; and Fokker Service Bulletin SBF100-53-107, dated February 26, 2008; for related information.

Material Incorporated by Reference

(j) You must use Fokker Service Bulletin SBF100-53-101, dated September 30, 2005; and Fokker Service Bulletin SBF100-53-107, dated February 26, 2008; as applicable; to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of Fokker Service Bulletin SBF100-53-107, dated February 26, 2008, under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) The Director of the Federal Register previously approved the incorporation by reference of Fokker Service Bulletin SBF100-53-101, dated September 30, 2005, on April 3, 2008 (73 FR 10650, February 28, 2008).

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 231, 2150 AE Nieuw-Vennep, the Netherlands; telephone +31 (0)252-627-350; fax +31 (0)252-627-211; e-mail technicalservices.fokkerservices@stork.com; Internet <http://www.myfokkerfleet.com>.

(4) You may review copies of the service information that is incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(5) You may also review copies of the service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on January 15, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-3365 Filed 2-25-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2008-1141; Directorate Identifier 2008-NM-025-AD; Amendment 39-15799; AD 2009-02-09]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing

airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During removal of forward and aft wing links, corrosion has been found on the wing links and the wing link attachment bolts in areas that are not readily accessible during the currently required Maintenance Review Board Report (MRBR) zonal inspections or Corrosion Prevention and Control Programme (CPCP) inspections. If left uncorrected, such corrosion could adversely affect the structural integrity of the wing to fuselage joint.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective April 2, 2009.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 2, 2009.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on October 31, 2008 (73 FR 64897). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

During removal of forward and aft wing links, corrosion has been found on the wing links and the wing link attachment bolts in areas that are not readily accessible during the currently required Maintenance Review Board Report (MRBR) zonal inspections or Corrosion Prevention and Control Programme (CPCP) inspections. If left uncorrected, such corrosion could adversely affect the structural integrity of the wing to fuselage joint.

For this reason, this Airworthiness Directive (AD) requires repetitive detailed visual inspections at the forward and aft wing links and wing link attachment bolts for

signs of corrosion, replacement of corroded nuts and bolts and repair of any defects.

The MRBR and CPCP will be amended to include the repeat inspections. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a Note within the AD.

Costs of Compliance

We estimate that this AD will affect about 1 product of U.S. registry. We also estimate that it will take about 20 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$1,600.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

- Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

2009-02-09 BAE Systems (Operations) Limited (Formerly British Aerospace Regional Aircraft): Amendment 39-15799. Docket No. FAA-2008-1141; Directorate Identifier 2008-NM-025-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective April 2, 2009.

Affected ADs

(b) None.

Applicability

(c) This AD applies to BAE Systems (Operations) Limited Model BAe 146-100A, -200A, and -300A series airplanes; and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes, certificated in any category, all models, all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 53: Fuselage.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: During removal of forward and aft wing links, corrosion has been found on the wing links and the wing link attachment bolts in areas that are not readily accessible during the currently required Maintenance Review Board Report (MRBR) zonal inspections or Corrosion Prevention and Control Programme (CPCP) inspections. If left uncorrected, such corrosion could adversely affect the structural integrity of the wing to fuselage joint.

For this reason, this Airworthiness Directive (AD) requires repetitive detailed visual inspections at the forward and aft wing links and wing link attachment bolts for signs of corrosion, replacement of corroded nuts and bolts and repair of any defects.

The MRBR and CPCP will be amended to include the repeat inspections.

Actions and Compliance

(f) Unless already done, do the following actions: Before accumulating 48 months on the wing link since new, or within 48 months of a wing link being repaired in accordance with a BAE Systems (Operations) Limited or European Aviation Safety Agency (EASA) approved repair scheme, or within 24 months after the effective date of this AD, whichever occurs latest, and thereafter at intervals not to exceed 48 months, inspect the wing links in accordance with paragraph 2.C. of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-203, dated May 7, 2007 ("the service bulletin").

(1) If any corrosion is found on bolts or nuts, replace the affected bolts and nuts with airworthy parts before next flight in accordance with the service bulletin.

(2) If any corrosion to the wing links is found during an inspection, repair before further flight in accordance with a method approved in accordance with EASA (or its delegated agent).

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI EASA Airworthiness Directive 2007-0303, dated December 14, 2007, and BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-203, dated May 7, 2007, for related information.

Material Incorporated by Reference

(i) You must use BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53-203, dated May 7, 2007, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact BAE Systems Regional Aircraft, 13850 McLearen Road, Herndon, Virginia 20171; telephone 703-736-1080; e-mail raebusiness@baesystems.com; Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(3) You may review copies of the service information that is incorporated by reference at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on January 15, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-3366 Filed 2-25-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2007-0254; Directorate Identifier 2007-NM-209-AD; Amendment 39-15795; AD 2009-02-05]

RIN 2120-AA64

Airworthiness Directives; Boeing Model 777 Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Boeing Model 777 airplanes. This AD requires installing software upgrades to the airplane information management system (AIMS) located in the flight compartment. This AD results from an investigation that revealed that detrimental effects could occur on certain AIMS software during flight. We are issuing this AD to prevent an unannounced loss of cabin pressure. If an undetected loss of pressure event were to cause an unsafe pressure in the cabin, the flight crew could become incapacitated.

DATES: This AD is effective April 2, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 2, 2009.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1, fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the

Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Jay Yi, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, Washington 98057-3356; telephone (425) 917-6494; fax (425) 917-6590.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an airworthiness directive (AD) that would apply to certain Boeing Model 777 airplanes. That NPRM was published in the **Federal Register** on November 28, 2007 (72 FR 67263). That NPRM proposed to require installing software upgrades to the airplane information management system (AIMS) located in the flight compartment.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comments received.

Request To Incorporate Revised Service Information

Boeing asks that we reference Boeing Service Bulletins 777-31A0119 and 777-31A0120, both Revision 2, both dated June 12, 2008, in the final rule. Boeing Alert Service Bulletin 777-31A0119, Revision 1, dated March 27, 2007; and Boeing Alert Service Bulletin 777-31A0120, Revision 1, dated March 23, 2007; were referenced in the NPRM as the appropriate sources of service information for accomplishing certain actions. Revision 2 of the service bulletins clarifies the procedures for upgrading to the Airplane Information Management System-1 (AIMS-1) Blockpoint 2006 (BP06) operational software.

We have reviewed Revision 2 of these service bulletins and we agree with the commenter, since no additional work is necessary on airplanes changed in accordance with Revision 1 of the referenced service information; Revision 2 of these service bulletins just provides certain clarifications. We have added Revision 2 of these service bulletins to the applicability specified in paragraph (c) of this AD, and to paragraph (f)(1) of this AD, as the appropriate sources of service information for accomplishing the actions specified. In addition, we have added credit for accomplishing the