

revised and allows the use of "Any subsequent approved revision of this document is acceptable" for service bulletin revisions. The FAA AD does not have a similar provision. This proposed revised AD will change the Applicability section based on the revised service bulletin.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; *telephone*: (816) 329-4119; *fax*: (816) 329-4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 et seq.), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(h) Refer to MCAI Direction Générale de l'aviation Civile Airworthiness Directive No F-2005-132, dated August 3, 2005; SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-129, dated June 2005; and SOCATA TBM Aircraft Mandatory Service Bulletin SB 70-129, AMENDMENT 1, dated February 2009 for related information.

Issued in Kansas City, Missouri, on May 6, 2009.

#### Scott A. Horn,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-11022 Filed 5-11-09; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2009-0446; Directorate Identifier 2009-CE-024-AD]

RIN 2120-AA64

#### Airworthiness Directives; EADS-PZL "Warszawa-Okęcie" S.A. Model PZL-104 WILGA 80 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above that would supersede an existing AD. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

An inspection of a PZL-104 aeroplane that had a relatively long operational background revealed a severe corrosion of the steel front fuselage structural elements.

It is likely that such corrosion can also be present on other aeroplanes of similar design and operational history.

If left uncorrected, this condition could lead to loss of strength of the structural front posts elements and consequent reduction of the structural strength of the aeroplane.

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by June 11, 2009.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: (202) 493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

*www.regulations.gov*; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; *telephone*: (816) 329-4059; *fax*: (816) 329-4090.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2009-0446; Directorate Identifier 2009-CE-024-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2009-0072, dated March 31, 2009 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

An inspection of a PZL-104 aeroplane that had a relatively long operational background revealed a severe corrosion of the steel front fuselage structural elements.

It is likely that such corrosion can also be present on other aeroplanes of similar design and operational history.

If left uncorrected, this condition could lead to loss of strength of the structural front posts elements and consequent reduction of the structural strength of the aeroplane.

For the reason stated above, this Airworthiness Directive (AD) mandates inspecting the fuselage front posts, repairing any corrosion found and replacing pads made of foam rubber by pads made of Neoprene to prevent water ingress.

You may obtain further information by examining the MCAI in the AD docket.

On April 15, 2009, we issued AD 2009-09-04, Amendment 39-15890 (74 FR 18979; April 27, 2009). That AD required actions intended to address an unsafe condition on the products listed above.

The Administrative Procedure Act does not permit the FAA to “bootstrap” a long-term requirement into an urgent safety of flight action where the rule becomes effective at the same time the public has the opportunity to comment. The short-term action and the long-term action were analyzed separately for justification to bypass prior public notice.

We are issuing this proposed AD to address the mandatory long-term action of repetitively inspecting the fuselage front posts through a revision to the airplane maintenance program.

#### Relevant Service Information

EADS PZL “Warszawa-Okęcie” S.A. has issued:

- Mandatory Bulletin (MB) No. 10409036, dated March 18, 2009; and
- PZL-104 Wilga 80 Maintenance Manual, pages 5-4 and 25-10, dated April 7, 2009.

The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA’s Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This Proposed AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the proposed AD.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD will affect 26 products of U.S. registry. We also estimate that it would take about 50 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$80 per work-hour. Required parts would cost about \$150 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$107,900, or \$4,150 per product.

In addition, we estimate that any necessary follow-on actions would take about 10 work-hours and require parts costing \$0, for a cost of \$800 per product. We have no way of determining the number of products that may need these actions.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;

2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and

3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by removing Amendment 39-15890 (74 FR 18979; April 27, 2009), and adding the following new AD:

#### EADS-PZL “Warszawa-Okęcie” S.A.:

Docket No. FAA-2009-0446; Directorate Identifier 2009-CE-024-AD.

#### Comments Due Date

(a) We must receive comments by June 11, 2009.

#### Affected ADs

(b) This AD supersedes AD 2009-09-04, Amendment 39-15890.

#### Applicability

(c) This AD applies to Model PZL-104 WILGA 80 airplanes, all serial numbers, certificated in any category.

#### Subject

(d) Air Transport Association of America (ATA) Code 53: Fuselage.

#### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

An inspection of a PZL-104 aeroplane that had a relatively long operational background revealed a severe corrosion of the steel front fuselage structural elements.

It is likely that such corrosion can also be present on other aeroplanes of similar design and operational history.

If left uncorrected, this condition could lead to loss of strength of the structural front posts elements and consequent reduction of the structural strength of the aeroplane.

For the reason stated above, this Airworthiness Directive (AD) mandates

inspecting the fuselage front posts, repairing any corrosion found and replacing pads made of foam rubber by pads made of Neoprene to prevent water ingress.

#### Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within 12 years from date of manufacture or within the next 2 months after May 18, 2009 (the effective date of AD 2009–09–04), whichever occurs later, inspect the fuselage front posts for signs of corrosion following paragraph 6.A. of EADS PZL “Warszawa-Okecie” S.A. Mandatory Bulletin No. 10409036, dated March 18, 2009.

(2) If corrosion or any corrosion damage is found during the inspection required in paragraph (f)(1) of this AD, before further flight, repair or replace any parts where corrosion or corrosion damage was found in accordance with an FAA-approved repair solution obtained from EADS–PZL “Warszawa-Okecie” S.A., Aleja Krakowska 110/114, 00–971 Warszawa, Poland; telephone: +48 22 577 22 11; fax: +48 22 577 22 03; e-mail: eadsplz@plz.eads.net.

(3) Within 12 years from date of manufacture or within the next 2 months after May 18, 2009 (the effective date of AD 2009–09–04), whichever occurs later, replace the rear glass padding following paragraph 6.C. of EADS PZL “Warszawa-Okecie” S.A. Mandatory Bulletin No. 10409036, dated March 18, 2009.

(4) Within 2 months after the effective date of this AD, amend the approved operator’s airplane maintenance program to incorporate the applicable tasks as described in PZL–104 Wilga 80 Maintenance Manual, pages 5–4 and 25–10, dated April 7, 2009.

#### FAA AD Differences

**Note:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested, using the procedures found in 14 CFR 39.19. Send information to *Attn:* Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329–4059; fax: (816) 329–4090. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the

provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

#### Related Information

(h) MCAI European Aviation Safety Agency (EASA) AD No.: 2009–0072, dated March 31, 2009, EADS PZL “Warszawa-Okecie” S.A. Mandatory Bulletin No. 10409036, dated March 18, 2009; and PZL–104 Wilga 80 Maintenance Manual, pages 5–4 and 25–10, dated April 7, 2009, for related information.

Issued in Kansas City, Missouri, on May 6, 2009.

**Scott A. Horn,**

*Acting Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. E9–11028 Filed 5–11–09; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF THE TREASURY

### 31 CFR Part 103

**RIN 1506–AA97**

#### Financial Crimes Enforcement Network; Amendment to the Bank Secrecy Act Regulations—Definitions and Other Regulations Relating to Money Services Businesses

**AGENCY:** Financial Crimes Enforcement Network (FinCEN), Department of the Treasury.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** The Financial Crimes Enforcement Network (“FinCEN”), a bureau of the Department of the Treasury (“Treasury”), is proposing to revise the regulations implementing the Bank Secrecy Act (“BSA”) regarding money services businesses (“MSBs”) to clarify which entities are covered by the definitions. Specifically, we are reviewing the MSB regulatory framework with a focus on providing efficient and effective regulation for the industry, as well as improving the ability of regulators, law enforcement, and FinCEN to safeguard the U.S. financial system from the abuses of terrorist financing, money laundering, and other financial crime.

The proposed changes are intended to more clearly delineate the scope of entities regulated as MSBs, so that determining which entities are obligated to comply will be more straightforward and predictable. This rulemaking proposes to amend the current MSB regulations in the following ways: By ensuring that certain foreign-located MSBs with a U.S. presence are subject to the BSA rules; by updating the MSB

definitions to reflect past guidance and rulings, current business operations, evolving technologies, and merging lines of business; and by combining all of stored value into one category, without substantively changing the existing definition, so that issuers of stored value and sellers or redeemers of stored value are in the same category. In addition, this rulemaking solicits comments on stored value to assist FinCEN with a future rulemaking proposing a revised definition of stored value and revising related regulations.

**DATES:** Written comments on the notice of proposed rulemaking must be submitted on or before September 9, 2009.

**ADDRESSES:** You may submit comments, identified by RIN 1506–AA97, by any of the following methods:

- *Federal e-rulemaking portal:* <http://www.regulations.gov>. Follow the instructions for submitting comments. Refer to Docket number TREAS–FinCen–2009–0002.

- *Mail:* FinCEN, P.O. Box 39, Vienna, VA 22183. Include RIN 1506–AA97 in the body of the text.

*Inspection of comments:* Comments may be inspected, between 10 a.m. and 4 p.m., in the FinCEN reading room in Vienna, VA. Persons wishing to inspect the comments submitted must request an appointment with the Disclosure Officer by telephoning (703) 905–5034 (Not a toll free call).

**FOR FURTHER INFORMATION CONTACT:** Regulatory Policy and Programs Division, FinCEN (800) 949–2732 and select option 1.

#### SUPPLEMENTARY INFORMATION:

##### I. Introduction

The term MSB, as currently defined in the BSA regulations, refers to each of the following distinct categories of financial service providers: (1) Currency dealer or exchanger, (2) check casher, (3) issuer of traveler’s checks, money orders, or stored value, (4) seller or redeemer of traveler’s checks, money orders, or stored value, (5) money transmitter, and (6) the United States Postal Service.<sup>1</sup>

MSBs play a critical role in providing financial services to, among others, a segment of the population that generally does not maintain bank accounts. Law enforcement, FinCEN, and other federal regulators have repeatedly stressed the need to prevent transactions that typically flow through these businesses from going underground, which would diminish transparency with respect to these transactions. Because MSBs

<sup>1</sup> 31 CFR 103.11(uu)(1)–(6).