

(c) Expenditures for Adjustment Assistance under this section may be up to \$10,000,000 annually per industry, subject to availability of funds, and shall be made under such terms and conditions as EDA deems appropriate.

Dated: August 13, 2009.

Dennis Alvord,

*Acting Deputy Assistant Secretary of
Commerce for Economic Development.*

[FR Doc. E9-19774 Filed 8-17-09; 8:45 am]

BILLING CODE 3510-24-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0447; Directorate Identifier 2008-NM-172-AD; Amendment 39-15993; AD 2009-17-02]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Saab Aerosystems Model SAAB 340A (SAAB/SF340A) and SAAB 340B Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

During refueling, the ground crew detected smoke from the refuel/defuel panel illuminated placard 160VU. * * *

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective September 22, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 22, 2009.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace

Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on May 14, 2009 (74 FR 22712). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

During refueling, the ground crew detected smoke from the refuel/defuel panel illuminated placard 160VU. The design of the refuel/defuel panel illuminated placard was changed during 1997 from its original specification, to fill the cavity inside the placard with silicone to avoid moisture/fluid ingress. SAAB has reviewed the working procedure and has developed a placard filled with a bi-component silicone-based material to minimize the cavity inside the panels.

For the reasons described above, this EASA AD requires the identification of the manufacturing date of the affected placard, a visual inspection of the placard for heat and/or burn marks and the installation of a new placard in accordance with the instructions of SAAB Service Bulletin (SB) 340-28-027.

This AD has been revised to identify the affected VIBRACHOC (the part manufacturer) placard with Part Number (P/N) C4FL5031C001, instead of the corresponding SAAB P/N 9303719-001, which was (also) quoted inaccurately. In addition, it has been recognised that the original AD did not allow installation of the placards with a manufacturing date before 31/97; that has now been corrected.

The unsafe condition is an electrical malfunction in the illuminated placard of the refuel and defuel panel, which could result in fire. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between this AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use

different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a note within the AD.

Costs of Compliance

We estimate that this AD will affect 141 products of U.S. registry. We also estimate that it will take about 2 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Required parts will cost about \$1,500 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$234,060, or \$1,660 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

2009-17-02 Saab AB, Saab Aerosystems:
Amendment 39-15993. Docket No. FAA-2009-0447; Directorate Identifier 2008-NM-172-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective September 22, 2009.

Affected ADs

(b) None.

Applicability

(c) Saab AB, Saab Aerosystems Model SAAB 340A (SAAB/SF340A) and SAAB 340B airplanes; certificated in any category; all serial numbers.

Subject

(d) Air Transport Association (ATA) of America Code 28: Fuel.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

During refueling, the ground crew detected smoke from the refuel/defuel panel illuminated placard 160VU. The design of the refuel/defuel panel illuminated placard was changed during 1997 from its original specification, to fill the cavity inside the placard with silicone to avoid moisture/fluid ingress. SAAB has reviewed the working procedure and has developed a placard filled with a bi-component silicone-based material to minimize the cavity inside the panels.

For the reasons described above, this EASA AD requires the identification of the manufacturing date of the affected placard, a visual inspection of the placard for heat and/or burn marks and the installation of a new placard in accordance with the instructions of SAAB Service Bulletin (SB) 340-28-027.

This AD has been revised to identify the affected VIBRACHOC (the part manufacturer) placard with Part Number (P/N) C4FL5031C001, instead of the corresponding SAAB P/N 9303719-001, which was (also) quoted inaccurately. In addition, it has been recognized that the original AD did not allow installation of the placards with a manufacturing date before 31/97; that has now been corrected.

The unsafe condition is an electrical malfunction in the illuminated placard of the refuel and defuel panel, which could result in fire.

Actions and Compliance

(f) Unless already done, do the following actions:

(1) Within 3 months after the effective date of this AD, inspect the illuminated placard of the refuel and defuel panel, part number (P/N) C4FL5031C001, for signs of heat and burn marks, in accordance with Saab Service Bulletin 340-28-027, Revision 01, dated July 7, 2008.

(2) If any sign of heat or burn marks are found, before further flight, replace the illuminated placard of the refuel and defuel panel with a new illuminated placard of the refuel and defuel panel, having part number C4FL5031C001, and marked with a manufacturer date before 31/97 (*i.e.*, week 31 of 1997), or a manufacturing date of 37/07 (*i.e.*, week 37 of 2007) or higher and marked 'Amdt:A.', in accordance with Saab Service Bulletin 340-28-027, Revision 01, dated July 7, 2008.

(3) If no signs of heat and burn marks are found, within 12 months after accomplishing the inspection required by (f)(1) of this AD is done, replace the illuminated placard of the fuel and defuel panel with a new illuminated placard of the refuel and defuel panel, having part number C4FL5031C001, and marked with a manufacturer date before 31/97 (*i.e.*, week 31 of 1997) or a manufacturing date of 37/07 (*i.e.*, week 37 of 2007) or higher and marked 'Amdt:A.', in accordance with Saab Service Bulletin 340-28-027, Revision 01, dated July 7, 2008.

(4) As of 15 months after the effective date of this AD, installing an illuminated placard of the refuel and defuel panel is prohibited on any airplane, unless it has a manufacturing date before 31/97, or unless it has a manufacturing date of 37/07 or higher and is marked 'Amdt:A'.

(5) Actions accomplished before the effective date of this AD in accordance with Saab Service Bulletin 340-28-027, dated April 30, 2008, are considered acceptable for compliance with the corresponding actions specified in paragraphs (f)(1), (f)(2), and (f)(3) of this AD.

FAA AD Differences

Note 1: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(g) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to Attn: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1112; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act, the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(h) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2008-0127R1, dated August 7, 2008; and Saab Service Bulletin 340-28-027, Revision 01, dated July 7, 2008, for related information.

Material Incorporated by Reference

(i) You must use Saab Service Bulletin 340-28-027, Revision 01, dated July 7, 2008, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Saab Aircraft AB, SAAB Aerosystems, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; e-mail saab2000.techsupport@saabgroup.com; Internet <http://www.saabgroup.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 3, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-19182 Filed 8-17-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0532; Directorate Identifier 2008-NM-024-AD; Amendment 39-15994; AD 2009-17-03]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The airbrake upper crossbeam on an airplane failed in-flight. The crossbeam failure caused damage to the rudder control system, resulting in loss of rudder control. Loss of rudder control will cause handling difficulties particularly during take-off, approach, and landing phases in cross winds.

* * * * *

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective September 22, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 22, 2009.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on June 11, 2009 (74 FR 27725). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

The airbrake upper crossbeam on an airplane failed in-flight. The crossbeam failure caused damage to the rudder control system, resulting in loss of rudder control. Loss of rudder control will cause handling difficulties particularly during take-off, approach, and landing phases in cross winds.

BAE Systems (Operations) Ltd has published Inspection Service Bulletin (ISB) 53-200 that revises and supersedes the inspection requirements, which are defined in the Maintenance Review Board Report (MRBR) SSI Task 53-40-125, Supplemental Structural Inspections Document (SSID) Tasks 53-40-125.1 and 53-40-125.2 (included in the Airworthiness Limitations Section of Aircraft Maintenance Manual Chapter 5 that is currently mandated as part of EASA AD 2007-0271 [which corresponds to an FAA NPRM, Directorate Identifier 2007-NM-363-AD]) and in Maintenance Planning Document (MPD) Task Reference 534025-DVI-10000-1. These revised inspection requirements and reduced inspection periods are to ensure that any fatigue damage is detected before it causes upper airbrake crossbeam failure. MRBR, SSID and MPD will be amended in due course to reflect these revised inspection periods.

For the reasons stated above, this Airworthiness Directive (AD) requires the [high frequency eddy current and low frequency phase analysis eddy current] inspection [for cracking, discrete surface damage, and discontinuity (corrosion and mechanical damage)] and, as necessary, repair of the airbrake upper crossbeam.

The required actions include replacing the three rivets with Hi-lok pins. For cracking, damage, or discontinuity that is outside certain limits defined in the service bulletin, the repair includes contacting BAE Systems (Operations) Limited for repair instructions and doing the repair. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a note within the AD.

Costs of Compliance

We estimate that this AD affects 1 product of U.S. registry. We also estimate that it takes about 6 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$80 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$480 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in