

TABLE 1—ENGINE MODELS AFFECTED

O-470-G, K, L, R, S, M, U
 IO-470-C, D, E, F, H, L, M, N, S, U, V, VO
 TSIO-470-B, C, D
 IO-520-A, B, BA, BB, C, CB, D, E, F, J, K,
 L, M, MB
 TSIO-520-AF, B, BB, C, CE, D, DB, E, EB,
 G, H, J, JB, K, KB, L, LB, M, N, NB, P, R,
 T, UB, VB, WB
 IO-550-A, B, C, D, E, F, L
 IOF-550-B, C, D, E, F, L

(d) These engines are installed on, but not limited to, Alexandria Aircraft LLC (formerly Bellanca) model 300 Super Viking; Beech Bonanza 33, 35 and 36 series, Beech Baron 56 and 58 series, Cessna 180, 182, 188, 205, 206, 207, 210, 303, 310, 320, 402, and 414 model series; Aero Commander 200 and 500; certain Rockwell (formerly Meyers) Windecker Eagle 200, and Navion airplanes.

Unsafe Condition

(e) This AD results from reports of 35 EQ3 cylinders found cracked. We are issuing this AD to prevent loss of engine power due to cracks in the cylinder head, possible engine failure, and fire in the engine compartment.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified unless the actions have already been done.

Identification and Initial Visual Inspection

(g) Within 20 flight hours after the effective date of this AD, identify EQ3 cylinders using Step 1 of TCM MSB No. MSB09-1B, dated July 14, 2009.

(1) Within 20 flight hours after the effective date of this AD, for EQ3 cylinders with 400 or more hours total time of operation on the effective date of this AD, perform an initial visual inspection of the cylinder for cracks using Step 2, paragraph B, of TCM MSB No. MSB09-1B, dated July 14, 2009.

(2) For EQ3 cylinders with fewer than 400 hours total time of operation on the effective date of this AD, perform an initial visual inspection of the cylinder for cracks before reaching 400 hours total time of operation, using Step 2, paragraph B, of TCM MSB No. MSB09-1B, dated July 14, 2009.

(3) Remove from service before flight, any cylinders found cracked.

Repetitive Visual Inspections

(h) Repeat the visual inspections required by this AD every 50 hours of operation. Use Step 2, paragraph B, of TCM MSB No. MSB09-1B, dated July 14, 2009, to perform the inspection.

(i) Remove from service before flight, any cylinders found cracked.

Removal of All EQ3 Cylinders From Service

(j) Within 1,300 hours total time of operation after the effective date of this AD, remove all EQ3 cylinders from service.

EQ3 Cylinder Installation Prohibition

(k) After the effective date of this AD, do not install any EQ3 cylinder onto any engine, or any EQ3 cylinder-equipped engine, onto any aircraft.

Previous Credit

(l) Initial visual inspections done before the effective date of this AD per TCM MSB No. MSB09-1A, dated March 11, 2009, comply with the initial inspection requirements specified in this AD.

Alternative Methods of Compliance

(m) The Manager, Atlanta Aircraft Certification Office, has the authority to approve alternative methods of compliance for this AD if requested using the procedures found in 14 CFR 39.19.

Special Flight Permits

(n) Under 14 CFR 39.23, we are limiting the special flight permits for this AD to engines that have no evidence of fuel or combustion staining in the cylinder crack location, and for a total special flight time of 5 hours.

Related Information

(o) Contact Anthony Holton, Engineer, Propulsion, Atlanta Aircraft Certification Office, FAA, Small Airplane Directorate, 1701 Columbia Avenue, College Park, Georgia 30337; e-mail anthony.holton@faa.gov; telephone: (404) 474-5567; fax: (404) 474-5606, for more information about this AD.

Material Incorporated by Reference

(p) You must use Teledyne Continental Motors Mandatory Service Bulletin No. MSB09-1B, dated July 14, 2009, to perform the actions required by this AD. The Director of the Federal Register approved the incorporation by reference of this service bulletin in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Contact Teledyne Continental Motors, Inc., PO Box 90, Mobile, AL 36601; telephone (251) 438-3411, or go to: <http://tcmlink.com/servicebulletins.cfm>, for a copy of this service information. You may review copies at the FAA, New England Region, 12 New England Executive Park, Burlington, MA; or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on September 8, 2009.

Peter A. White,

Assistant Manager, Engine and Propeller Directorate, Aircraft Certification Service.

[FR Doc. E9-22287 Filed 9-21-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD; Amendment 39-16011; AD 2009-18-15]

RIN 2120-AA64

Airworthiness Directives; Airbus Model A300, A310, and A300-600 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding an existing airworthiness directive (AD), which applies to certain Airbus Model A300 and A310 series airplanes. That AD currently requires replacement of the nose landing gear drag strut upper attachment pin. This new AD requires revising the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness (ICA) to require additional life limits and/or replacements for certain main landing gear and nose landing gear components, and also expands the applicability. This AD results from revisions to the ALS of the ICA to include new or more restrictive life limits and/or replacements. We are issuing this AD to ensure the continued structural integrity of these airplanes.

DATES: This AD becomes effective October 27, 2009.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of October 27, 2009.

ADDRESSES: For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is the Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West

Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that supersedes AD 87-16-06, amendment 39-5692 (52 FR 28241, July 29, 1987). The existing AD applies to certain Airbus Model A300 and A310 series airplanes. That NPRM was published in the **Federal Register** on April 1, 2009 (74 FR 14751). That NPRM proposed to continue to require replacement of the nose landing gear drag strut upper attachment pin. That NPRM also proposed to require revising the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness (ICA) to require additional life limits and/or replacements for certain main landing gear and nose landing gear components, and would also expand the applicability.

Comments

We provided the public the opportunity to participate in the development of this AD. We have considered the comments that have been received on the NPRM.

Request To Add Grace Period

TradeWinds Airlines requests that we add a “grace period” to the life limit placed on the nose landing gear (NLG) shock absorber bottom, part number (P/N) C62037-1, listed in Table 1 of the NPRM, as referenced in paragraph (h)(1)(i) of the NPRM. TradeWinds explains that this component was not listed in Chapter 5 of the Airbus A300 Airplane Maintenance Manual (AMM) and had no corresponding FAA AD issued against it. Therefore, for U.S. operators, there was never a requirement to track the life limit. TradeWinds suggests a grace period of the next NLG overhaul or restoration be added so this internal component can be replaced without unscheduled removal from the airplane.

We do not agree that it is necessary to add a grace period based on the operator’s next overhaul or restoration. Maintenance schedules vary among operators; there is no assurance that the overhaul or restoration would occur within the maximum interval of time allowable for the affected airplanes to operate safely. However, under the provisions of paragraph (l) of this AD, we will consider requests for adjustments to the compliance time if data are submitted to substantiate that such an adjustment would provide an acceptable level of safety. We have not changed the AD in this regard.

Request To Clarify Purpose of Service Information Letter (SIL)

TradeWinds Airlines requests that we clarify the purpose of Airbus Service

Information Letter (SIL) 32-118, Revision 02, dated October 24, 2007, as referenced in paragraph (j) of the NPRM. TradeWinds requests a note or some clarification to describe the use or application of the SIL as it pertains to the AD.

We agree with the request to clarify the purpose of the SIL. We have added Note 2 to the AD to include the following information from page 1 of the SIL:

Note 2: Airbus Service Information Letter 32-118, Revision 02, dated October 24, 2007, provides operators with guidance on the means to assign a conservative calculated life to parts whose history of accumulated landings is partial or unknown; and to select the limitations applicable to parts whose history of application details (aircraft type, aircraft model, weight variant, etc.) is partial or unknown.

Conclusion

We have carefully reviewed the available data, including the comments that have been received, and determined that air safety and the public interest require adopting the AD with the change described previously. We have determined that this change will neither increase the economic burden on any operator nor increase the scope of the AD.

Costs of Compliance

The following table provides the estimated costs for U.S. operators to comply with this AD.

ESTIMATED COSTS

Action	Work hours	Average labor rate per hour	Parts	Cost per airplane	Number of U.S.-registered airplanes	Fleet cost
Replacement (required by AD 87-16-06)	7	\$80	\$3,300	\$3,860	94	\$362,840
Revision (new action)	1	80	0	80	238	19,040

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in

air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on

the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866;
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket. See the **ADDRESSES** section for a location to examine the regulatory evaluation.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The Federal Aviation Administration (FAA) amends § 39.13 by removing amendment 39-5692 (52 FR 28241, July 29, 1987) and by adding the following new airworthiness directive (AD):

2009-18-15 Airbus: Amendment 39-16011. Docket No. FAA-2009-0292; Directorate Identifier 2008-NM-011-AD.

Effective Date

(a) This AD becomes effective October 27, 2009.

Affected ADs

(b) This AD supersedes AD 87-16-06.

Applicability

(c) This AD applies to all Airbus Model A300, A310, and A300-600 series airplanes, certificated in any category.

Subject

(d) Air Transport Association (ATA) of America Code 32: Landing Gear.

Unsafe Condition

(e) This AD results from revisions to the Airworthiness Limitations section (ALS) of the Instructions for Continued Airworthiness (ICA) to include new or more restrictive life limits and/or replacements. We are issuing this AD to ensure the continued structural integrity of these airplanes.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Note 1: This AD requires revisions to certain operator maintenance documents to include new replacements. Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these replacements, the operator may not be able to accomplish the replacements described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (l) of this AD. The request should include a description of changes to the required replacements that will ensure the continued operational safety of the airplane.

Restatement of the Requirements of AD 87-16-06

(g) For Model A300 and A310 series airplanes: Prior to the accumulation of 16,000 landings, or within the next 2,000 landings after September 3, 1987 (the effective date of AD 87-16-06), whichever occurs later, replace the nose landing gear drag strut upper attachment pin in accordance with Airbus Service Bulletin A300-32-374, Revision 1, dated July 15, 1986 (applicable to Model A300 airplanes); or A310-32-2023, Revision 2, dated November 14, 1986 (applicable to Model A310 airplanes).

New Requirements of This AD

ALS Revision

(h) For Model A300, A310, and A300-600 series airplanes: Within 3 months after the effective date of this AD, revise the ALS of the ICA to incorporate the applicable document listed in paragraph (h)(1), (h)(2), or (h)(3) of this AD. Accomplishing the actions specified in the applicable document satisfies the requirements of paragraph A. of AD 84-02-04, amendment 39-4795.

(1) For Model A300 series airplanes: Incorporate the applicable document listed in paragraph (h)(1)(i) or (h)(1)(ii) of this AD.

(i) Section 05-10-00, Revision 28, dated February 27, 1998, of Chapter 05, "Service Life Limits and Maintenance Checks," of the Airbus A300 Aircraft Maintenance Manual, except that the parts listed in Table 1 of this AD are subject to the life limits defined in the document listed in paragraph (h)(1)(ii) of this AD.

(ii) "Sub-part 1-2: Life Limits," and "Sub-part 1-3: Demonstrated Fatigue Lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated September 6, 2007, of the Airbus A300 ALS.

TABLE 1—PARTS SUBJECT TO THE LIFE LIMITS SPECIFIED IN THE DOCUMENT IDENTIFIED IN PARAGRAPH (H)(1)(II) OF THIS AD

Part No. (P/N)	Part name
P/N C61643-2, P/N C61643-4, P/N C61643-5	Main landing gear (MLG) shock absorber end fitting.
P/N A32210001205xx	Nose landing gear (NLG) pintle pin.
P/N C62037-1	NLG shock absorber bottom.
P/N 196-0328-501	Cross beam (Pratt & Whitney forward engine mount).

(2) For Model A310 series airplanes: Incorporate "Sub-part 1-2: Life Limits," and "Sub-part 1-3: Demonstrated Fatigue Lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006, of the Airbus A310 ALS.

(3) For Model A300-600 series airplanes: Incorporate "Sub-part 1-2: Life Limits," and "Sub-part 1-3: Demonstrated Fatigue Lives" of Part 1, "Safe Life Airworthiness Limitation Items," dated December 21, 2006, of the Airbus A300-600 ALS.

Initial Compliance Times and Repetitive Inspections

(i) Do the replacement at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD, except as provided by paragraph (j) of this AD. The replacement must be done

thereafter within the interval specified in the applicable document identified in paragraph (h)(1), (h)(2), or (h)(3) of this AD.

(1) For any life limitation/task that has been complied with before the effective date of this AD in accordance with the applicable document listed in paragraph (h)(1), (h)(2), or (h)(3) of this AD, or in accordance with paragraph (g) of this AD, use the last accomplishment of each limitation/task as a starting point for accomplishing each corresponding limitation/task required by this AD.

(2) For any life limitation/task that has not been complied with before the effective date of this AD in accordance with the applicable document listed in paragraphs (h)(1), (h)(2), and (h)(3) of this AD, or in accordance with paragraph (g) of this AD, the initial

compliance time starts from the date of initial entry into service as defined in the applicable document.

Special Compliance Times

(j) For any airplane on which the history of accumulated landings is partial or unknown, or where the history of application details (airplane type, model, weight variant, etc.) is partial or unknown, with or without using the information in Airbus Service Information Letter 32-118, Revision 02, dated October 24, 2007: Parts listed in Figure 1 of this AD must be replaced at the associated compliance time. The replacement must be done thereafter at the interval specified in the applicable document(s) specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD.

Note 2: Airbus Service Information Letter 32-118, Revision 02, dated October 24, 2007, provides operators with guidance on the means to assign a conservative calculated life to parts whose history of accumulated landings is partial or unknown; and to select the limitations applicable to parts whose history of application details (aircraft type, aircraft model, weight variant, etc.) is partial or unknown.
BILLING CODE 4910-13-P

Figure 1 – Special Compliance Times

Designation	Aircraft type applicability				Start date	Compliance Time (whichever occurs first after the “start date”)	
	A300	X				Landings	Calendar Time
	A310		X				
	A300-600			X			
P/N							
MAIN LANDING GEAR							
Aft pintle pin	A32140032200xx	X			December 13, 2007	13,500	9 years
	A32140056200xx	X			December 13, 2007	13,500	9 years
	A32140056202xx	X			December 13, 2007	13,500	9 years
	A32140057200xx	X			December 13, 2007	13,500	9 years
	A32140057202xx	X		X	December 13, 2007	13,500	9 years
	A32140062000xx	X			December 13, 2007	13,500	9 years
	A32140063000xx	X		X	December 13, 2007	13,500	9 years
Half ball housing (Fwd pintle bearing)	A32140036200xx	X			December 13, 2007	13,500	9 years
	A32140036202xx	X			December 13, 2007	13,500	9 years
	A32140036204xx	X			December 13, 2007	13,500	9 years
	A32140036206xx	X			December 13, 2007	13,500	9 years
	A32140042200xx	X		X	December 13, 2007	13,500	9 years
	A32140042202xx	X		X	December 13, 2007	13,500	9 years
	A32140068002xx	X			December 13, 2007	13,500	9 years
	A32140068004xx	X			December 13, 2007	13,500	9 years
	A32140069002xx	X		X	December 13, 2007	13,500	9 years
	A32140069004xx	X		X	December 13, 2007	13,500	9 years
Ball (Fwd pintle pin)	A32140012202xx	X			December 13, 2007	13,500	9 years
	A32140043202xx	X		X	December 13, 2007	13,500	9 years

Figure 1 – Special Compliance Times (continued)

Designation	Aircraft type applicability				Start date	Compliance Time (whichever occurs first after the “start date”)	
	A300	X				Landings	Calendar Time
	A310		X				
	A300-600			X			
P/N							
Pin (Multiple link/Frame 50)	A53833451200xx	X			December 13, 2007	13,500	9 years
	A53833451206xx	X			December 13, 2007	13,500	9 years
	A53834451200xx	X			December 13, 2007	13,500	9 years
	A53834451202xx	X		X	April 25, 2007	13,500	9 years
Pin (Drop link/Frame 50)	A53811122200xx		X		April 25, 2007	18,000	9 years
MLG Barrel Assembly							
Upper torque link pin nut	00-200-402	X			December 13, 2007	N/A	30 months
	SL40089	X			December 13, 2007	N/A	30 months
	SL40089P	X			December 13, 2007	N/A	30 months
	SL40123	X			December 13, 2007	N/A	30 months
	SL40123P	X	X	X	April 25, 2007	N/A	30 months
Torque link medium pin nut	00-200-358	X			December 13, 2007	N/A	30 months
	SL40114P	X	X		April 25, 2007	N/A	30 months
	SL40132	X			December 13, 2007	N/A	30 months
	SL40132P	X		X	April 25, 2007	N/A	30 months
Attaching fitting pin	C62311-1	X			December 13, 2007	13,500	9 years
	C62311-20	X		X	April 25, 2007	13,500	9 years
Pin (Connecting rod/Upper rod)	C65815	X			December 13, 2007	13,500	9 years
	C65815-1	X			December 13, 2007	13,500	9 years
	C65815-20	X			December 13, 2007	13,500	9 years
	C66472	X			December 13, 2007	13,500	9 years
	C66472-1	X			December 13, 2007	13,500	9 years
	C66472-20	X		X	April 25, 2007	13,500	9 years
	D52751		X		April 25, 2007	18,000	9 years

Figure 1 – Special Compliance Times (continued)

Designation	Aircraft type applicability				Start date	Compliance Time (whichever occurs first after the “start date”)	
	A300	X				Landings	Calendar Time
	A310		X				
	A300-600			X			
P/N							
MLG Shock Absorber Assembly							
Lower torque link pin nut	00-200-402	X			December 13, 2007	N/A	30 months
	SL40089	X			December 13, 2007	N/A	30 months
	SL40089P	X			December 13, 2007	N/A	30 months
	SL40123	X			December 13, 2007	N/A	30 months
	SL40123P	X	X	X	April 25, 2007	N/A	30 months
Bogie beam pivot pin nut	SL40054	X			December 13, 2007	at next removal / installation ⁽¹⁾⁽²⁾	
	SL40054P	X		X	April 25, 2007	at next removal / installation ⁽¹⁾⁽²⁾	
	SL40413P		X		April 25, 2007	at next removal / installation ⁽¹⁾⁽²⁾	
MLG Lock Link Assembly							
Lock link medium pin	C61485-1	X			December 13, 2007	N/A	30 months
	C61485-20	X		X	April 25, 2007	N/A	30 months
NOSE LANDING GEAR							
Pintle pin	A32210079200xx	X	X	X	April 25, 2007	13,500	9 years
NLG Telescopic Strut Assembly							
Nut (Cylinder / Locking cylinder)	C61375	X	X		April 25, 2007	13,500	9 years
	D55955	X	X	X	April 25, 2007	13,500	9 years
Locking sleeve	C61389	X	X		December 13, 2007	13,200	9 years
	C61389-1	X	X	X	April 25, 2007	13,500	9 years
NLG Barrel Assembly							
Pin (Clevis / Telescopic strut)	C62231-1	X			December 13, 2007	13,200	9 years
	C62231-2	X			December 13, 2007	13,200	9 years
	C62231-20	X	X	X	April 25, 2007	13,500	9 years
	D56530	X	X	X	April 25, 2007	13,500	9 years
Lower pin (Link / Clevis)	C62268-1	X			December 13, 2007	13,200	9 years
	C62268-2	X			December 13, 2007	13,200	9 years
	C62268-20	X	X	X	April 25, 2007	13,500	9 years
Link (Clevis / Barrel)	C62230-1	X	X	X	April 25, 2007	13,500	9 years
	D56526	X	X	X	April 25, 2007	13,500	9 years
Upper pin (Link / Barrel)	C62267-1	X			December 13, 2007	13,200	9 years
	C62267-2	X			December 13, 2007	13,200	9 years
	C62267-20	X	X	X	April 25, 2007	13,500	9 years

Figure 1 – Special Compliance Times (continued)

Designation	Aircraft type applicability				Start date	Compliance Time (whichever occurs first after the “start date”)	
	A300	X				Landings	Calendar Time
	A310		X				
	A300-600			X			
P/N							
End fitting pin nut	D68062	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
	MS17825-6	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
End fitting pin	AN6-17	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
	D61183	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
	D68063	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
	NAS1306-22D	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
End fitting	C62032	X	X	X	April 25, 2007	13,500	9 years
	C62032-1	X	X	X	April 25, 2007	13,500	9 years
Rack	C61453	X			December 13, 2007	13,200	9 years
	C61453-1	X	X	X	April 25, 2007	13,500	9 years
	C61453-20	X	X	X	April 25, 2007	13,500	9 years
	C61453-40	X	X	X	April 25, 2007	13,500	9 years
	C61453-41	X	X	X	April 25, 2007	13,500	9 years
Torque link pin (Upper & Lower)	C62223-1	X			December 13, 2007	13,200	9 years
	C62223-20	X	X	X	April 25, 2007	13,500	9 years
Torque link medium pin nut	SL40110P	X	X	X	April 25, 2007	N/A	30 months
NLG Shock Absorber Assembly							
Wheel axle nut	C62879	X	X	X	April 25, 2007	4,000	24 months
Upper cam dowel	C62270	X	X	X	December 13, 2007	at next removal / installation	
Upper cam	C62034-1	X	X	X	April 25, 2007	13,500	9 years
Lower cam	C62035	X	X	X	April 25, 2007	13,500	9 years
Restrictor	C62036	X			December 13, 2007	13,200	9 years
	C62036-1	X			December 13, 2007	13,200	9 years
	C62036-2	X			December 13, 2007	13,200	9 years
	C67863	X			December 13, 2007	13,200	9 years
	C67863-1	X	X	X	April 25, 2007	13,500	9 years
	C67863-2	X	X	X	April 25, 2007	13,500	9 years
	C67863-3	X			December 13, 2007	13,500	9 years
	C67863-4	X	X	X	April 25, 2007	13,500	9 years

Figure 1 – Special Compliance Times (continued)

Designation	Aircraft type applicability				Start date	Compliance Time (whichever occurs first after the “start date”)	
	A300	X				Landings	Calendar Time
	A310		X				
	A300-600			X			
P/N							
Lower cam dowel	C62866	X	X	X	December 13, 2007	at next removal / installation ⁽²⁾	
Nut (S/A/Barrel)	C64040	X			December 13, 2007	at next removal / installation ⁽¹⁾⁽²⁾	
	C64040-1	X	X	X	December 13, 2007	at next removal / installation ⁽¹⁾⁽²⁾	

⁽¹⁾ When the nut is temporarily removed and reinstalled for the purpose of performing maintenance outside a workshop, no replacement is required provided the nut’s removal and reinstallation are performed on the same assembly and neither the assembly nor the nut accumulates time in service during the period between the removal and reinstallation.

⁽²⁾ If the removal / installation was done after the start date, but before the effective date of this AD, the compliance time is within 3 months after the effective date of this AD.

BILLING CODE 4910-13-C

Alternative Intervals or Limits

(k) Except as provided by paragraph (l) of this AD, after accomplishing the actions specified in paragraphs (h), (i), and (j) of this AD, no alternative replacements, replacement intervals, or limitations may be used.

Alternative Methods of Compliance (AMOCs)

(l)(1) The Manager, ANM-116, International Branch, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested

using the procedures found in 14 CFR 39.19. Send information to ATTN: Tom Stafford, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1622; fax (425) 227-1149.

(2) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal

inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

Related Information

(m) European Aviation Safety Agency (EASA) Airworthiness Directive 2007-0293, dated November 29, 2007, also addresses the subject of this AD.

Material Incorporated by Reference

(n) You must use the service information contained in Table 2 of this AD to do the actions required by this AD, unless the AD specifies otherwise.

TABLE 2—MATERIAL INCORPORATED BY REFERENCE

Document	Revision	Date
Section 05-10-00 of Chapter 05, “Service Life Limits and Maintenance Checks,” of the Airbus A300 Aircraft Maintenance Manual.	28	February 27, 1998.
Airbus A300 Airworthiness Limitations Section, ALS Part 1, “Safe Life Airworthiness Limitations Items”	Original	September 6, 2007.
Airbus A300-600 Airworthiness Limitations Section, ALS Part 1, “Safe Life Airworthiness Limitations Items”.	Original	December 21, 2006.
Airbus A310 Airworthiness Limitations Section, ALS Part 1, “Safe Life Airworthiness Limitation Items”	Original	December 21, 2006.
Airbus Service Bulletin A300-32-374	1	July 15, 1986.
Airbus Service Bulletin A310-32-2023	2	November 14, 1986.

Airbus Service Bulletin A300-32-374, Revision 1, dated July 15, 1986, has the following effective pages:

Page No.	Revision level shown on page	Date shown on page
1, 3-8, 11	1	July 15, 1986.
2	Original ...	April 16, 1986.

(Airbus Service Bulletin A300-32-374, Revision 1, dated July 15, 1986 does not contain pages 9 and 10.)

Airbus Service Bulletin A310-32-2023, Revision 2, dated November 14, 1986, has the following effective pages:

Page No.	Revision level shown on page	Date shown on page
1, 5-9	2	November 14, 1986
2, 4	1	July 15, 1986
3	Original ...	April 16, 1986

Chapter 05 of Airbus A300 Aircraft Maintenance Manual has the following effective pages:

LIST OF EFFECTIVE PAGES

Page title/description	Page No.(s)	Revision No.	Date shown on page(s)
AMM Title Page	None shown	None shown *	February 27, 1998.
Chapter 05 Record of Revisions	1-2	28	February 27, 1998.
Chapter 05 Effective Pages	1-4	None shown *	February 27, 1998.
Chapter 05 Table of Contents	1-4	None shown *	February 27, 1998.
Section 05-10-00	1	None shown *	February 27, 1998.

* The revision number is indicated only in the Record of Revisions section of Chapter 05.

(The List of Effective Pages (LOEP) for Chapter 05 of the Airbus A300 Aircraft Maintenance Manual contains the following errors: Transmittal Letter page, page 4 of the LOEP and Table of Contents sections, page 2 of Subsection 05-00-01, page 1 of Subsection 05-11-11, and Subsection 05-10-00, are not listed in the LOEP; and the LOEP also does not specify a date for the Record of Revisions page. In addition, the LOEP identifies three pages for Subsection 05-11-00, Configuration 5; however, only one page exists. The LOEP identifies three pages for Subsection 05-11-00, Configuration 9; however, those pages do not exist.)

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Airbus SAS—EAW (Airworthiness Office), 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; e-mail: account.airworth-eas@airbus.com; Internet <http://www.airbus.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221 or 425-227-1152.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on August 24, 2009.

Ali Bahrami,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. E9-21033 Filed 9-21-09; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY

Internal Revenue Service

26 CFR Part 1

[TD 9452]

RIN 1545-BB28

Application of Separate Limitations to Dividends From Noncontrolled Section 902 Corporations; Correction

AGENCY: Internal Revenue Service (IRS), Treasury.

ACTION: Correcting amendment.

SUMMARY: This document contains corrections to final regulations (TD 9452) that were published in the **Federal Register** on Thursday, June 11, 2009, regarding the application of separate foreign tax credit limitations to dividends received from noncontrolled section 902 corporations.

DATES: This correction is effective on September 22, 2009 and is applicable in taxable years ending on or after April 20, 2009.

FOR FURTHER INFORMATION CONTACT: Richard Chewning, (202) 622-3850 (not a toll-free number).

SUPPLEMENTARY INFORMATION:

Background

The final regulations that are the subject of this document are under section 964 of the Internal Revenue Code.

Need for Correction

As published on Thursday, June 11, 2009 (74 FR 27886), the final regulations (TD 9452) contain errors that may prove to be misleading and are in need of clarification.

List of Subjects in 26 CFR Part 1

Income taxes, Reporting and recordkeeping requirements.

Correction of Publication

■ Accordingly, 26 CFR part 1 is corrected by making the following correcting amendments:

PART 1—INCOME TAXES

■ **Paragraph 1.** The authority citation for part 1 continues to read in part as follows:

Authority: 26 U.S.C. 7805 * * *

■ **Par. 2.** Section 1.964-1 is amended by revising the last sentence of paragraph (c)(2) and paragraph (c)(4)(i)(D) to read as follows:

§ 1.964-1 Determination of the earnings and profits of a foreign corporation.

* * * * *

(c) * * *

(2) * * * See also §§ 1.985-5, 1.985-6, and 1.985-7 relating to adjustments to earnings and profits of a QBU required when the QBU changes its functional currency or begins to use the dollar approximate separate transactions method of accounting.

(4) * * *

(i) * * *

(D) Whether the domestic shareholder received the written notice required by paragraph (c)(3)(iii) of this section.

* * * * *

LaNita VanDyke,

Chief, Publications and Regulations Branch, Legal Processing Division, Associate Chief Counsel, (Procedure and Administration).

[FR Doc. E9-22694 Filed 9-21-09; 8:45 am]

BILLING CODE 4830-01-P

DEPARTMENT OF DEFENSE

Department of the Army, Corps of Engineers

33 CFR Part 334

United States Navy Restricted Area, SUPSHIP Bath Detachment Mobile, Mobile, AL

AGENCY: U.S. Army Corps of Engineers, Department of Defense.

ACTION: Final rule.

SUMMARY: The U.S. Army Corps of Engineers (Corps) is adding regulations to establish a restricted area around the AUSTAL, USA shipbuilding facility located in Mobile, Alabama, because of