

**TABLE 1—AIRBUS ALL OPERATOR TELEXES**

Airbus all operator telex—	Dated—
A300–32A0447 .....	April 22, 2004.
A300–32A6093 .....	April 22, 2004.
A310–32A2132 .....	April 22, 2004.

**Torque Load Inspection and Corrective Action**

(h) At the latest of the compliance times specified in paragraphs (h)(1), (h)(2), and

(h)(3) of this AD, do an inspection of the torque load of the nuts of the NLG shock absorber-to-main barrel attachment bolts in accordance with the Accomplishment Instructions of the applicable service bulletin listed in Table 2 of this AD. Depending on the torque load value found during the inspection, before further flight: Retighten the bolt(s) or replace the discrepant bolt(s), or replace all bolts, in accordance with the applicable service bulletin listed in Table 2 of this AD. Thereafter, repeat the torque load inspection at intervals not to exceed 3,200 flight cycles or 30 months' time-in-service

accumulated by the NLG, whichever occurs first.

(1) Within 3,200 flight cycles or 30 months since NLG's first flight, whichever occurs first.

(2) Within 3,200 flight cycles or 30 months accumulated by the NLG since installation of new bolts, whichever occurs first.

(3) Within 3,200 flight cycles or 30 months after the effective date of this AD, whichever occurs first.

**TABLE 2—SERVICE INFORMATION FOR INSPECTIONS**

Airbus Mandatory Service Bulletin—	Revision level—	Dated—
A300–32–0447, including Appendix 01 .....	01	June 1, 2007.
A300–32–6093, including Appendix 01 .....	01	June 1, 2007.
A310–32–2132, including Appendix 01 .....	01	June 1, 2007.

(i) After accomplishment of the initial inspection in accordance with paragraph (h) of this AD, as applicable, the repetitive inspections of paragraph (g) of this AD are no longer required.

**Optional Terminating Action**

(j) For airplanes on which the modification of the shock absorber-to-barrel attachment has been done in accordance with the applicable service bulletin listed in Table 3 of this AD, the requirements of this AD are no longer required, as long as that modification remains installed.

**TABLE 3—SERVICE INFORMATION FOR OPTIONAL TERMINATING ACTION**

Airbus Service Bulletin—	Dated—
A300–32–0453 .....	June 1, 2007.
A300–32–6099 .....	June 1, 2007.
A310–32–2135 .....	June 1, 2007.

**Reporting Requirement**

(k) For each inspection required in paragraph (h) of this AD that results in re-torque or replacement of bolt(s): At the applicable time specified in paragraph (k)(1) or (k)(2) of this AD, send a report to Airbus, using Appendix 01 of the applicable service bulletin listed in Table 2 of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

**FAA AD Differences**

**Note 1:** This AD differs from the MCAI and/or service information as follows: No Differences.

**Other FAA AD Provisions**

(l) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International

Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057–3356; telephone (425) 227–2125; fax (425) 227–1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120–0056.

**Related Information**

(m) Refer to MCAI European Aviation Safety Agency (EASA) Airworthiness Directive 2008–0052R1, dated June 30, 2008; and the service information identified in Tables 1, 2, and 3 of this AD; for related information.

Issued in Renton, Washington, on May 3, 2010.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2010–11902 Filed 5–18–10; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA–2010–0477; Directorate Identifier 2009–NM–226–AD]

RIN 2120–AA64

**Airworthiness Directives; BAE Systems (Operations) Limited Model BAe 146 and Avro 146–RJ Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as: Three events have been reported where insulation material was found to be fouling pulleys in the aileron interconnect circuit in the cabin roof area. Interference between the cable and the insulation bag causes the material to be drawn into the gap between the pulley and the pulley guard. This condition, if not detected and corrected, could lead to restricted

aileron movement and consequently, reduced control of the aeroplane. The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by July 6, 2010.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact BAE Systems Regional Aircraft, 13850 McLearen Road, Herndon, Virginia 20171; telephone 703-736-1080; e-mail [raebusiness@baesystems.com](mailto:raebusiness@baesystems.com); Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments

to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2010-0477; Directorate Identifier 2009-NM-226-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We have lengthened the 30-day comment period for proposed ADs that address MCAI originated by aviation authorities of other countries to provide adequate time for interested parties to submit comments. The comment period for these proposed ADs is now typically 45 days, which is consistent with the comment period for domestic transport ADs.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2009-0205, Revision 1, dated January 12, 2010 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

Three events have been reported where insulation material was found to be fouling pulleys in the aileron interconnect circuit in the cabin roof area. The insulation material is contained in a bag, the material of which tends to become brittle with age. During the production life of the aeroplane type, several methods of bag retention were applied, all of which involved puncturing the bag. This puncture tends to result in a tear, which, if detected in time, can be repaired with tape; however, the affected cabin roof area is not frequently accessed for inspection. Over time, the weight of the bag also tends to cause tears in the material, making the insulation material sag, thereby causing interference with the cable and pulley.

Interference between the cable and the insulation bag causes the material to be drawn into the gap between the pulley and the pulley guard. This condition, if not detected and corrected, could lead to restricted aileron movement and consequently, reduced control of the aeroplane.

For the reasons described above, this AD requires the installation of additional guards, bolts and nuts on the aileron interconnect cable pulleys at frame 29 (left and right).

This AD has been revised to exclude aeroplanes from the Applicability that have been modified to freighter configuration in accordance with BAE Systems modification

No. HCM50200B. As this modification includes the removal of the insulation bags, the unsafe condition that is addressed by this AD cannot exist or develop on those aeroplanes.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

BAE Systems (Operations) Limited has issued Modification Service Bulletin SB.27-183-36246A, dated December 9, 2008. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

#### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a Note within the proposed AD.

#### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 1 product of U.S. registry. We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$340 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these costs. As we do not control

warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$765.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**BAE Systems (Operations) Limited:** Docket No. FAA-2010-0477; Directorate Identifier 2009-NM-226-AD.

##### Comments Due Date

(a) We must receive comments by July 6, 2010.

##### Affected ADs

(b) None.

##### Applicability

(c) This AD applies to BAE SYSTEMS (Operations) Limited Model BAe 146-100A, -200A, and -300A series airplanes and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes, certificated in any category, all serial numbers, except those airplanes modified to freighter configuration in accordance with BAE Systems modification No. HCM50200B.

##### Subject

(d) Air Transport Association (ATA) of America Code 27: Flight Controls.

##### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

Three events have been reported where insulation material was found to be fouling pulleys in the aileron interconnect circuit in the cabin roof area.

Interference between the cable and the insulation bag causes the material to be drawn into the gap between the pulley and the pulley guard. This condition, if not detected and corrected, could lead to restricted aileron movement and consequently, reduced control of the aeroplane.

##### Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

##### Actions

(g) Within 6 months after the effective date of this AD, install new aileron interconnect cable pulley guards, in accordance with paragraph 2.C. "Modification" of the Accomplishment Instructions of BAE SYSTEMS (Operations) Limited Modification Service Bulletin SB.27-183-36246A, dated December 9, 2008.

##### FAA AD Differences

**Note 1:** This AD differs from the MCAI and/or service information as follows: No differences.

#### Other FAA AD Provisions

(h) The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) Reporting Requirements: For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has approved the information collection requirements and has assigned OMB Control Number 2120-0056.

#### Related Information

(i) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2009-0205, Revision 1, dated January 12, 2010; and BAE SYSTEMS (Operations) Limited Modification Service Bulletin SB.27-183-36246A, dated December 9, 2008; for related information.

Issued in Renton, Washington, on May 4, 2010.

**Ali Bahrami,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2010-11903 Filed 5-18-10; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2010-0479 Directorate Identifier 2009-NM-220-AD]

RIN 2120-AA64

**Airworthiness Directives; Fokker Services B.V. Model F.28 Mark 0070 and 0100 Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.