

General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on product(s) identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

Therefore, I certify this proposed AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by removing Amendment 39–14961 (72 FR 13679, dated March 23, 2007) and adding the following new AD:

Eurocopter Deutschland GmbH: Docket No. FAA–2010–0780; Directorate Identifier 2009–SW–68–AD.

Comments Due Date

(a) We must receive your comments by September 10, 2010.

Other Affected ADs

(b) This AD supersedes AD 2006–26–51, Amendment 39–14961, Docket No. FAA 2006–26721, Directorate Identifier 2006–SW–28–AD.

Applicability

(c) This AD applies to Model MBB–BK 117 C–2 helicopters with a tail rotor control lever B642M1009103, installed, certificated in any category.

Reason

(d) The mandatory continued airworthiness information (MCAI) AD states: “EASA was informed by the manufacturer of an in-flight incident in which a dynamic weight broke off the control lever subsequently leading to considerable vibrations. A visual inspection revealed that the threaded bolt of the control lever had broken off.” This AD requires actions that are intended to prevent separation of dynamic weights, severe vibration, and subsequent loss of control of the helicopter.

Actions and Compliance

(e) Before further flight, unless already done, mark the position of the weights, remove the split pins, remove the weights, and visually inspect the tail rotor control lever in the area around the split pin bore for score marks, notching, scratching, or a crack. Inspect by following the Accomplishment Instructions, paragraph 3.A.(1) through 3.A.(3) and Figure 1, of Eurocopter Alert Service Bulletin MBB BK 117 C–2–64A–002, Revision 2, dated August 6, 2007 (ASB).

(1) If done previously, within the next 8 hours time-in-service (TIS) or before reaching 25 hours TIS after the last inspection, and thereafter at intervals not to exceed 8 hours TIS, repeat the visual inspection of the tail rotor control lever as required by paragraph (e) of this AD.

(2) If you find a score mark, a notch, or a scratch that exceeds the maintenance manual limits, or find a crack, before further flight:

- (i) Replace the tail rotor control lever with an airworthy tail rotor control lever; and
- (ii) Reidentify the tail rotor head, head assembly, and drive system with the new part numbers by following the Accomplishment Instructions, paragraph 3.B.(1) through 3.B.(8) and 3.C.(1) through 3.C.(2), of the ASB.

(f) Within 100 hours TIS, unless already done, replace the control levers and reidentify the tail rotor head, head assembly, and drive system with the new part numbers by following the Accomplishment Instructions, paragraph 3.B.(1) through 3.B.(8) and 3.C.(1) through 3.C.(2), of the ASB.

(g) Replacing the control levers and reidentifying the part numbers is terminating action for the requirements of this AD.

Differences Between the FAA AD and the MCAI AD

(h) We refer to flight hours as hours TIS. We do not refer to a date of October 31, 2007, for replacing the levers because the date has passed.

Other Information

(i) Alternative Methods of Compliance (AMOCs): The Manager, Safety Management Group, ATTN: DOT/FAA Southwest Region, Sharon Miles, ASW–111, Aviation Safety Engineer, Rotorcraft Directorate, Regulations and Guidance Group, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222–5122, fax (817) 222–5961, has the authority to approve AMOCs for this AD, if requested, using the procedures found in 14 CFR 39.19.

(j) Special flight permits are prohibited.

Related Information

(k) MCAI EASA Airworthiness Directive No. 2006–0237, dated August 31, 2007, which supersedes EASA Emergency AD 2007–0189–E, dated July 12, 2007, contains related information.

Joint Aircraft System/Component (JASC) Code

(l) The JASC Code is 6400: Tail rotor system-control lever.

Issued in Fort Worth, Texas, on August 3, 2010.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2010–19817 Filed 8–10–10; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2010–0781; Directorate Identifier 2007–SW–49–AD]

RIN 2120–AA64

Airworthiness Directives; Eurocopter France Model AS–365N2, AS 365 N3, and SA–365N1 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for the specified Eurocopter France model helicopters. This proposed AD would require replacing the aluminum tail rotor (T/R) blade pitch control shaft with a steel T/R blade pitch control shaft. This proposed AD is prompted by an incident involving a Eurocopter France Model AS–365N2 helicopter on which there was a loss of control of the T/R due to a broken shaft. The actions specified by this proposed AD are intended to prevent failure of the T/R blade pitch control shaft, loss of T/R control, and subsequent loss of control of the helicopter.

DATES: Comments must be received on or before October 12, 2010.

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

You may get the service information identified in this proposed AD from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, TX 75053-4005, telephone (800) 232-0323, fax (972) 641-3710, or at <http://www.eurocopter.com>.

You may examine the comments to this proposed AD in the AD docket on the Internet at <http://www.regulations.gov>.

FOR FURTHER INFORMATION CONTACT: Jim Grigg, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5126, fax (817) 222-5961.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to submit any written data, views, or arguments regarding this proposed AD. Send your comments to the address listed under the caption

ADDRESSES. Include the docket number "FAA-2010-0781, Directorate Identifier 2007-SW-49-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of the proposed AD. We will consider all comments received by the closing date and may amend the proposed AD in light of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed rulemaking. Using the search function of the docket Web site, you can find and read the comments to any of our dockets, including the name of the individual who sent or signed the

comment. You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

Examining the Docket

You may examine the docket that contains the proposed AD, any comments, and other information in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The Docket Operations office (telephone (800) 647-5527) is located in Room W12-140 on the ground floor of the West Building at the street address stated in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No. 2007-0220, dated August 13, 2007, to correct an unsafe condition for Eurocopter AS 365 N2, AS 365 N3, and SA 365 N1 helicopters, all serial numbers, equipped with an aluminum T/R blade pitch control shaft, part number (P/N) 365A33.6161.20 or P/N 365A33.6161.21. The EASA advises of an incident in which the pilot of a Model AS 365 N2 helicopter encountered a loss of control of the T/R, but executed an uneventful run-on landing. A subsequent investigation revealed that the T/R blade pitch control shaft, P/N 365A33.6161.21, had broken in the main section of the shaft sliding area, which appeared to be damaged by peening. The origin of the crack, which developed under fatigue loading, could not be determined. However, accidental damage (i.e., shock impact), is believed to have caused the initiation of a crack.

Related Service Information

Eurocopter has issued Alert Service Bulletin No. 01.00.59, dated June 21, 2007, which specifies removing any T/R blade pitch control shaft, P/N 365A33.6161.20 or P/N 365A33.6161.21, and replacing it with a steel T/R blade pitch control shaft, P/N 365A33.6214.20. The EASA classified this alert service bulletin as mandatory and issued EASA AD No. 2007-0220, dated August 13, 2007, to ensure the continued airworthiness of these helicopters.

FAA's Evaluation and Unsafe Condition Determination

These products have been approved by the aviation authority of France, and are approved for operation in the United States. Pursuant to our bilateral

agreement with France, the EASA, their technical representative, has notified us of the unsafe condition described in the EASA AD. We are proposing this AD because we evaluated all information provided by the EASA and determined the unsafe condition exists and is likely to exist or develop on other products of these same type designs. This proposed AD would require, within 100 hours time-in-service, removing any aluminum T/R blade pitch control shaft, P/N 365A33.6161.20 or P/N 365A33.6161.21, and replacing it with a steel T/R blade pitch control shaft, P/N 365A33.6214.20. The actions would be required to be accomplished by following specified portions of the alert service bulletin described previously.

Differences Between This Proposed AD and the EASA AD

Our proposed AD differs from the EASA AD in that we require compliance within 100 hours time-in-service instead of no later than December 31, 2007, since that date has passed.

Costs of Compliance

We estimate that this proposed AD would affect 36 helicopters of U.S. registry and the proposed actions would take approximately 12 work hours per helicopter to accomplish at an average labor rate of \$85 per work hour. Required parts would cost approximately \$3,525. Based on these figures, we estimate the total cost impact of the proposed AD on U.S. operators to be \$163,620 to replace the aluminum T/R blade pitch control shaft on the entire fleet, or \$4,545 per helicopter.

Regulatory Findings

We have determined that this proposed AD would not have federalism implications under Executive Order 13132. Additionally, this proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with

this proposed AD. See the AD docket to examine the economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in subtitle VII, part A, subpart III, section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

Eurocopter France: Docket No. FAA-2010-0781; Directorate Identifier 2007-SW-49-AD.

Applicability: Model AS-365N2, AS 365 N3, and SA-365N1 helicopters, with an aluminum tail rotor (T/R) blade pitch control shaft, part number (P/N) 365A33.6161.20 or P/N 365A33.6161.21, installed, certificated in any category.

Compliance: Required within 100 hours time-in-service, unless accomplished previously.

To prevent failure of the T/R blade pitch control shaft, loss of T/R control, and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove the aluminum T/R blade pitch control shaft, P/N 365A33.6161.20 or P/N 365A33.6161.21, and replace it with a steel

T/R blade pitch control shaft, P/N 365A33.6214.20, in accordance with the Accomplishment Instructions, Operational Procedure, paragraphs 2.B.1. through 2.B.3., of Eurocopter Alert Service Bulletin No. 01.00.59, dated June 21, 2007.

(b) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Safety Management Group, Rotorcraft Directorate, FAA, ATTN: Jim Grigg, Aviation Safety Engineer, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5126, fax (817) 222-5961.

(c) The Joint Aircraft System/Component (JASC) Code is 6500: Tail Rotor Drive System.

Note: The subject of this AD is addressed in European Aviation Safety Agency AD No. 2007-0220, dated August 13, 2007.

Issued in Fort Worth, Texas, on August 2, 2010.

Scott A. Horn,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2010-19823 Filed 8-10-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0761; Directorate Identifier 2010-NM-069-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 Series Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. This proposed AD would require installing two warning level indicator lights on the P2-2 center instrument panel in the flight compartment for certain airplanes. For a certain other airplane, this proposed AD would require activating the cabin altitude warning and takeoff configuration warning lights. For all airplanes, this proposed AD also would require revising the airplane flight manual to remove certain requirements included by previous AD actions, to require new pressure altitude limitations for certain airplanes, and to advise the flightcrew of the following changes: revised emergency procedures to use when a cabin altitude warning or

rapid depressurization occurs, and revised cabin pressurization procedures for normal operations. This proposed AD results from a design change in the cabin altitude warning system that would address the identified unsafe condition. We are proposing this AD to prevent failure of the flightcrew to recognize and react to a valid cabin altitude warning horn, which could result in incapacitation of the flightcrew due to hypoxia (lack of oxygen in body), and consequent loss of control of the airplane.

DATES: We must receive comments on this proposed AD by September 27, 2010.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; e-mail me.boecom@boeing.com; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.