

approximately \$714,000, which is less than \$750,000, and thus would be considered small business according to the SBA definition. Although there is no official data available to date, as these states were recently added to the order and have not completed one full crop year for reporting purposes, the industry estimates that the majority of producers in Arizona and New Mexico would also be considered small businesses.

This rule continues in effect the action that modified the aflatoxin sampling and testing regulations currently prescribed under the California, Arizona and New Mexico pistachio order, as well as removed unnecessary language and corrected terminology. The changes to § 983.150 are expected to reduce handler operating costs by providing a uniform and consistent aflatoxin sampling and testing procedure for pistachios shipped to all market destinations. Authority for the change in the order's rules and regulations is provided in § 983.50.

This action is expected to benefit producers and handlers, regardless of size and regardless of the market they ship into, as it streamlines handler operations and increases marketing flexibility. Reducing the number of required samples, the number of aflatoxin analyses, and the total weight of the lot samples, while increasing the weight of the test samples for each lot is expected to result in an estimated annual savings to the industry of approximately \$18,000, including reductions of \$900 for sampling, \$1,400 for testing, \$12,750 for labor, and \$3,750 in shipping costs for those small handlers that do not do testing on site.

This action will not impose any additional reporting or recordkeeping requirements on either small or large pistachio handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies. In addition, USDA has not identified any relevant Federal rules that duplicate, overlap or conflict with this rule.

Further, the Committee's meeting was widely publicized throughout the pistachio industry and all interested persons were invited to attend the meeting and participate in Committee deliberations. Like all Committee meetings, the meeting was a public meeting and all entities, both large and small, were able to express their views on this issue.

Comments on the interim rule were required to be received on or before September 21, 2010. No comments were received. Therefore, for the reasons

given in the interim rule, we are adopting the interim rule as a final rule, without change.

To view the interim rule, go to: <http://www.regulations.gov> and type the following docket number into the keyword search section: FV10-983-1 IR. Follow the link provided in the "Results" section of this page.

This action also affirms information contained in the interim rule concerning Executive Orders 12866 and 12988, Paperwork Reduction Act (44 U.S.C. chapter 35), and the E-Gov Act (44 U.S.C. 101).

After consideration of all relevant material presented, it is found that finalizing the interim rule, without change, as published in the **Federal Register** (75 FR 43045, July 23, 2010) will tend to effectuate the declared policy of the Act.

List of Subjects in 7 CFR Part 983

Marketing agreements and orders, Pistachios, Reporting and recordkeeping requirements.

PART 983—[AMENDED]

■ Accordingly, the interim rule that amended 7 CFR part 983 that was published at 75 FR 43045 on July 23, 2010, is adopted as a final rule, without change.

Dated: November 3, 2010.

David R. Shipman,

Acting Administrator, Agricultural Marketing Service.

[FR Doc. 2010-28240 Filed 11-8-10; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0700; Directorate Identifier 2010-NM-123-AD; Amendment 39-16500; AD 2010-23-11]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the products listed above. This AD results

from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

The manufacturer has informed Transport Canada that a certain number of the resolver stators, which were installed in the angle of attack (AOA) transducers, were not cleaned correctly. This condition can degrade the AOA transducer performance at low temperatures resulting in freezing of the AOA transducer resolver, which may provide inaccurate AOA data to the Stall Protection System (SPS). If not corrected, this condition can result in early or late activation of the stick shaker and/or stick pusher.

These conditions could result in reduced ability of the flight crew to maintain a safe flight and landing of the airplane. We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective December 14, 2010.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of December 14, 2010.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Joseph Licata, Aerospace Engineer, Avionics and Flight Test Branch, ANE-172, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7361; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on July 27, 2010 (75 FR 43882). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

The manufacturer has informed Transport Canada that a certain number of the resolver stators, which were installed in the angle of attack (AOA) transducers, were not cleaned correctly. This condition can degrade the AOA transducer performance at low temperatures resulting in freezing of the AOA transducer resolver, which may provide inaccurate AOA data to the Stall Protection System (SPS). If not corrected, this condition

can result in early or late activation of the stick shaker and/or stick pusher.

These conditions could result in reduced ability of the flight crew to maintain a safe flight and landing of the airplane. The required actions include an inspection to determine if certain AOA transducers are installed and replacement of affected transducers. You may obtain further information by examining the MCAI in the AD docket.

Comments

We gave the public the opportunity to participate in developing this AD. We considered the comment received. Air Line Pilots Association, International (ALPA), supports the NPRM.

Conclusion

We reviewed the available data, including the comment received, and determined that air safety and the public interest require adopting the AD as proposed.

Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have required different actions in this AD from those in the MCAI in order to follow our FAA policies. Any such differences are highlighted in a NOTE within the AD.

Costs of Compliance

We estimate that this AD will affect 380 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this AD to the U.S. operators to be \$32,300, or \$85 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that

section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

■ Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2010-23-11 Bombardier, Inc.: Amendment 39-16500. Docket No. FAA-2010-0700; Directorate Identifier 2010-NM-123-AD.

Effective Date

(a) This airworthiness directive (AD) becomes effective December 14, 2010.

Affected ADs

(b) None.

Applicability

(c) This AD applies to Bombardier, Inc. Model CL-600-2C10 (Regional Jet Series 700, 701, & 702), CL-600-2D15 (Regional Jet Series 705), and CL-600-2D24 (Regional Jet Series 900) airplanes, certificated in any category, equipped with Thales angle of attack transducers having part number (P/N) C16258AA.

Subject

(d) Air Transport Association (ATA) of America Code 27: Flight Controls.

Reason

(e) The mandatory continuing airworthiness information (MCAI) states: The manufacturer has informed Transport Canada that a certain number of the resolver stators, which were installed in the angle of attack (AOA) transducers, were not cleaned correctly. This condition can degrade the AOA transducer performance at low temperatures resulting in freezing of the AOA transducer resolver, which may provide inaccurate AOA data to the Stall Protection System (SPS). If not corrected, this condition can result in early or late activation of the stick shaker and/or stick pusher.

These conditions could result in reduced ability of the flight crew to maintain a safe flight and landing of the airplane.

Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

Inspection

(g) Within 750 flight hours after the effective date of this AD, inspect the serial number of each AOA transducer having P/N C16258AA to determine if the serial number is identified in paragraph 1.A. of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010. A review of airplane maintenance records is acceptable in lieu of this inspection if the serial number of the AOA transducer can be conclusively determined from that review.

(1) If the serial number is not listed in paragraph 1.A. of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010, no further action is

required by this AD other than compliance with paragraph (h) of this AD.

(2) If the serial number is listed in paragraph 1.A. of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010, and has the suffix "C", no further action is required by this AD other than compliance with paragraph (h) of this AD.

(3) If the serial number is listed paragraph 1.A. of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010, and does not have the suffix "C", before further flight, replace the AOA transducer with a new or serviceable transducer, in accordance with Part C of the Accomplishment Instructions of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010.

Note 1: To replace any AOA transducer, the replacement AOA transducer must either be outside of the affected serial numbers as identified in paragraph 1.A. of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010, or have the suffix "C".

(h) As of the effective date of this AD, no AOA transducer having both a serial number and P/N C16258AA as identified in paragraph 1.A. of Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010, may be installed on any airplane unless the AOA transducer has been inspected by the manufacturer and identified with the suffix "C".

FAA AD Differences

Note 2: This AD differs from the MCAI and/or service information as follows: No differences.

Other FAA AD Provisions

(i) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to *ATTN:* Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC on any airplane to which the AMOC applies, notify your principal maintenance inspector (PMI) or principal avionics inspector (PAI), as appropriate, or lacking a principal inspector, your local Flight Standards District Office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements:* For any reporting requirement in this AD, under the provisions of the Paperwork Reduction Act (44 U.S.C. 3501 *et seq.*), the Office of Management and Budget (OMB) has

approved the information collection requirements and has assigned OMB Control Number 2120-0056.

Related Information

(j) Refer to MCAI Canadian Airworthiness Directive CF-2010-13, dated May 6, 2010; and Bombardier Alert Service Bulletin A670BA-27-054, Revision A, dated January 18, 2010; for related information.

Material Incorporated by Reference

(k) You must use Bombardier Alert Service Bulletin A670BA-27-054,

Revision A, dated January 18, 2010, to do the actions required by this AD, unless the AD specifies otherwise.

(1) The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; e-mail thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(3) You may review copies of the service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html.

Issued in Renton, Washington, on October 21, 2010.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2010-28089 Filed 11-8-10; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2010-0870; Directorate Identifier 2010-CE-045-AD; Amendment 39-16505; AD 2010-23-16]

RIN 2120-AA64

Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (EMBRAER) Model EMB-500 Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for the

products listed above. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

It has been found the occurrences of failure of the Flow Control Shutoff Valve (FCSOV) in the closed position. Failure of the two valves (left and right) can cause the loss of the pneumatic source, and lead to loss of the cabin pressurization.

Since this condition affects flight safety, a corrective action is required. Thus, sufficient reason exists to request compliance with this AD.

We are issuing this AD to require actions to correct the unsafe condition on these products.

DATES: This AD becomes effective December 14, 2010.

On December 14, 2010, the Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.

For service information identified in this AD, contact EMBRAER Empresa Brasileira de Aeronautica S.A., Phenom Maintenance Support, Av. Brig. Farina Lima, 2170, Sao Jose dos Campos—SP, CEP: 12227-901—P.O. Box: 38/2, BRASIL, telephone: ++55 12 3927-5383; fax: ++55 12 3927-2610; E-mail: reliability.executive@embraer.com.br; Internet: <http://www.embraer.com.br>.

You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148.

FOR FURTHER INFORMATION CONTACT: Karl Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4146; fax: (816) 329-4090.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on September 1, 2010 (75 FR