

# Proposed Rules

Federal Register

Vol. 76, No. 169

Wednesday, August 31, 2011

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2011-0911; Directorate Identifier 2010-NM-248-AD]

RIN 2120-AA64

#### Airworthiness Directives; BAE SYSTEMS (Operations) Limited Model 4101 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as:

A door failure mode has been reported by an operator.

Investigation has shown that the passenger/crew entry door pin-guide plates can fail prior to the expected fatigue life. A metallurgical examination of the failed component (lower guide plate) concluded that the occurred failure was due to exfoliation corrosion.

The current inspection regime is not adequate to identify early stages of this corrosion.

This condition, if not corrected, can lead to the sudden depressurisation of the aeroplane and consequently may injure the occupants.

\* \* \* \* \*

The proposed AD would require actions that are intended to address the unsafe condition described in the MCAI.

**DATES:** We must receive comments on this proposed AD by October 17, 2011.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-40, 1200 New Jersey Avenue, SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact BAE SYSTEMS (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; e-mail [RApublications@baesystems.com](mailto:RApublications@baesystems.com); Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No.

FAA-2011-0911; Directorate Identifier 2010-NM-248-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2010-0179, dated August 30, 2010 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A door failure mode has been reported by an operator.

Investigation has shown that the passenger/crew entry door pin-guide plates can fail prior to the expected fatigue life. A metallurgical examination of the failed component (lower guide plate) concluded that the occurred failure was due to exfoliation corrosion.

The current inspection regime is not adequate to identify early stages of this corrosion.

This condition, if not corrected, can lead to the sudden depressurisation of the aeroplane and consequently may injure the occupants.

For the reasons described above, this [EASA] AD requires immediate and periodic ultrasonic inspections [for a split caused by exfoliation corrosion] of the door pin guides and the accomplishment of the relevant corrective actions [replacing the affected guideplates] as necessary.

You may obtain further information by examining the MCAI in the AD docket.

#### Relevant Service Information

BAE SYSTEMS (Operations) Limited has issued Service Bulletin J41-52-064, dated September 15, 2009. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

### Differences Between This AD and the MCAI or Service Information

We have reviewed the MCAI and related service information and, in general, agree with their substance. But we might have found it necessary to use different words from those in the MCAI to ensure the AD is clear for U.S. operators and is enforceable. In making these changes, we do not intend to differ substantively from the information provided in the MCAI and related service information.

We might also have proposed different actions in this AD from those in the MCAI in order to follow FAA policies. Any such differences are highlighted in a NOTE within the proposed AD.

### Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 2 products of U.S. registry. We also estimate that it would take about 2 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$340, or \$170 per product.

In addition, we estimate that any necessary follow-on actions would take about 2 work-hours and require parts costing \$525, for a cost of \$1,050 per product. We have no way of determining the number of products that may need these actions.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, part A, subpart III, Section 44701:

General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new AD:

**BAE SYSTEMS (Operations) Limited:** Docket No. FAA-2011-0911; Directorate Identifier 2010-NM-248-AD.

### Comments Due Date

(a) We must receive comments by October 17, 2011.

### Affected ADs

(b) None.

### Applicability

(c) This AD applies to all BAE SYSTEMS (Operations) Limited Model 4101 airplanes; certificated in any category.

### Subject

(d) Air Transport Association (ATA) of America Code 52: Doors.

### Reason

(e) The mandatory continuing airworthiness information (MCAI) states:

A door failure mode has been reported by an operator.

Investigation has shown that the passenger/crew entry door pin-guide plates can fail prior to the expected fatigue life. A metallurgical examination of the failed component (lower guide plate) concluded that the occurred failure was due to exfoliation corrosion.

The current inspection regime is not adequate to identify early stages of this corrosion.

This condition, if not corrected, can lead to the sudden depressurisation of the aeroplane and consequently may injure the occupants.

\* \* \* \* \*

### Compliance

(f) You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

### Actions

(g) Within 6 months after the effective date of this AD, do an ultrasonic inspection of the passenger/crew door upper and lower guide plates for a split caused by exfoliation corrosion, in accordance with the Accomplishment Instructions of BAE SYSTEMS (Operations) Limited Service Bulletin J41-52-064, dated September 15, 2009. Repeat the ultrasonic inspection, thereafter, at intervals not to exceed 48 Months.

(h) If a split caused by exfoliation corrosion of an area of 78mm<sup>2</sup> (0.12 in.<sup>2</sup>) or greater is found during any ultrasonic inspection required by paragraph (g) of this AD: Before further flight, replace any affected guide plates with a serviceable guide plate, in accordance with the Accomplishment Instructions of BAE SYSTEMS (Operations) Limited Service Bulletin J41-52-064, dated September 15, 2009.

### FAA AD Differences

**Note 1:** This AD differs from the MCAI and/or service information as follows: No differences.

### Other FAA AD Provisions

(i) The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Branch, ANM-116, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your

request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue, SW., Renton, Washington 98057-3356; telephone (425) 227-1175; fax (425) 227-1149. Information may be e-mailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

#### Related Information

(j) Refer to MCAI European Aviation Safety Agency Airworthiness Directive 2010-0179, dated August 30, 2010; and BAE SYSTEMS (Operations) Limited Service Bulletin J41-52-064, dated September 15, 2009; for related information.

Issued in Renton, Washington, on August 23, 2011.

Ali Bahrami,

Manager, Transport Airplane Directorate,  
Aircraft Certification Service.

[FR Doc. 2011-22224 Filed 8-30-11; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2011-0913; Directorate Identifier 2011-NM-031-AD]

RIN 2120-AA64

#### Airworthiness Directives; Cessna Aircraft Company Model 680 Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for the products listed above. This proposed AD would require adding diodes to the fuel cross-feed wiring, and revising the airplane flight manual to include procedures to use when the left or right generator is selected OFF. This proposed AD was prompted by a false cross-feed command to the right-hand fuel control card, due to the cross-feed

inputs on the left- and right-hand fuel control cards being connected together and causing an imbalance of fuel between the left and right wing tanks. We are proposing this AD to prevent lateral imbalance of the airplane, which can be corrected by deflecting the aileron trim, but which increases the pilot's workload. Uncontrolled fuel cross-feed results in lateral imbalance that could exceed the airplane's limitation in a short period of time. Exceeding the lateral imbalance limit could result in reduced control of the airplane.

**DATES:** We must receive comments on this proposed AD by October 17, 2011.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal*: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax*: 202-493-2251.

- *Mail*: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue, SE., Washington, DC 20590.
- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Cessna Aircraft Co., P.O. Box 7706, Wichita, Kansas 67277; telephone 316-517-6215; fax 316-517-5802; e-mail [citationpubs@cessna.textron.com](mailto:citationpubs@cessna.textron.com); Internet <https://www.cessnasupport.com/newlogin.html>.

You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (*phone*: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Nhien Hoang, Aerospace Engineer, Electrical Systems and Avionics Branch, ACE-119W, FAA, Wichita Aircraft Certification Office, 1801 Airport Road,

Room 100, Mid-Continent Airport, Wichita, Kansas 67209; *phone*: (316) 946-4190; *fax*: (316) 946-4107; *e-mail*: [nhien.hoang@faa.gov](mailto:nhien.hoang@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2011-0913; Directorate Identifier 2011-NM-031-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

##### Discussion

We received a report that a Model 680 airplane in flight displayed a DC EMER BUS L amber crew alerting system (CAS) message. Per the emergency/abnormal procedures checklist, the flightcrew identified a fault on the left main electrical bus and selected the left generator to OFF.

The co-pilot (flying the airplane due to the pilot's primary flight display being disabled by the left generator OFF, which also disabled the left fuel quantity indication) observed that an increasing amount of right aileron control input was required to maintain a wings-level attitude.

After the airplane safely landed, investigation showed that the left tank had 5,500 pounds of fuel (full) and the right tank 3,300 pounds. The flightcrew confirmed it had not selected the fuel cross-feed during flight. During the 20 minutes that elapsed between selecting the left generator OFF and landing, sufficient fuel had migrated from the right to the left tank creating an imbalance of 2,200 pounds. The maximum permissible fuel imbalance for this airplane is 400 pounds.

Loss of power on the left main electrical bus results in a false cross-feed command to the right-hand fuel control card, due to the cross-feed inputs on the left- and right-hand fuel control cards being connected together, thereby causing an imbalance of fuel between the left and right wing tanks.